

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D C C 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T
0 1 REPORT SOURCE L 0 5 0 0 0 3 1 6 7 0 6 0 3 8 0 8 0 7 0 2 8 0 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 DURING NORMAL OPERATIONS ESF VENT FAN HV-AES-1 CIRCUIT BREAKER TRIPPED DUE
0 3 TO A SHORT CIRCUIT IN THE MOTOR CONNECTION BOX, THAT CONSTITUTED AN
0 4 INOPERABLE VENTILATION SYSTEM PER T.S. 3.7.6.1. ACTION REQUIREMENTS
0 5 WERE MET AND THE SYSTEM RETURNED TO SERVICE 6/05/80 FOLLOWING MOTOR
0 6 REPLACEMENT. ON 6/14/80, SIMILAR FAILURE OCCURRED ON HV-AES-2.
0 7 AGAIN THE ACTION REQUIREMENTS WERE MET. THE MOTOR AND POWER CABLE
0 8 WERE REPLACED. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. FIRST OCCURRENCE.
7 8 9 80

0 9 S H 11 E 12 A 13 E L E C O N 14 Z 15 Z 16
7 8 9 10 11 12 13 18 19 20
17 LER/RO REPORT NUMBER 8 0 23 0 2 5 26 0 3 28 30 L 31 32 0
33 34 35 36 37 40 41 42 43 44 47
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
A 18 Z 19 Z 20 Z 21 0 0 0 0 22 N 23 N 24 A 25 R 1 6 5 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE CAUSE OF THE EVENT WAS APPARENTLY FAILURE OF THE INSULATION ON THE
1 1 WIRING IN THE CONNECTION BOXES. BOTH MOTORS WERE REPLACED AND THE SUPPLY
1 2 CABLE TO HV-AES-2 WAS REPLACED. THE DAMAGED PORTION OF THE HV-AES-1 SUPPLY
1 3 CABLE WAS REMOVED AND THE REMAINING CABLE TERMINATED TO THE NEW MOTOR.
1 4 THE HV-AES MOTOR TERMINATIONS IN UNIT 1 WERE INSPECTED AND REINSULATED.
7 8 9 80

1 5 E 28 1 0 0 29 30 N/A 31 A 32 OPERATOR OBSERVATION
7 8 9 10 12 13 44 45 46 80

1 6 Z 33 Z 34 35 N/A 36 LOCATION OF RELEASE
7 8 9 10 11 44 45 80

1 7 0 0 0 37 Z 38 39 N/A
7 8 9 10 11 12 13 80

1 8 0 0 0 40 41 N/A
7 8 9 10 11 12 80

1 9 Z 42 43 N/A
7 8 9 10 11 12 80

2 0 N 44 45 N/A
7 8 9 10 11 12 80

NAME OF PREPARER M. S. BROWN

PHONE: (616) 465-5901, EXT. 1398

800 709 0292

(3) (b) (7) (C)