

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

**CONTROL BLOCK:**

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	1	6	7	1	2	0	7	8	0	8	0	1	0	6	8	1	9
60	61								68	69						74	75							80
DOCKET NUMBER											EVENT DATE						REPORT DATE							

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)**

0 2 | DURING LOW POWER OPERATION, A 20 PSIG DIFFERENCE BETWEEN PRESSURIZER PRESSURE

0 3 | CHANNELS EXISTED. TRANSMITTER NPP-153 WAS FOUND TO HAVE EXCESSIVE DRIFT IN A NON-

0 4 | CONSERVATIVE DIRECTION CAUSING THE CORRESPONDING PRESSURIZER PRESSURE - HIGH REACTOR

0 5 | TRIP BISTABLE SETPOINT TO EXCEED THE LCO LIMIT BY 4.32 PSIG, T.S. TABLE 2.2-1 ITEM

0 6 | 10. THE APPROPRIATE ACTION REQUIREMENT OF T.S. TABLE 3.3-1 WAS MET. SIMILAR

0 7 | OCCURRENCES INCLUDE: 050-315/79-42.

0 8 |

SYSTEM CODE I A 11		CAUSE CODE E 12		CAUSE SUBCODE E 13		COMPONENT CODE I N S T R U 14				COMP. SUBCODE T 15		VALVE SUBCODE Z 16					
LER/RO REPORT NUMBER 17		EVENT YEAR 8 0 21 22		SEQUENCIAL REPORT NO. 0 3 7 24 25 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32							
ACTION TAKEN E 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 37 38 39 40		ATTACHMENT SUBMITTED Y 23		NPRD-4 FORM SUB. Y 24		PRIME COMP. SUPPLIER A 25		COMPONENT MANUFACTURER B 0 8 0 26 44 45 46 47	

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | THE PRESSURIZER PRESSURE TRANSMITTERS WERE RECALIBRATED. TRANSMITTERS NPP-151,  
1 1 | NPP-153 AND NPS-153 WERE FOUND TO HAVE DRIFTED EXCESSIVELY. ONLY TRANSMITTER NPP-153  
1 2 | (BARTON-MODEL NO.763) DRIFTED EXCESSIVELY IN A NON-CONSERVATIVE DIRECTION SUCH THAT  
1 3 | THE REACTOR TRIP BISTABLE TRIP SETPOINT WOULD EXCEED THE LCO VALUE. SINCE RECALI-  
1 4 | BRATING THESE TRANSMITTERS, THE PRESSURIZER PRESSURE INDICATION (SEE ATTACHED PAGE)

7 8 9 FACILITY STATUS (28) 10 11 12 % POWER (29) 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 OTHER STATUS (30) 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 METHOD OF DISCOVERY (31) 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 DISCOVERY DESCRIPTION (32) 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 OPERATOR OBSERVATION

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 Z 33 10 34

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES										
NUMBER			TYPE	DESCRIPTION						
1	7	0	0	0	(37)	Z	(38)	NA		

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0	0
0	0	0	40
		NA	

7	8	9	11	12	
LOSS OF OR DAMAGE TO FACILITY (43)					
TYPE		DESCRIPTION			
1	9	Z (42)	NA		

8101090692

		PUBLICITY		(45)		NRC USE ONLY
ISSUED	DESCRIPTION	(44)	NA	.		
2	0	N				

NAME OF PREPARER Jack L. Rischling

PHONE: (616) 465-5901

**NRC USE ONLY**

917-926



ATTACHMENT TO LER # 80-037/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

HAS BEEN CHECKED PERIODICALLY TO ENSURE NO ADDITIONAL INSTRUMENT DRIFT PROBLEMS HAVE OCCURRED. NO FURTHER ACTION IS REQUIRED AS A RESULT OF THIS EVENT.

THE  
FEDERAL BUREAU OF INVESTIGATION  
UNITED STATES DEPARTMENT OF JUSTICE  
WASHINGTON, D. C. 20535