

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8102270813 DOC.DATE: 81/02/20 NOTARIZED: NO DOCKET #
 FACIL:50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH.NAME AUTHOR AFFILIATION
 RISCHLING,J. Indiana & Michigan Electric Co.
 RECIP.NAME: RECIPIENT AFFILIATION
 Region 3, Chicago, Office of the Director

SUBJECT: Updated LER 80-035/03X-1:on 801206,rod position indication
 for rod N=9 did not respond properly while pulling shutdown
 control rods in preparation of going critical.Connector on
 top of rod position detector assembly appeared stepped on.

DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR 1 ENCL 1 SIZE:1x2
 TITLE: Incident Reports

NOTES:Send 3 copies of all material to I&E.


05000316

ACTION:	RECIPIENT ID CODE/NAME		COPIES		RECIPIENT ID CODE/NAME		COPIES	
			LTTR	ENCL			LTTR	ENCL
	VARGA,S.	04	3	3				
INTERNAL:	A/D COMP&STRU06		1	1	A/D ENV TECH 07		1	1
	A/D MATL & QU08		1	1	A/D OP REACT009		1	1
	A/D PLANT SYS10		1	1	A/D RAD PROT 11		1	1
	A/D SFTY ASSE12		1	1	ACC EVAL BR 14		1	1
	AEOD		3	3	ASLBP/J.HARD		1	1
	AUX SYS BR 15		1	1	CHEM ENG BR 16		1	1
	CONT SYS BR 17		1	1	CORE PERF BR 18		1	1
	DIR,DIV OF LIC		1	1	DIR,ENGINEERI20		1	1
	DIR,HUM FAC S21		1	1	DIR,SYS INTEG22		1	1
	EFF TR SYS BR23		1	1	EQUIP QUAL BR25		1	1
	GEOSCIENCES 26		1	1	I&C SYS BR 29		1	1
	I&E: 05		2	2	JORDAN,E./IE		1	1
	LIC GUID BR 30		1	1	MATL ENG BR 32		1	1
	MECH ENG BR 33		1	1	MPA		3	3
	NRC PDR 02		1	1	OP EX EVAL BR34		3	3
	OR ASSESS BR 35		1	1	POWER SYS BR 36		1	1
	RAD ASSESS BR39		1	1	REACT SYS BR 40		1	1
	REG FILE 01		1	1	REL & RISK A 41		1	1
	SFTY PROG EVA42		1	1	STRUCT ENG BR44		1	1
	SYS INTERAC B45		1	1				
EXTERNAL:	ACRS	46	16	16	LPDR 03		1	1
	NSIC	05	1	1	TERA:DOUG. MAY		1	1

MAR 02 1981

TOTAL NUMBER OF COPIES REQUIRED: LTTR

71 ENCL 71



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

February 20, 1981

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:


Attached please find Licensee Event Report RO 80-035/03X-1 which was revised to add a more definitive Cause Description and Corrective Action.

Sincerely,

D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.S. Hunter
R.W. Jurgensen
R.F. Kroeger
R.W. Kilburn
E. Swanson/N. DuBry RO:III
R.C. Callen MPSC
G. Charnoff, Esq.
J.M. Hennigan
W. Lavallee EPRI
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (30 copies)
Dir., MIPC (3 copies)



FEB 24 1981

A002
5
11/1



(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80				
	6	0	5	0	0	0	3	1	6	7	1	2	0	6	8	0	8	0	2	2	0	8	1	9

DOCKET NUMBER

EVENT DATE

REPORT DATE

08

7		8		9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE																											
0		9		I		E		E		X		E L E C T R O N						Z		Z																											
7		8		9		10		11		12		13						18		19		20																									
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER																			
17		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		40		41		42		43		44		47	
8		0		0		3		5		0		3		X		1		A		Z		C		B		0		0		7		N		Y		Z		X		9		9		9			

1	4	
---	---	--

7 8 9
FACILITY STATUS (28) 1 5 C
% POWER 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
0 0 0 0 NA
METHOD OF DISCOVERY (31) 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
B OPERATOR OBSERVATION (32)

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)
1 6 7 33 7 34 NA
2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

PERSONNEL EXPOSURES		TYPE		DESCRIPTION
NUMBER				
1	7	0	0	0
		37	Z	38
				NA

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1 8	0 0 0	40	NA

7		8	9	11	12	
		LOSS OF OR DAMAGE TO FACILITY				
TYPE		DESCRIPTION				
1	9	Z	42	NA		43

20		N		44	NA										NRC USE ONLY									
----	--	---	--	----	----	--	--	--	--	--	--	--	--	--	--------------	--	--	--	--	--	--	--	--	--

PHONE: 616-465-5901

SUPPLEMENT TO LER 50-316/80-35

CAUSE DESCRIPTION

THE DEFECTIVE CONNECTOR APPEARED TO HAVE BEEN STEPPED ON. IT SHOULD BE POINTED OUT THAT THE AREA ABOVE THE REACTOR HEAD IS A VERY DIFFICULT AREA TO WORK IN. SUPPORT CABLES ARE STRUNG OVER THE REACTOR HEAD TO FORM A GRID WHICH SUPPORTS INSTRUMENTATION AND POWER CABLES. DURING EXTENSIVE JOBS, PLANKS ARE PLACED ON THE SUPPORT CABLES TO PREVENT ANY DAMAGE AS REPORTED BY THIS LER. AT TIMES, IT IS NOT PRACTICABLE TO USE THE ADDITIONAL SUPPORTS ON THE GRID AREA WHICH INCREASES THE POSSIBILITY OF SUCH AN EVENT. TO PREVENT REOCCURRENCE, A MEMO WAS SENT TO ALL DEPARTMENT HEADS TO REVIEW THIS EVENT WITH THEIR PERSONNEL WHO MAY WORK IN THE AREA OF THE REACTOR HEAD.

