



THE UNIVERSITY OF CHICAGO LIBRARY

ITEM 10

Operations Department was performing ISI Test on Check Valve PW-275 on the Primary Water Supply to the Containment. Air operated valve NCR-252 was placed in the shut position and the test connection between these two valves opened to verify PW-275 seats on reverse flow in system. When leakage was observed at test connection the Operator looked at NCR-252 and found it was not fully seated, even though Control Room indication indicated valve was shut. A C&I Technician found the stroke adjusting nut improperly set and not permitting the valve to fully shut. The stroke was readjusted and the valve timing cycle was verified acceptable. The test connection was again opened with NCR-252 in the shut position and verified NCR-252 and PW-275 were both shut with no leakage from the test connection.

A review of maintenance and testing records revealed the last maintenance and stroke adjustment to NCR-252 were performed on February 4, 1980. Check valve PW-275 was successfully tested on July 4, 1980 with no leakage back through the check valve or through NCR-252. Valve NCR-252 had been cycled for Surveillance Testing on July 29, 1980 with acceptable timing and correct valve position indication in the Control Room.

Unit 2 had entered Mode 4 on July 12, 1980 and Mode 1 on July 13, 1980 and had operated at various power levels up to 100% until October 18, 1980 when the Unit tripped with a generator ground. Unit 2 had entered Mode 5 again on October 21, 1980. The maximum time NCR-252 could have been in a condition of not being able to fully shut as a Containment Isolation Valve was 81 days, but the exact number of days could not be determined.

