

# PRIORITY 1

ACCELERATED RIDS PROCESSING

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9503310040      DOC. DATE: 95/03/27      NOTARIZED: NO      DOCKET #  
 FACIL: 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana M      05000316  
 AUTH. NAME      AUTHOR AFFILIATION  
 WEBER, G.A.      Indiana Michigan Power Co. (formerly Indiana & Michigan Ele  
 BLIND, A.A.      Indiana Michigan Power Co. (formerly Indiana & Michigan Ele  
 RECIP. NAME      RECIPIENT AFFILIATION

SUBJECT: LER 95-002-00: on 950223, reactor trip occurred from steam  
 flow/steam feed flow mismatch coincident w/low level in SG.  
 Caused by transistor failure & blown fuse. Defective signal  
 controller replaced. W/950327 ltr.

DISTRIBUTION CODE: IE22T      COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 5  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

### NOTES:

RECIPIENT ID CODE/NAME	COPIES	LTTR	ENCL	RECIPIENT ID CODE/NAME	COPIES	LTTR	ENCL
PD3-1 PD	1		1	HICKMAN, J	1		1
INTERNAL: AEOD/SPD/RAB	2		2	AEOD/SPD/RRAB	1		1
FILE CENTER 02	1		1	NRR/DE/ECGB	1		1
NRR/DE/EELB	1		1	NRR/DE/EMEB	1		1
NRR/DISP/PIPB	1		1	NRR/DOPS/OECB	1		1
NRR/DRCH/HHFB	1		1	NRR/DRCH/HICB	1		1
NRR/DRCH/HOLB	1		1	NRR/DRSS/PRPB	2		2
NRR/DSSA/SPLB	1		1	NRR/DSSA/SRXB	1		1
RES/DSIR/EIB	1		1	RGN3 FILE 01	1		1
EXTERNAL: L ST LOBBY WARD	1		1	LITCO BRYCE, J H	2		2
NOAC MURPHY, G.A	1		1	NOAC POORE, W.	1		1
NRC PDR	1		1	NUDOCS FULL TXT	1		1

### NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL  
 DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM  
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTTR    27    ENCL    27

Indiana Michigan  
Power Company  
Cook Nuclear Plant  
One Cook Place  
Bridgman, MI 49106  
616 465 5901



March 27, 1995

United States Nuclear Regulatory Commission  
Document Control Desk  
Rockville, Maryland 20852

Operating Licenses DPR-74  
Docket No. 50-316

Document Control Manager:

In accordance with the criteria established by  
10 CFR 50.73 entitled Licensee Event Report System, the  
following report is being submitted:

95-002-00

Sincerely,

A handwritten signature in dark ink, appearing to read 'A. A. Blind'.

A. A. Blind  
Plant Manager

/mr

Attachment

c: J. B. Martin, Region III  
E. E. Fitzpatrick  
P. A. Barrett  
R. F. Kroeger  
M. A. Bailey - Ft. Wayne  
NRC Resident Inspector  
J. B. Hickman - NRC  
J. R. Padgett  
G. Charnoff, Esq.  
D. Hahn  
INPO  
S. J. Brewer

010041

9503310040 950327  
PDR ADDCK 05000316  
S PDR

1022'

## LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS  
INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD  
COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION  
AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR  
REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO  
THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF  
MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

## FACILITY NAME (1)

DONALD C. COOK NUCLEAR PLANT - UNIT 2

## DOCKET NUMBER (2)

05000 316

## PAGE (3)

1 OF 4

TITLE (4) REACTOR TRIP FROM LOOP-4 STEAM FLOW/FEED FLOW MISMATCH COINCIDENT WITH A  
LOW LEVEL IN NO. 4 STEAM GENERATOR

EVENT DATE (5)			LER NUMBER (6)			REPORT NUMBER (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
02	23	95	95	-- 002 --	00	03	27	95	FACILITY NAME	DOCKET NUMBER
										05000
									FACILITY NAME	DOCKET NUMBER
										05000

OPERATING MODE (9)	1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)				
POWER LEVEL (10)	100	20.402(b)	20.405(c)	<input checked="" type="checkbox"/>	50.73(a)(2)(iv)	73.71(b)
		20.405(a)(1)(i)	50.36(c)(1)	<input type="checkbox"/>	50.73(a)(2)(v)	73.71(c)
		20.405(a)(1)(ii)	50.36(c)(2)	<input type="checkbox"/>	50.73(a)(2)(vii)	OTHER
		20.405(a)(1)(iii)	50.73(a)(2)(i)	<input type="checkbox"/>	50.73(a)(2)(viii)(A)	(Specify in Abstract below and in Text, NRC Form 366A)
		20.405(a)(1)(iv)	50.73(a)(2)(ii)	<input type="checkbox"/>	50.73(a)(2)(viii)(B)	
		20.405(a)(1)(v)	50.73(a)(2)(iii)	<input type="checkbox"/>	50.73(a)(2)(x)	

## LICENSEE CONTACT FOR THIS LER (12)

## NAME

G. A. WEBER - PLANT ENGINEERING SUPERINTENDENT

## TELEPHONE NUMBER (include Area Code)

616-465-5901

## COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
X	JB	FC	T040	Y					

## SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
<input checked="" type="checkbox"/>	<input type="checkbox"/>				

## ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On February 23, 1995, at 1645 hours with Unit 2 in Mode 1 (Power Operation) at 100 percent Rated Thermal Power, a Reactor Trip occurred from a steam flow/steam feed flow mismatch coincident with a low level in the No. 4 Steam Generator. These conditions were the result of an apparent transistor failure and blown fuse on a digital board in the feed flow signal controller for the Loop 4 Feedwater Regulating Valve (FRV). The failed signal controller caused the FRV to close, creating a steam flow/feed flow mismatch. The Control Room Operator attempted to take manual control of the FRV. A Reactor Trip occurred when a low level condition was created in No. 4 Steam Generator. Following the Reactor Trip all systems functioned as required, with the exception of the generator trip circuitry. The Main Generator failed to trip when a limit switch, associated with Turbine Control/Stop Valve-D did not make-up mechanically when the valve closed. The generator remained connected to the grid for 128 seconds, until the generator was manually tripped. The defective FRV signal controller was replaced. The misaligned limit switch on Turbine Control/Stop Valve-D was repositioned for proper mechanical alignment. This event had no actual or potential impact on public health and safety.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
DONALD C. COOK NUCLEAR PLANT - UNIT 2	0   5   0   0   0   3   1   6	9   5	—   0   0   2	—   0   0	0   2	OF	0   4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Conditions Prior to Occurrence

Unit 2 in Mode 1 (Power Operation), at 100 percent Rated Thermal Power and no unusual evolutions in progress.

Description of Event

On February 23, 1995 at 1645 hours, a Unit 2 Reactor Trip occurred. The Reactor Trip was the result of a reactor protection actuation from a steam flow/feed flow mismatch, coincident with a low level in No. 4 Steam Generator (EIIS/SB-SG). A feed flow controller (EIIS/JB-FC) associated with the Loop 4 Feedwater Regulating Valve (2-FRV-240) (EIIS/JB-FCV) failed as a result of an apparent transistor failure and blown fuse on a digital board. Valve 2-FRV-240 closed as a result of the feed flow controller failure. The Control Room Operator attempted to take manual control of 2-FRV-240, to increase the level in No. 4 Steam Generator, but the level in No. 4 Steam Generator had already decreased to the low level setpoint, which resulted in the Reactor Trip.

Following the trip, all systems functioned as required, with the exception of the Generator Trip System. The generator (EIIS/EL-GEN) failed to trip due to a malfunctioning limit switch (EIIS/IT-ZIS) on the Turbine Control/Stop Valve-D (CV-D) (EIIS/IT-FCV), and was manually tripped from the Control Room. as a result of the switch failure, the generator remained connected to the grid for 128 seconds. There were no over-voltage or over-current conditions recorded.

There were two equipment problems identified during the Reactor Trip:

- Failure of feed flow controller for 2-FRV-240
- Failure of Turbine Control/Stop Valve-D limit switch

The 2-FRV-240 feed flow controller failure was attributed to an apparent transistor failure and blown fuse on a digital board in the feed flow controller. The area around the failed transistor was discolored due to excessive heat. The remaining Unit 2 steam generator level controllers, feed flow controllers, and the auto/manual stations are similar. These controllers were inspected for similar heat related problems. None of the inspected components had any indication of heat discoloration. This is the first failure of this type of component, which was installed as an equipment upgrade during the 1994 Refueling Outage.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE (3)			
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER					
DONALD C. COOK NUCLEAR PLANT - UNIT 2	0 5 0 0 0 3 1 6	9 5	0 0 2	0 0	0 0	3	OF	0	4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Description of Event continued

The main generator failed to trip when Control/Stop Valve-D closed and the associated limit switch did not makeup mechanically. The circular disc on the valve stem of Control Valve-D did not make adequate contact with the limit switch and a closed position signal was not indicated. The generator trip circuitry requires closed indication of all of the Main Turbine Stop/Control Valves and all six Reheat/Intercept Valves to actuate the Generator Trip Signal.

Cause of Event

The Reactor Trip was the result of an apparent transistor failure and blown fuse in the Feedwater controller for the No. 4 Steam Generator feedwater regulating valve. This caused the feedwater regulating valve to close, which created a steam flow/feed flow mismatch. When the No. 4 Steam Generator low level alarm setpoint was reached, a Reactor Trip occurred.

Analysis of Event

This event is being reported per 10CFR50.73 (a)(2)(IV) as an event that resulted in automatic actuation of Engineered Safety Features, including the Reactor Protection System. This event was reported to the U. S. Nuclear Regulatory Commission Operations Center as a Four Hour Report, per 10 CFR 50.72(B).

A Reactor Trip occurred following failure of the control circuit for the Loop 2 Feedwater Regulating Valve. This created a Steam Flow/Feed Flow mismatch, coincident with a subsequent low level in the No. 4 Steam Generator. All control rods fully inserted. The turbine tripped as expected. The generator did not trip as expected due to a misaligned limit switch on Control Valve-D. The generator remained connected to the grid for 128 seconds after the Reactor Trip, when the generator was manually tripped. There was no adverse effect noted on the turbine or generator. There was no over-current or over-voltage conditions recorded.

Normal off-site power was available, the emergency diesel generators were in standby, and no safety equipment was out of service prior to the trip. All systems functioned as required with the exception of the Generator Trip System. This event did not have any actual or potential adverse impact on the health and safety of the public.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
DONALD C. COOK NUCLEAR PLANT - UNIT 2	05000316	95	002	00	04	OF	04

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Corrective Actions

The defective signal controller for the Loop-4 Feedwater Regulating Valve was replaced: The remaining Unit 2 steam generator level controllers, feed flow controllers, and the auto/manual stations were inspected for indications of similar heat related problems. None of the controllers inspected had an indication of heat discoloration similar to that found in the Loop-4 feed flow controller.

The misaligned limit switch on Control Valve-D was repositioned for proper mechanical alignment.

Failed Component Identification

Component Name: Feed Flow Controller for Loop-4 Feed Regulating Valve  
(2-FRV-240)

Manufacturer: ABB Kent Taylor

Model: Part No. - 1701RZ10003C XL

EIIS Code: JB-FC

Previous Similar Events

None - this is the first event of this type.