

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9509190001 DOC.DATE: 95/09/14 NOTARIZED: NO DOCKET #
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
 AUTH.NAME AUTHOR AFFILIATION
 NICHOLS,W. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 BLIND,A.A. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 95-005-00:on 950728,lack of communication during bus
 deenergization resulted in unexpected turbine driven
 auxiliary feedpump start.Pump was secured from svc after
 being auto started & declared inoperable.W/950914 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTTR 1 ENCL 1 SIZE: 4
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES. LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-1 PD	1 1	HICKMAN,J	1 1
INTERNAL:	AEOD/SPD/RAB	2 2	AEOD/SPD/RRAB	1 1
	FILE CENTER	1 1	NRR/DE/ECGB	1 1
	NRR/DE/EELB	1 1	NRR/DE/EMEB	1 1
	NRR/DISP/PIPB	1 1	NRR/DRCH/HHFB	1 1
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1
	NRR/DRPM/PECB	1 1	NRR/DSSA/SPLB	1 1
	NRR/DSSA/SPSB/B	1 1	NRR/DSSA/SRXB	1 1
	RES/DSIR/EIB	1 1	RGN3 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE,J H	2 2
	NOAC MURPHY,G.A	1 1	NOAC POORE,W.	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL
 DESK, ROOM OWFN 5D8 (415-2083) TO ELIMINATE YOUR NAME FROM
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 26 ENCL 26

Indiana Michigan
Power Company
Cook Nuclear Plant
One Cook Place
Bridgman, MI 49106
616 465 5901



September 14, 1995

United States Nuclear Regulatory Commission
Document Control Desk
Rockville, Maryland 20852

Operating Licenses DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by
10 CFR 50.73 entitled Licensee Event Report System, the
following report is being submitted:

95-005-00

Sincerely,

A handwritten signature in cursive script that reads 'A. A. Blind'.

A. A. Blind
Plant Manager

/clc

Attachment

c: H. J. Miller, Region III
E. E. Fitzpatrick
P. A. Barrett
R. F. Kroeger
M. A. Bailey - Ft. Wayne
S. J. Brewer
J. R. Padgett
G. Charnoff, Esq.
D. Hahn
Records Center, INPO
NRC Resident Inspector

40000-
7509190001 750914
PDR ADOCK 05000315
S PDR

A handwritten signature in cursive script, possibly reading 'J. E. 221'.

LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

Donald C. Cook Nuclear Plant - Unit 1

DOCKET NUMBER (2)

05000 315

PAGE (3)

1 OF 3

TITLE (4)

Lack of Communication During Bus Deenergization Results in Unexpected Turbine Driven Auxiliary Feedpump Start

EVENT DATE (5)			LER NUMBER (6)			REPORT NUMBER (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
07	28	95	95	005	00	09	14	95		05000
OPERATING MODE (9)		1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more) (11)							
POWER LEVEL (10)		57	20.402(b)		20.405(c)		X		50.73(a)(2)(iv)	73.71(b)
			20.405(a)(1)(i)		50.36(c)(1)				50.73(a)(2)(v)	73.71(c)
			20.405(a)(1)(ii)		50.36(c)(2)				50.73(a)(2)(vii)	OTHER
			20.405(a)(1)(iii)		50.73(a)(2)(i)				50.73(a)(2)(viii)(A)	(Specify in Abstract below and in Text, NRC Form 366A)
			20.405(a)(1)(iv)		50.73(a)(2)(ii)				50.73(a)(2)(viii)(B)	
			20.405(a)(1)(v)		50.73(a)(2)(iii)				50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

NAME: W. Nichols, Operations Superintendent
TELEPHONE NUMBER (include Area Code): 616/465-5901, x2536

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	X	NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On July 28, 1995, with Unit 1 in Mode 3 and preparations underway for repair work on the 101AB startup transformer, the Turbine Driven Auxiliary Feed Pump (TDAFP) unexpectedly started on an automatic Engineered Safety Feature (ESF) signal. The pump was immediately secured.

The TDAFP start was determined to be the result of undervoltage conditions introduced as part of the transformer repair work when two of the Reactor Coolant Pump (RCP) buses were deenergized. The pump was restored to operable status after power was restored to the buses. The deenergization of the buses was part of the planned evolution, however, the automatic start of the TDAFP had not been identified as an expected occurrence during the pre-job briefings due to lack of communication between Operations management and the Control Room crew.

Based on the available information, this event was originally determined to not be reportable under either 10CFR50.72 or 10CFR50.73. However, the event was later reevaluated and determined to be reportable under 10CFR50.72(b)(2)(ii) and 10CFR50.73(a)(2)(v), as an ESF actuation.

This event has minimal safety significance as it resulted from planned maintenance and was not indicative of a degradation in the level of safety of the plant or a deterioration of plant conditions. At no time was the health or safety of the public in jeopardy.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 60.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Donald C. Cook Nuclear Plant - Unit 1	0 5 0 0 0 3 1 5	9 5	0 0 5	— 0 0	0 2	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Conditions Prior to Event

Unit 1 was in Mode 3, Hot Standby

Event Description

On July 28, 1995, preparations were underway for repair work on the Unit 1 101AB startup transformer. These plans included removing power from the 4 KV balance of plant buses, reenergizing them from the Unit 1 AB Diesel Generator, and then removing power from the A and B Reactor Coolant Pump (RCP) buses in order to facilitate the repairs.

Prior to execution the effects of the plan were discussed. The main concerns were the expected Turbine Driven Auxiliary Feedpump (TDAFP) auto start on undervoltage from the RCP buses and the potential for the RCP bus underfrequency relays to cause the remaining Reactor Coolant Pumps (RCPs) to trip. The TDAFP auto start was discussed by Shift and Operations management, but the possible underfrequency trip of the RCPs received significantly more attention.

When the plan was executed and the balance of plant buses powered from the Diesel Generator, the RCP buses were deenergized one at a time. After the second RCP bus was deenergized the TDAFP auto started due to the standing undervoltage condition on the A and B RCP buses.

Although Shift and Operations management had discussed the expected TDAFP auto start, the Control Room crew had not been briefed and did not expect the generation of the ESF signal or the start of the TDAFP.

Cause of Event

This event is attributable to lack of communications between Operations management and the Control Room crew. The expected TDAFP auto start had been discussed extensively by off-shift personnel, but the pertinent information was not conveyed to the crew during the pre-job briefing.

Analysis of Event

This event was determined to be reportable under 10CFR50.72(b)(2)(ii) and 10CFR50.73(a)(2)(iv), as an unexpected ESF actuation.

This event has minimal safety significance as it resulted from planned maintenance and was not indicative of a degradation in the level of safety of the plant or a deterioration of plant conditions. At no time was the health or safety of the public in jeopardy.

Based on the available information, this event was originally determined to not be reportable under either

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 600 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Donald C. Cook Nuclear Plant - Unit 1	0 5 0 0 0 3 1 5	9 5	0 0 5	0 0	0 3	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

10CFR50.72 or 10CFR50.73. However, the event was reevaluated in August of 1995 and determined to be reportable under 10CFR50.72(b)(2)(ii) and 10CFR50.73(a)(2)(iv), as an unexpected ESF actuation. A red phone call was made on August 17, 1995, in accordance with 10CFR72 reporting requirements. This LER is being submitted within 30 days of the red phone call, but does exceed the 30 day submittal period from the date of the initiating event.

Corrective Actions

The TDAFP was secured from service after it auto started and declared inoperable. The pump was restored to standby, operable status after power was restored to the 4 KV balance of plant buses and the plant lineup restored to normal.

The plant document which governs voluntary entry into Limiting Conditions for Operation (LCOs) will be revised to require that possible ESF/SSPS actuations be identified prior to the start of the evolution.

Failed Component Identification

None

Similar Events

None