

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9610280167 DOC. DATE: 96/10/22 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
 AUTH. NAME AUTHOR AFFILIATION
 FINISSI, M. American Electric Power Co., Inc.
 BLIND, A.A. American Electric Power Co., Inc.
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 96-004-00: on 960922, main generator trip on main transformer sudden overpressure. Due to Lightning Strike causes reactor trip. SPT relay was tested & replaced. W/961022 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 14
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD3-3 PD	1 1	HICKMAN, J	1 1
INTERNAL: AEOD/SPD/RAB	2 2	AEOD/SPD/RRAB	2 2
<u>FILE CENTER</u>	1 1	NRR/DE/ECGB	1 1
NRR/DE/EELB	1 1	NRR/DE/EMEB	1 1
NRR/DRCH/HHFB	1 1	NRR/DRCH/HICB	1 1
NRR/DRCH/HOLB	1 1	NRR/DRCH/HQMB	1 1
NRR/DRPM/PECB	1 1	NRR/DSSA/SPLB	1 1
NRR/DSSA/SRXB	1 1	RES/DSIR/EIB	1 1
RGN3 FILE 01	1 1		
EXTERNAL: L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1
NOAC MURPHY, G.A	1 1	NOAC POORE, W.	1 1
NRC PDR	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED

TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 25

C
A
T
E
G
O
R
Y

1

D
O
C
U
M
E
N
T

American Electric Power
Cook Nuclear Plant
One Cook Place
Bridgman, MI 49106
616 465 5901



October 22, 1996

United States Nuclear Regulatory Commission
Document Control Desk
Rockville, Maryland 20852

Operating Licenses DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

96-004-00

Sincerely,

A handwritten signature in cursive script that reads "A. A. Blind".

A. A. Blind
Site Vice President

/mbd

Attachment

c: A. B. Beach, Region III
E. E. Fitzpatrick
P. A. Barrett
S. J. Brewer
J. R. Padgett
D. Hahn
Records Center, INPO
NRC Resident Inspector

280059

9610280167 961022
PDR ADOCK 05000315
S PDR

IE 20%

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)
Donald C. Cook Nuclear Plant - Unit 1DOCKET NUMBER (2)
50-315

Page 1 of 3

TITLE (4)

Main Generator Trip on Main Transformer Sudden Overpressure Due to Lightning Strike Causes Reactor Trip

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
09	22	96	96	- 004 -	00	10	22	96	FACILITY NAME	DOCKET NUMBER

OPERATING MODE (9)	1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 50.73(a)(2)(iii) (Check one or more) (11)			
POWER LEVEL (10)	88	20.2201(b)	20.2203(a)(3)(i)	50.73(a)(2)(iii)	73.71(b)
		20.2203(a)(1)	20.2203(a)(3)(ii)	X 50.73(a)(2)(iv)	73.71(c)
		20.2203(a)(2)(i)	20.2203(a)(4)	50.73(a)(2)(v)	OTHER
		20.2203(a)(2)(ii)	50.36(c)(1)	50.73(a)(2)(vii)	(Specify in Abstract below and in Text, NRC Form 366A)
		20.2203(a)(2)(iii)	50.36(c)(2)	50.73(a)(2)(viii)(A)	
		20.2203(a)(2)(iv)	50.73(a)(2)(i)	50.73(a)(2)(viii)(B)	
		20.2203(a)(2)(v)	50.73(a)(2)(ii)	50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

NAME

Michael Finissi, Nuclear Engineering - System Engineering Mechanical Systems

TELEPHONE NUMBER (Include Area Code)

616/465-5901, x1045

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES

X NO

EXPECTED SUBMISSION DATE (15)

MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On September 22, 1996, at 0049 hours with Unit 1 in Mode 1 at 88 percent power, a Unit 1 Main Transformer Sudden Pressure Trip (SPT) signal was received. This signal caused a Main Generator trip, which in turn, caused a reactor trip. This event is being reported in accordance with 10CFR50.73(a)(2)(iv), as any event or condition that results in a manual or automatic actuation of any Engineered Safety Feature (ESF), including the Reactor Protection System (RPS).

The Main Transformer Sudden Pressure trip signal is attributed to a confirmed lightning strike which occurred approximately 200 milliseconds prior to the receipt of the SPT signal. The lightning strike was a through fault and seen by the Main Generator, but was not considered a large magnitude transient when compared with previous strikes at the site.

The SPT relay was tested and replaced due to inconsistent performance. The balance of the SPT relay circuitry was tested and found to be satisfactory. Transformer oil sample analysis was performed and verified that the SPT signal was spurious.

After the reactor trip, all safety systems operated normally in response to the trip signal and all post reactor trip responses were normal. The reactor was stabilized in Mode 3, Hot Standby. This event was evaluated and determined to have no actual or potential adverse effect on the health and safety of the public.

LICENSEE EVENT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL	REVISION	
Cook Nuclear Plant - Unit 1	50-315	96	- 004 -	00	2 OF 3

TEXT (if more space is required, use additional NRC Form 366A's) (17)

Conditions Prior to Event

Mode 1, Power Operation, at 88 percent Rated Thermal Power

Description of Event

On September 22, 1996, at 0048 hours, Unit 1 was operating at 88 percent power with all safety systems operational. Surveillance procedure 01 OHP 4030 STP.027AB, "AB Diesel Generator Operability Test", on the Unit 1 AB Emergency Diesel Generator (EDG) was nearing successful completion with the EDG running, but not loaded.

At 0048 hours 54 seconds, during a thunderstorm, both the Unit 1 and Unit 2 oscillographs recorded a lightning strike. The Unit 1 oscillograph initiated due to a Main Generator undervoltage condition which resulted from the strike. Although the Unit 2 oscillograph started, no other events occurred on that unit.

Approximately 200 milliseconds after the strike, the Operations Sequence Monitor (OSM) picked up a Unit 1 Main Transformer Sudden Pressure Trip (SPT) signal event. The SPT signal operated the Unit Differential Relays. The reactor trip breakers opened approximately 400 milliseconds after initial receipt of the SPT relay signal, due to the receipt of a turbine trip signal. The reactor trip officially occurred at 0049 hours.

All safety systems operated normally and the unit was stabilized in Mode 3 at normal post trip no load pressure and temperature.

Cause of Event

The Main Transformer Sudden Pressure trip signal is attributed to the confirmed lighting strike which occurred approximately 200 milliseconds prior to the initiation of the SPT relay signal. The lightning strike was a through fault and seen by the Main Generator, but was not considered a large magnitude transient when compared with previous strikes at the site.

The transformer and the SPT relay were both investigated to determine if a transformer fault produced the trip. The analysis performed on oil taken from the transformer after the event showed results comparable to results of analysis performed on the same transformer 3 days prior to the trip. No gas or gas bubbles were found in the SPT relay gas accumulation chamber. Transformer conservator level was as expected for ambient conditions and oil temperature. All investigative results indicated that no damage occurred to the transformer as a result of the lightning strike, and that the SPT relay signal was most likely spurious.

LICENSEE EVENT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)		DOCKET NUMBER (2)		LER NUMBER (6)			PAGE (3)
Cook Nuclear Plant - Unit 1		50-315		YEAR	SEQUENTIAL	REVISION	3 OF 3
				96	-- 004 --	00	

TEXT (if more space is required, use additional NRC Form 366A's) (17)

Analysis of Event

This event is being reported in accordance with 10CFR50.73(a)(2)(iv), as any event or condition that results in a manual or automatic actuation of any Engineered Safety Feature (ESF), including the Reactor Protection System (RPS). The RPS signal was in response to a turbine trip signal, which originated with the Main Transformer Sudden Pressure Trip relay signal.

Normal offsite power was available, the CD Emergency Diesel Generator was in standby and the AB EDG was running unloaded. No safety equipment was out of service prior to the trip. After the reactor trip, all safety systems operated normally in response to the trip signal and all post reactor trip responses were normal. This event was evaluated and determined to have no actual or potential adverse effect on the health and safety of the public.

Corrective Actions

The SPT relay was tested and replaced due to inconsistent performance. The balance of the SPT relay circuitry was tested and found to be satisfactory. Transformer oil sample analysis was performed and verified that the SPT signal was spurious.

Failed Component Identification

Not Applicable

Previous Similar Events

None