

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9711280303 DOC. DATE: 97/11/17 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
 AUTH. NAME AUTHOR AFFILIATION
 PISARSKY, F. Indiana Michigan Power Co.
 BLIND, A.A. Indiana Michigan Power Co.
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 97-024-01: on 970917, matl was discovered on containment degrades containment recirculation sump. Caused by improperly installed Temp-Mat. Fiberfrax matl & duct tape have been removed from containments. W/971117 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

RECIPIENT ID CODE/NAME	COPIES	LTTR	ENCL	RECIPIENT ID CODE/NAME	COPIES	LTTR	ENCL
PD3-3 PD	1		1	HICKMAN, J	1		1
INTERNAL: AEOD/SPD/RAB	2		2	AEOD/SPD/RRAB	1		1
<u>FILE CENTER</u>	1		1	NRR/DE/ECGB	1		1
NRR/DE/EELB	1		1	NRR/DE/EMEB	1		1
NRR/DRCH/HHFB	1		1	NRR/DRCH/HICB	1		1
NRR/DRCH/HOLB	1		1	NRR/DRCH/HQMB	1		1
NRR/DRPM/PECB	1		1	NRR/DSSA/SPLB	1		1
NRR/DSSA/SRXB	1		1	RES/DET/EIB	1		1
RGN3 FILE 01	1		1				
EXTERNAL: L ST LOBBY WARD	1		1	LITCO BRYCE, J H	1		1
NOAC POORE, W.	1		1	NOAC QUEENER, DS	1		1
NRC PDR	1		1	NUDOCS FULL TXT	1		1

NOTE TO ALL "RIDS" RECIPIENTS:
 PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 24

C
A
T
E
G
O
R
Y

1

D
O
C
U
M
E
N
T

Indiana Michigan
Power Company
Cock Nuclear Plant
One Cock Place
Brogman, MI 49106



November 17, 1997

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Operating Licenses DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

97-024-01

Sincerely,

A. A. Blind
Site Vice President

/mbd

Attachment

c: A. B. Beach, Region III
E. E. Fitzpatrick
P. A. Barrett
S. J. Brewer
J. R. Padgett
D. Hahn
Records Center, INPO
NRC Resident Inspector

11

Terz

9711280303 971117
PDR ADDCK 05000315
S PDR



LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MN88 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)
Donald C. Cook Nuclear Plant - Unit 1

DOCKET NUMBER (2)
50-315

Page 1 of 1

TITLE (4)

Interim LER - Update to Material Discovered in Containment Degrades Containment Recirculation Sump and Results in Condition Outside Design Basis

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME Cook Unit 2	DOCKET NUMBER 50-316
09	17	97	97	-- 024 --	01	11	17	97	FACILITY NAME	DOCKET NUMBER
OPERATING MODE (9)		5	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)							
POWER LEVEL (10)		0	20.2201(b)			20.2203(a)(3)(i)			50.73(a)(2)(iii)	73.71(b)
			20.2203(a)(1)			20.2203(a)(3)(ii)			50.73(a)(2)(iv)	73.71
			20.2203(a)(2)(i)			20.2203(a)(4)			50.73(a)(2)(v)	OTHER
			20.2203(a)(2)(ii)			50.36(c)(1)			50.73(a)(2)(vii)	(Specify in Abstract below and in Text, NRC Form 366A)
			20.2203(a)(2)(iii)			50.36(c)(2)			50.73(a)(2)(viii)(A)	
			20.2203(a)(2)(iv)			50.73(a)(2)(i)			50.73(a)(2)(viii)(B)	
			20.2203(a)(2)(v)		X	50.73(a)(2)(ii)			50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

NAME _____

TELEPHONE NUMBER (Include Area Code)

Mr. Frank Pisarsky, Mechanical Component Engineering Manager

616/465-5901. x2607

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

[illegible]

SUPPLEMENTAL REPORT EXPECTED (14)

X	YES	NO	EXPECTED SUBMISSION DATE (15)	MONTH 12	DAY 31	YEAR 97
---	-----	----	-------------------------------------	-------------	-----------	------------

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

This revision is being sent to update the status of the evaluation of this condition. On September 11, 1997 a fibrous material, known as Fiberfrax, was identified in a Unit 2 electrical cable tray. An investigation was initiated to determine the scope and magnitude of this condition. On September 17, 1997, at 1400 hours, it was determined that Fiberfrax was present in both Unit 1 and 2 containments in enough quantity to potentially cause excessive blockage of the containment recirculation sump screen, during the recirculation phase of a Loss of Coolant Accident (LOCA) and render the sump inoperable. A NRC prompt notification was made at 1629 hours on September 17, 1997, under 10CFR50.72(b)(2)(i). On October 17, 1997, Rev. 0 of this LER also reported that additional walkdowns identified instances in both containments where the fibrous insulation called Temp-Mat was not properly installed and where duct tape was present. The Fiberfrax, and duct tape have been removed from the containments.

The following is being reported to provide an update on the actions and evaluations being taken to resolve potential debris in containment and the impact on the recirculation sump under LOCA conditions. As reported in our telephone update on October 23, 1997, an analysis using bounding numbers from the best available industry data was performed. The fibrous material that was found in the cable trays and temporary insulation on piping on Unit 1 would not have caused the recirculation sump to be inoperable. A similar analysis for Unit 2 found that the Unit 2 recirculation sump would also have been operable. The NRC staff has questioned some aspects of the methodology used for the above analyses. We are evaluating the use of a different analytical methodology for debris generation and transport to confirm the operability determinations. We are also evaluating the impact of other materials that may potentially interact with the sump.

This interim LER is being reported under 10CFR50.73(a)(2)(ii)(B), as a condition outside the design basis of the plant. An update to this LER is scheduled to be issued by December 31, 1997, pending completion of the investigation and evaluations.