

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8802030470 DDC DATE: 88/01/28 NOTARIZED: NO DOCKET #
 FACIL: 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME AUTHOR AFFILIATION
 GIBSON Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 SMITH, W. G. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 88-001-00: on 871230, incorrect sample valve lineup for
 VRS-2500 auxiliary bldg vent radiation monitor discovered
 resulting in failure to meet Tech Spec 3.3.3.10 criteria.
 Caused by personnel error. Procedure changed. W/880129 ltr.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

| | RECIPIENT ID CODE/NAME | COPIES LTTR ENCL | RECIPIENT ID CODE/NAME | COPIES LTTR ENCL |
|-----------|---------------------------|---------------------|---------------------------|---------------------|
| | PD3-3 LA | 1 1 | PD3-3 PD | 1 1 |
| | WIGGINGTON, D | 1 1 | | |
| INTERNAL: | ACRS MICHELSON | 1 1 | ACRS MOELLER | 2 2 |
| | AEOD/DOA | 1 1 | AEOD/DSP/NAS | 1 1 |
| | AEOD/DSP/ROAB | 2 2 | AEOD/DSP/TPAB | 1 1 |
| | ARM/DCTS/DAB | 1 1 | DEDRO | 1 1 |
| | NRR/DEST/ADS | 1 0 | NRR/DEST/CEB | 1 1 |
| | NRR/DEST/ELB | 1 1 | NRR/DEST/ICSB | 1 1 |
| | NRR/DEST/MEB | 1 1 | NRR/DEST/MTB | 1 1 |
| | NRR/DEST/PSB | 1 1 | NRR/DEST/RSB | 1 1 |
| | NRR/DEST/SGB | 1 1 | NRR/DLPQ/HFB | 1 1 |
| | NRR/DLPQ/QAB | 1 1 | NRR/DOEA/EAB | 1 1 |
| | NRR/DREP/RAB | 1 1 | NRR/DREP/RPB | 2 2 |
| | NRR/DRIS/SIB | 1 1 | NRR/PMAS/ILRB | 1 1 |
| | REG FILE 02 | 1 1 | RES TELFORD, J | 1 1 |
| | RES/DE/EIB | 1 1 | RES/DRPS DIR | 1 1 |
| | RGN3 FILE 01 | 1 1 | | |
| EXTERNAL: | EG&G GROH, M | 5 5 | FORD BLDG HOY, A | 1 1 |
| | H ST LOBBY WARD | 1 1 | LPDR | 1 1 |
| | NRC PDR | 1 1 | NSIC HARRIS, J | 1 1 |
| | NSIC MAYS, G | 1 1 | | |

Indiana Michigan
Power Company
Cook Nuclear Plant
P.O. Box 458
Bridgman, MI 49106
616 465 5901



January 29, 1988

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Operating License DPR-58
Docket No. 50-316

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73
entitled Licensee Event Reporting System, the following
report is being submitted:

88-001-00

Sincerely,

W. G. Smith, Jr.
Plant Manager

WGS:afh

Attachment

cc: J. E. Dolan
A. B. Davis, Region III
M. P. Alexich
R. F. Kroeger
H. B. Bruggen
R. W. Jurgensen
NRC Resident Inspector
D. L. Wigginton, NRC
R. C. Callen
G. Charnoff, Esq.
Dottie Sherman, ANI Library
D. Hahn
INPO
PNSRC
A. A. Blind
P. A. Barrett/P. Lauzau

IE22
1/1

LICENSEE EVENT REPORT (LER)

| | | | | | | | | | | | | | | | | | | | | | | | | | | |
|--|--------|-----------|----------------|--|-----------------|-------|-----------------|------------------|----------------|--------------------------------------|---|-------------------------------|------------------|-------|--------------------|--|---|---|---|---|---|---|---|---|--|--|
| FACILITY NAME (1) DONALD C. COOK NUCLEAR PLANT, UNIT 2 | | | | | | | | | | DOCKET NUMBER (2) 0 5 0 0 0 3 1 6 | | | | | PAGE (3) 1 OF 4 | | | | | | | | | | | |
| TITLE (4) MISSED TECHNICAL SPECIFICATION REQUIRED VENT STACK SAMPLING AS A RESULT OF INCORRECT SAMPLE VALVE ALIGNMENT DUE TO PERSONNEL ERROR | | | | | | | | | | | | | | | | | | | | | | | | | | |
| EVENT DATE (5) | | | LER NUMBER (6) | | | | REPORT DATE (7) | | | OTHER FACILITIES INVOLVED (8) | | | | | | | | | | | | | | | | |
| MONTH | DAY | YEAR | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | MONTH | DAY | YEAR | FACILITY NAMES | | | | DOCKET NUMBER(S) | | | | | | | | | | | | | |
| 1 | 2 | 3 | 0 | 8 | 7 | 8 | 8 | 0 | 0 | 1 | 0 | 0 | 0 | 1 | 2 | 8 | 8 | 8 | 8 | 0 | 5 | 0 | 0 | 0 | | |
| OPERATING MODE (9) | | 2 | | THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11) | | | | | | | | | | | | | | | | | | | | | | |
| POWER LEVEL (10) | | 0 8 0 | | 20.402(b) | | | | 20.406(c) | | | | 50.73(a)(2)(iv) | | | | 73.71(b) | | | | | | | | | | |
| | | | | 20.406(a)(1)(i) | | | | 50.36(c)(1) | | | | 50.73(a)(2)(v) | | | | 73.71(c) | | | | | | | | | | |
| | | | | 20.406(a)(1)(ii) | | | | 50.36(c)(2) | | | | 50.73(a)(2)(vii) | | | | OTHER (Specify in Abstract below and in Text, NRC Form 366A) | | | | | | | | | | |
| | | | | 20.406(a)(1)(iii) | | | | 50.73(a)(2)(ii) | | | | 50.73(a)(2)(viii)(A) | | | | | | | | | | | | | | |
| | | | | 20.406(a)(1)(iv) | | | | 50.73(a)(2)(iii) | | | | 50.73(a)(2)(viii)(B) | | | | | | | | | | | | | | |
| | | | | 20.406(a)(1)(v) | | | | 50.73(a)(2)(iii) | | | | 50.73(a)(2)(x) | | | | | | | | | | | | | | |
| LICENSEE CONTACT FOR THIS LER (12) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| NAME L. S. GIBSON - TECHNICAL PHYSICAL SCIENCES SUPERINTENDENT | | | | | | | | | | TELEPHONE NUMBER | | | | | | | | | | | | | | | | |
| | | | | | | | | | | AREA CODE | | 6 1 6 4 6 5 - 5 9 0 1 | | | | | | | | | | | | | | |
| COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NRC | | CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NRC | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | |
| SUPPLEMENTAL REPORT EXPECTED (14) | | | | | | | | | | | | EXPECTED SUBMISSION DATE (15) | | MONTH | DAY | YEAR | | | | | | | | | | |
| YES (If yes, complete EXPECTED SUBMISSION DATE) | | | | | | | | | | | | X NO | | | | | | | | | | | | | | |

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On January 6, 1988, at 1310 hours, it was discovered that the sample valve lineup for VRS-2500, Unit 2 Auxiliary Building Vent Radiation Monitor, was incorrect. As a result of the incorrect lineup Technical Specification 3.3.3.10 Table 3.3-13 Section 3a was not met for continuous noble gas monitoring from December 30, 1987 to January 6, 1988.

The apparent cause of this event was cognitive personnel error. The chemistry technician involved did not restore the valves to their normal alignment after obtaining weekly grab sample off VRS-2500 on December 30, 1987 as per procedure.

After discovery of incorrect valve lineup on January 6, 1988, proper flow was restored to VRS-2500 and the valve lineup was verified correct (completed at 1320 hours).

The chemistry technician involved was counselled and the sampling procedure was changed to require independent verification of the proper valve alignment at VRS-2500.

8802030470 880128
PDR ADOCK 05000316
S PDR

TE22
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

| | | | | | | | | | | |
|---|--|--|--|--|----------------|----------------------|--------------------|----------|----|-----|
| FACILITY NAME (1) DONALD C. COOK NUCLEAR PLANT UNIT 2 | DOCKET NUMBER (2) 0 5 0 0 0 3 1 6 | | | | LER NUMBER (6) | | | PAGE (3) | | |
| | | | | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | | | |
| | | | | | 8 8 | 0 0 1 | 0 0 | 0 2 | OF | 0 4 |

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Conditions Prior to Occurrence

Unit 2 at 80 percent reactor thermal power.

Description of Event

On January 6, 1988 at 1310 hours, while obtaining a weekly sample from VRS-2500, Unit 2 Auxiliary Building Vent Radiation Monitor (EIIS/IL-MON), it was discovered that the sample valve lineup (EIIS/IL-SMV), to allow continuous monitoring of the Unit 2 Auxiliary Building Vent, was incorrect. The lineup, as found, was drawing air from the 650' auxiliary building elevation not the vent stack as required. (See attached sketch). Review of data from VRS-2500 indicates this condition had existed in all likelihood, since the last time VRS-2500 was sampled on December 30, 1987. At that time, the chemistry technician involved in sampling VRS-2500 did not restore the valving to its normal alignment as required by 2 THP 6020 LAB.135. During the time period (12/30/87 through 1/6/88), when the sample lineup was incorrect for VRS-2500, continuous noble gas monitoring or 8 hour grab samples as required by Technical Specification 3.3.3.10 Table 3.3-13 Section 3.a was not met. Other than the Auxiliary Building Vent Radiation Monitor, there were no inoperable structures, components, or systems that contributed to this event.

Cause of Event

The cause is cognitive personnel error. The valves were not restored to normal alignment after sampling VRS-2500 on December 30, 1987.

This is not the first occurrence regarding the failure to insure sample valves are in their correct alignment. Past preventive action for LERS 316/86-027-00; 316/86-001-00; 316/83-092-00 consisted of the implementation of a verification program. In the case of VRS-2500, the verification consisted of notifying the control room and remotely verifying that there were no alarms (including a flow alarm) for VRS-2500. This practice insured that there is a sample flow after sampling but does not verify correct sample flow path.

Analysis of Event

This incident is considered a missed surveillance in that the requirement for continuous noble gas monitoring in Technical Specification 3.3.3.10 Table 3.3-13 Section A was not met and is reportable under 10 CFR 50.73 (a)(2)(i).

During the time between December 30, 1987 and January 6, 1988 no gas decay tank (or other) releases were made which would cause release, via the vent

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

| | | | | | | | |
|---|--|----------------|----------------------|--------------------|----------|----|-------|
| FACILITY NAME (1) D. C. COOK NUCLEAR PLANT UNIT 2 | DOCKET NUMBER (2) 0 5 0 0 0 3 1 6 | LER NUMBER (6) | | | PAGE (3) | | |
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | | | |
| | | 8 8 | — 0 0 1 | — 0 0 | 0 3 | OF | 0 4 |

TEXT (If more space is required, use additional NRC Form 368A's) (17)

stack, above "normal" routine levels and therefore, we believe this event did not pose a threat to the health and safety of the public.

Corrective Action

After discovery of incorrect valve lineup on January 6, 1988, proper flow was restored to VRS-2500 and the valve lineup was verified correct (completed at 1320 hours). The technician involved was counselled as to the importance of insuring quality and procedure compliance. As preventive action a change to both 2 THP 6020 LAB.135 and 1 THP 6020 LAB.135 was written to require local independent verification of the proper valve alignment in addition to requesting Control Room personnel to verify the monitor has been returned to proper operational state.

Failed Component Identification

None

Previous Similar Events

- LER 316/86-027-00; Failure to Verify Sample Flow Path, Due to Procedural Deficiency, Results in a Lack of Continuous Vent Stack Tritium Monitoring.
- LER 316/86-001-00; Unit Vent Effluent Tritium
- LER 316/83-092-00; Sample Valves at Outlet of Boron Injection Tank Left Partially Open.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)

D. C. COOK NUCLEAR PLANT
UNIT 2

DOCKET NUMBER (2)

0 5 0 0 0 3 1 6

LER NUMBER (6)

YEAR

8 8

SEQUENTIAL
NUMBER

0 0 1


REVISION
NUMBER

0 0

PAGE (3)

0 4 OF 0 4

TEXT (If more space is required, use additional NRC Form 368A's) (17)



Configuration A reflects the as found condition. Configuration B is the correct by procedure flow path.