

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9901060076 DOC.DATE: 98/12/30 NOTARIZED: NO DOCKET #  
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315  
 AUTH.NAME . AUTHOR AFFILIATION  
 SMITH,R. Indiana Michigan Power Co.  
 SAMPSON,J.R. Indiana Michigan Power Co.  
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 98-053-00:on 981130,discovered use of inoperable  
 substitute subcooling margin monitor.Caused by condition  
 existing since installation of plant process computer in  
 1992.Updated LER will be submitted.With 981230 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

### NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD3-3 PD	1 1	STANG,J	1 1
INTERNAL: AEOD/SPD/RAB	2 2	AEOD/SPD/RRAB	1 1
<u>FILE CENTER</u>	1 1	NRR/DE/ECGB	1 1
NRR/DE/EELB	1 1	NRR/DE/EMEB	1 1
NRR/DRCH/HICB	1 1	NRR/DRCH/HOHB	1 1
NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1
NRR/DSSA/SPLB	1 1	RES/DET/EIB	1 1
RGN3 FILE 01	1 1		
EXTERNAL: L ST LOBBY WARD	1 1	LITCO BRYCE,J H	1 1
NOAC POORE,W.	1 1	NOAC QUEENER,DS	1 1
NRC PDR	1 1	NUDOCS FULL TXT	1 1

### NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS  
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL  
 DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED

TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 22

C  
A  
T  
E  
G  
O  
R  
Y  
  
1  
  
D  
O  
C  
U  
M  
E  
N  
T

40

Indiana Michigan  
Power Company  
Cook Nuclear Plant  
One Cook Plant  
Bridgman, MI 49106  
616 465 5901



December 30, 1998

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Operating License DPR-58  
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following interim report is being submitted:

LER 315/98-053-00, "Use of Inoperable Substitute Subcooling Margin Monitor"

No commitments were identified in this submittal.

Sincerely,

A handwritten signature in cursive script, reading "John R. Sampson".

J. R. Sampson  
Site Vice President

/mbd  
Attachment

c: J. L. Caldwell (Acting), Region III  
R. P. Powers  
P. A. Barrett  
J. B. Kingseed  
R. Whale  
D. Hahn  
Records Center, INPO  
NRC Resident Inspector

9901060076 981230  
PDR ADDCK 05000315  
S PDR



**LICENSEE EVENT REPORT (LER)**(See reverse for required number of  
digits/characters for each block)ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATORY  
INFORMATION COLLECTION REQUEST: 50.0 HRS. REPORTED LESSONS LEARNED ARE  
INCORPORATED INTO THE LICENSING PROCESS AND FED BACK TO INDUSTRY.  
FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND  
RECORDS MANAGEMENT BRANCH (T-6 F33), U.S. NUCLEAR REGULATORY  
COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION  
PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC  
20503

FACILITY NAME (1)

Cook Nuclear Plant Unit 1

DOCKET NUMBER (2)

05000-315

PAGE (3)

1 of 1

TITLE (4)

Interim LER - Use Of Inoperable Substitute Subcooling Margin Monitor

EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER	
11	30	1998	1998	--	053	--	00	12	30	1998	DC Cook Unit 2 05000-316
OPERATING MODE (9)		5		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)							
POWER LEVEL (10)		000		20.2201 (b)		20.2203(a)(2)(v)		<input checked="" type="checkbox"/> 50.73(a)(2)(i)		50.73(a)(2)(viii)	
				20.2203(a)(1)		20.2203(a)(3)(i)		50.73(a)(2)(ii)		50.73(a)(2)(x)	
				20.2203(a)(2)(i)		20.2203(a)(3)(ii)		50.73(a)(2)(iii)		73.71	
				20.2203(a)(2)(ii)		20.2203(a)(4)		50.73(a)(2)(iv)		OTHER	
				20.2203(a)(2)(iii)		50.36(c)(1)		50.73(a)(2)(v)		Specify in Abstract below or on NRC Form 366A	
				20.2203(a)(2)(iv)		50.36(c)(2)		50.73(a)(2)(vii)			

## LICENSEE CONTACT FOR THIS LER (12)

NAME

Mr. Robert Smith, Nuclear Information Systems Manager

TELEPHONE NUMBER (Include Area Code)

616/697-5103

## COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

## SUPPLEMENTAL REPORT EXPECTED (14)

<input checked="" type="checkbox"/> YES (If Yes, complete EXPECTED SUBMISSION DATE).		NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
				02	16	1999

Abstract (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On November 9, 1998, plant Instrument and Control (I&C) personnel performing cross-calibration checks on core exit thermocouple indications for the Plant Process Computer (PPC) found that all points were indicating 30 to 35 degrees F too high. Investigation by plant personnel has revealed that the PPC inputs for core exit thermocouples were calibrated as linear signals as opposed to calibration to a thermocouple curve. This resulted in the erroneous PPC indication. This condition has existed since installation of the PPC in 1992.

Technical Specification (TS) 3.3.3.8, "Post-Accident Instrumentation," allows the PPC subcooling margin indication to be substituted for the TS required subcooling monitor. TS surveillance Requirement 4.3.3.8, Table 4.3-7, Item 11 requires a monthly channel check and an 18 month channel calibration on the Reactor Coolant System Subcooling Margin Monitor. In the past, the PPC subcooling margin indication has been substituted for the TS required instrumentation. No TS surveillance testing was performed on the PPC core exit thermocouple input to the PPC subcooling margin monitors prior to substituting the PPC subcooling margin indication for TS required instrumentation. On November 30, 1998, this condition was determined to be reportable in accordance with 10 CFR 50.73(a)(2)(i)(B) as a condition prohibited by the plant's Technical Specifications due to missed surveillance testing.

Investigation into this condition is continuing, and is expected to be complete by February 1, 1999. An update to this interim LER will be submitted by February 16, 1998.