

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | F | L | T | P | S | 4 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | 5
2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T
0 1 | L | 8 | 0 | 5 | 0 | 0 | 0 | 2 | 5 | 1 | 7 | 0 | 6 | 1 | 1 | 7 | 9 | 8 | 0 | 7 | 1 | 1 | 7 | 9 | 9
2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
REPORT SOURCE COCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2 | While performing an inspection pursuant to I & E Bulletin 79-02, a
0 3 | mechanical snubber on the C steam generator feedwater line (Tag Number 22
0 4 | in TS 3.13) was found in a "locked-up" condition. Subsequent examination
0 5 | verified the integrity of the feedwater piping and the operability of the
0 6 | remaining feedwater snubbers. DER 250-79-6 also describes an inoperable
0 7 | mechanical snubber.

0 13 |
7 8 9 30

0 9 | C | H | 11 | B | 12 | A | 13 | S | U | P | O | R | T | 14 | D | 15 | Z | 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

17 | 7 | 9 | 18 | 0 | 0 | 19 | 0 | 13 | 20 | L | 21 | 0 | 22 | 0
23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

0 12 | A | 13 | X | 14 | Z | 15 | Z | 16 | 0 | 0 | 0 | 17 | N | 18 | Y | 19 | A | 20 | P | 0 | 2 | 19 | 1
21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPROW FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0 | Snubber overload caused damage to the thrust bearing. The exact cause
1 1 | of the overload is not known. We are evaluating the occurrence
1 2 | in conjunction with our Architect-Engineer, and a followup report will be
1 3 | submitted. The 10,000 lb. snubber was replaced with one rated at
1 4 | 15,000 lbs.

1 5 | X | 22 | 0 | 0 | 0 | 23 | NA | 24 | C | 25 | During IEB 79-02 inspection.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
ACTIVITY CONTENT RELEASED OR RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 | 0 | 0 | 0 | 39 | NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 | 0 | 0 | 0 | 40 | NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

1 9 | Z | 42 | NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
PUBLICITY ISSUED DESCRIPTION

2 0 | N | 44 | NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
NRC USE ONLY

NAME OF PREPAPER M. A. Schoppman PHONE (305) 552-3802

7907180565

