

**LICENSEE EVENT REPORT**

CONTROL BLOCK: 

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	F	L	T	P	S	3	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	3	9						14	15	25										26	30				37	38	39		
		LICENSEE CODE							LICENSE NUMBER											LICENSE TYPE					CAT				

CON'T

0	1
7	3

REPORT SOURCE

L	8	0	5	0	0	0	2	5	0	7	0	2	2	6	7	9	3	0	8	0	3	7	9	9		
60	61	DOCKET NUMBER										64	65	EVENT DATE					74	75	REPORT DATE					80

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)**

02 | During a refueling shutdown, a crack was found in a weld on a drain line

013 | in the B accumulator discharge piping. Nondestructive testing (NDT).

0 3 | showed additional cracking on the drain line elbow. This is reportable

05 | pursuant to TS 6.9.2.b.4.

016

07 \_\_\_\_\_

03 \_\_\_\_\_

7 8 9 10 11 12 13 14 15 16

0 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

S H 11 B 12 A 13 P I P E X X 14 A 15 Z 16

(17) LER/RO REPORT NUMBER 719 21 22

SEQUENTIAL REPORT NO. 0102 24 25 26

OCCURRENCE CODE 03 27 28

REPORT TYPE X 29 30

REVISION NO. 1

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRO-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTUR.		
A	18	F	19	Z	20	Z	21	0	0	0	0	Y	23	N	24	N	25	X	9	9

**CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)**

10 The cracks were in a 3/4 inch elbow (type 316 stainless steel) and the

11 weld attaching it to a 3/4 inch nipple. During normal operation, this

1 2 drain assembly is pressurized to approximately 650 psig. The elbow and

13 | welds were replaced and found acceptable following NDT examination.

1 4 | Additional corrective action is described in the attachment.

FACILITY STATUS			% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	H	0	0	0	NA		A	Operator Observation		

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 2 33 3 34

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES				DESCRIPTION	
NUMBER	TYPE				
117	00	37	Z	33	NA

PERSONNEL INJURIES											
NUMBER				DESCRIPTION (41)							
1	2	3	4	5	6	7	8	9	10	11	12
				0	0	0				(40)	NA

1. LOSS OF OR DAMAGE TO FACILITY (43)  
TYPE DESCRIPTION  
1 9 Z (42) NA 7908200 282 5

PUBLICITY  
ISSUED DESCRIPTION NA NRC USE ONLY

NAME OF PREPARER M. A. Schoppman

PHONE: <sup>88 39</sup>(305) 552-3802

Additional Cause Description and Corrective Action

The cracks in the 3B accumulator discharge piping drain line occurred in a 3/4 inch stainless steel elbow (type 316) and in the weld attaching it to a 3/4 inch stainless steel nipple (type 304). The cracks were observed on the upstream, socket end of the elbow and at its associated socket weld. The defective elbow was cut out of the piping and a new type 316 stainless steel elbow was welded in place. The new welds on the drain assembly were examined and found to be acceptable for use. The cause of the cracks could not positively be determined, however, they were most probably caused by stress due to line vibration. The drain assembly is pressurized to approximately 650 psig during normal operation. The equivalent drain lines from the 3A and 3C accumulators were also examined and found to be in satisfactory condition.

A plant change/modification will be implemented to provide additional support for vent and drain lines. The implementation schedule will initiate the changes on Unit 4 during the Winter 1980 refueling outage and on Unit 3 during a Fall 1979 outage. The plant change/modification on Unit 4 has been deferred from the Spring 1979 to the Winter 1980 refueling outage. This deferral has resulted from (1) the non-availability of QC type material due to long lead time and (2) the non-availability of qualified manpower due to the labor intensive inspection being performed in accordance with USNRC I & E Bulletin 79-02, Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts. During the Spring 1979 refueling outage of Unit 4, the accumulator discharge piping vents and drains were examined using NDT methods. The NDT examinations revealed no relevant indications or anomalies.



Handwritten marks and scribbles in the top right corner.

Faint, illegible handwritten text or markings in the middle left area.