

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F I L T P S 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 32

CCNT 01

REPORT SOURCE L 6 0 5 0 0 0 2 5 0 7 1 0 0 8 7 9 3 1 0 2 2 7 9 9

DOCKET NUMBER 60 61 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During a planned outage, a hex nut was discovered lodged in the internals

03 of the main steam supply valve to the 3C moisture separator-reheater. The

04 unit was brought to cold shutdown. Investigation revealed that the nut was

05 missing from the disc stud in the 3A main steam check valve. The disc and

05 disc stud were in the proper position and the valve was fully operable.

07 The 3B and 3C MSCVs were inspected and the disc stud nuts were found in

08 place.

SYSTEM CODE H B 11 CAUSE CODE E 12 CAUSE SUBCODE C 13 COMPONENT CODE V A L V E X 14 COMP. SUBCODE C 15 VALVE SUBCODE D 16

LER/RO REPORT NUMBER 17 7 9 EVENT YEAR 21 22 SEQUENTIAL REPORT NO. 24 25 OCCURRENCE CODE 27 28 REPORT TYPE 30 31 REVISION NO. 32 33

ACTION TAKEN A 18 FUTURE ACTION X 19 EFFECT ON PLANT C 20 SHUTDOWN METHOD Z 21 HOURS 22 0 0 0 0 ATTACHMENT SUBMITTED Y 23 APPROX. FORM SUB. Y 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER S 0 7 5 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of the hex nut dislodging from the disc stud was failure of the.

11 washer beneath the hex nut and subsequent failure of the associated locking

12 device. The hex nut was replaced on the 3A MSCV and an improved locking

13 device was installed on all three MSCVs. Main steam isolation valves are

14 scheduled for inspection during the November, 1979 refueling outage.

FACILITY STATUS G 28 % POWER 0 0 0 29 OTHER STATUS 30 NA METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION 32 During maintenance.

ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA

PERSONNEL EXPOSURES NUMBER 0 0 0 37 Z 38 DESCRIPTION 39 NA

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION 41 NA

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION 43 NA

PUBLICITY ISSUED DESCRIPTION 44 NA

NAME OF PREPARER M. A. Schoppman PHONE: (305) 552-3802

7911050 369

NRC USE ONLY



1-1-1  
1-1-1  
1-1-1

REPORTABLE OCCURRENCE 250-79-31  
LICENSEE EVENT REPORT  
PAGE TWO

Additional Event Description and Probable Consequences:

On Sunday, October 7, 1979, in the course of performing secondary system maintenance during a planned unit outage, a foreign object (hex nut) was discovered lodged in the internals of the main steam supply valve to the 3C moisture separator - reheater. Operation to place the reactor coolant system in cold shutdown (unplanned) was initiated to facilitate an investigation to determine the origin of the hex nut. On Monday, October 8, 1979, investigative efforts revealed that the nut was missing from the disc stud in the 3A main steam check valve (MSCV). The disc and disc stud were in the proper position and the valve was fully operable. The 3B and 3C MSCV's were inspected and the disc stud nuts were found in place although some distress was noted on the 3C lock washer.

Additional Cause Description and Corrective Action:

The cause of the hex nut dislodging from the disc stud was failure of the washer beneath the hex nut and subsequent failure of the associated locking device. Vibration resulted in the hex nut "backing off" the disc stud. The hex nut was replaced on the 3A MSCV and an improved locking device was installed on all three MSCV's. Additionally, the main steam isolation valves (MSIV's) are scheduled for inspection during the upcoming refueling outage next month.

During the reassembly of the MSCV's following the inspection and repair described above, 24 studs (securing the valve bonnet to the valve body) on the 3A MSCV and 10 studs on the 3C MSCV were overtorqued. The overtorquing resulted from personnel error in reading the pressure gauge scale on the hydraulic torque device. The affected studs were replaced with new studs which meet or exceed original design requirements. Maintenance personnel have been reinstructed in the proper use of this type of torque device.

