

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | F | L | T | P | S | 3 | 2 | 0 | 0 | 1 | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 4 | 5

7 3 9 14 15 23 25 30 37 42

CONT

01 | REPORT SOURCE | L | 6 | 0 | 5 | 1 | 0 | 0 | 0 | 2 | 1 | 5 | 1 | 0 | 7 | 0 | 0 | 1 | 0 | B | 1 | 8 | 1 | 0 | 3 | 0 | 2 | 1 | 0 | 1 | 8 | 0 | 9

7 3 60 61 63 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During a routine system walkthrough, the east fire pump was found to be

03 | inoperable. An investigation revealed that the pump may have been

04 | inoperable for 17 days due to its power supply breaker not being closed

05 | following periodic maintenance. The breaker was closed and the pump

06 | declared operable on 01/04/80. Inoperability of a fire pump in excess

07 | of 7 days is reportable pursuant to TS 3.14.2.b.1. Redundant pump was

08 | operable throughout this period.

09 |

SYSTEM CODE: A | B | 11

CAUSE CODE: A | 12

CAUSE SUBCODE: A | 13

COMPONENT CODE: P | U | M | P | X | X | 14

COMP. SUBCODE: B | 15

VALVE SUBCODE: Z | 16

17 | LER/RO REPORT NUMBER | 8 | 0 | 21 22

EVENT YEAR: 8 | 0 | 21 22

SEQUENTIAL REPORT NO.: 0 | 0 | 1 | 24 26

OCCURRENCE CODE: 0 | 1 | 3 | 28 29

REPORT TYPE: L | 30

REVISION NO.: 0 | 32

ACTION TAKEN: X | 33

FUTURE ACTION: G | 34

EFFECT ON PLANT: Z | 35

SHUTDOWN METHOD: Z | 36

HOURS: 0 | 0 | 0 | 0 | 37 40

ATTACHMENT SUBMITTED: Y | 41

4PRO-4 FORM SUB.: N | 42

PRIME COMP. SUPPLIER: A | 43

COMPONENT MANUFACTURER: F | 0 | 1 | 1 | 0 | 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The cause of this event was improper operator action following a

11 | maintenance clearance. Long term corrective action is a procedure

12 | change to require a daily check and log entry confirming that power is

13 | available to both fire pumps.

14 |

15 |

FACILITY STATUS: H | 23

POWER: 0 | 0 | 0 | 0 | 29

OTHER STATUS: NA | 30

METHOD OF DISCOVERY: C | 31

DISCOVERY DESCRIPTION: Shift Technical Advisor Observation | 32

ACTIVITY RELEASED OF RELEASE: Z | 33

CONTENT: Z | 34

AMOUNT OF ACTIVITY: NA | 35

LOCATION OF RELEASE: NA | 36

PERSONNEL EXPOSURES NUMBER: 0 | 0 | 0 | 37

TYPE: Z | 38

DESCRIPTION: NA | 39

PERSONNEL INJURIES NUMBER: 0 | 0 | 0 | 40

DESCRIPTION: NA | 41

LOSS OF OR DAMAGE TO FACILITY TYPE: Z | 42

DESCRIPTION: NA | 43

PUBLICITY ISSUED: N | 44

DESCRIPTION: NA | 45

80 02220 370

NAME OF PREPARER: M. A. Schoppman

PHONE: (305) 552-3802

NRC USE ONLY

REPORTABLE OCCURRENCE 250-80-001
LICENSEE EVENT REPORT
PAGE TWO

Additional Event Description and Probable Consequences

During a routine system walk through a shift technical advisor found the East fire pump to be inoperable. Subsequent investigation revealed that the pump may have been inoperable for 17 days due to its power supply breaker not having been closed following periodic maintenance on the breaker. The breaker was closed and the pump declared operable on 01/04/80. Inoperability of a Fire pump in excess of 7 days is reportable pursuant to TS 3.14.2.b.1. The redundant fire pump was operable throughout this period. Similar occurrences have been reported on LER 250-79-001, LER 250-79-024, and LER 250-79-027