

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

0 1 F I L T P S 3 2 0 0 0 - 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 1 4 5

LICENSEE CODE 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

CONT
0 1 REPORT SOURCE X 6 0 5 1 0 0 0 2 1 5 1 0 7 0 1 1 0 5 8 1 1 3 0 1 1 1 9 8 1 1 9

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 In the course of investigating potential cracks observed in the Lexan coil

0 3 spools of General Electric Co. type HFA relays, a new coil assembly in

0 4 spare parts storage was confirmed to have a crack in the spool end plate.

0 5 The concern is that a cracked spool could result in a broken piece which

0 6 could prevent desired contact action. A coil inspection program was

0 7 established and implemented. An evaluation pursuant to 10CFR21 requirements

0 8 is in progress. A similar HFA relay problem was reported as AO 251-75-8.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

0 9 SYSTEM CODE S H 11 CAUSE CODE B 12 CAUSE SUBCODE B 13 COMPONENT CODE R E L A Y X 14 COMP. SUBCODE A 15 VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 8 1 1 22 EVENT YEAR 8 1 23 SEQUENTIAL REPORT NO. 0 0 3 24 OCCURRENCE CODE 0 1 25 REPORT TYPE T 26 REVISION NO. 0 27

18 ACTION TAKEN A 18 19 FUTURE ACTION X 19 20 EFFECT ON PLANT Z 20 21 SHUTDOWN METHOD Z 21 22 HOURS 0 0 0 0 23 ATTACHMENT SUBMITTED N 24 APPROX. FORM SUB. Y 25 PRIME COMP. SUPPLIER A 26 COMPONENT MANUFACTURER G O 8 1 0 27

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 No operational failure of this type relay due to coil spool cracks has

1 1 been experienced. One coil in service was found cracked and was replaced.

1 2 Inspection results revealed possible indications on 39 of the 184 relays.

1 3 A periodic inspection will be implemented pending receipt of new coils

1 4 and/or relays.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

1 5 FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY C 31 DISCOVERY DESCRIPTION Special inspection 32

1 6 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

2 0 PUBLICITY ISSUED N 44 DESCRIPTION NA 45

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

NAME OF PREPARER P.L. Pace PHONE: (305) 552-3801

8102080569

