

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 1 1 1 1 1 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 F I L I T I P I S I 3 2 0 1 0 1 - 0 1 0 1 0 1 - 1 0 1 0 1 0 3 4 1 1 1 1 1 1 4 1 5

CONT

0 1 X 6 0 5 1 0 1 0 1 0 1 2 1 5 1 0 7 1 1 1 1 0 1 1 7 1 9 8 1 1 1 1 1 5 1 7 1 9 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 1 2 The NSSS vendor has identified and corrected an input error in each of two  
0 1 3 LOCA analyses specifically applicable to Turkey Point Units 3 and 4. The  
0 1 4 LOCA analyses for the 22% and the 25% steam generator tube plugging levels  
0 1 5 were affected. Correction of the error in the 22% analysis resulted in a  
0 1 6 reduction of the maximum allowable  $F_q$  from 2.10 to 1.90. Both units have  
0 1 7 less than 22% steam generator tube plugging.

0 1 8

0 9 Z Z 11 X 12 Z 13 Z Z Z Z Z 14 Z 15 Z 16

17 7 1 9 18 0 1 3 1 3 19 1 0 1 1 20 1 21 0 1 0 1 0 1 0 22 Y 23 N 24 7 25 7 1 9 9 1 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Both units are now operating with a revised  $F_q$  limit, and a T.S. change  
1 1 proposal will be formally submitted. Root cause and additional corrective  
1 2 action are discussed in the attachment.

1 3

1 4

1 5 E 23 1 1 0 0 29 NA 30 D 31 NSSS notification 32

1 6 Z 33 Z 34 NA 35 NA 36

1 7 0 0 0 37 Z 38 NA 39

1 8 0 0 0 40 NA 41

1 9 Z 42 NA 43

2 0 N 44 NA 45

NAME OF PREPARER M. A. Schoppman

PHONE: (305) 552-3802

8105050087

Additional Cause Description and Corrective Actions:

There are two methods which utilize pressure drops for input to SATAN computer code calculations. One is a standard technique and the other is used for steam generator tube plugging analyses when only the tube plugging input is changed. Since the 22% analysis involved an updated hot assembly flow area input to SATAN (unrelated to tube plugging), the first method should have been used. However, since the 22% analysis was a "tube plugging" analysis, the second method was inadvertently used.

With respect to the 25% analysis, a value for power in the hot assembly that was input to the SATAN calculation was 3% too low.

In order to assure that a similar error will not occur in the future, the following revisions to the NSSS vendor's procedures are being implemented.

- a. Automated cross checks of current input data with those of a previous analysis (or analysis for a similar plant) will be required (while it is now only recommended).
- b. Safeguards Engineering Standards dealing with SATAN pressure drops will be revised to include a cautionary statement about the impact of data changes on the methods used.
- c. A standard for steam generator tube plugging analysis will be written.