

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8608260038 DOC. DATE: 86/08/22 NOTARIZED: NO DOCKET #  
 FACIL: 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251  
 AUTH. NAME AUTHOR AFFILIATION  
 WOODY, C. O. Florida Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 MCDONALD, D. G. PWR Project Directorate 2


SUBJECT: RD 86-06: on 860821, IAEA safeguards inspectors view of  
 reactor head revealed second missing seal in addition  
 missing seal reported in RD 86-05. Remaining seals provided  
 indication that reactor head not removed since installation.

DISTRIBUTION CODE: S006D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2  
 TITLE: IAEA Safeguards Data

## NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PWR-A PD2 LA	1 0	PWR-A PD2 PD	1 0
	MCDONALD, D 16	1 1		
INTERNAL:	AEOD/PTB	1 0	IE/DI/DRPB	1 1
	NMSS/SGMC 02	6 6	NRR PWR-B SSPD	1 1
	<u>REG FILE</u> 01	1 1	RGN2 12	1 1
EXTERNAL:	LPDR	1 0	NRC PDR	1 0





AUG 22 1988

L-86-346

Office of Nuclear Reactor Regulation  
Attention: Mr. D. G. McDonald, Jr., Project Manager  
PWR Project Directorate #2  
Division of PWR Licensing - A  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dear Mr. McDonald:

Re: Turkey Point Unit 4  
Docket No. 50-251  
IAEA Reportable Occurrence 86-06

This letter and its attachment provides written notification of IAEA Reportable Occurrence 86-06 as requested by your June 3, 1986 letter.

Should you require additional information, please contact us.

Very truly yours,

*H. J. Boring*  
for C. O. Woody  
Group Vice President  
Nuclear Energy

COW/SAV:aa

Attachment

cc: Harold F. Reis, Esquire  
Mr. Gene Sparks, NRC Washington, M.S. 88155  
PNS-LI-86-193

8608260038 860822  
PDR ADCK 05000251  
S PDR

L1:1

*Soob*  
*1/1*

4/2



## ATTACHMENT

Re: IAEA Reportable Occurrence 86-06

### Summary of Event:

On Thursday, August 21, 1986, two IAEA safeguards inspectors were on-site as scheduled by their normal surveillance cycle. In addition to their pre-planned surveillance work, the inspectors requested to view the reactor head. This request was the result of IAEA Occurrence 86-05, which reported a seal being accidentally removed from the reactor head. The visual verification of the remaining seals on the reactor head revealed that a second seal was missing in addition to the missing seal previously reported. This second missing seal could not be found in the area surrounding the reactor head, and therefore cannot be returned to the IAEA.

### Results:

- 1) The IAEA safeguards inspectors will be reporting the additional missing seal in their inspection report.
- 2) The three visually verified remaining seals were considered by the inspectors to be sufficient corroboration to the operating records, indicating that the reactor head has not been removed since the physical inventory.
- 3) Additional seals were placed on the missile shields to increase the redundancy in the safeguards system.

### Conclusion:

The remaining seals provided the indication that the reactor head had not been removed since their installation. Therefore, the fuel inventory has not changed since its verification by the IAEA.