

## ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8805230009 DOC.DATE: 88/05/13 NOTARIZED: NO DOCKET #  
 FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250  
 AUTH.NAME AUTHOR AFFILIATION  
 SALAMON,G. Florida Power & Light Co.  
 CONWAY,W.F. Florida Power & Light Co.  
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 88-005-00:on 880415,loss of flowpath from boric acid  
 storage tanks to RCS due to coupling failure.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 4 W/8 ltr.  
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

## NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD2-2 LA	1 1	PD2-2 PD.	1 1
EDISON,G	1 1		
INTERNAL: ACRS MICHELSON	1 1	ACRS MOELLER	2 2
AEOD/DOA	1 1	AEOD/DSP/NAS	1 1
AEOD/DSP/ROAB	2 2	AEOD/DSP/TPAB	1 1
ARM/DCTS/DAB	1 1	DEDRO	1 1
NRR/DEST/ADS 7E	1 0	NRR/DEST/CEB 8H	1 1
NRR/DEST/ESB 8D	1 1	NRR/DEST/ICSB 7	1 1
NRR/DEST/MEB 9H	1 1	NRR/DEST/MTB 9H	1 1
NRR/DEST/PSB 8D	1 1	NRR/DEST/RSB 8E	1 1
NRR/DEST/SGB 8D	1 1	NRR/DLPQ/HFB 10	1 1
NRR/DLPQ/QAB 10	1 1	NRR/DOEA/EAB 11	1 1
NRR/DREP/RAB 10	1 1	NRR/DREP/RPB 10	2 2
NRR/DRIS/SIB 9A	1 1	NRR/PMAS/ILRB12	1 1
NUDOCS-ABSTRACT	1 1	REG FILE 02	1 1
RES TELFORD,J	1 1	RES/DE/EIB	1 1
RES/DRPS DEPY	1 1	RGN2 FILE 01	1 1
EXTERNAL: EG&G WILLIAMS,S	4 4	FORD BLDG HOY,A	1 1
H ST LOBBY WARD	1 1	LPDR	1 1
NRC PDR	1 1	NSIC HARRIS,J	1 1
NSIC MAYS,G	1 1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 46 ENCL 45

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) <b>Turkey Point Unit 3</b>										DOCKET NUMBER (2) <b>0 5 0 0 0 2 5 0</b>										PAGE (3) <b>1 OF 0 3</b>																		
TITLE (4) <b>Loss of Flowpath from Boric Acid Storage Tanks to Reactor Coolant System Due to Coupling Failure of the 3B Boric Acid Transfer Pump (BATP) and Seal Failure of the 3A BATP</b>																																						
EVENT DATE (5)						LER NUMBER (6)						REPORT DATE (7)						OTHER FACILITIES INVOLVED (8)																				
MONTH			DAY			YEAR			YEAR			SEQUENTIAL NUMBER			REVISION NUMBER			MONTH			DAY			YEAR			FACILITY NAMES						DOCKET NUMBER(S)					
																											<b>Turkey Point Unit 4</b>						<b>0 5 0 0 0 2 5 1</b>					
<b>4</b>			<b>15</b>			<b>88</b>			<b>88</b>			<b>005</b>			<b>00</b>			<b>05</b>			<b>13</b>			<b>88</b>									<b>0 5 0 0 0</b>					
OPERATING MODE (9) <b>1</b>						THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																																
POWER LEVEL (10) <b>1100</b>						20.402(b)						20.405(c)						50.73(a)(2)(iv)						73.71(b)														
						20.405(a)(1)(i)						50.38(a)(1)						50.73(a)(2)(v)						73.71(c)														
						20.405(a)(1)(ii)						50.38(a)(2)						50.73(a)(2)(vi)						OTHER (Specify in Abstract below and in Text, NRC Form 366A)														
						20.405(a)(1)(iii)						X 50.73(a)(2)(i)						50.73(a)(2)(vii)(A)																				
						20.405(a)(1)(iv)						50.73(a)(2)(ii)						50.73(a)(2)(vii)(B)																				
						20.405(a)(1)(v)						50.73(a)(2)(iii)						50.73(a)(2)(x)																				
LICENSEE CONTACT FOR THIS LER (12)																																						
NAME <b>Gabe Salamon, Compliance Engineer</b>															TELEPHONE NUMBER AREA CODE <b>3 0 5</b>						<b>2 4 6 - 6 5 6 0</b>																	
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																																						
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC																												
X	C/A	CIP/LIG	G 2 0 0	N																																		
X	C/A	SEAL	G 2 0 0	N																																		
SUPPLEMENTAL REPORT EXPECTED (14)															EXPECTED SUBMISSION DATE (15)						MONTH DAY YEAR																	
YES (If yes, complete EXPECTED SUBMISSION DATE)															X NO																							

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On April 14, 1988, at 0305, the 3B Boric Acid Transfer Pump (BATP) was taken out of service (OOS) due to the pump's failure to deliver flow. Technical Specification (TS) 3.6.b.4 requires a flow path from the boric acid storage tanks (BAST) when a reactor is critical. On April 15, at 1315, a Nuclear Operator reported that the 3A BATP seal tank was showing no water. As both pumps which were aligned to Unit 3 were now OOS, no flow path from the BASTs to Unit 3 for which credit could be taken existed. This placed the unit in TS 3.0.1, which requires that action be initiated within one hour to place the unit in a mode in which TS 3.6.b.4 does not apply (MODE 3). At 1415, the 4A BATP was aligned to Unit 3. The unit exited TS 3.0.1 and entered TS 3.6.d.2, which permits continued power operation with one of the three required BATPs OOS for 24 hours. IST of the 3B BATP was completed and the pump was returned to service at 1715 on April 15, at which time the unit exited TS 3.6.d.2. The cause of the 3B BATP's failure was a loose set screw in the motor/pump coupling. The cause of the 3A BATP's seal water level decrease was a failed seal. The 4A BATP was realigned to provide a boric acid flowpath to Unit 3, and the 3B BATP was returned to service at 1715 on April 15. The mechanical seal for the 3A BATP was replaced, and the pump was returned to service at 1600 on April 18.

IE22D  
11



## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Turkey Point Unit 3	0 5 0 0 0 2 5 0	8 8	0 0 5	0 0	0 2	OF	0 3

TEXT (If more space is required, use additional NRC Form 362A's) (17)

EVENT

On April 14, 1988, at 0305, with both units in MODE 1, the 3B Boric Acid Transfer Pump (BATP) (EIIS:CA) was taken out of service (OOS) due to the pump's failure to deliver flow. Turkey Point has four BATPs: two designated Unit 3 and two designated unit 4, and 3 Boric Acid Storage Tanks (BAST). Any of the pumps or tanks can be aligned to either unit. Technical Specification (TS) 3.6.c.2 requires three BATPs to be operable during dual unit operation. TS 3.6.b.4 requires the establishment of one flow path from the BASTs when a reactor is critical. With the 3B BATP OOS, three pumps remained operable, and entry into a TS action statement was not required. The pump was repaired by 0540 on April 15, however, it was not returned to service at that time as inservice testing (IST) was not yet complete. On April 15, at 1315, on his normal rounds, a Nuclear Operator reported that the 3A BATP seal tank was showing no water and the nitrogen cover gas pressure, which should have been greater than 35 psig, was at 15 psig and decreasing. At the time of this event, the 4A and 4B BATPs were aligned to Unit 4, the 3A BATP was OOS, and though the 3B BATP was capable of delivering flow to Unit 3, it too was technically OOS. As both pumps which were aligned to Unit 3 were OOS, no flow path from the BASTs to Unit 3 for which credit could be taken existed. Failure to have a flow path places the unit in TS 3.0.1, which requires that action be initiated within one hour to place the unit in a mode in which TS 3.6.b.4 does not apply (MODE 3). Preparations to enter mode 2 were initiated. At 1415, the 4A BATP was aligned to Unit 3. The unit exited TS 3.0.1 and entered TS 3.6.d.2, which permits continued power operation with one of the three required BATPs OOS, provided that it is restored to operable status within 24 hours. IST of the 3B BATP was completed and the pump was returned to service at 1715 on April 15. With only the 3A BATP now OOS and three BATPs operable, the unit exited TS 3.6.d.2.

CAUSE OF EVENT

The cause of the 3B BATP's failure to deliver adequate flow was a loose set screw in the coupling between the pump motor and the pump. The loose set screw permitted the motor to turn without imparting any motive force to the pump. The cause of the set screw becoming loose is not known as no excessive vibration was noted and the pump had been operating satisfactorily.

The cause of the 3A BATP's seal water level decrease was a failed seal. The seal is cooled by inleakage of water from the seal tank. This water is pressurized by a nitrogen cover.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Turkey Point Unit 3	05000250	88	005	00	03	OF	03

TEXT (If more space is required, use additional NRC Form 366A's) (17)

ANALYSIS OF EVENT.

During this event, both units were in MODE 1. With a unit in MODE 1, an emergency boration path is required. Even though the 3A BATP was OOS and the 3B BATP was technically OOS, the 3B BATP had the coupling set screw tightened and was available for use had emergency boration been required. In fact, no emergency boration was required as no transients or events requiring emergency boration occurred. Additionally, upon discovery of the loss of flowpath, one of the Unit 4 BATPs was quickly aligned to provide a flowpath to Unit 3. Additionally, the flowpath from the Refueling Water Storage Tank to the charging pumps and the safety injection pumps was available. Based on the above, the health and safety of the public were not affected.

CORRECTIVE ACTIONS

- 1) The 4A BATP was realigned to provide a boric acid flowpath to Unit 3 at 1415 on April 15.
- 2) IST of the 3B BATP was initiated at 1350 on April 15, completed satisfactorily, and the 3B BATP was returned to service at 1715 on April 15.
- 3) The mechanical seal for the 3A BATP was replaced, and the pump was returned to service at 1600 on April 18.

ADDITIONAL DETAILS

The BATPs are manufactured by Goulds, Inc., model number 3196-ST-8. The mechanical seals are manufactured by Durametallic.

Similar occurrences: a previous BATP seal failure was reported in LER 250-87-17.

FPL

MAY 13 1988

L-88-225  
10 CFR 50.73

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4  
Docket Nos. 50-250 and 50-251  
Reportable Event: 88-05  
Date of Event: April 15, 1988  
Loss of Flowpath from Boric Acid Storage  
Tanks to Reactor Coolant System Due  
to Coupling Failure of 3B Boric Acid  
Transfer Pump (BATP) and Seal Failure of 3A BATP

The attached Licensee Event Report (LER) is being submitted pursuant to the requirements of 10 CFR 50.73 to provide notification of the subject event.

Very truly yours,

*W. F. Conway*

W. F. Conway  
Senior Vice President - Nuclear

WFC/SDF/gp

Attachment

cc: Dr. J. Nelson Grace, Regional Administrator,  
Region II, USNRC  
Senior Resident Inspector, USNRC, Turkey Point Plant

SDF3.LER

*LE22*  
*11*

an FPL Group company