

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8812120190 DOC. DATE: 88/12/07 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light Co 05000250
 AUTH. NAME: LYONS, E. AUTHOR AFFILIATION: Florida Power & Light Co.
 CONWAY, W.F. Florida Power & Light Co.
 RECIP. NAME: RECIPIENT AFFILIATION

SUBJECT: LER 88-026-00: on 881107, Units 3 & 4 outside FSAR design basis w/ regard to hurricane flood protection. W/8 ltr.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 6
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1	PD2-2 PD	1 1
	EDISON, G	1 1		
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	ACRS WYLIE	1 1	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	1 1
	ARM/DCTS/DAB	1 1	DEDRO	1 1
	NRR/DEST/ADS 7E	1 0	NRR/DEST/CEB 8H	1 1
	NRR/DEST/ESB 8D	1 1	NRR/DEST/ICSB 7	1 1
	NRR/DEST/MEB 9H	1 1	NRR/DEST/MTB 9H	1 1
	NRR/DEST/PSB 8D	1 1	NRR/DEST/RSB 8E	1 1
	NRR/DEST/SGB 8D	1 1	NRR/DLPQ/HFB 10	1 1
	NRR/DLPQ/QAB 10	1 1	NRR/DOEA/EAB 11	1 1
	NRR/DREP/RAB 10	1 1	NRR/DREP/RPB 10	2 2
	NRR/DRIS/SIB 9A	1 1	NUDOCS-ABSTRACT	1 1
	REG FILE 02	1 1	RES/DSIR/EIB	1 1
	RES/DSR/PRAB	1 1	RGN2 FILE 01	1 1
EXTERNAL:	EG&G WILLIAMS, S	4 4	FORD BLDG HOY, A	1 1
	H ST LOBBY WARD	1 1	LPDR	1 1
	NRC PDR	1 1	NSIC HARRIS, J	1 1
	NSIC MAYS, G	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 43 ENCL 42

A/0-4

R
I
D
S
/
A
D
D
S
/
R
I
D
S
/
A
D
D
S

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Turkey Point Unit 3															DOCKET NUMBER (2) 0 5 0 0 0 2 5 0					PAGE (3) 1 OF 0 5					
TITLE (4) Units 3 and 4 Outside the Final Safety Analysis Report Design Basis with Regard to Hurricane Flood Protection																									
EVENT DATE (5)			LER NUMBER (6)					REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)														
MONTH	DAY	YEAR	YEAR		SEQUENTIAL NUMBER		REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)												
1	1	0	7	8	8	8	8	2	6	0	0	1	2	0	7	8	8	0	5	0	0	0	2	5	1
OPERATING MODE (8) 5			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																						
POWER LEVEL (10) 0 0 0		20.402(b)					20.406(c)					60.73(a)(2)(iv)					73.71(b)								
		20.406(a)(1)(i)					60.38(c)(1)					60.73(a)(2)(v)					73.71(c)								
		20.406(a)(1)(ii)					60.38(c)(2)					60.73(a)(2)(vii)					OTHER (Specify in Abstract below and in Text, NRC Form 355A)								
		20.406(a)(1)(iii)					60.73(a)(2)(i)					60.73(a)(2)(viii)(A)													
		20.406(a)(1)(iv)					60.73(a)(2)(ii)					60.73(a)(2)(vii)(B)													
		20.406(a)(1)(v)					60.73(a)(2)(iii)					60.73(a)(2)(ix)													
LICENSEE CONTACT FOR THIS LER (12)															TELEPHONE NUMBER										
NAME Edward Lyons, Compliance Engineer										AREA CODE 3 0 5					2 4 6 - 6 7 3 1										
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																									
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDPS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDPS															
SUPPLEMENTAL REPORT EXPECTED (14)										EXPECTED SUBMISSION DATE (15)					MONTH	DAY	YEAR								
YES (If yes, complete EXPECTED SUBMISSION DATE)										X NO															

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (10)

On November 7, 1988, at approximately 1900, with Unit 3 in cold shutdown and Unit 4 defueled, it was determined that Units 3 and 4 were outside their design basis with regard to hurricane flood protection. The Final Safety Analysis Report states, "The unit is designed for a hurricane tide to an elevation of +20 feet with wave run-up to an elevation of 22.5 feet on the east side of the unit." The following conditions were identified by a Quality Assurance auditor:

1) The diesel oil transfer pumps are mounted at elevation 19.0 feet without flood protection. 2) A section of a flood protection wall, approximately 8 feet in length, between the Emergency Diesel Generator (EDG) building and the Unit 3 switchgear enclosure has been temporarily removed as a portion of a plant modification. 3) The stoplogs on the east face of the Auxiliary Building provide protection only to elevation 20 feet. Items 1 and 2 above were caused by design error. Item 3 was caused by the lack of plant drawings that clearly identify stop log details. As an interim corrective action, temporary flood protection dikes will be erected using sandbags and polyethylene sheet, in the event of a hurricane warning. As long term corrective actions, plant modifications will be performed to provide flood protection for the above concerns.

8812120190 881207
PDR ADOCK 05000250
S FRC

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Turkey Point Unit 3	0 5 0 0 0 2 5 0	8 8	— 0 2 6	— 0 0	0 2	OF	0 5

TEXT (If more space is required, use additional NRC Form 368A's) (17)

DESCRIPTION OF THE EVENT

On November 7, 1988, at approximately 1900, with Unit 3 in cold shutdown and Unit 4 defueled, it was determined that Units 3 and 4 were outside their design basis with regard to hurricane flood protection. Appendix 5A of the Final Safety Analysis Report (FSAR) states, "The unit is designed for a hurricane tide to an elevation of +20 feet with wave run-up to an elevation of 22.5 feet on the east side of the unit." (All elevations are referenced from mean low water level.) The following concerns were identified by a Quality Assurance auditor on October 19, 1988, and subsequently evaluated by FPL's Nuclear Engineering Organization.

- 1) The diesel oil transfer pumps are located adjacent to the northeast corner of the Emergency Diesel Generator (EDG) building at elevation 19.0 feet. No flood protection is provided for these pumps.
- 2) A section of wall approximately 8 feet in length between the EDG building and the Unit 3 switchgear enclosure has been temporarily removed as a portion of a plant modification. This wall serves as a flood protection barrier. The modification package identifies this wall as a flood wall and provides requirements to restore the wall following implementation of the modification, but does not provide compensatory measures in the event of a hurricane. The modification package was prepared by a FPL contractor. The wall was removed in approximately mid-June, 1988.
- 3) The stoplogs on the east face of the Auxiliary Building provide protection only to elevation 20 feet. Based on interviews with plant personnel, it appears that these stop logs were originally constructed of wood. At some point in time, the wood stop logs were replaced with diamond plate. However, the plate did not provide protection to the correct height. Plant drawings provide details for the channels that the stop logs fit into, but do not provide details on the stop logs themselves. It is believed that the wood stop logs were replaced with plate because the wood became warped or rotted.

CAUSE OF THE EVENT

- 1) Item 1 above was caused by inadequate design in that no provisions are made for flood protection of the diesel oil transfer pumps.
- 2) Item 2 above was caused by a design oversight. It was recognized that the wall was a flood barrier, however, the modification package did not provide for compensatory measures in the event of a hurricane warning.
- 3) Item 3 above was caused by a lack of plant drawings that provide clear details of the stop logs.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Turkey Point Unit 3	0 5 0 0 0 2 5 0	8 8	— 0 2 6	— 0 0	0 3	OF	0 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

ANALYSIS

A technical assessment of the three concerns was performed by FPL's Nuclear Engineering Organization. This assessment includes a technical evaluation of the required flood protection (stoplog heights) for openings on the east side of the Auxiliary Building. This evaluation concluded that the plant was designed to provide flood protection to an elevation of +20 feet for hurricane tide, with wave run-up to an elevation of +22 feet on the east side of the Auxiliary Building and +22.5 feet for the Intake Cooling Water pumps. A review of original plant calculations for hurricane flooding indicated that the maximum probable hurricane tide would occur at elevation 18.3 feet and the maximum wave run-up would occur at elevation 21 feet for the east side of the Auxiliary Building. Additionally, wave run-up to 22.5 feet was predicted for the area of the intake structures. The plant grade is at elevation 18 feet. Following is an assessment of each of the three concerns.

1) Flood protection not provided for the diesel oil transfer pumps.

The diesel oil transfer pumps are located adjacent to the northeast corner of the EDG enclosure. The pumps are mounted on a 1 foot tall concrete pedestal which would place the base of the pumps at elevation 19 feet. The pump motors are located 6 inches above the base, which would make the pump vulnerable to any wave run-up or water surge that exceeds elevation 19.5 feet. The maximum water stage for a maximum probable hurricane at Turkey Point is to elevation 18.3 feet. Thus, the pump motors are in no danger of being immersed, but could experience splashing from wave run-up. Since the pumps are designed for outside service, they should be unaffected by conditions short of immersion. Furthermore, the fuel transfer pumps are located in an area of the plant where wave run-up is not a significant concern. Any wave run-up would be significantly retarded and dampened due to the numerous structures located east of the pumps.

2) Temporary removal of a portion of flood protection wall.

In the event of a hurricane warning (which is issued prior to a hurricane striking the coast) plant emergency procedures require installation and inspection of the flood protection stoplogs. The required stoplog which abuts the subject wall would not be able to be installed due to the absence of the wall. Although plant procedures do not provide specific actions to be taken when a stoplog cannot be installed, it is reasonable to assume that this condition would be noted and compensatory measures initiated. If compensatory measures could not be completed prior to the maximum probable hurricane flood at elevation 18.3 feet, some localized flooding could occur. The effect of this potential flooding is not known.

3) Stoplogs on the east side of the Auxiliary Building provide protection to only 20 feet.

Results from the original wave run-up analysis indicate that the maximum wave run-up at the east face of the Auxiliary Building would be to elevation 21 feet. This value was obtained without modeling any barriers or ground elevation changes between the intake structure and the Auxiliary Building. A review of the existing configuration east of the Auxiliary Building shows numerous barriers and an elevated roadway (elevation 19 feet, 1 inch) between the Auxiliary Building and the intake structure. It is assumed that the barriers

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Turkey Point Unit 3	0 5 0 0 0 2 5 0 8 8 —	0	2	6	—	0	4 OF 0

TEXT (If more space is required, use additional NRC Form 368A's) (17)

and the elevated roadway would retard and reduce wave run-ups from that of the original model, however, it is not known to what extent this would occur.

CORRECTIVE ACTIONS

- 1) A safety evaluation was prepared by FPL's Nuclear Engineering Organization. This evaluation delineates requirements for temporary flood protection of the diesel oil transfer pumps and the east side of the Auxiliary Building. The safety evaluation requires that, in the event of a hurricane warning, temporary flood protection dikes be constructed using sandbags and polyethylene sheet. This is a short term action until the permanent actions identified in corrective actions 6, 7, 8 and 9 below can be completed.
- 2) The modification package which removed the flood protection wall has been revised to provide instructions and details for the erection of a temporary flood barrier in the event of the issuance of a hurricane warning during implementation of the modification.
- 3) Plant procedures will be revised to require the erection of temporary flood barriers, in the event of a hurricane warning, as described by corrective actions 1 and 2 above. The required procedure revisions will be completed by December 16, 1988.
- 4) The Engineering Contractor responsible for preparation of the modification package has issued a memo to appropriate personnel identifying this event and the need to provide compensatory measures when a modification requires breaching a flood barrier.
- 5) The Engineering Contractor responsible for preparation of the modification package will revise its procedure for preparation of Turkey Point engineering packages to require compensatory measures be provided when a modification requires breaching a flood barrier. This action will be completed by January 1, 1989.
- 6) The flood protection wall which was removed will be restored following completion of the modification, as required by the original modification package.
- 7) Flood protection stop logs on the east face of the Auxiliary Building will be modified to provide protection to elevation 22 feet. In addition, other flood protection stop logs around the plant will be evaluated by Engineering and modified as necessary. These modifications will be completed by June 1, 1989.
- 8) Permanent flood protection will be provided for the diesel oil transfer pumps. This action will be completed by June 1, 1989.
- 9) Drawings identifying the network of flood protection barriers will be prepared and placed in the FPL Drawing Control System via an Engineering Package. The Engineering Package required for this work will be completed by June 1, 1989.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (5)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Turkey Point Unit 3	0 5 0 0 0 2 5 0 8 8	—	0 2 6	— 0 0	0 5	OF	0 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

- 10) The FSAR wording in Appendix 5A will be revised to clarify the design basis hurricane flood elevations. The required FSAR change package will be prepared concurrent with the Engineering package identified in item 9 above.

ADDITIONAL INFORMATION

Similar events: none



FPL

P.O. Box 14000, Juno Beach, FL 33408-0420

DECEMBER - 7 1988

L-88-515
10 CFR 50.73

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Reportable Event: 250-88-26
Date of Event: November 7, 1988
Units 3 and 4 Outside the Final Safety
Analysis Report Design Basis with
Regard to Hurricane Flood Protection

The attached License Event Report (LER) is being submitted pursuant to the requirements of 10 CFR 50.73 to provide notification of the subject event.

Very truly yours,

W. F. Conway
Senior Vice President - Nuclear

WFC/RHF/gp

Attachment

cc: Malcolm L. Ernst, Acting Regional Administrator, Region II,
USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

LE22
11

