

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8807060062 DOC.DATE: 88/06/15 NOTARIZED: NO DOCKET #
 FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251

AUTH.NAME : AUTHOR AFFILIATION
 CONWAY,W.F. Florida Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION
 GRACE,J.N. Region 2, Ofc of the Director

See Rpt.

SUBJECT: Forwards summary of mgt on shift weekly repts.

DISTRIBUTION CODE: D036D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 50
 TITLE: Turkey Point Management Onshift Program

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID	CODE/NAME	LTR	ENCL		ID	CODE/NAME	LTR	ENCL
	DRP/ADR-2		1	1		NRR/DRP-1/2		1	1
	PD2-2 PD		1	1		EDISON,G		2	2
INTERNAL:	AEOD		1	1		DEDRO		1	1
	NRR DEPY		1	1		NRR DIR		1	1
	NRR MORISSEAU,D		1	1		NRR/ADP 12-G-18		1	1
	NRR/ADT 12-G-18		1	1		NRR/DLPQ/PEB		1	1
	NRR/DOEA DIR 11		1	1		NRR/DRIS DIR 9A		1	1
	NUDOCS-ABSTRACT		1	1		OE LIEBERMAN,J		1	1
	OGC 15-B-18		1	1		<u>REG FILE</u> 01		1	1
	RGN2 FILE		1	1					
EXTERNAL:	LPDR		1	1		NRC PDR		1	1
	NSIC		1	1					

TOTAL NUMBER OF COPIES REQUIRED: LTR 23 ENCL 23

R
I
D
S
/
A
D
D
S
/
A
D
D
S



38 JUN 20 A 9: 55

JUNE 15 1988

L-88-262

Dr. J. Nelson Grace
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street, N. W., Suite 2900
Atlanta, Georgia 30323


Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Management-on-Shift Weekly Report

Dear Dr. Grace:

Pursuant to the Nuclear Regulatory Commission Order dated October 19, 1987, the attached summary of Management-on-Shift (MOS) reports is submitted. The Plant Supervisor-Nuclear Shift Reports are also being submitted.

Should there be any questions on this information, please contact us.

Very truly yours,


for W. F. Conway

Senior Vice President - Nuclear

WFC/SDF/gp

Attachment - sent to RP

cc: J. Lieberman, Director, Office of Enforcement, USNRC
Dr. G. E. Edison, Project Manager, NRR, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant
R. E. Tallon, President, FPL

*Original
TO: Region 2
J036
11*

8807060062 880615
PDR ADOCK 05000250
R PDC

an FPL Group company

EE36

4

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

MANAGEMENT ON SHIFT (MOS)

WEEK STARTING: 06/06/88

WEEKLY SUMMARY REPORT

PAGE 1 OF 2

Four MOS Observers were on shift. Paul Geddes, Westinghouse Electric Corporation (06/06-12/88, days); Andrew P. Drake, Westinghouse Electric Corporation (06/06-13/88, evenings); Daniel E. Meils, Turkey Point Plant Chemistry Supervisor (06/06-08/88, evenings); and Larry L. Thomas, Turkey Point Nuclear Plant Outage Manager (06/09-13/88, evenings).

Both Units 3 and 4 operated at 100% power throughout the reporting period.

No immediate safety problems were identified by the MOS Observers during the reporting period.

One questionable work practice was identified by the MOS Observers concerning poor maintenance practice which resulted in operating shift supervision preventing I&C specialists from performing work on the wrong train of Reactor Protection.

During the reporting period, the MOS Observers noted seven recommendations and areas for improvement. These comments and suggestions involved:

- Perceived weaknesses in the design package for the new Control Room HVAC system.
- Explaining the basis for the Hi-flow trip of the new HVAC system to operations.
- The apparent misplacement of the Control Room Night Order book.
- The excessive number of spurious fire alarms during inclement weather.
- The reliability of the access control gates inside the Control Room.
- Excessive short runs of SI pumps to fill the SI accumulators.
- The cancellation of PWOs without concurrence by the originator.

8807060062

ATTACHMENT: MOS DAILY REPORTS

MANAGEMENT ON SHIFT (MOS)

WEEKLY SUMMARY REPORT

WEEK STARTING: 06/06/88

PAGE 2 OF 2

During the reporting period the Plant Supervisor-Nuclear (PSN) MOS reporting program continued.

The PSNs identified three questionable work practices. The concerns dealt with control of personnel working in a potentially dangerous area (skyclimber over Main Steam platform), identification of correct train to be worked on PWOs, and returning equipment to service without a complete release of the associated clearance.

The PSN's noted nine recommendations and areas for improvement. These comments and suggestions involved:

- A suggestion to design and install protective cones over weather-sensitive fire detectors. The suggestion included a proposed design.
- A request for a flow balance on Moisture Separator Reheater drains.
- A recommendation for a weekly plant walkdown to identify steam leaks.
- The lack of reliability of the Waste Gas compressors.
- Two concerns related to reliability of the Nuclear Jobs Planning System (NJPS) computer on backshifts.
- A concern expressed about feedback to the Control Room for non-conformance report (NCR) dispositions which render equipment inoperable and the required actions to be taken by Technical Specifications for the inoperable equipment.
- A repeat of an earlier (5/20/88) concern on repair of a fault sense recorder. The original concern is still under evaluation.
- A request for engineering evaluation of the D.C. Bus ground location method.

ATTACHMENT: MOS DAILY REPORTS

To: Operations Superintendent - Nuclear

Date: 06/06/88

From: Paul Geddes
(MOS Observer)Shift: ☒ Day
☐ Night

A. Plant evolutions observed

- Both units, 100% power
- Various-shift meetings
- Various routine operations

B. Immediate safety problems

None

C. Questionable work practices

None

D. Areas for improvement

None at this time.

E. Professionalism, Summary of Shift, Comments

No unprofessional behavior observed

Completed By: Paul Geddes
MOS Observer

Date: 06/06/88

Reviewed By: [Signature]
Operations Superintendent - Nuclear

Date: 6/7/88

Management
Review By:

9:03 16/7/88 CJB 16/7/88 1
PM-N Date SVB Date VP Date

To: Operations Superintendent - Nuclear

Date: 06/06-07/88

From: Andrew P. Drake
(MOS Observer)Shift: ☐ Day
☒ Night

A. Plant evolutions observed

- Unit 3, 100% power
- Unit 4, 100% power
- End of shift briefing - peak shift
- Peak/mid shift turnover
- Mid shift briefing
- Normal operations

B. Immediate safety problems

None observed

C. Questionable work practices

None observed

D. Areas for improvement

None observed

E. Professionalism, Summary of Shift, Comments

No comments

Completed By: Andrew P. Drake
MOS Observer

Date: 06/06-07/88

Reviewed By: [Signature]
Operations Superintendent - Nuclear

Date: 6/7/88

Management

NMR: LHC: NMR KTR

11

11



12

13

14



To: Operations Superintendent - Nuclear

Date: 06/06-07/88

From: Daniel Meils
(MOS Observer)Shift: ☐ Day
☒ Night

A. Plant evolutions observed

- Dual Unit 100% operations
- Tour - Radiation Controlled area, Auxiliary Building, Power Block, Water Treatment Plant
- Troubleshooting - Control Room Normal Air Intake Radiation Monitor Channel A

B. Immediate safety problems

None

C. Questionable work practices

None

D. Areas for improvement

While observing troubleshooting of Control Room Normal Air Intake Radiation Monitor Channel A - a lengthy discussion ensued with the Startup Supervisor on shift. From this discussion several problems were noted:

1. Initial design of the whole package was weak.
2. Vendor-supplied equipment had several errors as provided.
3. Startup does not have direct access to Instrumentation and Control workers to perform startup verifications. This greatly impedes Startup's ability to perform its function.

Improvements:

1. Evaluate this design package to determine where we failed. Then fix it.
2. Hold vendors accountable for supplying correct parts.
3. Get budget approval for Startup to hire several I&C workers to perform startup verifications.

E. Professionalism, Summary of Shift, Comments

Quiet well run shifts.

Completed By: Daniel Meils
MOS Observer

Date: 06/06-07/88

Reviewed By: [Signature]
Operations Superintendent - Nuclear

Date: 6/7/88

Management

11/100 11/100 11/100

1. A
2. B
3. C
4. D
5. E
6. F
7. G
8. H
9. I
10. J
11. K
12. L
13. M
14. N
15. O
16. P
17. Q
18. R
19. S
20. T
21. U
22. V
23. W
24. X
25. Y
26. Z
27. AA
28. AB
29. AC
30. AD
31. AE
32. AF
33. AG
34. AH
35. AI
36. AJ
37. AK
38. AL
39. AM
40. AN
41. AO
42. AP
43. AQ
44. AR
45. AS
46. AT
47. AU
48. AV
49. AW
50. AX
51. AY
52. AZ
53. BA
54. BB
55. BC
56. BD
57. BE
58. BF
59. BG
60. BH
61. BI
62. BJ
63. BK
64. BL
65. BM
66. BN
67. BO
68. BP
69. BQ
70. BR
71. BS
72. BT
73. BU
74. BV
75. BW
76. BX
77. BY
78. BZ
79. CA
80. CB
81. CC
82. CD
83. CE
84. CF
85. CG
86. CH
87. CI
88. CJ
89. CK
90. CL
91. CM
92. CN
93. CO
94. CP
95. CQ
96. CR
97. CS
98. CT
99. CU
100. CV
101. CW
102. CX
103. CY
104. CZ
105. DA
106. DB
107. DC
108. DD
109. DE
110. DF
111. DG
112. DH
113. DI
114. DJ
115. DK
116. DL
117. DM
118. DN
119. DO
120. DP
121. DQ
122. DR
123. DS
124. DT
125. DU
126. DV
127. DW
128. DX
129. DY
130. DZ
131. EA
132. EB
133. EC
134. ED
135. EE
136. EF
137. EG
138. EH
139. EI
140. EJ
141. EK
142. EL
143. EM
144. EN
145. EO
146. EP
147. EQ
148. ER
149. ES
150. ET
151. EU
152. EV
153. EW
154. EX
155. EY
156. EZ
157. FA
158. FB
159. FC
160. FD
161. FE
162. FF
163. FG
164. FH
165. FI
166. FJ
167. FK
168. FL
169. FM
170. FN
171. FO
172. FP
173. FQ
174. FR
175. FS
176. FT
177. FU
178. FV
179. FW
180. FX
181. FY
182. FZ
183. GA
184. GB
185. GC
186. GD
187. GE
188. GF
189. GG
190. GH
191. GI
192. GJ
193. GK
194. GL
195. GM
196. GN
197. GO
198. GP
199. GQ
200. GR
201. GS
202. GT
203. GU
204. GV
205. GW
206. GX
207. GY
208. GZ
209. HA
210. HB
211. HC
212. HD
213. HE
214. HF
215. HG
216. HH
217. HI
218. HJ
219. HK
220. HL
221. HM
222. HN
223. HO
224. HP
225. HQ
226. HR
227. HS
228. HT
229. HU
230. HV
231. HW
232. HX
233. HY
234. HZ
235. IA
236. IB
237. IC
238. ID
239. IE
240. IF
241. IG
242. IH
243. II
244. IJ
245. IK
246. IL
247. IM
248. IN
249. IO
250. IP
251. IQ
252. IR
253. IS
254. IT
255. IU
256. IV
257. IW
258. IX
259. IY
260. IZ
261. JA
262. JB
263. JC
264. JD
265. JE
266. JF
267. JG
268. JH
269. JI
270. JJ
271. JK
272. JL
273. JM
274. JN
275. JO
276. JP
277. JQ
278. JR
279. JS
280. JT
281. JU
282. JV
283. JW
284. JX
285. JY
286. JZ
287. KA
288. KB
289. KC
290. KD
291. KE
292. KF
293. KG
294. KH
295. KI
296. KJ
297. KK
298. KL
299. KM
300. KN
301. KO
302. KP
303. KQ
304. KR
305. KS
306. KT
307. KU
308. KV
309. KW
310. KX
311. KY
312. KZ
313. LA
314. LB
315. LC
316. LD
317. LE
318. LF
319. LG
320. LH
321. LI
322. LJ
323. LK
324. LL
325. LM
326. LN
327. LO
328. LP
329. LQ
330. LR
331. LS
332. LT
333. LU
334. LV
335. LW
336. LX
337. LY
338. LZ
339. MA
340. MB
341. MC
342. MD
343. ME
344. MF
345. MG
346. MH
347. MI
348. MJ
349. MK
350. ML
351. MM
352. MN
353. MO
354. MP
355. MQ
356. MR
357. MS
358. MT
359. MU
360. MV
361. MW
362. MX
363. MY
364. MZ
365. NA
366. NB
367. NC
368. ND
369. NE
370. NF
371. NG
372. NH
373. NI
374. NJ
375. NK
376. NL
377. NM
378. NN
379. NO
380. NP
381. NQ
382. NR
383. NS
384. NT
385. NU
386. NV
387. NW
388. NX
389. NY
390. NZ
391. OA
392. OB
393. OC
394. OD
395. OE
396. OF
397. OG
398. OH
399. OI
400. OJ
401. OK
402. OL
403. OM
404. ON
405. OO
406. OP
407. OQ
408. OR
409. OS
410. OT
411. OU
412. OV
413. OW
414. OX
415. OY
416. OZ
417. PA
418. PB
419. PC
420. PD
421. PE
422. PF
423. PG
424. PH
425. PI
426. PJ
427. PK
428. PL
429. PM
430. PN
431. PO
432. PP
433. PQ
434. PR
435. PS
436. PT
437. PU
438. PV
439. PW
440. PX
441. PY
442. PZ
443. QA
444. QB
445. QC
446. QD
447. QE
448. QF
449. QG
450. QH
451. QI
452. QJ
453. QK
454. QL
455. QM
456. QN
457. QO
458. QP
459. QQ
460. QR
461. QS
462. QT
463. QU
464. QV
465. QW
466. QX
467. QY
468. QZ
469. RA
470. RB
471. RC
472. RD
473. RE
474. RF
475. RG
476. RH
477. RI
478. RJ
479. RK
480. RL
481. RM
482. RN
483. RO
484. RP
485. RQ
486. RR
487. RS
488. RT
489. RU
490. RV
491. RW
492. RX
493. RY
494. RZ
495. SA
496. SB
497. SC
498. SD
499. SE
500. SF
501. SG
502. SH
503. SI
504. SJ
505. SK
506. SL
507. SM
508. SN
509. SO
510. SP
511. SQ
512. SR
513. SS
514. ST
515. SU
516. SV
517. SW
518. SX
519. SY
520. SZ
521. TA
522. TB
523. TC
524. TD
525. TE
526. TF
527. TG
528. TH
529. TI
530. TJ
531. TK
532. TL
533. TM
534. TN
535. TO
536. TP
537. TQ
538. TR
539. TS
540. TT
541. TU
542. TV
543. TW
544. TX
545. TY
546. TZ
547. UA
548. UB
549. UC
550. UD
551. UE
552. UF
553. UG
554. UH
555. UI
556. UJ
557. UK
558. UL
559. UM
560. UN
561. UO
562. UP
563. UQ
564. UR
565. US
566. UT
567. UY
568. UZ
569. VA
570. VB
571. VC
572. VD
573. VE
574. VF
575. VG
576. VH
577. VI
578. VJ
579. VK
580. VL
581. VM
582. VN
583. VO
584. VP
585. VQ
586. VR
587. VS
588. VT
589. VU
590. VV
591. VW
592. VX
593. VY
594. VZ
595. WA
596. WB
597. WC
598. WD
599. WE
600. WF
601. WG
602. WH
603. WI
604. WJ
605. WK
606. WL
607. WM
608. WN
609. WO
610. WP
611. WQ
612. WR
613. WS
614. WT
615. WU
616. WV
617. WW
618. WX
619. WY
620. WZ
621. XA
622. XB
623. XC
624. XD
625. XE
626. XF
627. XG
628. XH
629. XI
630. XJ
631. XK
632. XL
633. XM
634. XN
635. XO
636. XP
637. XQ
638. XR
639. XS
640. XT
641. XU
642. XV
643. XW
644. XX
645. XY
646. XZ
647. YA
648. YB
649. YC
650. YD
651. YE
652. YF
653. YG
654. YH
655. YI
656. YJ
657. YK
658. YL
659. YM
660. YN
661. YO
662. YP
663. YQ
664. YR
665. YS
666. YT
667. YU
668. YV
669. YW
670. YX
671. YY
672. YZ
673. ZA
674. ZB
675. ZC
676. ZD
677. ZE
678. ZF
679. ZG
680. ZH
681. ZI
682. ZJ
683. ZK
684. ZL
685. ZM
686. ZN
687. ZO
688. ZP
689. ZQ
690. ZR
691. ZS
692. ZT
693. ZU
694. ZV
695. ZW
696. ZX
697. ZY
698. ZZ
699. AA
700. AB



Date 06/06/88

Shift Report

Shift Peak

Shift Management

PSN Schimkus APSN Murphy NWE Eddinger

A. Questionable Work Practices/Actions Taken/Recommendations

None

B. Areas for Improvement/Recommendations/Actions Taken

1. A constant problem is experienced with the Appendix "R" ultraviolet and infrared fire detector which has been addressed numerous times by our Control Room operating staff. When heavy rains or dry dusty weather occur, the lens devices of these detectors become either covered with water droplets or covered with dust. The detector sets off the alarm on Control Room Fire panel C 39 A, which is not only erroneous but annoying due to the continuous intermittent alarm and buzzer.

Recommendations: (See drawing) Recommend that these type detectors have cones mounted around the lens which do not inhibit the detector's field of vision, however create a block to any water intrusion, and an air block to most particulate suspended in the air environment.

Actions taken: On 6/06/88, declared Unit 4 Intake Fire Detection Alarm Point 26 out-of-service and hung Fire Impairment tag.

2. NJPS (Nuclear Job Planning System) is probably one of our most important tools in the Nuclear Control Room. On most weekends, holidays, and many backshifts it can be expected to become inoperable and lock-up, then it is a painstaking process to locate someone to bring it back on the line. Most of these times the PSN contacts a tape recorder, whose owner in many cases never answers back till the next scheduled employee work day, which can be three days up the road.

Recommendation: Appoint a duty computer programmer who is responsible for the machine 24 hours a day and have this person or persons carry a beeper, supply a home phone number and have a duty call list placed in the PSN duty call book.

3. 3A Reheater Drain Tank outlet flow orifice (FE-5120) outlet flange has steam issuing thru the lagging and is becoming worse. PWO #312347 was issued on November 7, 1987 when the leak started. Unit 3 was at cold shutdown at this time and the secondary was cold until 12/20/87. The leak was not repaired during the outage nor has been repaired to this day. Maintenance repaired two other leaks within five feet of this leak; however, no attention was paid to this steam leak by any of the individuals in the area. Fermaite has been to the plant a number of times since Unit 3 returned to service, however, this leak has not been placed on the Fermaite list.

Reviewed By L. W. P. [Signature] Date 6/17/88 Actions Completed Date

18

19

20

21

22

23



24

25

26

27

28

29

30

31

32

33

34

35

36



Continuation Page

Recommendations: At least once per working week (no lesser frequency) the Maintenance Superintendent, Operations (NTO), and Mechanical GEMS Coordinator shall make a tour of the Secondary Steam Systems (full tour). They shall document all leaks and those with no PWO shall be identified by Mechanical GEMS Coordinator who will be responsible to initiate a PWO. All leaks found on line shall be evaluated for on-line fix without utilizing the usual SNOW (Short Notice Outage Work) network approach.

If attention to secondary leaks is put on the same level as primary leaks i.e., boric acid Unit 4 vessel head, etc., the plant may receive less attention from our regulators, INPO, etc. as they tour our secondary for numerous reasons, and the individuals working our secondary will feel a sense of safety as they perform their jobs.

C. Good Practices/Professionalism Observed

1. The cleaning efforts of contractor employee Barbara Jones have been above and beyond the call of duty. She is very concerned about the cleanliness of our Control Room and it has become evident from her efforts, following the shift she is working. Please supply her with the tools she needs to her job efficiently i.e., a quiet vacuum cleaner.

100

100

100

100

100

100

100



100

100

100

100



100

100




Date 06/06/88

Shift Report

Page 3

Continuation Page



10

11

12



Date 06/06-07/88

Shift Report

Shift Mid

Shift Management

SN Wogan APSN Singer NWE Vetromile

A. Questionable Work Practices/Actions Taken/Recommendations

None observed

B. Areas for Improvement/Recommendations/Actions Taken

None at this report

C. Good Practices/Professionalism Observed

Units 3 and 4 at 100% power

Reviewed By D.A. Pina Date 6/7/88 Actions Completed Date

To: Operations Superintendent - Nuclear

Date: 06/07/88

From: Paul Geddes
(MOS Observer)Shift: ☒ Day
☐ Night

A. Plant evolutions observed

- Both units, 100% power
- Various shift meetings
- Auxilliary Feedwater Test
- Reactor Protection Test
- Plant Tour

B. Immediate safety problems

None

C. Questionable work practices

None

D. Areas for improvement

None.

E. Professionalism, Summary of Shift, Comments

No problems observed

Completed By: Paul Geddes
MOS Observer

Date: 06/07/88

Reviewed By: [Signature]
Operations Superintendent - Nuclear

Date: 6/8/88

Management
Review By:CJB 16/8/88 [Signature] 16/8/88
PM-N Date SVP Date[Signature] 16/8/88
VP Date

1947



1947

To: Operations Superintendent - Nuclear

Date: 06/07-08/88

From: Andrew P. Drake
(MOS Observer)Shift: ☐ Day
☒ Night**A. Plant evolutions observed**

- Unit 3, 100% power
- Unit 4, 100% power
- Peak Shift End of shift briefing
- Peak/mid shift turnover
- Mid shift briefing
- Normal operations
- Unit 3 Reactor Protection Trip Logic Test
- Unit 3B Emergency Diesel Generator Test

B. Immediate safety problems

None observed

C. Questionable work practices

None observed

D. Areas for improvement

1. Performance of Reactor Protection Test on peak shift identified a Reactor Coolant System flow relay problem on Train "B" (Relay FC-3-416X). A PWO was written (WA880607191835) for repairs. The mid shift I & C crew started to work the PWO and went to the relay cabinet, R34, as identified on the PWO. This however was a Train "A" cabinet. The mid shift NWE was monitoring the work and noticed the incorrect train was about to be worked and took actions to correct the error. During discussion with the I & C Supervisor, APSN, and NWE several items were noted on the PWO that could have prevented or reduced the possibility of this occurrence:
 - a. The equipment name did not have the train identified on it. This would alert the technician as to the train he is to work on
 - b. The wrong relay rack was given, R34 instead of R39. R34 is a Train "A" rack and R39 is Train "B". If item a. had been performed the error would have been more evident.

10

10

10

10

10

10

10

10

10

10

10

10

10

10

10

10

10

10

- c. Work description section should identify train of component as well as component. (i.e. "replace Train "B" relay FC-3-416X" instead of 'replace relay FC-3-416X')
 - d. A single key will open relay cabinets on Train "A" and "B" on both units. If there were a separate key/lock set for each train on each unit (4keys) then you would be assured that the proper unit and train was being worked on.
 - e. PWO entered on GEMS should contain train designation to assist in working up PWO package.
2. Night Order Book is no longer in the Control Room
- a. Why has it been removed?
 - b. The turnover sheet no longer requires it to be reviewed. How is information already in it to be transmitted to the crews?
 - c. How is the type of information found in the book going to be transmitted in the future?
 - d. The Night Order Book was a good way to pass information on from shift to shift and retain for reference. It should continue to be used for this and not be discontinued.

B. Professionalism, Summary of Shift, Comments

Mid shift NWE performed his job very well as was demonstrated by the "catch" of the train error on relay FC-3-416X work.

Excessive animal and other sounds effects were present on the plant PA tonight. This type of activity had decreased over the last few months.

Completed By: Andrew P. Drake
MOS Observer

Date: 06/06-07/88

Reviewed By: [Signature]
Operations Superintendent - Nuclear

Date: 6/8/88

Management
Review By:

3/B 16/8/88 [Signature] 16/8/88 7/15 1 6/8/88
PM:N Date SVP Date VP Date

24

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

To: Operations Superintendent - Nuclear

Date: 06/07-08/88

From: Daniel Meils
(MOS Observer)Shift: ☐ Day
☒ Night

A. Plant evolutions observed

- ° Shift Turnover, Control Room Ventilation Radiation Monitor troubleshooting, 3-OSP-049.1
- ° Tour - Radiation Controlled Area, Auxillary Building, Power Block

B. Immediate safety problems

None

C. Questionable work practices

While conducting a tour of the work site, the NWE observed the Instrumentation and Control Specialists in the wrong cabinet. They had gained access to Train "A" not Train "B" as required. Upon review of the PWO it was found to indicate the Train "A" panel vs. the Train "B" panel as required.

D. Areas for improvement

1. Notify the Human Performance Evaluation System (HPES) of near miss to perform a complete analysis of events surrounding this event. (See C)
Consider all possible corrective actions to eliminate occurrences. (e.g., seperate keys for Train "A" vs. "B".)
2. Repeat alarms (more than 10 in 5 minutes) on the Fire Detection panel C39A must be eliminated immediately. By the end of the shift these alarms had affected the behavior of the whole shift.

E. Professionalism, Summary of Shift, Comments

APSN, NWE, and two RCOs completed a thorough briefing of 3-OSP-049.1 prior to performing the evolution.

Repeat back communications was utilized in the field while conducting 3-OSP-049.1

Completed By: Daniel Meils
MOS Observer

Date: 06/07-08/88

Reviewed By: [Signature]
Operations Superintendent - Nuclear

Date: 6/8/88

Management
Review Rv

CMB 6/8/88 JSD 6/8/88 JLD 6/8/88

1. The first part of the document is a list of names and addresses of the members of the committee. The names are listed in alphabetical order, and the addresses are given in full. The list is as follows:

2. The second part of the document is a list of the names and addresses of the members of the committee. The names are listed in alphabetical order, and the addresses are given in full. The list is as follows:

3. The third part of the document is a list of the names and addresses of the members of the committee. The names are listed in alphabetical order, and the addresses are given in full. The list is as follows:

4. The fourth part of the document is a list of the names and addresses of the members of the committee. The names are listed in alphabetical order, and the addresses are given in full. The list is as follows:

5. The fifth part of the document is a list of the names and addresses of the members of the committee. The names are listed in alphabetical order, and the addresses are given in full. The list is as follows:

6. The sixth part of the document is a list of the names and addresses of the members of the committee. The names are listed in alphabetical order, and the addresses are given in full. The list is as follows:

7. The seventh part of the document is a list of the names and addresses of the members of the committee. The names are listed in alphabetical order, and the addresses are given in full. The list is as follows:

Date 06/07/88

Shift Report

Shift Peak

Shift Management

PSN Schimkus APSN Murphy NWE Eddinger

A. Questionable Work Practices/Actions Taken/Recommendations

None

B. Areas for Improvement/Recommendations/Actions Taken

1. Waste Gas Compressors A & B should always be available to lower vent header pressure or perform Volume Control Tank purges. My experience since being a nuclear operator until now is that either these compressors are a low priority item or they were designed to malfunction once per week. The frequency of these waste gas compressors malfunctioning appears to have increased significantly over the past few years. The problems encountered are seal leaks which gas out the Auxillary Building, Moisture Seperator level control malfunctions, compressor unloader control valves sticking open, motor breaker and line contactor problems, etc. These compressors are Nash type water seal pumps which incorporate a simple principle to pump gas yet they are basically inefficient and rarely can raise waste gas decay tank pressure above 80 psig.

Recommendation:

1. Call in a vendor to analyze this entire system and replace whatever parts are necessary to "make it work".
2. Send some of our Maintenance people to a school for maintenance/repair of Nash pumps to learn techniques for trouble shooting I&C and mechanical problems.
Note: This school would be a benefit not only in respect to waste gas compressors but also breathing air compressors which stay inoperable longer during outages than actually operating. They are also Nash type compressors.
2. On 5-20-88 I entered a MOS report on Fault Sense Recorder (Sangamo) continuous operation. I have not as yet received an answer to my question, however if PTN is responsible for a system fault (blackout) you may be expected to supply some answers and your key piece of equipment is out of service again.
Actions: Submitted another PWO to allow another temporary fix.
Recommendations: Repair or replace this equipment.

C. Good Practices/Professionalism Observed

1. Although the Unit 4 Turbine Trip Test was postponed till tomorrow, the Turbine Operator walked down the system and discovered that the Turbine oil pressure light on the front standard indicating the turbine is latched with proper oil pressure is inoperable. He immediately notified the PSN and generated a PWO. The turbine Trip Test will be postponed until this is repaired.

Viewed By [Signature] Date 6/8/88 Actions Completed Date

PSN MOS

Date Started 05/20/88

Date Finished 05/20/88

Initiating PSN Schlmkus PSN _____ Completed PSN Schlmkus

Initiating APSN Dallau APSN _____ Completed APSN Dallau

A. Questionable Work Practices/Actions Taken/Recommendations

None

B. Areas for Improvement/Recommendations/Actions Taken

The Sangamo Fault Sense Recorder is out of service and has been for over a month. It has run one day at a time from PWO to PWO since Christmas 1987. If an unexplainable line fault occurs which could cause relay action from our plant out into the system relays, PTN would have limited resources to explain how our plant was the cause or non-cause of the system disturbance.

Recommend a total upgrade of our fault sense recorder.

C. Good Practices/Professionalism Observed

Routine operations.

[Signature] Date 5/21/88 Actions Completed

Date

Date 06/07/88

Shift Report

Shift DAY

Shift Management

PSN Salkeld APSN Guyer NWE Spence

A. Questionable Work Practices/Actions Taken/Recommendations

The skylimber being used for the tendon surveillance was moved above the Main Steam Platform and personnel were working upon it. The Construction Supervisor came to the Control Room to request advance notification if we were going to "release any steam." In fact we were engaged in a load-threatening periodic at that time. It took approximately 40 minutes to get the men out of the skylimber. We have requested notification prior to placing personnel in areas where operations can affect their safety.

B. Areas for Improvement/Recommendations/Actions Taken

None.

C. Good Practices/Professionalism Observed

Yes

Reviewed By J. A. Palmer Date 6/8/88 Actions Completed Date

Date 06/07-08/88

Shift Report

Shift Mid

Shift Management

PSN Jones APSN Haley NWE Matuzewski

A. Questionable Work Practices/Actions Taken/Recommendations

During the replacement of relay FC-3-416 the Instrumentation and Control Technicians (I&C Techs) were found to be in the Train "A" racks instead of Train "B". The NWE immediately asked them to get out of the racks. When the NWE signed the PWO he instructed the techs to "THINK "B". The rack they were in is clearly labelled Train A. Although no problem occurred the potential was there.

The PWO was not clear as to what train was to be worked on. The PWO specified Rack 34. The correct rack should have been 39. The I&C Techs should not have opened the train "A" rack after being told "THINK "B"". Operations should review PWOs to insure correct information is available as completely as possible. GEMS Coordinators should be aware of train operability when planning Reactor Protection Relay Replacement (PWO attached).

B. Areas for Improvement/Recommendations/Actions Taken

C. Good Practices/Professionalism Observed

Reviewed By K. Hance Date 6/8/88 Actions Completed _____ Date _____

DUPLICATE PRINTING WORK ORDER

Unit	PWO JO SPEC ER	Work Request #	DUPLICATE PRINTING
FTN	03	8021 / 63	WAB80607191835

GENERATOR SECTION

JOB PLANNING SECTION

APPROVAL

CONTROL SECTION

Component Tag Number FC-3-416				Associated Component				System 041							
Equipment Name Component Description RCC FLOW LOG - SIG. COMP															
Q/C REQUIRED															
Detect Work Request INTERMITTANT ACTUATION DURING RX PROTECTION TEST (RELAY IS IN RCC CABLE SPREADING ROOM.															
Location RCC FLOW ROOM. PROTECTION & CONTROL RACKS								Detecting Tag NONE							
Seriousness Reason QSP ACCEPTANCE CRITERIA 13-QSP-043.11															
										NPRDS 110 Status at Time of Failure 120 Failure Symptom 130 Failure Detection					
QIP	Rework Job	Y	Why?	UNKNOWN											
By (Originator and Plant Department) D L EDDINGER / 4				Date 060788	Time 19 18	Approved By D L EDDINGER				Date 060788	LCO				
Lead Maintenance Dept 2				170 Priority	A1		180 Unit Condition Required		B		NPRDS	Y			
Clearance Required (Y or N)		Clearance Number 3-80-06-025		Rad. Work Permit Required (Y or N)		RWP Number		Safety Class O-Group		SR					
10 CFR 50.49 item (Y or N)		Additional Fire Protection Review (Y or N)		Post Maint. Test Req. (Y or N)		IST Required (Y or N)		FYP		PME					
Manpower Requirements		2.0		Work Type	190		Crew	6		Estimated Manhours	8				
										Standard (X)					
Assigned To JMM															
O.C. Requirements															
Work Description 1. PERFORM I/V PER ATTACH #3 FOR WIRE REMOVAL AND REPLACEMENT. 2. INSURE CHANNEL IS REMOVED FROM SERVICE. 3. REPLACE RELAY FC-3-416X (M&S# 005-59220-8) 4. IF PROBLEMS ARISE CONTACT FS/QC FOR RESOLUTION. 5. FMT: SEE AP 0190.28 STEP 8.1.3 6. REF: 5610-M-430-146															
JOURNEYMAN: If TEDB Datasheet attached, verify by observation								Plan Pack Prepared By Date PAT ROY / 060788							
Plan Pack Approval Supervisor Date PAT ROY / 060788								Q/C Approval Date PER TELECON W/E. GUERRA 6/7/88 Patrick Roy							
NPS Permission to Start <i>[Signature]</i>								Date 6/8/88		Time 0306		LCO	Y		
NPS Notification of Completion								Date		Time					
KEY FIELDS MUST MATCH LOGUSER MASTER LISTING															
TRAN CODE	CHARGE LOCN	PLANT	PWO JO SPEC ER	DEPT	CREW	WORK TYPE	ER	ACCOUNT NUMBER	UNIT NO.	EQUIP I.D.	MAJOR EQUIP	MAJOR EQUIP MFR.	MINOR EQUIP	MINOR EQUIP MFR.	REASON CAUSE
300	914	W	8021	2	6	5	63	530020	03		RS80	HSS			
OUTAGE CODE	ACTION CODE	OUTAGE START				OUTAGE END				CURTAILED		DO NOT HOLD			
		MO	DAY	YR	HOUR	MIN	MO	DAY	YR	HOUR	MIN			If Outage Code 1, 2, 3, 5 : Process Immediately	
PROBLEM DEFINITION WORK DESCRIPTION COMMENTS TAG NUMBER															PRIORITY
															01

To: Operations Superintendent - Nuclear

Date: 06/08/88

From: Paul Geddes
(MOS Observer)Shift: ☒ Day
☐ Night

A. Plant evolutions observed

- Both units, 100% power
- Various meetings
- Reactor Trip Breaker replacement and testing
- Pressurizer pressure surveillance
- "A" Diesel Generator test and return to service

B. Immediate safety problems

None

C. Questionable work practices

None

D. Areas for improvement

None

E. Professionalism, Summary of Shift, Comments

Well run shifts

Completed By: Paul Geddes
MOS Observer

Date: 06/08/88

Reviewed By: L.W. Preece
Operations Superintendent - Nuclear

Date: 6/9/88

Management
Review By:

J. Lane 16/9/88 AO 16/9/88
PM-N Date SVP Date VP Date
06/08/88

10

11

12



13

14

15

16

17



18

19

20

21

22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
841
842
843
844
845
846
847
848
849
850
851
852
853
854
855
856
857
858
859
860
861
862
863
864
865
866
867
868
869
870
871
872
873
874
875
876
877
878
879
880
881
882
883
884
885
886
887
888
889
890
891
892
893
894
895
896
897
898
899
900
901
902
903
904
905
906
907
908
909
910
911
912
913
914
915
916
917
918
919
920
921
922
923
924
925
926
927
928
929
930
931
932
933
934
935
936
937
938
939
940
941
942
943
944
945
946
947
948
949
950
951
952
953
954
955
956
957
958
959
960
961
962
963
964
965
966
967
968
969
970
971
972
973
974
975
976
977
978
979
980
981
982
983
984
985
986
987
988
989
990
991
992
993
994
995
996
997
998
999
1000

100



To: Operations Superintendent - Nuclear

Date: 06/08-09/88

From: Andrew P. Drake
(MOS Observer)Shift: ☐ Day
☒ Night

A. Plant evolutions observed

- Units 3 and 4, 100% power
- End of peak shift briefing
- Peak/mid shift turnover
- Mid shift briefing

B. Immediate safety problems

None observed

C. Questionable work practices

None observed

D. Areas for improvement

No comments

E. Professionalism, Summary of Shift, Comments

1. Dave Taylor discussed training brief 232 on Control Room habitability modifications with the peak and mid shift operators. Having him present the material and be available to answer questions was extremely beneficial to the operators. The use of plant personnel knowledgeable on training brief information should be used as a standard practice when new systems or modifications are presented to the operators.
2. Update on item D.1 of my report on 6/07-08/88 covering Reactor Coolant System flow relay FC-3-416X. The original PWO as entered by the peak shift crew did not contain the rack number (R34). This information was added on during the workup of the work package. It was also noted to the PSN that the original PWO did not contain the train in which the relay was to be worked.

Completed By: Andrew P. Drake
MOS Observer

Date: 06/08-09/88

Reviewed By: *[Signature]*
Operations Superintendent - Nuclear

Date: 6/9/88

Management
Review By:*[Signature]* 6/9/88 *[Signature]* 6/9/88
VP 06/08-09/88

To: Operations Superintendent - Nuclear

Date: 06/08-09/88

From: Daniel Meils
(MOS Observer)Shift: ☐ Day
☒ Night

A. Plant evolutions observed

- Dual Unit, 100% power operations
- Nuclear Operator and Turbine Operator rounds
- Standby Feed Pump test
- Tour - Radiation Controlled Area, Power Block, Auxilliary Building, Water Treatment Plant

B. Immediate safety problems

None

C. Questionable work practices

None

D. Areas for improvement

None

E. Professionalism, Summary of Shift, Comments

Well run shifts

Completed By: Daniel Meils
MOS Observer

Date: 06/08-09/88

Reviewed By: H.W. Pearce
Operations Superintendent - Nuclear

Date: 6/9/88

Management
Review By:

J. Cross 10/9/88 SVP Date 6/9/88 VP Date 6/9/88

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

Date 06/08/88

Shift Report

Shift _____ Day _____

Shift Management

PSN _____ Salkeld _____ APSN _____ Guyer _____ NWE _____ Spence _____

A. Questionable Work Practices/Actions Taken/Recommendations

None

B. Areas for Improvement/Recommendations/Actions Taken

None

C. Good Practices/Professionalism Observed

Good tailboard briefings and coordination between Maintenance Departments and Operations allowed a large number of load-threatening periodics to be done without a problem.

Reviewed By *[Signature]* Date 6/9/88 Actions Completed _____ Date _____

10

11

12

13

14

15

16

17

18

19

20

Date 06/08/88

Shift Report

Shift Mid

Shift Management

PSN Jones APSN Haley NWE

A. Questionable Work Practices/Actions Taken/Recommendations

We've seen a problem as indicated in PSN logs 6/08/88. Maintenance Department requested a Temporary Lift of "A" Emergency Diesel Generator (EDG) to check for radiator leaks and belts during test run of EDG. At 1035 "A" EDG test was completed satisfactorily and the EDG declared back in service. At 1710 it was discovered that clearance was on Temporary Lift. At 1711 "A" EDG was declared back in service after proper release was secured. Recommend that the Maintenance Procedure requires a full release of equipment after their inspections are complete.

B. Areas for Improvement/Recommendations/Actions taken

On Unit #3 the steam temperature going to low pressure turbine is approximately 10° lower than what we see on Unit #4. All high level alarms are in for the 4 Moisture Separator Reheaters. We believe that if the Technical Department would do a drain flow balance on the Moisture Separator Reheater Drain system we may be able to gain a few more megawatts.

C. Good Practices/Professionalism Observed

Reviewed By D. V. F. L. L. L. Date 6/8/88 Actions Completed Date

14

15



Date 06/08/88

Shift Report

Shift Peak

Shift Management

PSN Schimkus APSN Murphy NWE Eddinger

A. Questionable Work Practices/Actions Taken/Recommendations

None

B. Areas for Improvement/Recomendations/Actions Taken

None

C. Good Practices/Professionalism Observed

1. Routine operations. Good actions by Turbine Operators and RCO's on Unit 3 to alleviate high vibration on Turbine Generator #9 Bearing and troubleshoot Unit #4 Main Generator Ground Annunciator during heavy rainstorm.
2. Excellent management response to observing backshift operations/maintenance activities. Plant tours and open conversation with operators and maintenance personnel has become a daily routine with our Site Vice President and Plant Manager. This is respected and appreciated by our entire staff.

Reviewed By [Signature] Date 6/9/88 Actions Completed Date

10

11

12

13

14

15



16

17



18

19

20

21

22

23

24



To: Operations Superintendent - Nuclear

Date: 06/09/88

From: Paul Geddes
(MOS Observer)Shift: ☒ Day
☐ Night

A. Plant evolutions observed

- Both units, 100% power
- Steam Generator level surveillance
- "B" Auxiliary Feed Pump test

B. Immediate safety problems

None

C. Questionable work practices

None

D. Areas for improvement

None

E. Professionalism, Summary of Shift, Comments

No specific response is required, but I want to re-emphasize that the waste gas compressors need to be fixed. The Auxiliary Building was gassed again today. This is a personnel hazard (radioactive gas) and is an unsatisfactory situation.

Completed By: Paul Geddes
MOS Observer

Date: 06/09/88

Reviewed By: X.W. Parie
Operations Superintendent - Nuclear

Date: 6/10/88

Management
Review By:

PM-N 16/10/88 SVP 16/10/88 VP 16/10/88
Date Date Date
06/09/88

To: Operations Superintendent - Nuclear

Date: 06/09-10/88

From: L. L. Thomas
(MOS Observer)Shift: ☐ Day
☒ Night

A. Plant evolutions observed

- Steady state operations
- Pre-shift briefing
- Emergency Response Team (ERT) on Control Room Ventilation
- O-OSP-025.1, Interlock Test Control Room Heating Ventilating and Air Conditioning

B. Immediate safety problems

None

C. Questionable work practices

None

D. Areas for improvement

None

E. Professionalism, Summary of Shift, Comments

ERT functioned very well, all departments very cooperative. Most likely prevented plant shutdown.

Completed By: L. L. Thomas
MOS Observer

Date: 06/09-10/88

Reviewed By: [Signature]
Operations Superintendent - Nuclear

Date: 6/10/88

Management [Signature] 16/10/88[Signature] 6/10/88

To: Operations Superintendent - Nuclear

Date: 06/09-10/88

From: Andrew P. Drake

Shift: ☐ Day
☒ Night

(MOS Observer)

A. Plant evolutions observed

- Units 3 and 4, 100% power normal operations
- End of peak shift briefing
- Peak-mid shift turnover
- Beginning mid shift briefing
- Continuation of Control Room Heating, Ventilation and Air Conditioning system testing
- Tour of Turbine Building

B. Immediate safety problems

None observed

C. Questionable work practices

None observed

D. Areas for improvement

No comments

E. Professionalism, Summary of Shift, Comments

No comments

Completed By: Andrew P. Drake
MOS Observer

Date: 06/09-10/88

Reviewed By: [Signature]
Operations Superintendent - Nuclear

Date: 6/10/88

Management

[Signature] 6/10/88[Signature] 6/10/88

Date 06/09/88

Shift Report

Shift _____ Day _____

Shift Management

SN Schimkus APSN Guyer NWE Spence

A. Questionable Work Practices/Actions Taken/Recommendations

None

B. Areas for Improvement/Recommendations/Actions Taken

None

C. Good Practices/Professionalism Observed

Plant Manager interaction with various support groups questioning progress being made on hot items is receiving a thumbs up by the operators. This is a definite step forward to enhance our inter-departmental communications. We appreciate the feed-back we are receiving.

Reviewed By L. W. Lura Date 6/10/88 Actions Completed _____ Date _____

Date 06/09/88

Shift Report

Shift _____ Peak _____

Shift Management

PSN Schimkus APSN Murphy NWE Matuzewski

A. Questionable Work Practices/Actions Taken/Recommendations

None

B. Areas for Improvement/Recommendations/Actions Taken

None

C. Good Practices/Professionalism Observed

Routine operations. Good progress in accomplishing all shift objectives stated at pre-shift briefing.

Reviewed By Lu T. Garcia Date 6/14/88 Actions Completed _____ Date _____

Date 06/10/88

Shift Report

Shift Mid

Shift Management

PSN Jones APSN Haley NWE

A. Questionable Work Practices/Actions Taken/Recommendations

None

B. Areas for Improvement/Recommendations/Actions Taken

None

C. Good Practices/Professionalism Observed

Reviewed By J.W. Hara Date 6/16/88 Actions Completed Date

To: Operations Superintendent - Nuclear

Date: 06/10/88

From: Paul Geddes
(MOS Observer)Shift: ☒ Day
☐ Night

A. Plant evolutions observed

- Both units, 100% power
- Rod position indication testing
- Radiological Controlled Area tour
- Various meetings
- 480 Volt undervoltage relay testing

B. Immediate safety problems

None

C. Questionable work practices

None

D. Areas for improvement

None

E. Professionalism, Summary of Shift, Comments

Well run shifts

Completed By: Paul Geddes
MOS Observer

Date: 06/10/88

Reviewed By: J.W. Hill
Operations Superintendent - Nuclear

Date: 6/13/88

Management
Review By:J. Carr 6/13/88 [Signature] 6/13/88
PM-N Date SVP Date

VP Date

06/10/88

To: Operations Superintendent - Nuclear

Date: 06/10-11/88

From: L. L. Thomas
(MOS Observer)Shift: ☐ Day
☒ Night

A. Plant evolutions observed

- Steady state operations, 100% power
- End of shift meeting
- Shift turnover and briefing
- 4-OSP-200.3
- 3-OSP-200.3

B. Immediate safety problems

None

C. Questionable work practices

None

D. Areas for improvement

None

E. Professionalism, Summary of Shift, Comments

Problem with 3A Reactor Coolant Pump #1 seal leakoff flow was handled well by the mid shift.

Completed By: L. L. Thomas
MOS Observer

Date: 06/10-11/88

Reviewed By: [Signature]
Operations Superintendent - Nuclear

Date: 6/13/88

Management
Review By:

[Signature] 16/13/88 [Signature] 16/13/88
DAN AT DICK CVD Note VP Date

22

23

24

25

26

27

28

29

To: Operations Superintendent - Nuclear

Date: 06/10-11/88

From: Andrew P. Drake
(MOS Observer)Shift: ☐ Day
☒ Night

A. Plant evolutions observed

- ° Units 3 and 4, 100% power
- ° Normal operations

B. Immediate safety problems

None observed

C. Questionable work practices

None observed

D. Areas for improvement

No comment

E. Professionalism, Summary of Shift, Comments

No comments

Completed By: Andrew P. Drake
MOS Observer

Date: 06/10-11/88

Reviewed By: [Signature]
Operations Superintendent - Nuclear

Date: 6/13/88

Management
Review By:[Signature] 6/13/88 [Signature] 6/13/88
Date Date

VP 06/10 Date

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

Date 06/10/88

Shift Report

Shift _____ Day _____

Shift Management

PSN Wogan APSN Singer NWE Vetromile

A. Questionable Work Practices/Actions Taken/Recommendations

None

B. Areas for Improvement/Recommendations/Actions Taken

None

C. Good Practices/Professionalism Observed

Units 3 and 4 at 100% power.

Reviewed By [Signature] Date 6/13/88 Actions Completed _____ Date _____

Date 06/10/88

Shift Report

Shift Peak

Shift Management

PSN Schimkus APSN Murphy NWE Spence

A. Questionable Work Practices/Actions Taken/Recommendations

None

B. Areas for Improvement/Recommendations/Actions Taken

None

C. Good Practices/Professionalism Observed

When a lack of communication occurred on status of 3A Condensate Pump to establish adequate seal water pressure and vendor recommendations were not received, the APSN contacted the Maintenance Superintendant who immediately showed concern and within one hour had activated additional maintenance personnel to find the root cause. His additional orders were to re-disassemble the mechanical seal if no apparent root cause was found. Excellent support by Mechanical Maintenance.

Reviewed By [Signature] Date 6/12/88 Actions Completed Date

11 3 3



11 3 3

11 3 3

11 3 3

11 3 3



11 3 3



Date 06/11/88

Shift Report

Shift Mid

Shift Management

PSN Jones APSN Haley NWE

A. Questionable Work Practices/Actions Taken/Recommendations

None

B. Areas for Improvement/Recommendations/Actions Taken

None

C. Good Practices/Professionalism Observed

Reviewed By *[Signature]* Date 6/13/88 Actions Completed Date

To: Operations Superintendent - Nuclear

Date: 06/11/88

From: Paul Geddes
(MOS Observer)Shift: ☒ Day
☐ Night

A. Plant evolutions observed

- Both units at 100% power
- Volume Control Tank purge
- 3A Condensate pump return to service
- Reassembly of 3C Steam Generator Blowdown Valve
- Plant tour

B. Immediate safety problems

None

C. Questionable work practices

None

D. Areas for improvement

None

E. Professionalism, Summary of Shift, Comments

Quiet shift. The Volume Control Tank purge did not gas the Auxilliary Building, which indicates the problem may have been identified.

Completed By: Paul Geddes
MOS Observer

Date: 06/11/88

Reviewed By: [Signature]
Operations Superintendent - Nuclear

Date: 6/13/88

Management
Review By:

[Signature] 16/12/88 [Signature] 16/13/88
PM-N Date SVP Date VP 06/11/88

To: Operations Superintendent - Nuclear

Date: 06/11-12/88

From: L. L. Thomas
(MOS Observer)Shift: ☐ Day
☒ Night

A. Plant evolutions observed

- Steady state operations
- Shift turnover and shift briefing
- Placed 3C steam Generator Blowdown valve back-in-service tested satisfactorily.

B. Immediate safety problems

None

C. Questionable work practices

None observed

D. Areas for improvement

None

E. Professionalism, Summary of Shift, Comments

None

Completed By: L. L. Thomas
MOS Observer

Date: 06/11-12/88

Reviewed By: [Signature]
Operations Superintendent - Nuclear

Date: 6/13/88

Management
Review By:[Signature] 6/13/88 [Signature] 6/13/88
SVP VP Date Date
06/11-12/88

To: Operations Superintendent - Nuclear

Date: 06/11-12/88

From: Andrew P. Drake
(MOS Observer)Shift: ☐ Day
☒ Night

A. Plant evolutions observed

- ° Units 3 and 4, 100% power
- ° Normal operations

B. Immediate safety problems

None observed

C. Questionable work practices

None observed

D. Areas for improvement

No comments

E. Professionalism, Summary of Shift, Comments

Nice quiet shifts.

Completed By: Andrew P. Drake
MOS Observer

Date: 06/10-11/88

Reviewed By: [Signature]
Operations Superintendent - Nuclear

Date: 6/13/88

Management
Review By:[Signature] 6/13/88 [Signature] 6/13/88
VP Date

VP Date

25

26

27
28
29
30



31

32

33

34

35



36

37



Date 06/11/88

Shift Report

Shift _____ Day _____

Shift Management

PSN Wogan APSN Singer NWE Vetromile

A. Questionable Work Practices/Actions Taken/Recommendations

None

B. Areas for Improvement/Recommendations/Actions Taken

Regulation and compliance group response to operability of RHR/PASS valves on NCR 88-0065 was less than satisfactory on 6/10/88. We recommend a closer working relationship concerning safety related equipment, Tech. Spec. items and operability concerns. It seems like Engineering Group, Licensing Group and Operations speak a different language when the words "operability concern" are spoken.

C. Good Practices/Professionalism Observed

Normal

Reviewed By Ali P. Ali Date 6/13/88 Actions Completed _____ Date _____

21
22
23
24

25
26
27
28



29

30

31

32

33

34

35

36

37

38

39

40

41

42



43

44

45

46

47

48

49

50

51



Date 06/11/88

Shift Report

Shift _____ Peak _____

Shift Management

PSN Schimkus APSN Murphy NWE Spence

A. Questionable Work Practices/Actions Taken/Recommendations

None

B. Areas for Improvement/Recommendations/Actions Taken

None

C. Good Practices/Professionalism Observed

A totally dedicated effort was observed by the PSN on two pieces of major plant equipment. Thanks to the Maintenance Superintendent and his staff, 3A Condensate pump was returned to service following problems with establishing proper seal water pressure. Also Unit 3 Containment Boundary Valve CV-3-6275C (3C Steam Generator Blowdown isolation) was disassembled to prove no problem existed internally to cause valve seat binding. Maintenance did discover a discrepancy in valve shaft length which is the probable cause of over driving valve into seats upon closure. Operations appreciates your support.

Reviewed By J. L. Pinner Date 6/13/88 Actions Completed _____ Date _____

Date 06/12/88

Shift Report

Shift Mid

Shift Management

PSN Jones APSN Haley NWE

A. Questionable Work Practices/Actions Taken/Recommendations

None

B. Areas for Improvement/Recommendations/Actions Taken

None

C. Good Practices/Professionalism Observed

Reviewed By *[Signature]* Date *6/12/88* Actions Completed Date

To: Operations Superintendent - Nuclear

Date: 06/12/88

From: Paul Geddes
(MOS Observer)Shift: ☒ Day
☐ Night

A. Plant evolutions observed

- Both Units, 100% power
- 2 shift meetings
- Plant tour

B. Immediate safety problems

None

C. Questionable work practices

None

D. Areas for improvement

None

E. Professionalism, Summary of Shift, Comments

Uneventful shift

Completed By: Paul Geddes
MOS Observer

Date: 06/12/88

Reviewed By: P. W. Polace
Operations Superintendent - Nuclear

Date: 6/13/88

Management
Review By:P. Geddes 6/12/88 VS 6/13/88
PM-N Date SVP Date VP 06/12/88



To: Operations Superintendent - Nuclear

Date: 06/12-13/88

From: L. L. Thomas
(MOS Observer)Shift: ☐ Day
☒ Night

A. Plant evolutions observed

- Shift briefings and turnover
- Steady state operations
- 4-OSP-059.2 Intermediate Range Nuclear Instrumentation Analog channel operational test

B. Immediate safety problems

None

C. Questionable work practices

None

D. Areas for improvement

None

E. Professionalism, Summary of Shift, Comments

Good immediate action by midshift NWE on decreasing instrument air pressure (T-3 relief valve lifted).

Completed By: L. L. Thomas
MOS Observer

Date: 06/12-13/88

Reviewed By: [Signature]
Operations Superintendent - Nuclear

Date: 6/13/88

Management
Review By:[Signature] 16/13/88 [Signature] 16/13/88
VP Date

To: Operations Superintendent - Nuclear

Date: 06/12-13/88

From: Andrew P. Drake
(MOS Observer)Shift: ☐ Day
☒ Night

A. Plant evolutions observed

- Units 3 and 4, 100% power
- Normal operations
- Intermediate Range Channel Periodics on both units
- End of peak shift briefing
- Peak to mid shift turnover
- Mid shift briefing

B. Immediate safety problems

None observed

C. Questionable work practices

None observed

[illegible]

42

D. Areas for improvement

1. Plant Work Orders (PWO's) are still being cancelled without adequate checks and/or work being performed. PWO's should only be cancelled by the Originators immediate supervisor and only after consulting with the originator. If the originator does not agree with cancellation the PWO should be left active and additional measures looked into (i.e., engineering evaluation, monitoring equipment trends, etc.)
2. The entrance gates in the Control Room (particularly the one by the Nuclear Watch Engineer's office) should be removed. They (one or more) are always broken. The idea of restricting access to the control Room is good, however, these gates are not suitable for this control function.
3. Training needs to state the correct basis for the "Hi Flow" trip in the new Control Room Heating Ventilation and Air Conditioning system recently turned over to operations. The operators have heard two reasons 1) Hi flow would suck the filters out of position, 2) Hi flow will decrease the Iodine removal capability of the filters. Both sound reasonable. Which, if either, is correct?
4. Plant Engineering needs to look at the daily (sometimes twice a day) fill of accumulators on Units 3 and 4. The Safety Injection pumps are started and run for only about 1 minute (enough to fill the accumulators to clear the low level alarms) and then shutdown. This would mean a pump could experience more than 100 start/stop cycles with an average run time of about one minute. a) What effect is this going to have on the pump's reliability? b) What plans are being made to permanently stop the accumulator leaks so this evolution is not a daily occurrence?

E. Professionalism, Summary of Shift, Comments

1. These last seven days I have observed more cooperation and team work between Operations, Mechanical Maintenance, Instrumentation and Control, Chemistry, Health Physics and other personnel than on any of my earlier trips. While breakdowns in communications still occur, I have observed several instances where people are trying to correct and prevent additional cases.

Completed By: Andrew P. Drake
MOS ObserverDate: 06/12-13/88Reviewed By: S. W. Pearce
Operations Superintendent - NuclearDate: 6/13/88Management
Review By:P. L. L. 16/13/88 VP 16/13/88
PM-N Date SVP Date VP Date
06/12-13/88

Shift Report

Date 06/12/88

Shift _____ Day _____

Shift Management

SN Wogan APSN Singer NWE Vetromile

A. Questionable Work Practices/Actions Taken/Recommendations

None

B. Areas for Improvement/Recommendations/Actions Taken

None

C. Good Practices/Professionalism Observed

Maintenance support and Technical support on Saturday 6/11/88 was good and accomplished everything they were tasked with i.e., blowdown valve Unit 3 and gas leakage in Auxilliary Building.

Reviewed By [Signature] Date 6/12/88 Actions Completed _____ Date _____

11

12

13



14

15

16

17

18

19

20

21



22



Date 06/12/88

Shift Report

Shift Peak

Shift Management

PSN Schimkus APSN Murphy NWE Spence

A. Questionable Work Practices/Actions Taken/Recommendations

None

B. Areas for Improvement/Recommendations/Actions Taken

1. PSN (Schimkus) is offering an apology for a shift report on 6/6/88 concerning Nuclear Job Planning System and inability to contact individuals necessary to ensure proper operation of the system on weekends, holidays and backshifts. The report had validity, however the corporate NJPS system planners were not the problem. After receiving some feedback I did some research and found that our corporate NJPS people have more than adequately supplied phone numbers and 24 hour service for trouble and breakdowns. The root cause of my problem points to the inability to obtain the "help" phone number directly from the computer terminal screen when both of my terminals become locked up, and no other terminals are available on weekends, holidays, and backshifts. Other problems discovered on-site were:

- A. Turkey Point Nuclear has no appointed duty call person for NJPS and there is no directive to have the PTN NJPS Coordinator supply this, with beeper responsibilities.
- B. The PSN NJPS has erroneous or outdated information, "Tape Stuck" to the terminal which indicates a phone number to call for problems.
- C. The PSN Duty Call Supervisor book has an outdated sheet with erroneous phone numbers and area codes for contact of NJPS individuals at the General Office. Note: A new letter dated 5/06/88 was sent to the plant but didn't get entered in our Duty Call Book.

I have submitted an interoffice memo to the Operations Supervisor and it is attached to this report. It offers recommendations to alleviate some of the confusion.

My apologies to the corporate NJPS personnel as this was in in-plant problem. (This is additional information for CTRAC item 88-1216.)

2. The plant 125 volt D.C. Bus's only have one method to detect D.C. grounds. An alarm annunciates showing a D.C. bus ground. The following actions are to utilize ONOP-9608.1 and open any breaker which can cause the ground while not opening breakers which can cause unit trip. We have approximately 50 - 60 loads on each bus. We need Engineering to supply a method to sense individual grounds on a single bus without opening breakers until the ground disappears. Actions: Submit R.E.A. to incorporate a fix or plant change.

Reviewed By [Signature] Date 6/12/88 Actions Completed Date

Date

6/12/88

Shift Report

Page

2

Continuation Page

C. Good Practices/Professionalism Observed

Observed a good pre-shift meeting where I&C Supervisor requested assistance from NWE to troubleshoot a possible problem with inadequate intake screen spray water pressure. The I&C Supervisor did this on his own, following the ANPO on shift raising concern about the problem. This is what I consider good communications.

2000



22

2

2



2



22

Shift Report

Date

6/13/88

Shift

Mid

Shift Management

N

Jones

APSN

Haley

NWE

A. Questionable Work Practices/Actions Taken/Recommendations

None

B. Areas for Improvement/Recommendations/Actions Taken

Provision should be made to have sufficient Hagan Modules set up to replace any that fail within 24 hours of failure. We have had a failed module since steam generator level and protection periodic was started on 6/09/88, Thursday. This has left us in a precarious position over the weekend with one channel of protection in the tripped mode.

C. Good Practices/Professionalism Observed

Reviewed By [Signature] Date 6/13/88 Actions Completed _____ Date _____

23

