

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8908010109 DOC. DATE: 89/07/19 NOTARIZED: NO DOCKET #  
 FACIL: 50-251 Turkey Point Plant, Unit 4, Florida Power and Light c 05000251  
 AUTH. NAME AUTHOR AFFILIATION  
 WOODY, C.O. Florida Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 EBNETER, S.D. Region 2, Ofc of the Director

SUBJECT: Documents util 890718 request & justification for  
 discretionary enforcement re intake cooling water sys.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2  
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

## NOTES:

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	PD2-2 PD	1	1	EDISON, G	1	1
INTERNAL:	AEOD	1	1	AEOD/DEIIB	1	1
	AEOD/TPAD	1	1	DEDRO	1	1
	NRR SHANKMAN, S	1	1	NRR/DEST DIR	1	1
	NRR/DLPQ/PEB	1	1	NRR/DOEA DIR 11	1	1
	NRR/DREP/EPB 10	1	1	NRR/DREP/RPB 10	2	2
	NRR/PMAS/ILRB12	1	1	NUDOCS-ABSTRACT	1	1
	OE LIEBERMAN, J	1	1	OGC/HDS2	1	1
	<del>REG FILE</del> 02	1	1	RES MORISSEAU, D	1	1
	RGN2 FILE 01	1	1			
EXTERNAL:	LPDR	1	1	NRC PDR	1	1
	NSIC	1	1			

## NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR. 23 ENCL 23

R  
I  
D  
S  
/  
A  
D  
D  
S  
/  
A  
D  
D  
S

*Handwritten signature/initials*





8/15  
JUL 25 5:27

July 19, 1989  
L-89-266

Mr. Stewart D. Ebnetter  
Regional Administrator, Region II  
U.S. Nuclear Regulatory Commission  
101 Marietta St., N.W., Suite 2900  
Atlanta, Georgia 30323

Dear Mr. Ebnetter

Re: Turkey Point Unit 4  
Docket No. 50-251  
Intake Cooling Water System  
Request for Discretionary Enforcement

On July 18, 1989, during discussions with the NRC Region II and Headquarters Staffs, Florida Power & Light Company (FPL) requested NRC approval to isolate the 4A intake cooling water (ICW) header to allow cleaning of the 4A ICW basket strainer. The NRC subsequently approved discretionary enforcement for a period of time not to exceed one hour. The NRC requested that FPL keep the Turkey Point NRC Resident Inspector informed of the plant status during backwash of the 4A strainer. The purpose of this letter is to document FPL'S request and the justification for the discretionary enforcement, as well as to identify the circumstances which led to the discretionary enforcement.

At 2:25 PM on July 16, 1989, with Unit 4 in Mode 1, the 4B ICW header was declared inoperable due to low flow conditions. Technical Specification 3.4.5.b allows the unit to remain at power for 24 hours with one ICW header out of service before placing the unit in hot standby, and further allows the unit to remain in hot standby for 48 hours before going to cold shutdown. Unit 4 shutdown was initiated at 3:25 AM on July 17, 1989 and the unit came off line at 5:52 AM. The unit entered Mode 4 at 12:30 AM on July 18, 1989. Troubleshooting of the ICW System indicated that the disk for the 4-50-308 valve may be separated from the upper shaft.

Examination and repair of the 4-50-308 valve requires isolation of the 4B ICW header. Although no degraded flow conditions were indicated for the 4A ICW header, to ensure the maximum flow capability, FPL determined that backwash of the 4A ICW strainer was prudent. However, with the 4B ICW header at reduced flow (approximately 8200 gpm) and therefore, technically inoperable, NRC approval was required to isolate the 4A ICW header and backwash the strainer.

8908010109 890719  
PDR ADOCK 05000251  
P PDC

71

U. S. Nuclear Regulatory Commission  
L-89-266  
Page two

At approximately Noon on July 18, 1989, FPL contacted the NRC Senior Resident Inspector to discuss the situation with him and about 3:30 PM FPL contacted NRC Region II to request approval for the proposed action.

FPL had determined that the proposed action was justified based on:

1. the short duration (less than one hour) that the 4A ICW header would be isolated with the 4B header in a degraded flow condition, and
2. an engineering calculation that indicated that the 4B ICW header flow was adequate to remove the existing operational component cooling water heat loads, and
3. an engineering calculation that indicated sufficient time to restore flow through the 4A ICW header in the event that flow through the 4B ICW header was instantaneously lost while cleaning the 4A strainer, such that the limiting components in the component cooling water system would not be affected, and
4. the stationing of operators to immediately restore flow in the 4A ICW header in the unlikely event of loss of flow in the 4B ICW header.

This justification was reviewed by the Turkey Point Plant Nuclear Safety Committee.

FPL appreciates the prompt consideration given by the NRC Residents and the Region II and Headquarters Staffs in this matter.

Very truly yours,



C.O. Woody  
Acting Senior Vice President - Nuclear

COW/PLP/vmg

cc: Document Control Desk, USNRC  
Senior Resident Inspector, USNRC Turkey Point Plant

