

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8910240294 DOC. DATE: 89/10/19 NOTARIZED: NO DOCKET #
 FACIL: 50-251 Turkey Point Plant, Unit 4, Florida Power and Light Co. 05000251
 AUTH. NAME: LYONS, E. AUTHORITY AFFILIATION: Florida Power & Light Co.
 HARRIS, K.N. Florida Power & Light Co.
 RECIP. NAME: RECIPIENT AFFILIATION

SUBJECT: LER 89-003-01: on 890505, reactor trip while performing SG
 GP Set III channel test due to inadequate admin controls.
 W/8 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 4
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1	PD2-2 PD	1 1
	EDISON, G	1 1		
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	ACRS WYLIE	1 1	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	DEDRO	1 1	NRR/DEST/ESB 8D	1 1
	NRR/DEST/ICSB 7	1 1	NRR/DEST/MEB 9H	1 1
	NRR/DEST/MTB 9H	1 1	NRR/DEST/PSB 8D	1 1
	NRR/DEST/RSB 8E	1 1	NRR/DEST/SGB 8D	1 1
	NRR/DLPQ/HFB 10	1 1	NRR/DLPQ/PEB 10	1 1
	NRR/DOEA/EAB 11	1 1	NRR/DREP/RPB 10	2 2
	NUDOCS-ABSTRACT	1 1	REG FILE 02	1 1
	RES/DSIR/EIB	1 1	RGN2 FILE 01	1 1
EXTERNAL:	EG&G WILLIAMS, S	4 4	L ST LOBBY WARD	1 1
	LPDR	1 1	NRC PDR	1 1
	NSIC MAYS, G	1 1	NSIC MURPHY, G.A	1 1
	NUDOCS FULL TXT	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 38 ENCL 38



LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Turkey Point Unit 4										DOCKET NUMBER (2) 0 5 0 0 0 2 5 1										PAGE (3) 1 OF 0 3																																																						
TITLE (4) Reactor Trip While Performing Steam Generator Protection Set III Channel Test Due to Inadequate Administrative Controls																																																																										
EVENT DATE (5)									LER NUMBER (6)									REPORT DATE (7)									OTHER FACILITIES INVOLVED (8)																																															
MONTH			DAY			YEAR			YEAR			SEQUENTIAL NUMBER			REVISION NUMBER			MONTH			DAY			YEAR			FACILITY NAMES N/A												DOCKET NUMBER(S) 0 5 0 0 0																																			
0			5			0			5			8			9			8			9			-			0			0			3			-			0			1			1			0			1			9			8			9			0 5 0 0 0											
OPERATING MODE (9) 3									THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																																																																	
POWER LEVEL (10) 0 0 0									20.402(b)									20.405(c)									<input checked="" type="checkbox"/> 50.73(a)(2)(iv)									73.71(b)																																						
									20.405(a)(1)(i)									50.38(c)(1)									50.73(a)(2)(v)									73.71(c)																																						
									20.405(a)(1)(ii)									50.38(c)(2)									50.73(a)(2)(vi)									OTHER (Specify in Abstract below and in Text, NRC Form 366A)																																						
									20.405(a)(1)(iii)									50.73(a)(2)(i)									50.73(a)(2)(vii)(A)																																															
									20.405(a)(1)(iv)									50.73(a)(2)(ii)									50.73(a)(2)(vii)(B)																																															
									20.405(a)(1)(v)									50.73(a)(2)(iii)									50.73(a)(2)(ix)																																															
LICENSEE CONTACT FOR THIS LER (12)																																																																										
NAME Ed Lyons - Regulation and Compliance Engineer																				TELEPHONE NUMBER AREA CODE 3 0 5 2 4 6 1 6 5 9 0																																																						
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																																																																										
CAUSE			SYSTEM			COMPONENT			MANUFACTURER			REPORTABLE TO NPDOS			CAUSE			SYSTEM			COMPONENT			MANUFACTURER			REPORTABLE TO NPDOS																																															
SUPPLEMENTAL REPORT EXPECTED (14)																				EXPECTED SUBMISSION DATE (15)										MONTH DAY YEAR																																												
YES (If yes, complete EXPECTED SUBMISSION DATE)																				<input checked="" type="checkbox"/> NO																																																						

ABSTRACT (Limit to 1400 spaces, i.e. approximately fifteen single space typewritten lines) (16)

On May 5, 1989, at 0152, with Unit 4 in Hot Standby, and during rod drop testing, a Reactor Protection System (RPS) actuation occurred while performing procedure 4-SMI-071.4. The reactor tripped when Instrumentation and Control personnel (non-licensed utility personnel) placed bistable BS-4-446-1 in the Test position in accordance with procedure 4-SMI-071.4. This simulated a reactor power greater than 10%, enabling the low power permissive's reactor trips. An investigation determined that the reactor trip logic was completed by a turbine trip signal generated by an indication of closed turbine stop valves. Although the turbine stop valves (TSV) were physically verified to be in an open position, the RPS indicated they were closed due to the presence of lifted leads in the TSVs' position sensing circuitry. The Event Response Team has identified the physical root cause of this event as the presence of lifted leads in the turbine stop valves' position sensing circuitry due to inadequate administrative controls. A contributing factor was determined to be that the Sequence of Events General Alarm Summary did not identify the TSVs in the "Alarm Condition." The subject leads were landed. A new Administrative Site Procedure was developed to improve control of Process Sheets and Installation Lists. The General Alarm Summary software has been modified to prevent the loss of alarm status.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (8)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Turkey Point Unit 4	0 5 0 0 0 2 5 1	8 9	— 0 0 3	— 0 1	0 2	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

EVENT

On May 5, 1989, at 0152, with Unit 4 in Mode 3 (Hot Standby), a Reactor Protection System (RPS) (EIIS:JC) actuation occurred while performing procedure 4-SMI-071.4, "Steam Generator Protection Set III Analog Channel Test." At the time of occurrence, control banks C and D were withdrawn for rod drop testing in accordance with procedure 4-PMI-028.3, "RPI Hot Calibration, CRDM Stepping Test, and Rod Drop Test." The reactor tripped when Instrumentation and Control personnel (non-licensed utility personnel) placed bistable BS-4-446-1 in the Test position in accordance with step 6.2.3.1 of procedure 4-SMI-071.4. Placing BS-4-446-1 in the Test position simulated a reactor power greater than 10%. This enabled the RPS low power permissive's (P-7) reactor trips, providing one-half of the reactor trip logic. A subsequent investigation determined that the coincident half of the reactor trip logic was provided by a turbine trip signal due to the presence of lifted leads in the turbine stop valve position sensing circuitry. The lifted leads prevented the RPS from receiving a signal indicating the turbine stop valves (EIIS:TA) were open. The turbine stop valves were physically verified to be in an open position.

All systems functioned as designed, and Unit 4 remained stable in Mode 3 throughout the event. An Event Response Team was formed to determine the root cause(s) of the incident and establish the corrective actions to prevent recurrence.

CAUSE OF EVENT

The Event Response Team's investigation into the event has established the physical root cause of the event as the presence of lifted leads in the turbine stop valves' position sensing circuitry due to inadequate administrative controls. Through personnel interviews, FPL believes that work activities on the turbine stop valve limit switch terminal boxes was performed in the November, 1988, time frame. The procedure governing the work being performed on the turbine stop valve limit switches at the time the limit switch leads were lifted was Administrative Site Procedure ASP-2, "Preparation of Site Procedures/Process Sheets." This procedure did not require the lifting of these leads to be documented.

A contributing factor to the trip was that the Sequence of Events (SOE) General Alarm Summary did not identify the turbine stop valves in the "Alarm Condition." During a review of the Sequence of Events (SOE) General Alarm Summary, it was found that several SOE channels did not appear on the report. An analysis showed the deficiency existed in the General Alarm Summary software.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Turkey Point Unit 4	05000251	89	003	01	03	OF	03

TEXT (If more space is required, use additional NRC Form 366A's) (17)

ANALYSIS OF EVENT

A post-trip review was conducted to assess the proper operation of safety-related equipment. The review established that no thermodynamic response to the trip occurred and that plant parameters responded as expected. Other than the automatic initiation of the reactor trip, there were no manual or automatic reactor protection system or engineered safety features actuations. Although the lifted leads prevented the RPS from receiving a true indication of the turbine stop valves position, the RPS was in the fail safe position indicating the turbine stop valves were closed. Based on the above, the health and safety of the public were not affected.

CORRECTIVE ACTIONS

- 1) The lifted leads for the turbine stop valves' position sensing circuitry were landed on May 5, 1989.
- 2) Although the lifted lead condition was identified in May 1989, a new Administrative Site Procedure was developed to improve control of Process Sheets and Installation Lists. This new procedure, ASP-34, "Preparation of Process Sheets and Installation Lists," was issued on January 23, 1989, and superseded that part of ASP-2 addressing Process Sheets. This procedure describes the requirements for the control and documentation of Backfit Construction work activities and is applicable to all Safety Classifications of work performed by Backfit Construction at Turkey Point Units 3 and 4.

Subsequent to the issuance of ASP-34, an enhancement was made to specify that Process Sheets or Installation Lists are required for maintenance work that is not directly implemented on a Plant Work Order (PWO) or in accordance with an approved ASP.

- 3) The General Alarm Summary software has been modified to prevent the loss of alarm status information.

ADDITIONAL INFORMATION

Similar occurrences: LER 250-89-004 describes a reactor trip due to a defective procedure during performance of OP 14004.1 (the old procedure including the Steam Generator Protection Set III Analog Channel Test), LER 251-88-010 delineates a reactor trip due to personnel error during the performance of OP 14004.1, and LER 250-86-030 describes a reactor trip and safety injection due to inadequate planning of post-maintenance testing associated with OP 14004.1.