

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8911220168 DOC. DATE: 89/11/16 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 AUTH. NAME AUTHOR AFFILIATION
 POWELL, D.R. Florida Power & Light Co.
 HARRIS, K.N. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 89-015-00: on 891019, charging pumps declared inoperable
 due to inadequate troubleshooting techniques.

W/8 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 4
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1	PD2-2 PD	1 1
	EDISON, G	1 1		
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	ACRS WYLIE	1 1	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	DEDRO	1 1	NRR/DEST/ESB 8D	1 1
	NRR/DEST/ICSB 7	1 1	NRR/DEST/MEB 9H	1 1
	NRR/DEST/MTB 9H	1 1	NRR/DEST/PSB 8D	1 1
	NRR/DEST/RSB 8E	1 1	NRR/DEST/SGB 8D	1 1
	NRR/DLPQ/HFB 10	1 1	NRR/DLPQ/PEB 10	1 1
	NRR/DOEA/EAB 11	1 1	NRR/DREP/RPB 10	2 2
	NUDOCS-ABSTRACT	1 1	REG FILE 02	1 1
	RES/DSIR/EIB	1 1	RGN2 FILE 01	1 1
EXTERNAL:	EG&G, WILLIAMS, S	4 4	L ST LOBBY WARD	1 1
	LPDR	1 1	NRC PDR	1 1
	NSIC MAYS, G	1 1	NSIC MURPHY, G.A	1 1
	NUDOCS FULL TXT	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 38 ENCL 38

AO-4



L-89-420
10 CFR 50.73

NOV 16 1989


U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Unit 3
Docket No. 50-250
Reportable Event: 89-15
Date of Event: October 19, 1989
Charging Pumps Declared Inoperable Due to
Inadequate Troubleshooting Techniques used
to Determine the Cause for Reduced Charging
Flow to the Reactor Coolant System

The attached Licensee Event Report is being submitted pursuant to the requirements of 10 CFR 50.73 to provide notification of the subject event.

Very truly yours,


K. N. Harris
Vice President
Turkey Point Plant Nuclear

KNH/DRP/DH/rat

Attachment

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

8911220168 891116
PDR ADOCK 05000250
S PDC

an FPL Group company

IE22
1/1

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Turkey Point Unit 3										DOCKET NUMBER (2) 0 5 0 0 0 2 5 0										PAGE (3) 1 OF 0 3																																													
TITLE (4) Charging Pumps Declared Inoperable Due To Inadequate Troubleshooting Techniques Used To Determine The Cause For Reduced Charging Flow To The Reactor Coolant System.																																																																	
EVENT DATE (5)									LER NUMBER (6)									REPORT DATE (7)									OTHER FACILITIES INVOLVED (8)																																						
MONTH			DAY			YEAR			YEAR			SEQUENTIAL NUMBER			REVISION NUMBER			MONTH			DAY			YEAR			FACILITY NAMES N/A												DOCKET NUMBER(S) 0 5 0 0 0																										
1			0			1			9			8			9			8			9			0			1			5			0			0			1			1			6			8			9			0 5 0 0 0											
OPERATING MODE (9) 1									THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more of the following) (11)																																																								
POWER LEVEL (10) 0 4 5									<input type="checkbox"/> 20.402(b)									<input type="checkbox"/> 20.406(e)									<input type="checkbox"/> 80.73(a)(2)(iv)									<input type="checkbox"/> 73.71(b)																													
									<input type="checkbox"/> 20.406(a)(1)(i)									<input type="checkbox"/> 80.36(c)(1)									<input type="checkbox"/> 80.73(a)(2)(v)									<input type="checkbox"/> 73.71(c)																													
									<input type="checkbox"/> 20.406(a)(1)(ii)									<input type="checkbox"/> 80.36(c)(2)									<input checked="" type="checkbox"/> 80.73(a)(2)(vi)									<input type="checkbox"/> OTHER (Specify in Abstract below and in Text NRC Form 366A)																													
									<input type="checkbox"/> 20.406(a)(1)(iii)									<input checked="" type="checkbox"/> 80.73(a)(2)(i)																																															
									<input type="checkbox"/> 20.406(a)(1)(iv)									<input type="checkbox"/> 80.73(a)(2)(ii)																																															
									<input type="checkbox"/> 20.406(a)(1)(v)									<input type="checkbox"/> 80.73(a)(2)(iii)																																															
LICENSEE CONTACT FOR THIS LER (12)																																																																	
NAME David R. Powell, Regulation and Compliance Supervisor																								AREA CODE 3 0 5						TELEPHONE NUMBER 2 4 6 - 6 5 5 9																																			
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																																																																	
CAUSE		SYSTEM		COMPONENT		MANUFACTURER		REPORTABLE TO NRC				CAUSE		SYSTEM		COMPONENT		MANUFACTURER		REPORTABLE TO NRC																																													
X		C		B P		U		0 5 5		Y																																																							
SUPPLEMENTAL REPORT EXPECTED (14)																																																																	
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)																								<input checked="" type="checkbox"/> NO						EXPECTED SUBMISSION DATE (15)																																			
																														MONTH DAY YEAR																																			

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On October 19, 1989, at 1030, with Unit 3 in Mode 1 at 45 percent power, all three charging pumps were declared out of service (OOS). An evaluation of reduced charging flow to the Reactor Coolant System (RCS) revealed that none of the pumps singularly could maintain proper pressurizer level with a 45 gpm letdown orifice in service. Only two charging pumps are required to be operable for unit operation. Technical Specification (TS) 3.6.d.1 allows 1 of 2 operable charging pumps to be OOS for 24 hours. Failure to meet TS 3.6.d.1 Limiting Condition for Operation (LCO) placed Unit 3 in TS 3.0.1 which requires the unit to be in hot standby within 7 hours. Inadequate troubleshooting techniques used to investigate the reduced charging pump flow condition led to the incorrect determination that the 3A and 3C charging pumps were inoperable. The 3B charging pump internal discharge valves and valve guides were found to be worn and the center suction valve guide was found to be "backed out." This allowed flow from the 3A and 3C charging pumps to be recirculated through the idle 3B charging pump. This also affected performance of the 3B charging pump. Upon isolation of the 3B charging pump for venting, charging flow increased. The 3A and 3C charging pumps were declared operable based on the ability to maintain pressurizer level with a 60 gpm orifice in service. At 1120, Unit 3 exited TS 3.0.1.

TEXT (If more space is required, use additional NRC Form 305A's) (17)

The cause for the TS 3.0.1 entry was inadequate troubleshooting techniques used to determine the cause for the reduced charging pump flow condition. Failure to isolate the 3B charging pump while troubleshooting the reduced charging pump

FACILITY NAME (1) Turkey Point Unit 3	DOCKET NUMBER (2) 0 5 0 0 0 2 5 0	LER NUMBER (6)			PAGE 3		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 9	0 1 5	0	0	0 3	OF 0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

flow condition led to the incorrect determination that the 3A and 3C charging pumps were inoperable.

The charging pumps at Turkey Point are of the positive displacement type. Inspection of the 3B charging pump revealed that the pump internal valves and valve guides on the discharge side of the pump were worn. Also, the center suction valve guide was found to be "backed out." This condition allowed flow from the 3A and 3C charging pumps to be recirculated through the idle 3B charging pump. This also affected performance of the 3B charging pump.

ANALYSIS OF THE EVENT

The basis for Technical Specification 3.6 is to ensure three flow paths for injection of borated water into the RCS. The flow paths are: from the Boric Acid Tanks through the Boric Acid Transfer Pumps to the suction of the charging pumps; from the Refueling Water Storage Tank (RWST) to the suction of the charging pumps; and from the RWST to the suction of the safety injection pumps.

With three charging pumps declared out of service, the normal and alternate boration flow paths to the RCS were not available. However, the safety injection pumps remained operable during this time, thus, providing a flow path from the RWST to the RCS for injection of borated water. Sufficient shutdown capability for the most severe anticipated cooldown transient (main steam line break), assuming the most reactive rod control cluster to be fully withdrawn, is achieved via the use of boron from the RWST through the safety injection system.

During the time Unit 3 was in TS 3.0.1, charging flow was never completely lost. The 3A and 3C charging pumps remained running, providing flow to the RCP seals and a minimum flow of approximately 20 gpm to the RCS.

CORRECTIVE ACTIONS

- 1) The three suction/discharge valves on the 3B charging pump were overhauled in accordance with procedure O-PMM-047.8. The 3B charging pump was satisfactorily tested and returned to service at 0510 on October 22, 1989.
- 2) FPL has obtained recommended torque values for the charging pump suction/discharge valve guides from the Union Pump Company. These values will be incorporated into procedure O-PMM-047.8 by December 8, 1989.
- 3) Off-Normal Operating Procedures 3/4-ONOP-047.1, "Loss of Charging Flow in Modes 1 Through 3," will be revised to contain guidance for troubleshooting reduced charging pump flow conditions. These procedure revisions will be completed by December 29, 1989.

ADDITIONAL INFORMATION

No similar Licensee Event Reports have been located.