

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8912260046 DOC. DATE: 89/12/18 NOTARIZED: NO DOCKET #
 FACIL: 50-251 Turkey Point Plant, Unit 4, Florida Power and Light Co 05000251
 AUTH. NAME AUTHOR AFFILIATION
 POWELL, D.R. Florida Power & Light Co.
 HARRIS, K.N. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 89-006-01: on 890713, degraded intake cooling water flow
 condition to CCW HXs & unit shutdown required by TS.
 W/8 1tr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 6
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	PD2-2 LA	1 1	PD2-2 PD	1 1
	EDISON, G	1 1		
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	ACRS WYLIE	1 1	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	DEDRO	1 1	NRR/DET/ECMB 9H	1 1
	NRR/DET/EMEB9H3	1 1	NRR/DET/ESGB 8D	1 1
	NRR/DLPQ/LHFB11	1 1	NRR/DLPQ/LPEB10	1 1
	NRR/DOEA/OEAB11	1 1	NRR/DREP/PRPB11	2 2
	NRR/DST/SELB 8D	1 1	NRR/DST/SICB 7E	1 1
	NRR/DST/SPLB8D1	1 1	NRR/DST/SRXB 8E	1 1
	NUDOCS-ABSTRACT	1 1	REG FILE 02	1 1
	RES/DSIR/EIB	1 1	RGN2 FILE 01	1 1
EXTERNAL:	EG&G WILLIAMS, S	4 4	L ST LOBBY WARD	1 1
	LPDR	1 1	NRC PDR	1 1
	NSIC MAYS, G	1 1	NSIC MURPHY, G.A	1 1
	NUDOCS FULL TXT	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTR 38 ENCL 38

AD-4



DEC 18 1985

L-89-454
10 CFR 50.73


U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Unit 4
Docket No. 50-251
Reportable Event: 89-06-01
Date of Event: July 13, 1989
Degraded Intake Cooling Water Flow Condition to Component
Cooling Water Heat Exchangers and Unit Shutdown Required
by Technical Specifications due to Valve Failure

The attached Licensee Event Report is being submitted pursuant to the requirements of 10 CFR 50.73 to provide supplemental information on the subject event.

Very truly yours,


K. N. Harris
Vice President
Turkey Point Plant Nuclear

KNH/DRP/DWH/rat

attachment

cc: Stewart D. Ebnetter, Regional Administrator,
Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

8912260046 891218
PDR ADOCK 05000251
S PDC





2
1

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Turkey Point Unit 4										DOCKET NUMBER (2) 0 5 0 0 0 2 1 5 1 1										PAGE (3) 1 OF 0 5																											
TITLE (4) Degraded Intake Cooling Water Flow Condition To Component Cooling Water Heat Exchangers and Unit Shutdown Required By Technical Specifications Due to Valve Failure																																															
EVENT DATE (5)						LER NUMBER (6)						REPORT DATE (7)						OTHER FACILITIES INVOLVED (8)																													
MONTH			DAY			YEAR			YEAR			SEQUENTIAL NUMBER			REVISION NUMBER			MONTH			DAY			YEAR			FACILITY NAMES						DOCKET NUMBER(S)														
0 7			1 3			8 9			8 9			- 0 0 6			- 0 1 1			2 1 8			8 9									0 5 0 0 0						0 5 0 0 0											
OPERATING MODE (9)						THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																																									
1						20.402(b)						20.406(e)						80.73(a)(2)(iv)						73.71(b)																							
POWER LEVEL (10)						20.406(a)(1)(i)						80.36(a)(1)						X 80.73(a)(2)(v)						73.71(c)																							
0 2 5						20.406(a)(1)(ii)						80.36(a)(2)						80.73(a)(2)(vi)						OTHER (Specify in Abstract below and in Text NRC Form 365A)																							
						20.406(a)(1)(iii)						X 80.73(a)(2)(i)						80.73(a)(2)(vii)(A)																													
						20.406(a)(1)(iv)						80.73(a)(2)(ii)						80.73(a)(2)(vii)(B)																													
						20.406(a)(1)(v)						80.73(a)(2)(iii)						80.73(a)(2)(i)																													
LICENSEE CONTACT FOR THIS LER (12)																																															
NAME																								TELEPHONE NUMBER																							
David R. Powell, Regulation and Compliance Supervisor																								3 0 5 2 1 4 6 1 - 6 1 5 1 5 1 9																							
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																																															
CAUSE			SYSTEM			COMPONENT			MANUFACTURER			REPORTABLE TO NPDs			CAUSE			SYSTEM			COMPONENT			MANUFACTURER			REPORTABLE TO NPDs																				
X			B, I			I, S, V			P, 3, 4, 0			N																																			
SUPPLEMENTAL REPORT EXPECTED (14)																																															
YES (If yes, complete EXPECTED SUBMISSION DATE)																								X NO						EXPECTED SUBMISSION DATE (15)						MONTH				DAY				YEAR			

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED DATE:
EXPIRES DATE:

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER 16				PAGE 3	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Turkey Point Unit 4	0 5 0 0 0 2 5 1	8 9	- 0 0 6	- 0 1	0 2	OF 0 5	

TEXT (If more space is required, use additional NRC Form 308A's) (17)

Description of the Event

At 1625 on July 13, 1989, with Unit 4 in Mode 1 at 25% power, the 4A Intake Cooling Water (ICW)/Component Cooling Water (CCW) basket strainer (EIIS system BI, component: BSKT) was taken out of service for cleaning. (See simplified drawing of the ICW system attached.) At 1635 the Nuclear Operator observed a degraded flow condition on the CCW heat exchangers (EIIS System: CC, component: HX) and immediately notified the Control Room operator. The Nuclear Operator was instructed to valve the 4A ICW/CCW basket strainer back in service. At 1640, ICW flow was restored to the CCW heat exchangers. The Operations personnel believed the source of reduced ICW flow to the CCW heat exchangers to be clogging of the 4B ICW/CCW basket strainer. Between 1725 and 2125 the 4B ICW/CCW basket strainer was out of service for cleaning. The basket strainer was found to be more clogged than normal.

At approximately 2200 on July 14, 1989 the onsite Technical Department was directed to perform an evaluation of the ICW degraded flow condition. At 0800, on July 15, 1989, the Technical Department system engineer notified Operations Department personnel that an analysis of the degraded ICW flow condition on July 13, 1989 revealed that the ICW flow to the CCW heat exchangers was below the design basis flow rate from 1625 to 1640 on July 13, 1989.

At 1824 on July 15, 1989, an attempt was made to valve out the 4A ICW/CCW basket strainer for cleaning when ICW flow to the CCW heat exchangers decreased. The strainer was returned to a normal alignment while ICW flow was maintained above 15,400 gpm. Since the 4B ICW/CCW basket strainer had previously been cleaned and showed a differential pressure decrease to approximately 1.0 psid, Operations personnel suspected the strainer to be clogged and the differential pressure gauge to be in error.

At 1425 on July 16, 1989, with Unit 4 in Mode 1 at 100% power, the 4B ICW/CCW basket strainer was taken out of service in accordance with Technical Specification 3.4.5.b.1 for cleaning and to inspect for obstructions. The inspection showed no significant blockage. Subsequent evaluation of the degraded ICW flow condition by the System Engineer indicated probable flow restriction in or around 4B ICW header isolation valve 4-50-308.

Due to the frequency of cleaning ICW/CCW basket strainers, a management decision was made not to continue operation with only one header of ICW operable. Therefore, at 0325 on July 17, 1989, a Unit 4 shutdown was initiated and at 0607 Unit 4 was placed in Mode 3 (hot standby).

Examination and repair of the 4-50-308 valve required isolation of the 4B ICW header. Although no degraded flow conditions were indicated for the 4A ICW/CCW basket strainer, to ensure the maximum flow capability, FPL determined that backwash of the 4A ICW/CCW basket strainer was prudent. However, with the 4B ICW header at reduced flow (approximately 8200 gpm) and therefore, technically inoperable, NRC approval was required to isolate the 4A ICW/CCW basket strainer.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPENDIX A
(EXCLUDED)

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Turkey Point Unit 4	0 5 0 0 0 2 5 1	89	— 0 0 6	— 0 1	0 3 of 0 5

TEXT (If more space is required, use additional NRC Form 305A's) (17)

On July 18, 1989, the NRC approved a discretionary enforcement for a period of time not to exceed one hour to perform the requested backwash of the 4A ICW/CCW basket strainer. This operation took place between 2000 and 2100 on July 18, 1989.

Valve 4-50-308 was replaced and the 4B ICW header was returned to service at 1900 on July 20, 1989. Technical Specification Action Statement time requirements associated with the 4B ICW header low flow condition were met.

Cause of the Event

The cause of the degraded ICW flow to the CCW heat exchangers was due to failure of 4B ICW header isolation valve 4-50-308. Upon disassembly, the valve disc was found to be in the partially opened position and separated from the valve stem. Two tapered pins, connecting the disc to the valve upper stem, failed in the threaded region. A metallurgical analysis performed by FPL Nuclear Services concluded that the mechanism of failure was fatigue. The fatigue failure was most likely caused by cyclic loading from oscillation of the valve disc when normally open, combined with the pins working loose.

Analysis of the Event

The minimum required total flow to the CCW heat exchangers during power operation was less than the design basis flow from 1625 to 1640 on July 13, 1989. During this time, the CCW heat exchanger outlet temperature reached a maximum recorded value of approximately 109 degrees F.

The limiting components in the CCW system from the perspective of operating CCW temperatures are the Reactor Coolant Pumps seals. Based on this limitation, the CCW heat exchanger outlet temperature may exceed 105 degrees F up to 125 degrees F for a maximum period of 2 hours. Since the CCW heat exchanger outlet temperature reached a maximum recorded value of approximately 109 degrees F during the 15 minutes of degraded ICW flow, it may be concluded that this condition had no significant affect on plant equipment.

The degraded ICW flow to the CCW heat exchangers occurred during the backwashing of the 4A ICW/CCW basket strainer. Within 5 minutes of recognizing the degraded ICW flow condition, total ICW flow to the CCW heat exchangers was restored to above 15,400 gpm. Had a Design Basis Accident occurred during this time, ICW flow to the CCW heat exchangers could have been restored in time to accommodate the heat loads generated by a Large Break Loss of Coolant Accident.

During the time the 4B ICW header was out of service to repair valve 4-50-308, ICW total flow to the CCW heat exchangers was maintained above that required to mitigate the consequences of a Design Basis Accident.

The installed valve is a Model XR-70 36" manual butterfly valve supplied by the Henry Pratt Company. The replacement valve is a Model R1A 36" manual butterfly valve supplied by the Henry Pratt Company. FPL Engineering has determined that the R1A valves have several design differences, including a centered instead of

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)										
		YEAR	SEQUENTIAL NUMBER				REVISION NUMBER		PAGE			
Turkey Point Unit 4	0 5 0 0 0 2 5 1	8 9	—	0	0	6	—	0	1	0	4	OF 0 5

TEXT (If more space is required, use additional NRC Form 308A's) (17)

an offset stem, which would result in different loads on the taper pins. Based on this and many years of service without taper pin failures, the Model R1A valves in the ICW system are not suspect of being subject to the fatigue failure experienced on the Model XR-70 valve. The Model R1A 36" manual butterfly valve is used in the Unit 3 ICW system. Three Model XR-70 36" manual butterfly valves remain in the Unit 4 ICW system.

Corrective Actions

- 1) Caution statements have been added to procedures 3/4-OP-019, "Intake Cooling Water System," for operators to ensure that total ICW flow to the CCW heat exchangers does not drop below 15,400 gpm while valving an ICW/CCW basket strainer out of service for backwashing.
- 2) While valve 4-50-308 was removed from the 4B ICW header, a "crawl through" inspection was conducted to ensure removal of any obstructions to the 4B ICW/CCW basket strainer.
- 3) Valve 4-50-308 was replaced. After ensuring valve integrity and operability, the 4B ICW header was returned to service.
- 4) A disc/stem tapered pin from the 4-50-308 valve was recovered from the 4B ICW header. A metallurgical analysis performed by FPL Nuclear Services concluded that the mechanism of failure was fatigue. The fatigue failure was most likely caused by cyclic loading from oscillation of the valve disc when normally open, combined with the pins working loose.
- 5) A valve throttling test will be performed on valves 4-50-307, 309 and 310. The test will determine whether or not a throttled valve position will stop the oscillations. Elimination of the oscillations is also expected to reduce the possibility of the taper pins loosening. This test should be performed by January 15, 1990.
- 6) If the valve throttling test is successful in reducing oscillations, FPL Nuclear Engineering will evaluate the effect on ICW system flow with the valves throttled. If acceptable, a Design Equivalent Engineering Package (DEEP) will be issued. This action should be complete by February 15, 1990.
- 7) FPL Nuclear Engineering is pursuing design details for modifying the Model XR-70 36" manual butterfly valves such that the taper pins would be prevented from working loose. (The same modification will be considered for Model XR-70 30" manual butterfly valves installed in the Units 3 and 4 ICW system.) FPL Nuclear Engineering will issue a schedule for this task by January 10, 1990.
- 8) FPL Nuclear Engineering will issue a test request to inspect the Model XR-70 30" manual butterfly valves installed in the Unit 3 ICW system during the 1990 refueling outage for evidence of loosened taper pins. This request will be issued by December 15, 1989. The need to inspect the Model XR-70 30" manual butterfly valves installed in the Unit 4 ICW system will be based on the results of the Unit 3 inspection.



c
k

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPENDIX A
EXHIBIT A

FACILITY NAME (11) Turkey Point Unit 4	DOCKET NUMBER 12 0 5 0 0 0 2 5 1 8 9 — 0 0 6 — 0 1 0 5 OF 0 5	LER NUMBER 16		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER

TEXT (If more space is required, use additional NRC Form 388A's) (17)

Additional Information

No similar Licensee Event Reports have been reported.



11