

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9005080186 DOC.DATE: 90/05/01 NOTARIZED: NO DOCKET #
 FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 AUTH.NAME AUTHOR AFFILIATION
 POWELL,D.R. Florida Power & Light Co.
 HARRIS,K.N. Florida Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 90-007-00:on 900408,automatic start of 3B CCW pump due
 to low CCW pump discharge header pressure.

W/9 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 4
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1		PD2-2 PD	1 1
	EDISON,G	1 1			
INTERNAL:	ACNW	2 2		AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1		AEOD/ROAB/DSP	2 2
	DEDRO	1 1		NRR/DET/ECMB 9H	1 1
	NRR/DET/EMEB9H3	1 1		NRR/DET/ESGB 8D	1 1
	NRR/DLPQ/LHFB11	1 1		NRR/DLPQ/LPEB10	1 1
	NRR/DOEA/OEAB11	1 1		NRR/DREP/PRPB11	2 2
	NRR/DST/SELB 8D	1 1		NRR/DST/SICB 7E	1 1
	NRR/DST/SPLB8D1	1 1		NRR/DST/SRXB 8E	1 1
	REG FILE 02	1 1		RES/DSIR/EIB	1 1
	RGN2 FILE 01	1 1			
EXTERNAL:	EG&G STUART,V.A	4 4		L ST LOBBY WARD	1 1
	LPDR	1 1		NRC PDR	1 1
	NSIC MAYS,G	1 1		NSIC MURPHY,G.A	1 1
	NUDOCS FULL TXT	1 1			

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 35 ENCL 35

A0-4



FPL

P.O. Box 14000, Juno Beach, FL 33408-0420

MAY 01 1990

L-90-158
10 CFR 50.73


U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Unit 3
Docket No. 50-250
Reportable Event: 90-07
Date of Event: April 8, 1990
Automatic Start of the 3B Component Cooling Water (CCW)
Pump Due to Low CCW Pump Discharge Header Pressure

The attached Licensee Event Report is being submitted pursuant to the requirements of 10 CFR 50.73 to provide notification of the subject event.

Very truly yours,


K. N. Harris
Vice President
Turkey Point Plant Nuclear

KNH/DRP/DWH/rat

attachment

cc: Stewart D. Ebnetter, Regional Administrator, Region II,
USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

9005080186 900501
PDR ADOCK 05000250
S PIC

an FPL Group company

TE22
11

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Turkey Point Unit 3										DOCKET NUMBER (2) 0 5 0 0 0 2 5 0 1										PAGE (3) OF 0 3	
TITLE (4) Automatic Start Of The 3B Component Cooling Water (CCW) Pump Due To Low CCW Pump Discharge Header Pressure																					
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)											
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES N/A						DOCKET NUMBER(S) 0 5 0 0 0						
0	4	08	9	0	0	0	0	7	0	0	0	5	0	1	9	0	0	5	0	0	0
OPERATING MODE (9) 5			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (13)																		
POWER LEVEL (10) 0 0 0			20.402(b)				20.406(a)				X 80.73(a)(2)(iv)				73.71(b)						
			20.406(a)(1)(i)				80.38(a)(1)				80.73(a)(2)(v)				73.71(c)						
			20.406(a)(1)(ii)				80.38(a)(2)				80.73(a)(2)(vi)				OTHER (Specify in Abstract below and in Text, NRC Form 355A)						
			20.406(a)(1)(iii)				80.73(a)(2)(i)				80.73(a)(2)(vii)(A)										
			20.406(a)(1)(iv)				80.73(a)(2)(ii)				80.73(a)(2)(vii)(B)										
			20.406(a)(1)(v)				80.73(a)(2)(iii)				80.73(a)(2)(viii)										
			20.406(a)(1)(vi)				80.73(a)(2)(iv)				80.73(a)(2)(ix)										
LICENSEE CONTACT FOR THIS LER (12)																					
NAME David R. Powell, Superintendent of Licensing										TELEPHONE NUMBER 3 0 5 2 4 6 1 6 5 5 9											
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																					
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS											
SUPPLEMENTAL REPORT EXPECTED (14)										EXPECTED SUBMISSION DATE (15)				MONTH	DAY	YEAR					
YES (If yes, complete EXPECTED SUBMISSION DATE)										X NO											
ABSTRACT Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines (16)																					

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (18)

At 0935, on April 8, 1990, with Unit 3 in Mode 5 (Cold Shutdown), the 3B Component Cooling Water (CCW) pump automatically started upon sensing a CCW pump discharge header pressure below the 60 psig setpoint. At the time of this event, the 3A CCW pump was supplying cooling water to the Train A and B CCW System loads. Upon closure of manual valve 3-787A (CCW pump suction header sectionalizing valve) in accordance with Operating Surveillance Procedure 3-OSP-030.7, "CCW Manual Valve Operability Test," the 16 inch Train B header return path to the 3A CCW pump suction was diverted through the CCW System surge tank and a 4 inch line to the 3A CCW pump suction. The 3A CCW pump attempted to supply a CCW System flow demand of approximately 9740 gpm with a suction flow of approximately 5000 gpm. The low CCW pump discharge header pressure condition was the result of inadequate procedural controls in procedure 3-OSP-030.7 for the evolution being performed. A potential CCW pump discharge header low pressure condition, upon closing valve 3-787A with the 3A CCW pump supplying the Train A and B CCW System loads, was not considered a probable occurrence when procedure 3-OSP-030.7 was developed. The Unit 3 CCW pumps remained operable and the 3A CCW pump continued to operate during this event. Changes have been initiated to 3/4-OSP-030.7.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Turkey Point Unit 3	0 5 0 0 0 2 5 0	9 0	—	0 0 7	—	0 0	0 2 OF 0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION OF THE EVENT

At 0935, on April 8, 1990, with Unit 3 in Mode 5 (Cold Shutdown), the 3B Component Cooling Water (CCW) pump (EIIS:CC, Component:P) automatically started upon sensing a CCW pump discharge header pressure below the 60 psig setpoint. The 3A CCW pump continued to operate during this event.

At the time of this event, the 3A CCW pump was supplying approximately 9740 gpm cooling water flow through a 16 inch pump discharge line to the Train A and B CCW System loads. Upon closure of manual valve 3-787A (CCW pump suction header sectionalizing valve) in accordance with Operating Surveillance Procedure 3-OSP-030.7, "CCW Manual Valve Operability Test," the 16 inch Train B header return path to the 3A CCW pump suction was diverted to the CCW System surge tank. The surge tank level increased above the 55 percent high level setpoint. The 4 inch line from the surge tank to the 3A CCW pump suction did not allow enough flow to pass to make up for the reduction in suction flow caused by closing valve 3-787A. The 3A CCW pump attempted to meet a CCW System load demand of approximately 9740 gpm with a suction flow of approximately 5000 gpm. The resulting dynamics of the CCW system caused the CCW pump discharge header pressure to drop below the 60 psig setpoint.

At 1028, the NRC Operations Center was notified of the above event in accordance with 10CFR50.72(b)(2)(ii). Technical Specification 3.4 classifies the CCW pumps as Engineered Safety Features (ESFs), therefore; this event is being reported as an automatic actuation of an ESF in accordance with 10CFR50.73(a)(2)(iv).

CAUSE OF THE EVENT

The low CCW pump discharge header pressure condition was the result of inadequate procedural controls in Operating Surveillance Procedure 3-OSP-030.7 for the evolution being performed. A potential CCW pump discharge header low flow or low pressure condition, upon closing valve 3-787A with the 3A CCW pump supplying the Train A and B CCW System loads, was not considered a probable occurrence when 3-OSP-030.7 was developed.

ANALYSIS OF THE EVENT

The Unit 3 CCW pumps remained operable and the 3A CCW pump continued to operate during this event. The reduced CCW pump discharge header pressure condition was not of sufficient duration to adversely affect performance of the 3B RHR pump or other CCW System loads. Upon automatic starting of the 3B CCW pump, the CCW pump discharge header pressure was restored to above the low pressure setpoint of 60 psig.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (11) Turkey Point Unit 3	DOCKET NUMBER (21) 0 5 0 0 0 2 5 0 9 0 - 0 0 7 - 0 0	LER NUMBER (61)			PAGE (31)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9 0	0 0 7	0 0	Q 3	OF	0 3

TEXT: If more space is required, use additional NRC Form 366A's (17)

CORRECTIVE ACTIONS

1. On-The-Spot-Changes (OTSCs) were generated against Operating Surveillance Procedures 3/4-OSP-030.7. These changes require verifying that two CCW pumps are in operation prior to manipulating manual valves which could result in a CCW pump discharge header low pressure condition.
2. CCW System configurations specified in Operating Procedures will be reviewed to determine their susceptibility for automatically starting a CCW pump due to a low pump discharge header pressure condition. This review will be completed by May 25, 1990. Procedure revisions will be initiated, if required.

ADDITIONAL INFORMATION

Similar Occurrences: LER 50-251/87-026, LER 50-251/87-012-01, LER 50-251/87-011, and LER 50-251/87-002 reported previous automatic starts of a CCW pump. However, none of these occurrences shared the same root cause as identified in this LER.

