

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9210280075 DOC. DATE: 92/10/19 NOTARIZED: NO DOCKET #  
 FACIL: 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251  
 AUTH. NAME AUTHOR AFFILIATION  
 PLUNKETT, T.F. Florida Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 EBNETER, S.D. Region 2 (Post 820201)

SUBJECT: Special rept: on 920918, overpressure mitigating sys actuation occurred due to increase in RCS pressure experienced as motor-operated valves approached fully closed position. Night order issued & inservice testing procedure revised.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: NRR RAGHAVAN, L

05000251/

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1	PD2-2 PD	1 1
	AULUCK, R	1 1		
INTERNAL:	ACNW	2 2	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	NRR/DET/EMEB 7E	1 1	NRR/DLPQ/LHFB10	1 1
	NRR/DLPQ/LPEB10	1 1	NRR/DOEA/OEAB	1 1
	NRR/DREP/PRPB11	2 2	NRR/DST/SELB 8D	1 1
	NRR/DST/SICB8H3	1 1	NRR/DST/SPLB8D1	1 1
	NRR/DST/SRXB 8E	1 1	REG FILE 02	1 1
	RES/DSIR/EIB	1 1	RGN2 FILE 01	1 1
EXTERNAL:	EG&G BRYCE, J.H	2 2	L ST LOBBY WARD	1 1
	NRC PDR	1 1	NSIC MURPHY, G.A	1 1
	NSIC POORE, W.	1 1	NUDOCS FULL TXT	1 1


NOTES: 1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK.  
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 30 ENCL 30

*IAH*





P.O. Box 029100, Miami, FL, 33102-9100

OCT 19 1992  
L-92-275  
10 CFR 50.36

Stewart D. Ebnetter  
Regional Administrator, Region II  
U.S. Nuclear Regulatory Commission  
101 Marietta St., N.W., Suite 2900  
Atlanta, GA 30323

Dear Mr. Ebnetter:

Re: Turkey Point Unit 4  
Docket No. 50-251  
Special Report - Overpressure  
Mitigating Systems - PORV Actuation

In accordance with Technical Specification 6.9.2, the attached Special Report is provided for your information.

Should there be any questions on this information, please contact us.

Very truly yours,

T. F. Plunkett  
Vice President  
Turkey Point Nuclear

Attachment

TFP/OIH


cc: Document Control Desk, USNRC, Washington, D.C.  
R. C. Butcher, Senior Resident Inspector, USNRC, Turkey Point  
Plant

270040

9210280075 921019  
PDR ADOCK 05000251  
S PDR

an FPL Group company

IF22  
11



## SPECIAL REPORT

### Purpose:

This Special Report is submitted in accordance with the requirements of Technical Specification (T.S.) 3.4.9.3, Action b.3, which requires the submission of a Special Report pursuant to T.S. 6.9.2 in the event either the Power Operated Relief Valves (PORVs) or a 2.20 square inch vent is used to mitigate a Reactor Coolant System (RCS) pressure transient.

### Event and Action Taken:

On September 19, 1992 at 12:55 a.m., the Turkey Point Unit 4, 4A Residual Heat Removal (RHR) pump was stopped to perform the required Inservice Testing (IST) for MOV-4-750 and MOV-4-751 prior to entering Mode 4, in accordance with Procedure 4-OSP-206.3, "Inservice Valve Testing Hot Standby to Cold Shutdown". At 1:03 a.m., actuation of the Overpressure Mitigating System (OMS) occurred due to an increase in RCS pressure experienced as MOV-4-750 and MOV-4-751 approached the fully closed position. The OMS system operated as designed, with PORV PCV-4-456 lifting at 415 psig. The PORV properly reseated at 350 psig.

### Root Cause:

Testing of MOV-4-750 and MOV-751 while the RCS was in a water solid condition in conjunction with a delay in stopping the charging pump, caused the RCS pressure increase and the subsequent actuation of the OMS.

### Corrective Actions:

The corrective actions which have been completed include:

1. A Night Order was issued to remind personnel of the importance of evaluating the care required for sensitive evolutions prior to performing the evolutions. This action was completed September 20, 1992.
2. Procedure 4-OSP-206.3, "Inservice Valve Testing Hot Standby to Cold Shutdown," was revised to prevent cycling of MOV-750 and/or MOV-751 while the RCS is in a water solid condition. This action was completed September 20, 1992.

