

FILE NUMBER
INCIDENT REPORT

DATE RECEIVED
3-23-77

NUMBER OF COPIES RECEIVED

(1 cy' ea encl rec'd)

ACKNOWLEDGED

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

ACRS 76 CYS ~~HOLDING~~/SENT

INTERNAL DISTRIBUTION

KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

NSIC:

CONTROL NUMBER

770820104

100-100

100-100

100-100
100-100
100-100

100-100

100-100

100-100

100-100

100-100

100-100

100-100


NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

March 14, 1977

REGULATORY DOCKET FILE COPY



Mr. James P. O'Reilly
Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

Licensee Event Reports, 76-43 and 76-44, are hereby submitted in the format designated in the Booklet 00E-SS-001 as revised December 8, 1975. These reports were not submitted within 30 days of the event, since the occurrence was not recognized as reportable at that time.

Very truly yours,


R.R. Schneider
Vice President -
Electric Production

MAS/mtm

Attachments

CERTIFIED - RETURN RECEIPT REQUEST

770870104

~~33884048~~

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	1	0	3									
7	8	9				14	15								25	26			30	31	32									

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE					REPORT DATE											
01	CON'T	-	-	L	L	0	5	0	-	0	2	2	0	1	1	1	6	7	6	0	3	1	4	7	7
7	8	57	58	59	60	61					68			69			74			75			80		

EVENT DESCRIPTION

02	One emergency vent loop out of service to repair observation doors. Surveillance																			80
03	performed on redundant vent system to demonstrate operability.																			80
04																				80
05																				80
06	LER 76-44																			80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	S	C	F	Z	Z	Z	Z	Z	Z	Z	9	9	9	9	N
7	8	9	10	11	12				17	43	44			47	48

CAUSE DESCRIPTION

03	Observation door found bent during routine inspection, made repairs while unit was																			80
09	on load.																			80
10																				80

FACILITY STATUS		% POWER		OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
11	E	0	7	4	NA				B	NA				
7	8	9	10	12	13			44	45	46			80	

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE				
12	Z	Z	NA				NA					
7	8	9	10	11			44	45				80

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION																
13	0	0	0	Z	NA															
7	8	9	11	12	13															

PERSONNEL INJURIES

NUMBER		DESCRIPTION																			
14	0	0	0	NA																	
7	8	9	11	12																	

CONSEQUENCES PROBABLE

15	NA																			80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																		
16	Z	NA																		
7	8	9	10																	

PUBLICITY

17	NA																			80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	Timely report not made since event was not recognized as reportable at the time.																			80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																				80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

RECEIVED DOCUMENT
PROCESSING UNIT

1977 MAR 23 PM 4 17

USNRC-REG. 1-

18 MAR 77 11: 23

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: Mr. James P. O'Reilly..

FROM: Niagara Mohawk Power Corp.
Syracuse, New York
R. R. Schneider

DATE OF DOCUMENT
2/11/77DATE RECEIVED
2/22/77

☒ LETTER
☒ ORIGINAL
☐ COPY

☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

One signed

DESCRIPTION

Ltr. trans the following:

PLANT NAME:

Nine Mile Point Unit No. 1

(1-P)

ENCLOSURE

Licensee Event Report (RO 50-220/77-02) on
1/14/77 concerning one main steam line high
flow sensor not being set to actuate as
required by tech specs.....

**ACKNOWLEDGED
DO NOT REMOVE**

(1-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION 2/23/77

RJL

☒ BRANCH CHIEF: Lear

☒ W/3 CYS FOR ACTION

☒ LIC. ASST.: Parrish

☒ W/ CYS

☒ ACRS 16 CYS HOLDING/SENT: (M.B. (2/23/77))

INTERNAL DISTRIBUTION

☒ REG FILE

☒ NRC PDR

☒ I & E (2)

☒ MIPC

☒ SCHROEDER/IPPOLITO

☒ HOUSTON

☒ NOVAK/CHECK

☒ GRIMES

☒ CASE

☒ BUTLER

☒ HANAUER

☒ TEDESCO/MACCARY

☒ EISENHUT

☒ BAER

☒ SHAO

☒ VOLLMER/BUNCH

☒ KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

☒ LPDR Oswego, N.Y.

☒ TIC:

☒ NSIC:

CONTROL NUMBER

1812

0 7 4

Figure 1. The effect of the concentration of the *Agrobacterium* suspension on the transformation efficiency of *Agrobacterium* strains.

100

[illegible]

0 4 9 2 0 0 0

5

$$\left(\begin{array}{c} \uparrow \\ \downarrow \end{array} \right) \quad \left(\begin{array}{c} \uparrow \\ \downarrow \end{array} \right)$$

6. " " " " "

11-11-68

— 2 —

• 6 2 3

24

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

February 11, 1977

Mr. James P. O'Reilly
Director
United States Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, PA. 19406




RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification, we hereby submit Licensee Event Report LER 77-02.

This report was completed in the format designated in the Licensee Event Report Instruction Booklet 00E-SS-001, dated October 1974, revised December 8, 1975.


Very truly yours,


R.R. Schneider
Vice President -
Electric Production

MAS/mtm

Enc.

Regulatory Docket File



1812



0121

LICENSEE EVENT: REPORT

CONTROL BLOCK: | | | | | | |

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE						EVENT TYPE	
0	1	N	Y	N	M	P	1			-					-		4	1	1	1	1		0	3							
7	8	9					14	15								25	26						31	32							

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER								EVENT DATE						REPORT DATE								
0	1	-	-			0	5	0	-	0	2	2	0	0	1	1	4	7	7		0	2	1	1	7	7
7	8	57	58	59	60	61							68	69					74	75					80	

EVENT DESCRIPTION

02	During routine surveillance, it was found that one main steam line high flow sensor	
7 8 9		
03	was not set to actuate within the tolerance band of 105 psid \pm 1 psid. Setting found	80
7 8 9		
04	at 95 psid. Set point was corrected to actuate at 105 psid as required by Technical	80
7 8 9		
05	Specifications. Found setting was in conservative direction.	80
7 8 9		
06		LER 77-02 80
7 8 9		
	PRIME	80

7 8 9 SYSTEM CODE CAUSE CODE COMPONENT CODE PRIME COMPONENT SUPPLIER COMPONENT MANUFACTURER VIOLATION

07 C D E I N S T R U N B 0 8 0 N

7 8 9 10 11 12 17 43 44 47 48

CAUSE DESCRIPTION

08	7	8	9	• Apparent set point drift in conservative direction.	80
09	7	8	9		80
10	7	8	9		80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	E	099	N/A	B	Report by technician				
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
12	Z	Z	N/A	N/A					

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	Z	N/A

PERSONNEL INJURIES

NUMBER				DESCRIPTION
14	0	0	0	N/A

~~OFX&XX~~ CONSEQUENCES

[illegible]

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
15	Z	N/A

PUBLICITY

17 | None

ADDITIONAL FACTORS

None

19

16 FEB 77 12: 27

USNRC-REG. 1-

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: J.P.O'REILLY

FROM: NIAGARA MOHAWK PWR CORP.
SYRACUSE, N.Y.
R.R. SCHNEIDERDATE OF DOCUMENT
1/19/77DATE RECEIVED
1/28/77☐ LETTER
☒ ORIGINAL
☐ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
1

DESCRIPTION

LTR. TRANS THE FOLLOWING.....

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: NINE MILE PT # 1

ENCLOSURE

LICENSEE EVENT REPORT FOR R.O.# 76-42, ON
12/2/76 CONCERNING REACTOR BUILDING INTEGRITY
DISRUPTING WHEN BOTH ATRKLOCK DOORS WERE
OPENED TOGETHER.....LICENSEE EVENT REPORT FOR R.O.# 77-01, ON
1/6/77 CONCERNING CHANGED ROD WORTH MINIMIZER
OPERABILITY BEING FROM 10% TO 20% POWER LEVEL(1 SIGNED CY. RECEIVED)
(3 PAGES)NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

SAB 2/1/77

BRANCH CHIEF:	LEAR
W/3 CYS FOR ACTION	
LIC. ASST.:	PARRISH
W/ CYS	
ACRS 16 CYS HOLDING SENT	

CATEGORY-B DOCUMENT
F/INFO ACRS

INTERNAL DISTRIBUTION

REG FILE	
NRC PDR	
I & E (2)	
MIPC	
SCHROEDER/IPPOLITO	
HOUSTON	
NOVAK/CHECK	
GRIMES	
CASE	
BUTLER	
HANAUER	
TEDESCO/MACCARY	
EISENHUT	
BAER	
SHAO	
VOLLMER/BUNCH	
KREGER/J. COLLINS	

EXTERNAL DISTRIBUTION

LPDR: OSWEGO, N.Y.	
TIC:	
NSIC:	

CONTROL NUMBER

1004

[illegible]

1 2 3

100

• 1000 •


Regulatory

File Cyd

NIAGARA MOHAWK POWER CORPORATION


NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202



January 19, 1977

Mr. James P. O'Reilly
Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406




RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1
Technical Specification 6.9, we hereby submit Licensee Event
Reports 76-42 and 77-01.

These reports were completed within the intent of the Licensee
Event Report Instruction Booklet 00E-SS-001, dated October 1974,
revised December 24, 1974.

Sincerely yours,


R.R. Schneider
Vice President -
Electric Production

mtm

Enc.

1004



LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE					EVENT TYPE				
01	N	Y	N	M	P	1			-				-		4	1	1	1	1	0	3												
7	8	9				14	15							25	26				30	31	32												
CATEGORY														REPORT TYPE		REPORT SOURCE		DOCKET NUMBER								EVENT DATE					REPORT DATE		
01	CON'T	M	I				L	L			0	5	0	-	0	2	2	0	1	2	2	2	7	6	0	1	1	8	7	7			
7	8						59	60			61							68	69					74	75					80			

EVENT DESCRIPTION

02	Reactor Building Integrity disrupted momentarily when both air lock doors were	80
03	opened together. There was no significant effect since a negative pressure	80
04	existed in the building, preventing any release of radioactive gases to the	80
05	atmosphere.	80
06	LER 76-42	80
PRIME		80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOLATION		
07	Z Z	D	Z	Z	Z	Z	Z	Z	Z	9	9	9	N	
7	8 9 10	11	12					17	43	44			47	48

CAUSE DESCRIPTION

08	Two doors were opened simultaneously in the Reactor Building Extension air lock	80
09	Standing Order NMPSO #12 was issued specifying control procedures to follow in	80
10	opening doors.	80

FACILITY STATUS		% POWER			OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		
11	E	0	9	8				A	Reported by on the job operator			
7	8	9	10	11	12	13	14	15	16	17	18	
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE				
12	Z	Z	N/A			N/A						
7	8	9	10	11	12	13	14	15	16	17	18	

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	3	0	0	0	Z N/A

PERSONNEL INJURIES

NUMBER			DESCRIPTION
14	0	0	N/A

7 8 9 11 12 80

~~000000~~ CONSEQUENCES Probable

15	No effect to public or personnel on job or plant operation.	80
----	---	----

LOSS OR DAMAGE TO FACILITY

			TYPE	DESCRIPTION
15	Z			N/A

PUBLICITY

17 | None

ADDITIONAL FACTORS

1a Interlock lights were being installed at the time of the event. These will replace .

19 _____

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME 01 N Y N M P 1	LICENSE NUMBER 15 - 25	LICENSE TYPE 4 1 1 1 1	EVENT TYPE 0 1
---	---	---	---

CATEGORY 01 CONT	REPORT TYPE M I	REPORT SOURCE L	DOCKET NUMBER 0 5 0 - 0 2 2 0	EVENT DATE 0 1 0 6 7 7	REPORT DATE 0 1 1 8 7 7
---	--	--	--	---	--

EVENT DESCRIPTION

02 Changed Rod worth minimizer operability from 10% to 20% power level. This report

03 is due to General Electric information previously supplied referencing the RWM

04 Operability was incorrect. This involved a set point change to 20%.

05 LER '77-01

05

SYSTEM CODE 07 Z Z	CAUSE CODE D	COMPONENT CODE Z Z Z Z Z Z	PRIME COMPONENT SUPPLIER Z	COMPONENT MANUFACTURER Z 9 9 9	VIOLATION N
---	---	---	---	---	--

CAUSE DESCRIPTION

08 Supplement 3 to NEDO-20360 specifies different RWM operability periods than in

09 affect. Operating Procedure OP-37 Rev. 4 and Technical Specification changes have

10 been prepared. No safety implications.

FACILITY STATUS 11 E	% POWER 0 9 8	OTHER STATUS	METHOD OF DISCOVERY D	DISCOVERY DESCRIPTION G.E. Notification
---	--	--------------	--	--

FORM OF ACTIVITY RELEASED 12 Z	CONTENT OF RELEASE Z	AMOUNT OF ACTIVITY N/A	LOCATION OF RELEASE N/A
---	---	---------------------------	----------------------------

PERSONNEL EXPOSURES

NUMBER 13 0 0 0	TYPE Z	DESCRIPTION N/A
--	---	--------------------

PERSONNEL INJURIES

NUMBER 14 0 0 0	DESCRIPTION N/A
--	--------------------

CONSEQUENCES PROBABLE

15 None

LOSS OR DAMAGE TO FACILITY

TYPE 16 Z	DESCRIPTION N/A
--	--------------------

PUBLICITY

17 N/A

ADDITIONAL FACTORS

18 None

19

24 JAN 77 2:36

USNRC-REG. 1-

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWKDATE: January 7, 1977SUBJECT: Reportable Occurrence No. 50- 220 77- 01/1P
(24 Hour Notification)The enclosed prompt Reportable Occurrence is being submitted
in accordance with Technical Specification Section 6.TO: James P. O'Reilly
Directorate of Regulatory Operations
Region I
631 Park Avenue
King of Prussia, PA. 19106FROM: Niagara Mohawk Power Corporation
Nine Mile Point - J.A. FitzPatrick Site

P.O. Box #32
Lycoming, New York 15093TO J.P. O'Reilly (R)
FROM T.E. LempageDocket No. 50- 220REFERENCE: License DPR- 63TO R.H. Schwind
FROM T.E. LempageReport No.: 50- 220 77- 01/1PReport Date: January 7, 1977Occurrence Date: January 6, 1977Facility: Nine Mile Point #1TO
FROM

Identification of Occurrence:

During a management review (SORC) of recently received information from the NSSS supplier, it was revealed that the RNM operability limits should be equal to or greater than 20% rather than the current Technical Specification value of 10% of rated.

Conditions Prior to Occurrence:

<input checked="" type="checkbox"/>	Steady State Power	<input type="checkbox"/>	Routine Shutdown
<input type="checkbox"/>	Hot Standby	<input type="checkbox"/>	Load Changes
<input type="checkbox"/>	Cold Shutdown	<input type="checkbox"/>	Other
<input type="checkbox"/>	Refueling Shutdown		
<input type="checkbox"/>	Routine Startup		

Description of the Occurrence:

SEE ATTACHMENT

Apparent Cause of the Occurrence:

<input type="checkbox"/>	Design	<input type="checkbox"/>	Procedure
<input type="checkbox"/>	Manufacture	<input type="checkbox"/>	Unusual Service Conditions
<input type="checkbox"/>	Installation/Const.	<input type="checkbox"/>	Component Failure
<input type="checkbox"/>	Operator	<input checked="" type="checkbox"/>	Other (Specify)
		<input type="checkbox"/>	Re-analysis

Analysis of Occurrence:

No threat ever existed to the general public due to the conservative operation at the plant. The set point for RHM operability has been set much higher than the required 10%. Additionally, an extra operator is on duty during startup thru approximately 30% of rated power level who would be available for monitoring the rod withdrawal sequence.

Corrective Action:

As has been indicated, the OP's have been changed, reviewed and approved. The Technical Specification change is in the process of being submitted for NRC review, approval and issuance.

Failure Data:

N/A

ATTACHMENT to 50-220/77-01/1P ..

Description of the Occurrence:

The General Electric Company notified the off-site fuel engineering group that the reload core analysis indicated that the RWM operability setpoint should be 28% to allow for the drop rod accident. NRC Licensing was notified and a Technical Specification change discussed. The plant was notified on the 29th of December, 1976 and immediate changes were made to Operating Procedures. It was during the review of these changes at Site Operations Review Committee Meeting that the question of reporting requirements was raised and the committee prudently directed an immediate call to Region I to inform them of the event and the discussion held with NRC Licensing (Washington).

50-220

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: Mr O'Reilly

FROM: Niagara Mohawk Pwr Corp
Syracuse, NY
R R SchneiderDATE OF DOCUMENT
1-5-77

DATE RECEIVED 1-14-77

☒ LETTER
☒ ORIGINAL
☐ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

one signed

DESCRIPTION

Ltr trans the following:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: Nine Mile Pt #1

ENCLOSURE

Licensee Event Report (RO#76-40) on 12-10-76
concerning failure of reactor water level
sensors to actuate within tech spec limits....Licensee Event Report (RO#76-41) on 12-10-76
concerning actuation of drywell pressure
sensors sooner than required by tech specs....NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION 1-14-77 ehf

BRANCH CHIEF:

W/3 CYS FOR ACTION

LIC. ASST.:

W/1 CYS

ACRS 16 CYS HOLDING/SENT

INTERNAL DISTRIBUTION

☒ REG FILE

NRC PDR

I & E (2)

MIPC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES

CASE

BUTLER

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/BUNCH

KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

LPDR: Oswego, NY

TIC:

NSIC:

CONTROL NUMBER

467

22
A.O.

DO NOT REPLY
ACKNOWLEDGED

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

Regulatory Docket File

January 5, 1977

Mr. James P. O'Reilly
Director of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406



RE: Docket No. 50-220

Dear Mr. O'Reilly:


In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Reports 76-40 and 76-41.

These reports were completed within the intent of the Licensee Event Report Instruction Booklet 00E-SS-001, dated October 1974, revised December 24, 1974. Due to the minimal significance category of these reports, no supplemental reports are included.

Very truly yours,



R.R. Schneider
Vice President
Electric Production



TJD/mtm

Enc.



LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

16

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME					LICENSE NUMBER					LICENSE TYPE					EVENT TYPE									
01	N	Y	N	M	P	1			-					-			4	1	1	1	1	0	3	
7	8	9				14	15									25	26					30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE					REPORT DATE											
01	CON'T	-	-	L	L	0	5	0	-	0	2	2	0	1	2	1	0	7	6	0	1	0	4	7	7
7	8	57	58	59	60	61							68	69						74	75				80

EVENT DESCRIPTION

02	During routine surveillance, it was discovered that 10-10-10 reactor water level	80
03	sensors RE-18A,B, & C did not actuate within the tolerance set point band of	80
04	$<127.1 \pm 2.6$ ". A was 121.5", B was 122.0" and C was 120.0". All were in the con-	80
05	servative direction.	80
06	LER 76-40	80
	PRIME	80

7 8 9 10 11 12 13 14 15 16 17 43 44 45 46 47 48

SYSTEM CODE CAUSE CODE COMPONENT CODE PRIME COMPONENT SUPPLIER COMPONENT MANUFACTURER VIOLATION

07 I B E I N S T R U N B 0 8 0 -

CAUSE DESCRIPTION

03	Apparent set point drift:	80
03	Barton Model #288	80
10	Serial Number 3468, 3470, and 3471	80

	FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
7 8	[E]	[0][9][1]		[b]	
9		10 12	13	44	46
	FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY		LOCATION OF RELEASE
7 8	[Z]	[Z]	N/A	N/A	
9		10 11	44	45	80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	3	0	0	0	Z N/A

PERSONNEL INJURIES

NUMBER				DESCRIPTION
1	4	0	0	N/A

7 8 9 11 12 80

~~XXXXXX~~ CONSEQUENCES PROBABLE

None

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
15	Z	N/A


PUBLICITY

17 | None

ADDITIONAL FACTORS

11a | None

19



LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME 01 N Y N M P 1										LICENSE NUMBER 1 5 0 0 2 2 0										LICENSE TYPE 4 1 1 1 1					EVENT TYPE 0 3	
CATEGORY 01 CON'T		- -		REPORT TYPE L		REPORT SOURCE L		DOCKET NUMBER 0 5 0 0 2 2 0					EVENT DATE 1 2 1 0 7 6					REPORT DATE 0 1 0 4 7 7								

EVENT DESCRIPTION

02	During routine surveillance testing on high drywell pressure, all four sensors actuated	80
03	sooner than the required $3.5 \pm .053$ psi set point. RE-04A was 3.4 psi, B was 3.3 psi,	80
04	C was 3.4 psi and D was 3.4 psi. All were in the conservative direction.	80
05		80
06	LER 76-41	80

SYSTEM CODE 07 I B		CAUSE CODE E		COMPONENT CODE I N S T R U				PRIME COMPONENT SUPPLIER N		COMPONENT MANUFACTURER B 0 8 0			VIOLATION -	
---	--	---	--	---	--	--	--	---	--	---	--	--	--	--

CAUSE DESCRIPTION

08	Apparent set point drift	80
09	Barton Model #289	80
10	Serial # 794, 795, 793, and 796	80

FACILITY STATUS 11 E		% POWER 0 9 0		OTHER STATUS		METHOD OF DISCOVERY b		DISCOVERY DESCRIPTION	
FORM OF ACTIVITY RELEASED 12 Z		CONTENT OF RELEASE Z		AMOUNT OF ACTIVITY N/A		LOCATION OF RELEASE N/A			

PERSONNEL EXPOSURES

13	NUMBER 0 0 0	TYPE Z	DESCRIPTION N/A	80
--	---	---	--------------------	----

PERSONNEL INJURIES

14	NUMBER 0 0 0	DESCRIPTION N/A	80
--	---	--------------------	----

CONSEQUENCES PROBABLE

15	None	80
--	------	----

LOSS OR DAMAGE TO FACILITY

16	TYPE Z	DESCRIPTION N/A	80
--	---	--------------------	----

PUBLICITY

17	None	80
--	------	----

ADDITIONAL FACTORS

18	None	80
--	------	----

19		80
--	--	----

USNRC-REG. 1--

11 JAN 77 12:00

50-220

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: James P. O'Reilly

FROM: Niagara Mohawk Power Corp.
Syracuse, N.Y. 13202
R.R. Schneider

DATE OF DOCUMENT

11-20-76

DATE RECEIVED

12-3-76

☒ LETTER
☒ ORIGINAL
☐ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

1 signed org.

DESCRIPTION Ltr, Trans the Following:

DO NOT REMOVE**ACKNOWLEDGED**

PLANT NAME: NINE MILE PT. UNIT #1

ENCLOSURE Licensee Event Report LER-76-39
occurring on 11-16-76 Reporting of con-
centrations in milk samples greater than
19 pCi/l. due to Chinese Weapons Testing
With Attachment...

(1 encl rec'd)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

JCM 12-6-76

<input checked="" type="checkbox"/> BRANCH CHIEF:	Lear
<input checked="" type="checkbox"/> W/3 CYS FOR ACTION	
<input checked="" type="checkbox"/> LIC. ASST.:	Parrish
<input checked="" type="checkbox"/> W/1 CYS	
<input checked="" type="checkbox"/> ACRS 16 CYS HOLDING/SENT	Cat-B on 12-6-76

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE	
<input checked="" type="checkbox"/> NRC PDR	
<input checked="" type="checkbox"/> I & E (2)	
<input checked="" type="checkbox"/> MIPC	
<input checked="" type="checkbox"/> SCHROEDER/IPPOLITO	
<input checked="" type="checkbox"/> HOUSTON	
<input checked="" type="checkbox"/> NOVAK/CHECK	
<input checked="" type="checkbox"/> GRIMES	
<input checked="" type="checkbox"/> CASE	
<input checked="" type="checkbox"/> BUTLER	
<input checked="" type="checkbox"/> HANAUER	
<input checked="" type="checkbox"/> TEDESCO/MACCARY	
<input checked="" type="checkbox"/> EISENHUT	
<input checked="" type="checkbox"/> BAER	
<input checked="" type="checkbox"/> SHAO	
<input checked="" type="checkbox"/> VOLLMER/BUNCH	
<input checked="" type="checkbox"/> KREGER/J. COLLINS	

EXTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> LPDR: Oswego, N.Y.	
<input checked="" type="checkbox"/> TIC:	
<input checked="" type="checkbox"/> NSIC:	

CONTROL NUMBER

T 12247
no 4

2
2
2
2

- . T I

8

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

Regulatory Docket File

November 20, 1976

Mr. James P. O'Reilly
Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406




RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Environmental Technical Specifications 5.6.3.1, we hereby submit Licensee Event Report 76-39.

This report was completed within the intent of the Licensee Event Report Instruction Booklet 00E-SS-001, dated October 1974, revised December 24, 1974.

Very truly yours,


R.R. Schneider
Vice President -
Electric Production

MH/mtm

Enc.



12247



1911

1912

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
0	1	N	Y	N	M	P	1					-					-			4	1	1	1	1	0	4
7	8	9					14	15										25		26				30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER								EVENT DATE						REPORT DATE							
0	1	-	-	T	L	0	5	0	-	0	2	2	0	1	1	1	6	7	6	1	1	2	0	7	6
7	8	57	58	59	60	61							88	69					74	75					80

EVENT DESCRIPTION

02 Informed by contractor that a milk sample contained a concentration of I-131 in
7 8 9 80

03 excess of 19 pCi/l. The sample contained concentration of 19.9 ± 0.4 . Section 5.6 .
7 8 9 80

04 Paragraph 5.6.3.1(b) of Appendix B requires reporting of concentrations in
7 8 9 80

05 individual milk samples greater than 19 pCi/l. Sample collected on 11/1/76.
7 8 9 80

06 LER 76-39
7 8 9 80

CAUSE DESCRIPTION

08	Concentrations are due to Chinese Weapons Testing that occurred prior to sampling.	80
09	(See attachment for substantiating information).	80
10		80

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																																																																																																																																																	
11		F		097			OTHER STATUS																		a		DISCOVERY DESCRIPTION																																																																																																																																																																																															
7		8		9		10			11			12			13			14			15			16			17			18			19			20			21			22			23			24			25			26			27			28			29			30			31			32			33			34			35			36			37			38			39			40			41			42			43			44			45			46			47			48			49			50			51			52			53			54			55			56			57			58			59			60			61			62			63			64			65			66			67			68			69			70			71			72			73			74			75			76			77			78			79			80		
7		8		9		10			11			12			13			14			15			16			17			18			19			20			21			22			23			24			25			26			27			28			29			30			31			32			33			34			35			36			37			38			39			40			41			42			43			44			45			46			47			48			49			50			51			52			53			54			55			56			57			58			59			60			61			62			63			64			65			66			67			68			69			70			71			72			73			74			75			76			77			78			79			80		
12		Z		Z			N/A																		N/A		LOCATION OF RELEASE																																																																																																																																																																																															
7		8		9		10			11			12			13			14			15			16			17			18			19			20			21			22			23			24			25			26			27			28			29			30			31			32			33			34			35			36			37			38			39			40			41			42			43			44			45			46			47			48			49			50			51			52			53			54			55			56			57			58			59			60			61			62			63			64			65			66			67			68			69			70			71			72			73			74			75			76			77			78			79			80		

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	Z	N/A

PERSONNEL INJURIES

NUMBER			DESCRIPTION
14	0	0	N/A

~~MAXX~~ CONSEQUENCES PROBABLE

1	5	None
7	8	9
		80

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
16	Z		N/A

PUBLICITY

17	None	
----	------	--


ADDITIONAL FACTORS

18	None	80
----	------	----

19
7 8 9 (315) 343 2110 Ext. 1310 80

NAME: M. Hedrick

PHONE: (315) 343-2110 Ext. 1310⁸⁰



ATTACHMENT TO LER 76-39

I. RELEASE DATA

TOTAL SITE HALOGEN AND PARTICULATE AIRBORNE ACTIVITY RELEASE DATA - Ci/sec

<u>DATE</u>	<u>Q NMP-1</u>	<u>DATE</u>	<u>Q JAF</u>	<u>Q JAF</u>
9/7/76	4.62 E-9	9/7/76	5.27 E-9	6.12 E-10
9/14/76	4.66 E-9	9/14/76	4.30 E-10	1.17 E-10
9/20/76	6.11 E-9	9/21/76	7.94 E-10	4.86 E-10
9/28/76	1.81 E-8	9/28/76	1.45 E-10	5.24 E-10
9/29/76	6.60 E-9	9/29/76	4.61 E-10	1.75 E-10
10/4/76	4.72 E-9	10/5/76	3.70 E-10	3.75 E-10
10/12/76	5.89 E-9	10/12/76	7.89 E-10	1.43 E-9
10/18/76	6.39 E-9	10/19/76	4.33 E-9	4.88 E-9
10/25/76	1.42 E-8	10/26/76	7.23 E-9	1.31 E-9
10/27/76	7.57 E-9	11/2/76	4.32 E-9	4.25 E-9
10/28/76	8.37 E-9			
11/1/76	1.10 E-8			

01 53 92101 65

-1 1010-0.1000

LICENSEE EVENT REPORT

CONTROL BLOCK: [] [] [] [] [] []
 1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE					EVENT TYPE							
0	1	N	Y	N	M	P	1			-					-			4	1	1	1	1	0	3
7	8	9					14	15								25	26					30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE						REPORT DATE										
0	1	-	-	L	L	0	5	0	-	0	2	2	0	1	0	2	5	7	6	0	3	1	4	7	7	
7	8	57	58	59	60	61							68	69						74	75					80

EVENT DESCRIPTION

02	No. 12 Feedwater Pump, one of two redundant pumps for the HPCI System, was taken out	80
03	of service for repair of sealwater strainer and small gear box leaks. No. 11	80
04	Feedwater Pump, the redundant pump, was operable and operating during maintenance.	80
05	on No. 12 pump.	80
06	LER 76-43	80
	PRIME	80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOLATION		
0	7	C	H	F	Z	Z	Z	Z	Z	Z	9	9	9	N
7	8	9	10	11	12				17	43	44		47	48

CAUSE DESCRIPTION

08	One of a redundant component was taken out of service to perform maintenance while	80
09	unit was on load.	80
10		80

11	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
FACILITY STATUS			% POWER			OTHER STATUS																		METHOD OF DISCOVERY			DISCOVERY DESCRIPTION																																															
E			078			NA																		C			NA																																															
FORM OF ACTIVITY RELEASED			CONTENT OF RELEASE			AMOUNT OF ACTIVITY																					LOCATION OF RELEASE																																															
Z			Z			NA																					NA																																															

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
13	0	0	0	NA

PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	NA

~~XXXXXX~~ CONSEQUENCES PROBABLE

[illegible]

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
16	Z		NA

PUBLICITY

17	NA	.	80
7	8	9	

ADDITIONAL FACTORS

13 Timely report not made since event was not recognized as reportable occurrence at the
7 8 9 80
time.
13

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: Mr. James P. O'Reilly

FROM: Niagara Mohawk Power Corp.
Syracuse, New York
R. R. Schneider

DATE OF DOCUMENT
11/5/76DATE RECEIVED
11/16/76

☒ LETTER
☐ ORIGINAL
☒ COPY

☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
No signed copy

DESCRIPTION

Ltr. trans the following:

ACKNOWLEDGED

DO NOT REMOVE

(1-P)

PLANT NAME:

Nine Mile Point Unit #1

ENCLOSURE

Licensee Event Report (RO 50-220/76-36) on 10/15/76 concerning one Lo-Lo-Reactor Water Level Switch (RE 18A) failing to provide a trip at the required 124, +2, -2.6 indicated inches.

(1-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

11/16/76

RJL

☒ BRANCH CHIEF: Lear

☐ W/3 CYS FOR ACTION

☒ LIC. ASST.: Parrish

☐ W/ CYS

☒ ACRS 16 CYS HOLDING/SENT TO *Car. B. (11/16/76)*

INTERNAL DISTRIBUTION

☒ REG FILE

☒ NRC PDR

☒ I & E (2)

☒ MIPC

☒ SCHROEDER/IPPOLITO

☒ HOUSTON

☒ NOVAK/CHECK

☒ GRIMES

☒ CASE

☒ BUTLER

☒ HANAUER

☒ TEDESCO/MACCARY

☒ EISENHUT

☒ BAER

☒ SHAO

☒ VOLLMER/BUNCH

☒ KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

☒ LPDR: Oswego, N. Y.

☒ TIC:

☒ NSIC:

CONTROL NUMBER

11663

CHURCHILL WOODS
EVONIST T...

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

Regulatory Docket File



November 5, 1976

Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1
Technical Specifications 6.9, we hereby submit Licensee Event
Report 76-36.

This report was completed within the intent of the Licensee
Event Report Instruction Booklet 00E-SS-001, dated October 1974,
revised December 24, 1974.


Very truly yours,

ORIGINAL SIGNED BY R.R. SCHNEIDER


R.R. Schneider
Vice President -
Electric Production

TJD/mtm

Enc.



11663



LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME							LICENSE NUMBER							LICENSE TYPE					EVENT TYPE				
01	N	Y	N	M	P	1			-					-		4	1	1	1	1	0	3	
7	8	9				14	15									25	26				30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE					REPORT DATE											
01	CON'T	-	-	L	L	0	5	0	-	0	2	2	0	1	0	1	5	7	6	1	1	0	5	7	6	
7	8	57	58	59	60	61							68	69						74	75					80

EVENT DESCRIPTION

02	During routine surveillance testing, one Lo-Lo-Lo Reactor Water Level Switch (RE-18A)	80
7 8 9		
03	failed to provide a trip at the required 124, +2, -2.6 indicated inches. It was	80
7 8 9		
04	found to trip at 118" and was reset at 126 inches. } All redundant components	80
7 8 9		
05	were operable.	80
7 8 9		
05	LER 76-36	80
7 8 9		
	PRME	80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE						COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
0	7	I	B	E	I	N	S	T	R	U	N	B	0	8	0	-	
7	8	9	10	11	12					17	43	44			47	48	

CAUSE DESCRIPTION

08	Apparent set point drift. The device was inspected and recalibrated	80
09		80
10		80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	E	095				b			
7	8	9	10	12	13	44	45	46	80
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
12	Z	Z		N/A			N/A		
7	8	9	10	11	44	45			80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	3	0	0	0	Z N/A

PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	N/A

02593E CONSEQUENCES PROBABLE

15 None - had the signal been required, redundant sensors would provide the desired action

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
13	Z		N/A

PUBLICITY

17	None
----	------

ADDITIONAL FACTORS

1a | None

19 _____

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: Mr. James P. O'Reilly

FROM: Niagara Mohawk Power Corp.
Syracuse, New York
R. R. Schneider

DATE OF DOCUMENT
10/25/76DATE RECEIVED
11/2/76

☒ LETTER
☒ ORIGINAL
☐ COPY

☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
One signed

DESCRIPTION

Ltr. trans the following:

DO NOT REMOVE**ACKNOWLEDGED**

(1-P)

PLANT NAME:

Nine Mile Point Unit 1

ENCLOSURE

Licensee Event Report (RO 50-220/76-37) on 10/19/76 concerning the July 1976 Monthly Chemical Proportional Composite being inadvertently discarded prior to performing chemical liquid waste analyses.

(1-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION 11/2/76

RJL

☒ BRANCH CHIEF: Lear

☒ W/3 CYS FOR ACTION

☒ LIC. ASST.: Parrish

☒ W/1 CYS

☒ ACRS 16 CYS HOLDING/SENT TO *Car. B. (11/2/76)*

INTERNAL DISTRIBUTION

☒ REG FILE

☒ NRC PDR

☒ I & E (2)

☒ MIPC

☒ SCHROEDER/IPPOLITO

☒ HOUSTON

☒ NOVAK/CHECK

☒ GRIMES

☒ CASE

☒ JUTNER

☒ HANAUER

☒ TENDISCO/MACCARY

☒ EISENHAUT

☒ PAIR

☒ SHAO

☒ VOLLMER/MUNCH

☒ KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

☒ PDR: Oswego, N.Y.

☒ TTC:

☒ NJIC:

CONTROL NUMBER

11109

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

October 25, 1976

Mr. James P. O'Reilly
Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406


RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Report 76-37.


This report was completed within the intent of the Licensee Event Report Instruction Booklet 00E-SS-001, dated October 1974, revised December 24, 1974. Due to the minimal significance category of this report, no supplemental report is included.

Very truly yours,


R.R. Schneider
Vice President -
Electric Production


TJD/mtm

Enc.



INRC PUBLIC DOCUMENT ROOM

11109



LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER												LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	1	0	4											
7	8	9				14	15								25	26				30	31	32										

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE					REPORT DATE										
01	CONT	-	T	L	0	5	0	-	0	2	2	0	1	0	1	9	7	6	1	0	2	5	7	6
7	8	57	58	59	60	61						68	69					74	75					80

EVENT DESCRIPTION

02	July 1976 Monthly Chemical Proportional Composite was inadvertently discarded																								80
03	prior to performing chemical liquid waste analyses, which are required per																								80
04	Appendix B, Table 2.3-2. The composite sample was discarded because it was not																								80
05	promptly labelled after preparation.																								80
06	LER 76-37																								80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER			VIOLATION		
07	Z	Z			Z	Z	Z	Z	Z	Z	--	Z	9	9	9	--
7	8	9	10	11	12					17	43	44			47	48

CAUSE DESCRIPTION

08	Technician did not label composite sample prior to being called away on another																								80
09	job, and it was poured out during routine lab clean-up. Commenced procedural																								80
10	review to clarify requirements for compositing.																								80

FACILITY STATUS		% POWER			OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION													
11	E	Z	Z	Z	N/A			Z	Management review of analyses														
7	8	9	10	11	12	13	44	45	46														

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY										LOCATION OF RELEASE										
12	Z	Z		N/A										N/A										
7	8	9	10	11																				

PERSONNEL EXPOSURES

NUMBER			TYPE		DESCRIPTION																		
13	0	0	0	Z	N/A																		
7	8	9	11	12																			

PERSONNEL INJURIES

NUMBER			DESCRIPTION																			
14	0	0	0	N/A																		
7	8	9																				

OFFSITE CONSEQUENCES PROBABLE

15	None																								80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																						
16	Z	N/A																						
7	8	9																						

PUBLICITY

17	N/A																								80
----	-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	Reviewed requirements for compositing with technician responsible including																								80
19	procedural requirement for promptly reporting problems encountered.																								80

NAME: R.W. Leach

PHONE: 315-343-2110 (1303)

NRC-DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORTTO:

Mr. James P. O'ReillyFROM:
Niagara Mohawk Power Corp.
Syracuse, New York
R. R. SchneiderDATE OF DOCUMENT
10/15/76DATE RECEIVED
11/3/76☒ LETTER
☒ ORIGINAL
☐ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
One signed

DESCRIPTION

Ltr. trans the following:

ACKNOWLEDGED

DO NOT REMOVE

(1-P)

PLANT NAME:
Nine Mile Point Unit #1

ENCLOSURE

Licensee Event Report (RO 50-220/76-34) on
10/12/76 concerning milk samples collected
not being counted within time required by
tech specs.
(RO 50-220/76-35) on 10/12/76 concerning
Benthos collections not being made within
the time required by tech specs.

(2-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION 11/4/76

R.J.L.

☒ BRANCH CHIEF: Lear
☒ W/3 CYS FOR ACTION
☒ LIC. ASST.: Parrish
☒ W/ CYS
☒ ACRS 16 CYS HOLDING/SENT TO EA Car. B. (11/4/76)

INTERNAL DISTRIBUTION

☒ REG FILE
☒ NRC PDR
☒ I & E (2)
☒ MIPC
☒ SCHROEDER/IPPOLITO
☒ HOUSTON
☒ NOVAK/CHECK
☒ GRIMES
☒ CASE
☒ BUTLER
☒ HANAUER
☒ TEDESCO/MACCARY
☒ EISENHUT
☒ BAER
☒ SHAO
☒ VOLLMER/BUNCH
☒ KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

☒ LPDR: Oswego, New York
☒ TIC:
☒ NSIC:

CONTROL NUMBER

11146

100

100

100

100

100

100

100

100

100

100

100

100

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

October 15, 1976

Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406




RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Reports 76-34 and 76-35.


These reports were completed within the intent of the Licensee Event Report Instruction Booklet 00E-SS-001, dated October 1974, revised December 24, 1974.

Very truly yours,


R.R. Schneider
Vice President -
Electric Production

MH/mtn

Enc.



REGULATORY DOCKET FILE COPY

11146

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME					LICENSE NUMBER					LICENSE TYPE					EVENT TYPE								
01	N	Y	N	M	P	1			-				-			4	1	1	1	1	0	4	
7	8	9				14	15								25	26					30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE					REPORT DATE											
01	CON'T	-	-	T	L	0	5	0	-	0	2	2	0	1	0	1	2	7	6	1	0	1	5	7	6
7	8	57	58	59	60	61							68	69						74	75				80

EVENT DESCRIPTION

02	During management review of contractor data, it was found that milk samples collected	80
03	on 9/20/76 were not counted until 9/28-30/1976. Samples were received on 9/28/76.	80
04	Counting was started upon receipt, however, all samples could not be counted on this	80
05	date. Samples were therefore counted on the ninth day. ETS Sect. 3.2.c requires	80
06	counting within 8 days of collection. LER 76-34	80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOLATION			
0	7	Z	Z	F	Z	Z	Z	Z	Z	Z	2	9	9	9	-
7	8	9	10	11	12				17	43	44			47	48

CAUSE DESCRIPTION

08	Samples were shipped on 9/21/76 via air freight (alternate carrier during UPS strike)	
7 8 9		.80
09	but were not received by contractor until 9/28/76. Milk samples were 7 days in	
7 8 9		.80
10	shipment.	
7 8 9		.80

11		FACILITY STATUS		% POWER			OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION											
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1	1	Z	Z	Z		N/A				a													
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
12		FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE			AMOUNT OF ACTIVITY					LOCATION OF RELEASE											
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1	2	Z	Z			N/A						N/A											
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
13	0	0	Z	N/A

PERSONNEL INJURIES

NUMBER			DESCRIPTION
14	0	0	N/A

~~DEFENSE~~ CONSEQUENCES Probable.

1	5	None.		
7	8	9		80

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
16	Z		N/A

PUBLICITY

[illegible]

ADDITIONAL FACTORS

18 Milk samples are collected by Lawler, Matusky & Skelly Eng., Oswego, New York and
7 8 9 80
shipped to Eberline Instrument Corp., Chicago, for analysis.
19
7 8 9 80

NAME: M. Hedrick

PHONE: 315-343-2110 X1310

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
0	1	N	Y	N	M	P	1					-						-		4	1	1	1	1	0	4
7	8	9					14	15									25			26				30	31	32

CON'T		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE				REPORT DATE									
0	1	-	-	T	L	0	5	0	-	0	2	2	0	1	0	1	2	7	6	1	0	1	5	7	6
7	8	57	58	59	60	61							68	69					74	75					80

EVENT DESCRIPTION

02	Lake Surveillance Program. Benthos collections are required bimonthly. The August	80
03	1976 samples were not collected until 9/4/76. This is in excess of the +25% time	80
04	variation allowed in Sect. 1.16 of the Safety Technical Specifications. LER 76-35	80
05		80
06		80
PRIME		80

SYSTEM CODE			CAUSE CODE		COMPONENT CODE						PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER			VIOLATION	
0	7		Z	Z	F	Z	Z	Z	Z	Z	Z	Z	Z	9	9	9	-
7	8	9	10		11	12					17	43	44			47	48

CAUSE DESCRIPTION

08	Contractor divers could not be used for the August collections due to recent OSHA	
7 8 9		80
09	regulations imposed on professional divers. Availability of a certified diver was	
7 8 9		80
10	such that collection was delayed until September 4, 1976.	
7 8 9		80

7 8		9		10 11 12			13 14		15 16		17 18		19 20				
FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION								
11		Z			Z Z Z		N/A		a								
7 8		9			10 11 12			13 14		15 16		17 18 19 20					

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	2	Z		N/A		N/A	
7	8	9	10	11	44	45	80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	3	0	0	0	Z N/A

PERSONNEL INJURIES

NUMBER			DESCRIPTION
14	000		N/A

~~QXFXN~~ CONSEQUENCES probable.

1	5	None		
7	8	9		80

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
18	Z		N/A

PUBLICITY

17	N/A	80
----	-----	----

ADDITIONAL FACTORS

18 Contractor is Lawler, Matusky, and Skelly Eng., Oswego, New York.

19

NAME: M. Hedrick

315-343-2110 X1310

40

LICENSEE EVENT REPORT

CONTROL BLOCK: [] [] [] [] [] []
1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME							LICENSE NUMBER							LICENSE TYPE					EVENT TYPE					
0	1	N	Y	N	M	P	1			-					-			4	1	1	1	1	0	3
7	8	9					14	15								25	26				30	31	32	

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE					REPORT DATE								
01	CONT	L	L	0	5	0	—	0	2	2	0	0	9	2	0	7	6	1	0	1	4	7	6
7	8	57	58	59	60	61					68	69					74	75					80

EVENT DESCRIPTION

012 SEE ATTACHED

03 1 80

04 7 R 9 80

05 | _____ 80

7 8 9 PRIME LER 76-28 80

7		8		9		SYSTEM CODE		CAUSE CODE		COMPONENT CODE						PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION													
0		7				S		B		B		C		K		T		B		R		K		N		G		0		8		0		-	
7		8		9		10		11		12		13		14		15		16		17		43		44		45		46		47		48			

CAUSE DESCRIPTION

08	No real cause can be attributed to this item. With the degree of redundancy	80
----	---	----

inherent in the system, no hazard was or is presented to the general public.

[illegible]

7 8 9		FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		
1 1		Z			- - -						Z		Management Design Review		
7 8		9			10 11 12			13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43			44 45		46 47 48 49 50 51 52 53 54 55 56 57 58 59 60		

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	2	Z		N/A		N/A	
7	8	9	10	11	44	45	80

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION	
13	0	0	0	Z	N/A

PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	N/A

~~QUESTIONS~~ CONSEQUENCES PROBABLE

15 | None 80

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
15	Z		N/A

PUBLICITY

17 | None

ADDITIONAL FACTORS

13 None 80

13

7 89 80

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORTTO:
Mr. James P. O'ReillyFROM:
Niagara Mohawk Power Corp.
Syracuse, New York
R. R. SchneiderDATE OF DOCUMENT
10/14/76DATE RECEIVED
11/3/76☒ LETTER
☒ ORIGINAL
☐ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
One signed

DESCRIPTION

Ltr. trans the following:

ACKNOWLEDGED (1-P),

DO NOT REMOVE

PLANT NAME:

Nine Mile Point Unit #1

ENCLOSURE

Licensee Event Report (RO 50-220/76-28) on
9/20/76 concerning the discovery that if the
control switch for the containment spray pump
were placed in lockout, the sister pump
was enabled from automatic starting.

(2-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

11/4/76

RJJ

<input checked="" type="checkbox"/> BRANCH CHIEF:	Lear
<input type="checkbox"/> W/3 CYS FOR ACTION	
<input checked="" type="checkbox"/> LIC. ASST.:	Parrish
<input type="checkbox"/> W/ CYS	
<input checked="" type="checkbox"/> ACRS 16 CYS HOLDING/SENT TO	Car. B. (11/4/76)

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE	
<input checked="" type="checkbox"/> NRC PDR	
<input checked="" type="checkbox"/> I & E (2)	
<input checked="" type="checkbox"/> MIPC	
<input checked="" type="checkbox"/> SCHROEDER/IPPOLITO	
<input checked="" type="checkbox"/> HOUSTON	
<input checked="" type="checkbox"/> NOVAK/CHECK	
<input checked="" type="checkbox"/> GRIMES	
<input checked="" type="checkbox"/> CASE	
<input checked="" type="checkbox"/> BUTLER	
<input checked="" type="checkbox"/> HANAUER	
<input checked="" type="checkbox"/> TEDESCO/MACCARY	
<input checked="" type="checkbox"/> EISENHUT	
<input checked="" type="checkbox"/> BAER	
<input checked="" type="checkbox"/> SHAO	
<input checked="" type="checkbox"/> VOILMER/FUNCH	
<input checked="" type="checkbox"/> KREGER/J. COLLINS	

EXTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> LPDR: Oswego, New York	
<input checked="" type="checkbox"/> TTC:	
<input checked="" type="checkbox"/> NSIC:	

CONTROL NUMBER

11147

11
12
13

14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200

201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300

301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400

401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500

501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600

601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700

701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

October 14, 1976

Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406




RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Report 76-28.


This report was completed within the intent of the Licensee Event Report Instruction Booklet 00E-SS-001, dated October 1974, revised December 24, 1974. Due to the minimal significance category of this report, no supplemental report is included.

Very truly yours,


R.R. Schneider
Vice President -
Electric Production

TJD/mtm

Enc.



REGULATORY DOCKET FILE COPY

11147

EVENT DESCRIPTION

During a management review of existing plant design, it was discovered that if the control switch for the containment spray pump were placed in lockout, the sister pump was enabled from automatic starting. The containment spray system is 400% redundant with 4 pumps. The emergency power supply for the effected sister pumps is the same EDG. This precluded start of a sister pump with one in lockout is only effected by an automatic start signal. The pump could be started manually from the Control Room. An electrical change is being considered to eliminate this situation and in the interum, a change has been made to Operating Procedure OP-19 stating that the pumps will never be placed in the lockout position when operability is required.

40



THE
NATIONAL
ARCHIVES
COLLECTION
OF
DOCUMENTS
AND
RECORDS
OF
THE
UNITED
STATES
OF
AMERICA
1783-1800

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: J.P.O'REILLY

FROM: NIAGARA MOHAWK POWER CORP.
SYRACUSE, N.Y.
R.R. SCHNEIDERDATE OF DOCUMENT
9-24-76DATE RECEIVED
10-4-76☒ LETTER☐ NOTORIZED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

☒ ORIGINAL☒ UNCLASSIFIED☐ COPY

30

DESCRIPTION

LTR. TRANS THE FOLLOWING.....

**DO NOT REMOVE
ACKNOWLEDGED**

PLANT NAME: NINE MILE PT. # 1

ENCLOSURE

LICENSEE EVENT REPORT # 76-32, ON 8-27-76,
CONCERNING MAIN STEAM LINE BREAK INSTRUMENTATION
RE-22A TRIPPING.....LICENSEE EVENT REPORT # 76-33, ON 9-8-76,
CONCERNING SURVEILLANCE THAT WAS REQUIRED BY
BY TECH. SPEC. BEING PERFORMED.....

(1 NONE SIGNED CY. RECEIVED)

(3 PAGES)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J..COLLINS.

FOR ACTION/INFORMATION

SAB 10-5-76

<input checked="" type="checkbox"/> BRANCH CHIEF:	LEAR
<input checked="" type="checkbox"/> W/3 CYS FOR ACTION	
<input checked="" type="checkbox"/> LIC. ASST.:	PARRISH
<input checked="" type="checkbox"/> W/ CYS	
<input checked="" type="checkbox"/> ACRS 16 CYS XXXXXX /SENT TO LA	

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE				
<input checked="" type="checkbox"/> NRC PDR				
<input checked="" type="checkbox"/> I & E (2)				
<input checked="" type="checkbox"/> MIPC				
<input checked="" type="checkbox"/> SCHROEDER/IPPOLITO				
<input checked="" type="checkbox"/> HOUSTON				
<input checked="" type="checkbox"/> NOVAK/CHECK				
<input checked="" type="checkbox"/> GRIMES				
<input checked="" type="checkbox"/> CASE				
<input checked="" type="checkbox"/> BUTLER				
<input checked="" type="checkbox"/> HANAUER				
<input checked="" type="checkbox"/> TEDESCO/MACCARY				
<input checked="" type="checkbox"/> EISENHUT				
<input checked="" type="checkbox"/> BAER				
<input checked="" type="checkbox"/> SHAO				
<input checked="" type="checkbox"/> VOLLMER/BUNCH				
<input checked="" type="checkbox"/> KREGER/J. COLLINS				

EXTERNAL DISTRIBUTION

CONTROL NUMBER

<input checked="" type="checkbox"/> IPDR: OSWEGO, N.Y.				
<input checked="" type="checkbox"/> TIC:				
<input checked="" type="checkbox"/> NSIC:				

10074

Regulatory

File Cy.

NIAGARA MOHAWK POWER CORPORATION


NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202



September 24, 1976

Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pa. 19406



RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Reports 76-32 and 76-33.

These reports were completed within the intent of the Licensee Event Report Instruction Booklet 00E-SS-001, dated October, 1974, revised December 24, 1974. Due to the minimal significance category of these reports, no supplemental report is included.

Very truly yours,

Original Signed by R.R. Schneider

R.R. Schneider
Vice President -
Electric Production

TJD/mtm

Enc.

10074



LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER														LICENSE TYPE										EVENT TYPE			
01	N	Y	N	M	P	1									4	1	1	1	1	0	3																				
7	8	9				14	15								25	26				30	31	32																			

CATEGORY				REPORT TYPE		REPORT SOURCE		DOCKET NUMBER								EVENT DATE						REPORT DATE					
01	CON	-	-	L	L			0	5	0	-	0	2	2	0	0	8	2	7	7	6	0	9	2	3	7	6
7	8			57	58	59	60	61							68	69						74	75				80

EVENT DESCRIPTION

02	During surveillance testing (RE-22), Main Steam Line Break Instrumentation, it was																																																																															
03	found that RE-22A tripped at 108psig rather than the required value of 105±1 psig.																																																																															
04	All redundant instruments preformed properly, thus no hazard was presented to																																																																															
05	the general public.																																																																															
06	LER 76-32																																																																															

SYSTEM CODE				CAUSE CODE		COMPONENT CODE												PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	I	B		E		I	N	S	T	R	U	A	B	0	8	0	-								
7	8	9	10	11		12						17	43	44			47	48							

CAUSE DESCRIPTION

08	The Barton Model 278, Serial Number 759, was inspected for mechanical defects																																																																															
09	and friction. No reason other than set point drift could be found. RE-22A																																																																															
10	was recalibrated and returned to service.																																																																															

FACILITY STATUS				% POWER				OTHER STATUS												METHOD OF DISCOVERY		DISCOVERY DESCRIPTION																	
11	E			0	9	4										b		N/A																					
7	8	9		10			12	13								44	45	46																					

FORM OF ACTIVITY RELEASED				CONTENT OF RELEASE				AMOUNT OF ACTIVITY												LOCATION OF RELEASE																	
12	Z			Z			N/A																														
7	8	9		10			11								44	45	N/A																				

PERSONNEL EXPOSURES

NUMBER				TYPE		DESCRIPTION														
13	0	0	0	Z		N/A														
7	8	9		11	12	13														

PERSONNEL INJURIES

NUMBER				DESCRIPTION															
14	0	0	0	N/A															
7	8	9		11	12														

DEFINITE CONSEQUENCES PROBABLE

15	None																																																																															
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

LOSS OR DAMAGE TO FACILITY

TYPE				DESCRIPTION															
16	Z			N/A															
7	8	9		10															

PUBLICITY

17	None																																																																															
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

ADDITIONAL FACTORS

18	None																																																																															
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

19																																																																																
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

NAME: _____ PHONE: _____



4 - 1



20

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE				EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	0	3									
7	8	9				14	15									25	26				30	31	32						

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE				REPORT DATE											
01	CON'T	-	-	L	L	0	5	0	-	0	2	2	0	0	9	0	8	7	6	0	9	2	3	7	6
7	8	57	58	59	60	61							68	69					74	75					80

EVENT DESCRIPTION

02	During a management review, it was revealed that surveillance required by																								80
03	Technical Specifications 4.3.6(a) on vacuum breaker exercising following																								80
04	relief valve discharge to Torus had not been performed following scrams on																								80
05	8-6-76 and 8-23-76.																								80
06	LER 76-33																								80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER			VIOLATION		
07	Z	Z	D	Z	Z	Z	Z	Z	Z	-	Z	9	9	9	-
7	8	9	10	11	12				17	43	44			47	48

CAUSE DESCRIPTION

08	The surveillance requirements were never posted on the Startup Check-off Sheets.																								80
09	This has been changed in OP-43 and also on Startup Form ST-M3.																								80
10																									80

FACILITY STATUS		% POWER		OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
11	E	0	9	5	N/A					During a review				
7	8	9	10	12	13				44	45			46	80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE				
12	Z	Z	N/A				N/A					
7	8	9	10	11				44	45			80

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION	
13	0	0	0	Z	N/A
7	8	9	11	12	13

PERSONNEL INJURIES

NUMBER		DESCRIPTION	
14	0	0	0
7	8	9	12

PROBABLE CONSEQUENCES

15	NONE																								80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION	
16	Z	N/A	
7	8	9	10

PUBLICITY

17	None																								80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	None																								80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																									80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: _____ PHONE: _____



50-220

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

INCIDENT REPORT

TO: MR J P O'REILLY

FROM: NIAGARA MOHAWK POWER CORP
SYRACUSE, NY
R R SCHNEIDER

DATE OF DOCUMENT

9-3-76

DATE RECEIVED

9-15-76

☒ LETTER
☐ ORIGINAL
☒ COPY☐ NOTORIZED☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

None SIGNED

DESCRIPTION

LTR TRANS THE FOLLOWING.....

ENCLOSURE

LICESNEEE EVENT REPORT 50-220/76-31 ON 8/9/76
REF DURING A ROUTINE REACTOR STARTUP #11 FEED-
WATER PUMP FAILED TO START WHEN MANUALLY INITIA-
TED.....

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: Nine Mile Point

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J..COLLINS

FOR ACTION/INFORMATION

BRANCH CHIEF:

LEAR

W/3 CYS FOR ACTION

LIC. ASST.:

K. PARRISH

W/ CYS

ACRS 17 CYS HOLDING SENT TO LA

INTERNAL DISTRIBUTION

☒ REG FILE☒ NRC PDR☒ I & E (2)☒ MIPC☒ SCHROEDER/IPPOLITO☒ HOUSTON☒ NOVAK/CHECK☒ GRIMES☒ CASE☒ BUTLER☒ HANAUER☒ TEDESCO/MACCARY☒ EISENHUT☒ BAER☒ SHAO☒ VOLLMER/BUNCH☒ KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

LPDR: OSWEGO, NY

TTC:

NSIC:

CONTROL NUMBER


9411

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

September 3, 1976



File Cy.

Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pa. 19406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1
Technical Specification 6.9, we hereby submit Licensee Event
Report LER 76-31.

This report was completed within the intent of the Licensee
Event Report Instruction Booklet 00E-SS-001, dated October, 1974,
revised December 24, 1974. Due to the minimal significance
category of the report, no supplemental report is included.

Very truly yours,

ORIGINAL SIGNED BY R.R. SCHNEIDER

R.R. Schneider
Vice President -
Electric Production

TJD/mtn

Enc.

9411

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME 01 N Y N M P 1	LICENSE NUMBER 15	LICENSE TYPE 4 1 1 1 1 1	EVENT TYPE 0 1
7 8 9 14	15 25	26 30	31 32

CON'T 01	CATEGORY M I	REPORT TYPE L	REPORT SOURCE L	DOCKET NUMBER 0 5 0 - 0 2 2 0	EVENT DATE 0 8 0 9 7 6	REPORT DATE 0 9 0 1 7 6
7 8	57 58	59	60	61 68	69 74	75 80

EVENT DESCRIPTION

02 During a routine reactor startup, #11 Feedwater pump failed to start when manually initiated. #11 FW pump is one of two pumps required for HPCI. #12 FW pump, the redundant component, was started successfully, therefore no hazard was presented to the general public.

LER 76-31

SYSTEM CODE I B	CAUSE CODE E	COMPONENT CODE I N S T R U	PRIME COMPONENT SUPPLIER N	COMPONENT MANUFACTURER A 1 0 9	VIOLATION -
7 8 9 10	11	12 17	43	44 47	48

CAUSE DESCRIPTION

03 An Agastat time delay relay model #2462 PD Serial #2683521, 120 V DC failed to function thus not allowing operation of the pump.

FACILITY STATUS 0	% POWER 0 7 7	OTHER STATUS _____	METHOD OF DISCOVERY a	DISCOVERY DESCRIPTION during plant startup
7 8 9	10 12 13	44	45 46	80

FORM OF ACTIVITY RELEASED Z	CONTENT OF RELEASE Z	AMOUNT OF ACTIVITY N/A	LOCATION OF RELEASE _____
7 8 9	10 11	44	45 80

PERSONNEL EXPOSURES

NUMBER 0 0 0	TYPE Z	DESCRIPTION N/A
7 8 9 11	12	13 80

PERSONNEL INJURIES

NUMBER 0 0 0	DESCRIPTION N/A
7 8 9 11	12 80

HEALTH CONSEQUENCES PROBABLE

15 None

LOSS OR DAMAGE TO FACILITY

TYPE Z	DESCRIPTION N/A
7 8 9 10	80

PUBLICITY

17 None

ADDITIONAL FACTORS

19 None

19

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: MR. J. P. O'REILLY

FROM: NIAGARA MOHAWK POWER CORP.
SYRACUSE N.Y.
R.R. SCHNEIDERDATE OF DOCUMENT
7-6-76DATE RECEIVED
7-27-76☒ LETTER ☐ NOTORIZED
☒ ORIGINAL ☒ UNCLASSIFIED
☐ COPY

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
1 signedDESCRIPTION
LTR. TRANS. THE FOLLOWING.....

ACKNOWLEDGED

DO NOT REMOVE

ENCLOSURE
LICENSEE EVENT REPORT (RO 76-23) on 6-25-76
concerning REACTOR RECIRCULATION PUMP.....
LICENSEE EVENT REPORT (RO 76-24) on 6-13-76
concerning APRM'S 17 & 18 which failed to
produce a scram signal.....
LICENSEE EVENT REPORT (RO 76-25) on 6-27-76
concerning #11 & #15 APRM'S which failed to
produce a scram signal.....
(1 signed cy recieved)
(4 pgs.)

PLANT NAME: Nine Mile Pt. #1

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO

CRG 7-27-76

<input checked="" type="checkbox"/> BRANCH CHIEF:	Lear
<input type="checkbox"/> W/3 CYS FOR ACTION	
<input checked="" type="checkbox"/> LIC. ASST.:	Parrish
<input type="checkbox"/> W/ CYS	
<input type="checkbox"/> ACRS 16 CYS HOLDING/SENT TO LA	

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE	
<input checked="" type="checkbox"/> NRC PDR	
<input checked="" type="checkbox"/> I & E (2)	
<input checked="" type="checkbox"/> MIPC	
<input checked="" type="checkbox"/> SCHROEDER/IPPOLITO	
<input checked="" type="checkbox"/> HOUSTON	
<input checked="" type="checkbox"/> NOVAK/CHECK	
<input checked="" type="checkbox"/> GRIMES	
<input checked="" type="checkbox"/> CASE	
<input checked="" type="checkbox"/> BUTLER	
<input checked="" type="checkbox"/> HANAUER	
<input checked="" type="checkbox"/> TEDESCO/MACCARY	
<input checked="" type="checkbox"/> EISENHUT	
<input checked="" type="checkbox"/> BAER	
<input checked="" type="checkbox"/> SHAO	
<input checked="" type="checkbox"/> VOLLMER/BUNCH	
<input checked="" type="checkbox"/> KREGER/J. COLLINS	

EXTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> PDR: OSWEGO, N.Y.	
<input checked="" type="checkbox"/> TIC:	
<input checked="" type="checkbox"/> NSIC:	

CONTROL NUMBER

9569



2. 1

.....

.....

.....

.....

.....

.....

.....

.....

NIAGARA MOHAWK POWER CORPORATION

Regulatory

File Cy

NIAGARA MOHAWK

300 ERIE BOULEVARD
SYRACUSE, N.Y. 13202

July 6, 1976
Sectord
Docket Clerk




Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pa. 29406

RE: Docket No. 50-220

In accordance with Nine Mile Point Nuclear Station Unit #1
Environmental Technical Specification 5.6.3.1, we hereby submit Licensee
Event Reports 76-23, 76-24, and 76-25.

This report was completed within the intent of the Licensee
Event Report Instruction Booklet 00E-SS-001, dated October 1974, re-
vised December 24, 1974. Due to the minimal significance category of
the report, no supplemental report is included.

Very truly yours,


R. R. Schneider
Vice President -
Electric Operations

TJD/aih
Enc.

7569



23

1. The first part of the document is a list of names and addresses. The names are: John Doe, Jane Doe, and John Doe. The addresses are: 123 Main St, 456 Main St, and 789 Main St.

2. The second part of the document is a list of names and addresses. The names are: John Doe, Jane Doe, and John Doe. The addresses are: 123 Main St, 456 Main St, and 789 Main St.

3. The third part of the document is a list of names and addresses. The names are: John Doe, Jane Doe, and John Doe. The addresses are: 123 Main St, 456 Main St, and 789 Main St.

4. The fourth part of the document is a list of names and addresses. The names are: John Doe, Jane Doe, and John Doe. The addresses are: 123 Main St, 456 Main St, and 789 Main St.

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	1	0	1									
7	8	9				14	15								25	26			30	31	32									

CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER						EVENT DATE					REPORT DATE								
01	CON'T	M	I	L	L	0	5	0	-	0	2	2	0	0	6	2	5	7	6	0	7	0	1	7	6
7	8	57	58	59	60	61						68	69		74					75				80	

EVENT DESCRIPTION

02	Operator noted smoke from relay 4-112 B/40, Reactor Recirculation Pump - Lo Lo Level.																				80
03	Trip (#12HFA51A49F). Relay assumed the tripped condition thus no hazard was presented																				80
04	to plant or general public.																				80
05																RO 76-23					80
06																					80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	I	B	E	I	N	S	T	R	U	N	G	0	8	0	-
7	8	9	10	11	12				17	43	44			47	48

CAUSE DESCRIPTION

08	Coil apparently shorted causing smoking and blown fuse. Relay replaced with similar																				80
09	device.																				80
10																					80

FACILITY STATUS		% POWER		OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION														
11	C	0	8	1					a															
7	8	9	10	12	13				44	45	46													80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY						LOCATION OF RELEASE														
12	Z	Z	N/A																					
7	8	9	10	11					44	45														80

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION																				
13	0	0	0	Z	N/A																			
7	8	9		11	12	13																		80

PERSONNEL INJURIES

NUMBER		DESCRIPTION																						
14	0	0	0	N/A																				
7	8	9		11	12																			80

OFFSITE CONSEQUENCES probable

15	NONE																				80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																						
16	Z	NONE																						
7	8	9		10																				80

PUBLICITY

17	NONE																				80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18																					80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																					80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

7 8 9 Name: T. Dente Phone: 315 343-2110

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE					EVENT TYPE						
0	1	N	Y	N	M	P	L			-					-		4	1	1	1	1	0	1												
7	8	9					14	15								25	26					30	31	32											
CATEGORY														REPORT TYPE		REPORT SOURCE		DOCKET NUMBER								EVENT DATE					REPORT DATE				
0	1	CON	T	M	1	L	L	0	5	0	-	0	2	2	0	0	6	1	3	7	6	0	7	0	1	7	6								
7	8			57	58	59	60	61							68	69						74	75					80							

EVENT DESCRIPTION

02	During weekly surveillance testing of the APRM System, APRM's 17 & 18 failed to produce	80
03	a scram signal at the required flow bias set point. 20% flow test tripped higher than	80
04	required by approximately 1%. All redundant (6) APRM's operable.	80
05	RO 76-24	80
06		80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					FRAME COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION			
0	7	F	I	N	S	T	R	U	N	6	0	8	0	-		
7	8	9	10	11	12	13	14	15	16	17	43	44	45	46	47	48

CAUSE DESCRIPTION

08	Set point drift. Instrument recalibrated to required specifications.	7 8 9	80
09		7 8 9	80
10		7 8 9	80

11	FACILITY STATUS E	% POWER 098	OTHER STATUS	METHOD OF DISCOVERY b	DISCOVERY DESCRIPTION
7 8	9	10 11 12	13	44 45	46
12	FORM OF ACTIVITY RELEASED Z	CONTENT OF RELEASE Z	AMOUNT OF ACTIVITY N/A		LOCATION OF RELEASE
7 8	9	10 11	44	45	

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
13	0	0	0	N/A

PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	N/A

xxxxx OFFSITE CONSEQUENCES probable

1	5	NONE
7	8	9

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
16	2		N/A

PUBLICITY

17 | NONE

ADDITIONAL FACTORS

7 8 9

19 |
7 8 9 NAME: T. Dente PHONE: 315 343-2110 80

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	1	0	1									
7	8	9				14	15							25	26				30	31	32									

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE					REPORT DATE											
01	CON'T	M	I	L	L	0	5	0	-	0	2	2	0	0	6	2	7	7	6	0	7	0	1	7	6
7	8	57	58	59	60	61				68	69				74	75				80					

EVENT DESCRIPTION

02	During weekly surveillance testing of the APRM's, #11 & #15 APRM's failed to produce																							
03	a scram signal at the required flow bias set point. 20% flow test tripped higher																							
04	than required by less than 1%. All redundant (6) APRM's operable.																							
05																								
06	RO 76-25																							

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	R	B	F	I	N	S	T	R	U	N	G	0	8	0	-	
7	8	9	10	11	12	17			43	44	47			48		

CAUSE DESCRIPTION

08	Set point drift. Instruments calibrated to required specifications.																							
09																								
10																								

FACILITY STATUS		% POWER		OTHER STATUS					METHOD OF DISCOVERY		DISCOVERY DESCRIPTION										
11	E	0	9	8						b											
7	8	9	10	12	13				44	45	46	80									
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY					LOCATION OF RELEASE												
12	Z	Z	N/A																		
7	8	9	10	11				44	45	80											

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION										
13	0	0	0	Z	N/A									
7	8	9	11	12	13									

PERSONNEL INJURIES

NUMBER		DESCRIPTION											
14	0	0	0	N/A									
7	8	9	11	12									

OTHER CONSEQUENCES probable

15	NONE																							
7	8	9																						80

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION											
16	Z	N/A											
7	8	9	10										80

PUBLICITY

17	NONE																							
7	8	9																						80

ADDITIONAL FACTORS

18																								
7	8	9																						80

19																								
7	8	9																						80



10-10-10

- - 7

50-220

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

INCIDENT REPORT

TO:

FROM:

MR. JAMES P. O'REILLY

NIAGARA MOHAWK POWER CORP.
SYRACUSE, NEW YORK
R. R. SCHNEIDER

DATE OF DOCUMENT

5/28/76

DATE RECEIVED

6/7/76

☒ LETTER
☐ ORIGINAL
☒ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP.

INPUT FORM

NUMBER OF COPIES RECEIVED

NONE SIGNED

DESCRIPTION

LTR. TRANS THE FOLLOWING:

(1-P)

PLANT NAME:

NINE MILE POINT #1

ENCLOSURE

LICENSEE EVENT RPT. (RO 50-220/76-22) ON
5/27/76 CONCERNING THE NUMBER OF FISH BEING
IMPINGED EXCEEDING THE ETS LIMIT.ACKNOWLEDGED
DO NOT REMOVE

(2-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO 6/9/76

RJL

☒ BRANCH CHIEF: LEAR
☐ W/3 CYS FOR ACTION
☒ LIC. ASST: PARRISH
☐ W/1 CYS
ACRS 16 CYS HOLDING/SENT TO LA

INTERNAL DISTRIBUTION

☒ REG FILE
☒ NRC PDR
☒ I & E (2)
☒ MIPC (3)
☒ SCHROEDER/IPPOLITO
☒ HOUSTON
☒ NOVAK/CHECK
☒ GRIMES/SCHWENCER (1) EA
☒ CASE
☒ HANAUER
☒ TEDESCO/MACCARY
☒ EISENHUT
☒ LAER
☒ SHAO
☒ VOLLMER/BUNCH
☒ KREGER/J. COLLINS


EXTERNAL DISTRIBUTION

☒ LPDR: OSWEGO, N. Y.
☒ TIC
☒ NSIC

CONTROL NUMBER

5662


NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

May 28, 1976

Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pa. 29406



RE: Docket No. 50-220


In accordance with Nine Mile Point Nuclear Station Unit #1 Environmental Technical Specification 5.6.3.1, we hereby submit Licensee Event Report 76-22.

This report was completed within the intent of the Licensee Event Report Instruction Booklet 00E-SS-001, dated October 1974, revised December 24, 1974. Due to the minimal significance category of the report, no supplemental report is included.

Very truly yours,

Original Signed by R.R. Schneider

Regulatory Docket File



R. R. Schneider
Vice President -
Electric Operations

MCH/aih

Enc. 2 copies

cc: (20 copies) Director, Office of Inspection
and Enforcement

(2 copies) Director, Office of Management Information
and Program Control

5662

LICENSEE EVENT REPORT

CONTROL BLOCK: [] [] [] [] [] []
 1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME: 01 N Y N M P 1
 LICENSE NUMBER: 15 25
 LICENSE TYPE: 4 1 1 1 1
 EVENT TYPE: 0 4
 END
 CATEGORY: 01 CONT M I
 REPORT TYPE: T
 REPORT SOURCE: L
 DOCKET NUMBER: 0 5 0 0 2 2 0
 EVENT DATE: 0 5 2 7 7 6
 REPORT DATE: 0 5 2 8 7 6

EVENT DESCRIPTION

02		During routine impingement sampling by contractor personnel on 05/19-20/76 it was	
7	8		80
03		determined the numbers' of fish being impinged had exceeded the ETS limit of	
7	8		80
04		20,000/24 hr. (Sect. 3.1.2.a2). This condition continued until 5/27/76.	
7	8		80
05			
7	8		80
05		(see attachment for numbers)	RO 76-22
7	8		80
		PRIME	

7 8 9			SYSTEM CODE			CAUSE CODE			COMPONENT CODE						PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION				
0	7		H	F		F			Z	Z	Z	Z	Z	Z		Z				Z	9	9	9		-
7	8	9	10			11			12					17		43				44				47	48

CAUSE DESCRIPTION

There was no apparent cause for this occurrence related directly to station operation. The principle species involved, alewives, rainbow smelt, and three spine stickleback, migrate inshore annually at this time of year. (Con't.)

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60
11		E		091		OTHER STATUS																		a		DISCOVERY DESCRIPTION																											
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60
12		Z		Z		N/A																				LOCATION OF RELEASE																											
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	25	N/A

PERSONNEL INJURIES

NUMBER			DESCRIPTION
14	0	0	N/A

OFFSITE CONSEQUENCES probable

15 | NONE | 80

LOSS OR DAMAGE TO FACILITY


TYPE		DESCRIPTION
15	Z	N/A

PUBLICITY

17	N/A
----	-----

ADDITIONAL FACTORS

7-29-68 | Continuous sampling by contractor personnel continued until numbers fell below 20,000/24 hr. as per EIS. (Spec. 5.6.3.1).




Con't.

There appears to be a correlation between wind speed and direction and the impingement numbers. The higher impingement numbers occurred when wind directions were north westerly and northerly with correspondingly high wind speeds, creating extreme wave activity on the lake. Conversely, as wind speeds dropped and/or direction changed to southerly, the numbers of fish impinged would decrease accordingly.

IMPINGEMENT NUMBERS

05/19-20/76	123,015
05/20-21/76	123,597
05/21-22/76	171,326
05/22-23/76	130,011
05/23-24/76	175,931
05/24-25/76	80,705
05/25-26/76	24,891
05/26-27/76	12,688



50-220

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

INCIDENT REPORT

TO:
MR J P O'REILLYFROM: NIAGARA MOHAWK POWER CORP
SYRACUSE, NY
R R SCHNEIDER

DATE OF DOCUMENT

5-25-76

DATE RECEIVED

5-29-76

☒ LETTER
☒ ORIGINAL
☐ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

(1) Signed

DESCRIPTION

LTR TRANS THE FOLLOWING.....

ENCLOSURE

- (A) LER 50-220 (RO 76-19) ON 4-23-76 RE SWITCH USED FOR TURBINE WAS FOUND TO ACTUATE AT 364 PSIG RATHER THAN THE REQUIRED 355.....
- (b) LER 50-220 (RO 76-20) ON 4-23-76 RE 1Bo5C SWITCH TO ACTUATE AT 20.4 RATHER THAN 19 PSID.....
- (c) LER 50-220 5-15-76 (RO 76-21) RE REACTOR SHUTDOWN COOLING SYSTEM D.C. FAILED TO FUNCTION.....

ACKNOWLEDGED
DO NOT REMOVE1 PG
.....
3 ENCL

PLANT NAME: Nine Mile Pt. #1

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO

6-3-76 RRB

✓ BRANCH CHIEF: LEAR

✓ W/3 CYS FOR ACTION

✓ LIC. ASST: PARRISH

W/ CYS

ACRS CYS 17 HOLDING/SENT TO LA

INTERNAL DISTRIBUTION

✓ REG FILE

✓ NRC PDR

✓ I & E (2)

✓ MIRC (3)

✓ SCHROEDER/IPPOLITO

✓ HOUSTON

✓ NOVAK/CHECK

✓ GRIMES/SCHWENCER

✓ CASE

✓ HANAUER

✓ TEDESCO/MACCARY

✓ EISENHUT

✓ BAER

✓ SHAO

✓ VOLLMER/BUNCH

✓ KREGER/J. COLLINS

1 EACH

EXTERNAL DISTRIBUTION

✓ LPDR: OSWEGO, NY

✓ TIC

✓ NSIC

CONTROL NUMBER

5419

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 1 1 1 1 1

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE					EVENT TYPE								
01	N	Y	N	M	P	1									4	1	1	1	1	0	3																
7	8	9				14	15										25						26						30						31		32

CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER										EVENT DATE					REPORT DATE						
01	CONT	M	1	L	L	0	5	0	-	0	2	2	0	0	4	2	3	7	6	0	5	2	1	7	6		
7	8			57	58	59	60	61					68	69							74	75					80

EVENT DESCRIPTION

02	During surveillance testing 02-13B a switch used for turbine auticipatory trip bypass																												80
03	reactor scram was found to actuate at 364 psig rather than the required 355 + 5 psig.																												80
04	Plant was operating above point thus required action would occur if required.																												80
05																													80
06	RO 76-19																												80

SYSTEM CODE				CAUSE CODE		COMPONENT CODE										PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER					VIOLATION	
07	I	A	E	I	N	S	T	R	U	N	B	0	7	0	-									
7	8	9	10	11	12				17	43	44			47	48									

CAUSE DESCRIPTION

08	Setpoint drift switch was recalibrated and placed back in service.																												80
09																													80
10																													80

FACILITY STATUS				% POWER				OTHER STATUS										METHOD OF DISCOVERY		DISCOVERY DESCRIPTION									
11	C	0	6	0									b																
7	8	9		10	11	12	13						44	45	46												80		

FORM OF ACTIVITY RELEASED				CONTENT OF RELEASE				AMOUNT OF ACTIVITY										LOCATION OF RELEASE									
12	Z	Z																									
7	8	9		10	11								44	45												80	

PERSONNEL EXPOSURES

NUMBER				TYPE		DESCRIPTION																				
13	0	0	0	Z																						
7	8	9		11	12	13																				80

PERSONNEL INJURIES

NUMBER				DESCRIPTION																						
14	0	0	0																							
7	8	9		11	12																					80

ON-SITE CONSEQUENCES probable

15	NONE																												80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE				DESCRIPTION																						
16	Z																									
7	8	9		10																						80


PUBLICITY

17	NONE																												80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	No hazard to plant or general public.																												80
----	---------------------------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																													80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----



NIAGARA MOHAWK POWER CORPORATION

NIAGARA MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

May 25, 1976

Regulatory Docket File

Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pa.. 29406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

Enclosed please find LER Reports (76-19, 76-20, & 76-21) for Nine Mile Point Unit 1. These reports are in the acceptable format as required and as a point of clarification and due to the previously submitted type T reports on fish impingement, the numbering does not follow in chronological order. This system is being changed to prevent this problem in the future.

Very truly yours,

Original Signed by R.R. Schneider

R.R. Schneider
Vice President
Electric Operations

TJD/aih

Enc. 3 copies

CC: K.R. Goller (30 copies) /

5419

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE										EVENT TYPE			
01	N	Y	N	M	P	1									4	1	1	1	1	0	3																
7	8	9				14	15										25	26							30	31	32										

CATEGORY				REPORT TYPE		REPORT SOURCE		DOCKET NUMBER								EVENT DATE						REPORT DATE						
01	CON'T			M	1	L	L	0	5	0	-	0	2	2	0	0	5	1	5	7	6	0	5	2	4	7	6	
7	8			57	58	59	60	61							68	69												80

EVENT DESCRIPTION

02	During reactor shutdown one shutdown cooling system D.C. operated I.V. (38-02)																													80
03	failed to function (open). Valve was manually opened to allow operation of the																													80
04	system. System is fully operable.																													80
05	RO 76-21																													80
06																														80

SYSTEM CODE				CAUSE CODE		COMPONENT CODE										PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER						VIOLATION	
07	C	F	E	V	A	L	V	O	P	A	L	2	0	0	-										
7	8	9	10	11	12				17	43	44			47	48										

CAUSE DESCRIPTION

08	Motor found with an "open in" the windings. Motor will be rewound.																													80
09																														80
10																														80

FACILITY STATUS				% POWER				OTHER STATUS								METHOD OF DISCOVERY		DISCOVERY DESCRIPTION										
11	D	0	0	0	a																							
7	8	9	10	12	13									44	45	46												80

FORM OF ACTIVITY RELEASED				CONTENT OF RELEASE				AMOUNT OF ACTIVITY								LOCATION OF RELEASE											
12	Z	Z	N/A																								
7	8	9	10	11										44	45												80

PERSONNEL EXPOSURES

NUMBER				TYPE		DESCRIPTION																				
13	0	0	d	Z	N/A																					
7	8	9	11	12	13																					80

PERSONNEL INJURIES

NUMBER				DESCRIPTION																						
14	0	0	d	N/A																						
7	8	9	11	12																						80

OFFSITE CONSEQUENCES . probable

15	NONE																													80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE				DESCRIPTION																						
16	Z	N/A																								
7	8	9	10																							80

PUBLICITY

17	NONE																													80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	NONE																													80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																														80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME: 01 N Y N M P 1
 LICENSE NUMBER: 15 - - - - - 25
 LICENSE TYPE: 4 1 1 1 1
 EVENT TYPE: 0 3
 CATEGORY: 01 CONT M 1
 REPORT TYPE: L
 REPORT SOURCE: L
 DOCKET NUMBER: 0 5 0 - 0 2 1 2 0
 EVENT DATE: 0 4 2 3 7 6
 REPORT DATE: 0 5 2 1 7 6

EVENT DESCRIPTION

02	During surveillance testing found 1B05C to actuate at 20.4 psid rather than required	80
03	19 psid. Switch is used to indicate emergency cooling high flow and isolate the	80
04	system. Redundant components operable that no hazard presented to plant or offsite	80
05	personnel.	80
06	RO 76-20	80
	PRIME	80

CAUSE DESCRIPTION

08	Setpoint drift which is within the expected range.	
7 8 9		80
09		
7 8 9		80
10		
7 8 9		80

11		c		060		OTHER STATUS		b		DISCOVERY DESCRIPTION	
7	8	9	10	11	12	13	14	15	16	17	18
12		Z		Z		N/A				LOCATION OF RELEASE	
7	8	9	10	11	12	13	14	15	16	17	18

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
13	0	0	3	N/A

PERSONNEL INJURIES

NUMBER				DESCRIPTION
1	4	0	0	N/A

OTHER CONSEQUENCES probable

1	5	NONE	
7	8	9	80

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
1	5	2	N/A

7 8 9 10 80

PUBLICITY

17 NONE

ADDITIONAL FACTORS

18 NONE

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO:

MR. JAMES P. O'REILLY

FROM:

NIAGARA MOHAWK POWER CORP.
SYRACUSE, NEW YORK
R. R. SCHNEIDER

DATE OF DOCUMENT

5/12/76

DATE RECEIVED

5/18/76

☒ LETTER
☐ ORIGINAL
☒ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP.

INPUT FORM

NUMBER OF COPIES RECEIVED

NONE SIGNED

DESCRIPTION

LTR. TRANS THE FOLLOWING:

ENCLOSURE

LICENSEE EVENT RPT. (RO 50-220/76-18) ON
5/8/76 CONCERNING FISH IMPINGEMENT ON
TRAVELING SCREENS EXCEEDING ETS LIMITS.ACKNOWLEDGED
DO NOT REMOVE

PLANT NAME:

NINE MILE POINT #1

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO

5/19/76

RJL

<input checked="" type="checkbox"/>	BRANCH CHIEF:	LEAR		
	W/3 CYS FOR ACTION			
<input checked="" type="checkbox"/>	LIC. ASST:	PARRISH		
	W/ CYS			
	ACRS /6 CYS	HOLDING/SENT TO LA		

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/>	REG FILE				
<input checked="" type="checkbox"/>	NRC PDR				
<input checked="" type="checkbox"/>	I & E (2)				
<input checked="" type="checkbox"/>	MIPC (3)				
<input checked="" type="checkbox"/>	SCHROEDER/IPPOLITO				
<input checked="" type="checkbox"/>	HOUSTON				
<input checked="" type="checkbox"/>	NOVAK/CHECK				
<input checked="" type="checkbox"/>	GRIMES/SCHWENCER (1) EA				
<input checked="" type="checkbox"/>	CASE				
<input checked="" type="checkbox"/>	E. WILLIAMS				
<input checked="" type="checkbox"/>	HANAUER				
<input checked="" type="checkbox"/>	TEDESCO/MACCARY				
<input checked="" type="checkbox"/>	EISENHUT				
<input checked="" type="checkbox"/>	BAER				
<input checked="" type="checkbox"/>	SHAO				
<input checked="" type="checkbox"/>	VOLLMER/BUNCH				
<input checked="" type="checkbox"/>	KREGER/J. COLLINS				

EXTERNAL DISTRIBUTION

<input checked="" type="checkbox"/>	LPDR: OSWEGO, N.Y.				
<input checked="" type="checkbox"/>	TIC				
<input checked="" type="checkbox"/>	NSIC				

CONTROL NUMBER

5045

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944


NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

May 12, 1976

Regulatory Docket File



Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pa. 29406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Environmental Technical Specification 5.6.3.1, we hereby submit Licensee Event Report 76-18.

This report was completed within the intent of the Licensee Event Report Instruction Booklet OOE-SS-001, dated October 1974, revised December 24, 1974. Due to the minimal significance category of the report, no supplemental report is included.

Very truly yours,

Original Signed by R.R. Schneider

R. R. Schneider
Vice President -
Electric Operations

MCH/aih

Enc. 2 copies

cc: (20 copies) Director, Office of Inspection
and Enforcement.

(2 copies) Director, Office of Management Information
and Program Control

5045

50-220

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

INCIDENT REPORT

TO:

MR. JAMES P. O'REILLY

FROM:

NIAGARA MOHAWK POWER CORP.
SYRACUSE, NEW YORK
R. R. SCHNEIDER

DATE OF DOCUMENT

5/7/76

DATE RECEIVED

5/19/76

☒ LETTER☐ NOTORIZED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

☐ ORIGINAL
☒ COPY☒ UNCLASSIFIED

NONE SIGNED

DESCRIPTION

LTR. TRANS THE FOLLOWING:

PLANT NAME:

NINE MILE POINT #1

ENCLOSURE

LICENSEE EVENT RPT. (RO 50-220/76-17) ON
4/28/76 CONCERNING FISH BEING IMPINGED ON
TRAVELING SCREENS EXCEEDING ETS LIMIT.ACKNOWLEDGED
DO NOT REMOVENOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO

5/20/76

RJL

<input checked="" type="checkbox"/> BRANCH CHIEF:	LEAR		
<input checked="" type="checkbox"/> W/3 CYS FOR ACTION			
<input checked="" type="checkbox"/> LIC. ASST:	PARRISH		
<input checked="" type="checkbox"/> W/1 CYS			
<input checked="" type="checkbox"/> ACRS 16 CYS HOLDING/SENT TO LA			

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE			
<input checked="" type="checkbox"/> NRC PDR			
<input checked="" type="checkbox"/> I & E (2)			
<input checked="" type="checkbox"/> MIPC (3)			
<input checked="" type="checkbox"/> SCHROEDER/IPPOLITO			
<input checked="" type="checkbox"/> HOUSTON			
<input checked="" type="checkbox"/> NOVAK/CHECK			
<input checked="" type="checkbox"/> GRIMES/SCHWENCER (1) EA			
<input checked="" type="checkbox"/> CASE			
<input checked="" type="checkbox"/> F. WILLIAMS			
<input checked="" type="checkbox"/> HANAUER			
<input checked="" type="checkbox"/> TEDESCO/MACCARY			
<input checked="" type="checkbox"/> EISENHUT			
<input checked="" type="checkbox"/> BAER			
<input checked="" type="checkbox"/> SHAO			
<input checked="" type="checkbox"/> VOLIMER/BUNCH			
<input checked="" type="checkbox"/> KREGER/J. COLLINS			

EXTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> LPDR: OSWEGO, N.Y.			
<input checked="" type="checkbox"/> TIC			
<input checked="" type="checkbox"/> NSIC			

CONTROL NUMBER

5064

071712

071712

071712

071712 (071712-071712) 071712
071712 071712 071712 071712
071712 071712 071712 071712

071712 071712 071712 071712

071712 071712 071712 071712


071712

071712

071712


071712

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

May 7, 1976



Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pa. 29406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Environmental Technical Specification 5.6.3.1, we hereby submit Licensee Event Report 76-17.

This report was completed within the intent of the Licensee Event Report Instruction Booklet OOE-SS-001, dated October 1974, revised December 24, 1974. Due to the minimal significance category of the report, no supplemental report is included.

Very truly yours,

Original Signed by R.R. Schneider

R.R. Schneider
Vice President
Electric Operations

MCH/aih

Enc. 2 copies

cc: (20 copies) Director, Office of Inspection
and Enforcement

(2 copies) Director, Office of Management Information
and Program Control

5064



8800

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME: 01 N Y N M P 1 14 15 25 26 30 31 32

REPORT TYPE: 01 CONT 57 58 59 60 61 68 69 74 75 80

EVENT DESCRIPTION

02 During routine impingement sampling by contractor personnel (4/28-29/76) it was
03 found that the numbers of fish being impinged on the traveling screens exceeded
04 the ETS limit of 20,000/24 hr. period as per Sect. 3.1.2.a2
05 (See Attachment)
06 RO 76-17

SYSTEM CODE: 07 H F 10 11 12 17 43 44 47 48

CAUSE DESCRIPTION

08 There was no apparent cause for this occurrence that could be directly related to
09 changes in plant operations. The principal species impinged, alewives, rainbow
10 smelt migrate inshore annually at this time of year.

FACILITY STATUS: 11 F 9 10 12 13 44 45 46 80

PERSONNEL EXPOSURES: 13 0 0 0 11 12 13 80

PERSONNEL INJURIES: 14 0 0 0 11 12 80

OFFSITE CONSEQUENCES probable: 15 NONE 80

LOSS OR DAMAGE TO FACILITY: 16 Z 10 80

PUBLICITY: 17 N/A 80

ADDITIONAL FACTORS: 18 Contractor personnel remained on Site until numbers fell below 20,000/24 hr. as
19 per ETS. This occurred on 5/01/76.

IMPINGEMENT NUMBER

4/28-29/76	105,750
4/29-30/76	52,497
4/30-5/1/76	41,998
5/1-2/76	17,949

below ETS limit of 20,000/24 hr.

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

DATE OF DOCUMENT
4/28/76

DATE RECEIVED
5/4/76

NUMBER OF COPIES RECEIVED
NONE SIGNED

MR. JAMES P. O'REILLY

FROM:

NIAGARA MOHAWK POWER CORP.
SYRACUSE, N. Y.
R. R. SCHNETDER

PROP.

INPUT FORM

☒ LETTER
☐ NOTORIZED
☐ ORIGINAL
☒ UNCLASSIFIED
☐ COPY

DESCRIPTION

LTR. TRANS THE FOLLOWING:

ENCLOSURE

LICENSEE EVENT RPT. (RO 50-220/76-14) ON
4/19-20/76 AND 4/20-21/76) CONCERNING FISH
BEING IMPINGED ON TRAVELING SCREENS EXCEEDING
ETS LIMITS.
76-15 ON 4/23/76=IMPINGEMENT NUMBERS WERE
INCREASING & WOULD EXCEED ETS LIMIT.
76-16 ON 4/26/76 & 4/27/76=NUMBER OF FISH
BEING IMPINGED ON TRAVELING SCREENS EXCEEDING
ETS LIMIT.

ACKNOWLEDGED
DO NOT REMOVE

PLANT NAME:

NINE MILE PT. #1

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO 5/6/76 RJL

☒ BRANCH CHIEF: *LEAR*
W/3 CYS FOR ACTION
☒ LIC. ASST: *PARRISH*
W/ / CYS
ACRS /6 CYS HOLDING/SENT TO LA

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/>	REG FILE				
<input checked="" type="checkbox"/>	NRC PDR				
<input checked="" type="checkbox"/>	I & E (2)				
<input checked="" type="checkbox"/>	MIPC (3)				
<input checked="" type="checkbox"/>	SCHROEDER/IPPOLITO				
<input checked="" type="checkbox"/>	HOUSTON				
<input checked="" type="checkbox"/>	NOVAK/CHECK				
<input checked="" type="checkbox"/>	GRIMES/SCHWENGER				
<input checked="" type="checkbox"/>	CASE				
<input checked="" type="checkbox"/>	F. WILLIAMS				
<input checked="" type="checkbox"/>	HANAUER				
<input checked="" type="checkbox"/>	TEDESCO/MACCARY				
<input checked="" type="checkbox"/>	EISENHUT				
<input checked="" type="checkbox"/>	BAER				
<input checked="" type="checkbox"/>	SHAO				
<input checked="" type="checkbox"/>	VOLAMER/BUNCH				
<input checked="" type="checkbox"/>	KREGER/J. COLLINS				

EXTERNAL DISTRIBUTION

<input checked="" type="checkbox"/>	LPDR: OSWEGO, N.Y.				
<input checked="" type="checkbox"/>	TTC				
<input checked="" type="checkbox"/>	NSIC				

CONTROL NUMBER

4450

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	1	0	4									
7	8	9				14	15											26				30	31	32						

CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER						EVENT DATE						REPORT DATE															
01	CONT	M	I	T	L	050-0220						042076						042076															
7	8	57	58	59	60	61											69								75								80

EVENT DESCRIPTION

02 During routine impingement sampling by contractor personnel on 4/19-20/76 and 4/20-21/76

03 it was determined that the numbers of fish being impinged on the traveling screens

04 exceeded the ETS limits of 20,000/24 hr. period on per Sect. 3.1.2.a 2.

05 04/20/76-23,118 (90% alewives) - 04/21/76 - 40,614 (93% alewives)

06 RO-76-14

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	H F	F	Z Z Z Z Z Z				Z	Z 9 9 9				-			
7	8	9	10	11				17	43				47	48	

CAUSE DESCRIPTION

08 There was no apparent cause for this occurrence related to changes in plant operation.

09 The principal species impinged, alewives, rainbow smelt migrate for spawning annual

10 at this time of year.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION										
11	F	060				a												
7	8	9	10	12	13	44	45	46	80									

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE									
12	Z	Z		N/A				N/A									
7	8	9	10	11			44	45									80

PERSONNEL EXPOSURES

NUMBER			TYPE		DESCRIPTION	
13	0	0	0	Z	N/A	
7	8	9	11	12	13	80

PERSONNEL INJURIES

NUMBER			DESCRIPTION		
14	0	0	0	N/A	
7	8	9	11	12	80

OFFSITE CONSEQUENCES probable

15 NONE

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION		
16	Z	N/A		
7	8	9	10	80

PUBLICITY

17 N/A

ADDITIONAL FACTORS

18 Additional contractor personnel were dispatched to continue monitoring until numbers

19 fell below 20,000/24 hr. as per ETS.

NAME: M. Hedrick



315-343-2110

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

April 28, 1976



Regulatory Docket File

Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pa. 19406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Environmental Technical Specification 5.6.3.1, we hereby submit Licensee Event Reports 76-14, 76-15, and 76-16.

These reports were completed within the intent of the Licensee Event Report Instruction Booklet 00E-SS-002, dated October 1974, revised December 24, 1974. Due to the minimal significance category of the report, no supplemental report is included.

Very truly yours,

Original Signed by R. R. Schneider

R.R. Schneider
Vice President -
Electric Operations

MCH/aih

Enc. 2 copies

CC: (20 copies) Director, Office of Inspection & Enforcement
(2 copies) Director, Office of Management Information and Program Control

4450

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE										EVENT TYPE																																																																					
01 N Y N M P 1										15										4 1 1 1 1										0 4																																																																					
7 8 9										25										26										30																																																																					
01 CON'T										CATEGORY										REPORT TYPE										REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE																																							
01										M I										T										L										0 5 0 0 2 2 0										0 4 2 4 7 6										0 4 2 6 7 6																																							
7 8										57 58										59										60										61										68										69										74										75										80									

EVENT DESCRIPTION

02 During routine surveillance of fish impingement by offsite contractor personnel on																																																																															
03 4/23/76 it was found that impingement numbers were increasing and would exceed ETS																																																																															
04 limit of 20,000/hr. period. This limit was exceeded on 4/24-25/76. (ETS-Sect. 3.1.2.a2)																																																																															
05 04/24/76 - 80,156 (96% alewives) - 04/25/76 - 67,328 (97% alewives) RO 76-15																																																																															
06																																																																															

SYSTEM CODE										CAUSE CODE										COMPONENT CODE										PRIME COMPONENT SUPPLIER										COMPONENT MANUFACTURER										VIOLATION																													
07 H F										F										Z Z Z Z Z Z										Z										Z 9 9 9										-																													
7 8 9 10										11										12										17										43										44										47										48									

CAUSE DESCRIPTION

08 There was no apparent cause for this occurrence related to changes in plant																																																																															
09 operation. The principle species impinged, alewives and smelt migrate inshore																																																																															
10 for spawning annually at this time of year.																																																																															

FACILITY STATUS										% POWER										OTHER STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION																													
11 F										0 6 9										N/A										a										N/A																													
7 8										9										12 13										44										45										46										80									
FORM OF ACTIVITY RELEASED										CONTENT OF RELEASE										AMOUNT OF ACTIVITY										LOCATION OF RELEASE																																							
12 Z										Z										N/A										N/A																																							
7 8										9										10 11										44										45										80																			

PERSONNEL EXPOSURES

NUMBER										TYPE										DESCRIPTION									
13 0 0 0										Z										N/A									
7 8 9										11										12 13									

PERSONNEL INJURIES

NUMBER										DESCRIPTION									
14 0 0 0										N/A									
7 8 9										11 12									

RESULTS CONSEQUENCES Probable

15 NONE																																																																															
7 8 9																																																																															

LOSS OR DAMAGE TO FACILITY

TYPE										DESCRIPTION									
15 Z										N/A									
7 8 9										10									

PUBLICITY

17 N/A																																																																															
7 8 9																																																																															

ADDITIONAL FACTORS

18 Contractor personnel remained on site to monitor impingement until numbers fell																																																																															
below 20,000/24 hr. as per ETS.																																																																															
19																																																																															
7 8 9																																																																															

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE					EVENT TYPE				
0	1	N	Y	N	M P	1			-				-		4	1	1	1	1	0	4
7	8	9				14	15							25	26				30	31	32

01		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE											
7	8	M	I	T	L	0	5	0	-	0	2	2	0	0	4	2	7	7	6	0	4	2	8	7	6
CON'T		57	58	59	60	61					68	69					74	75					80		

EVENT DESCRIPTION

EVENT DESCRIPTION		
02	During routine impingement sampling by contractor personnel on 04/26/76 - 04/27/76	
03	the numbers of fish being impinged on the traveling screens exceeded ETS limit of	
04	20,000/24 hr. (Sect. 3.1.2 a 2).	
05	04/26-27/76 - 27,922 (94% alewives)	
05		RO 76-16

SYSTEM CODE		CAUSE CODE		COMPONENT CODE						PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOlation
07	H F	F		Z	Z	Z	Z	Z	Z	Z	9	9	9	-
7	8 9 10	11		12					17	43				48

CAUSE DESCRIPTION

02 | There was no apparent cause for this occurrence related to changes in plant operation.

7 8 9 | 80

09 | The principle species impinged alewives and rainbow smelt migrate inshore for spawn-

7 8 9 | 80

10 | ing at this time of year.

7 8 9 | 80

7 8		9		10 11 12			13 14 15			16 17		18 19 20		
		FACILITY STATUS		% POWER			OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		
1	1		F	0	7	8	N/A			a				
7	8	9		10	11	12	13	14	15	16	17	18	19	

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
1	2	3	N/A	N/A
7	8	9	10	11
45	80			

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
13	0	0	3	N/A

PERSONNEL INJURIES

NUMBER			DESCRIPTION
14	0	0	N/A

~~OFF SITE CONSEQUENCES~~

15 NONE 80

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
15	3		N/A

PUBLICITY

17	N/A
----	-----

ADDITIONAL FACTORS

Contractor personnel remained onsite to monitor impingement until numbers fell below

19 | 20,000/24 hr. as per ETS. | 80

NAME: M. Hedrick

PHONE: 315-343-2110 Ext. 1310⁸⁰

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORTTO: NRC
FROM: NIAGARA MOHAWK POWER CORP
SYRACUSE, NY
R R SCHNEIDERDATE OF DOCUMENT
3-3-76DATE RECEIVED
3-12-76☒ LETTER
☐ ORIGINAL
☒ COPY
☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

DESCRIPTION

LTR TRANS THE FOLLOWING.....

ACKNOWLEDGED
DO NOT REMOVE

PLANT NAME: NINE MILE PT.

ENCLOSURE

LICENSEE EVENT REPORTS:

50-220/76-02 ON 2-4-76 RE INTERPOLATION FROM
TECH SPEC CURVES WITHOUT GRID OR BREAKPOINTS..
50-220/76-03 ON 2-7-76 RE SET POINT DRIFT....
50-220-76-04 ON 2-7-76 RE SET POINT DRIFT....
50-220/76-05 ON 2-10-76 RE DETECTOR HAD FAIL-
ed.....
50-220/76-05 ON 2-15-76 RE LINKAGE ARM ON
MERCROID WAS DISCONNECTED FOR NO APPARENT
REASON.....

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO 3-17-76 *RIS*

BRANCH CHIEF:	LEAR
W/3 CYS FOR ACTION	
LIC. ASST:	PARRISH
W/ CYS	
ACRS CYS HOLDING/SENT TO LA	

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE				
<input checked="" type="checkbox"/> NRC PDR				
<input checked="" type="checkbox"/> I & E (2)				
<input checked="" type="checkbox"/> MIPC (3)				
<input checked="" type="checkbox"/> SCHROEDER/IPPOLITO				
<input checked="" type="checkbox"/> HOUSTON				
<input checked="" type="checkbox"/> NOVAK/CHECK				
<input checked="" type="checkbox"/> GRIMES/SCHWENCER				
<input checked="" type="checkbox"/> CASE				
<input checked="" type="checkbox"/> E. WILLIAMS				
<input checked="" type="checkbox"/> HANAUER				
<input checked="" type="checkbox"/> TEDESCO/MACCARY				
<input checked="" type="checkbox"/> EISENHUT				
<input checked="" type="checkbox"/> BAER				
<input checked="" type="checkbox"/> SHAO				
<input checked="" type="checkbox"/> VOLLMER/BUNCH				
<input checked="" type="checkbox"/> KREGER/J. COLLINS				

EXTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> LPDR: OSWEGO, NY				
<input checked="" type="checkbox"/> TIC				
<input checked="" type="checkbox"/> NSIC				

CONTROL NUMBER


2549



22 11


.....

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

March 3, 1976



Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pa. 29406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Report 76-02 through 76-06 which documents the Reportable Occurrences for February 1976.

This report conforms to the requirements of Regulatory Guide 1.16, Revision 2 and was completed within the intent of the Licensee Event Report Instruction Booklet 00E-SS-001, dated October 2974, revised December 24, 1974. Due to the minimal significance category of the report, no supplemental report is included.

Very truly yours,

Original signed by R.R. Schneider

R.R. Schneider
Vice President -
Electric Operations

TJD/mm

Enc. 3 copies

cc: K.R. Goller (30 copies)

2549

8123

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1										4	1	1	1	1	0	1								
7	8	9				14	15								25	26					30	31	32							

CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER						EVENT DATE				REPORT DATE									
01	CONT	M	1	L	L	0	5	0		0	2	2	0	0	2	0	4	7	6	0	3	0	3	7	6
7	8	57	58	59	60	61					68	69			74	75					80				

EVENT DESCRIPTION

02	Following a review it was discovered that the KW/FT vs Exposure curve points for																							80
03	MAPHLGR placed in the process computer for Type 5 Fuel (8x8) were in error by no																							80
04	more than .1 KW/FT nominal MAPHLGR limit 8.52 KW/FT																							80
05	RO 76-02																							80
06																								80

SYSTEM CODE				CAUSE CODE		COMPONENT CODE						PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER			VIOLATION	
07	Z	Z		A		Z	Z	Z	Z	Z	Z	N	Z	9	9	9	N	
7	8	9	10	11	12					17	43	44			47	48		

CAUSE DESCRIPTION

08	Interpolation from Technical Specification curves without grid or breakpoints.																							80
09																								80
10	RO 76-02																							80

FACILITY STATUS			% POWER			OTHER STATUS						METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
11	E		0	9	4							Z	Routine Review						
7	8	9	10	11	12	13					44	45	46				80		
FORM OF ACTIVITY RELEASED			CONTENT OF RELEASE			AMOUNT OF ACTIVITY						LOCATION OF RELEASE							
12	Z		Z			N/A						N/A							
7	8	9	10	11	12						44	45					80		

PERSONNEL EXPOSURES

NUMBER			TYPE		DESCRIPTION																			
13	0	0	0	Z	N/A																			
7	8	9	11	12	13																			80

PERSONNEL INJURIES

NUMBER			DESCRIPTION																				
14	0	0	0	N/A																			
7	8	9	11	12																			80

OFFSITE CONSEQUENCES Probable
 NONE

15																								80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																						
16	Z	NONE																						
7	8	9	10																					80

PUBLICITY

17	NONE																							80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	Due to the small error and the degree of conservatism present no hazard was presented																							80
19	to the General Public.																							80

NAME: T. Dente PHONE: 315-343-2110



LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE					EVENT TYPE							
0	1	N	Y	N	M	P	1			-					-			4	1	1	1	1	0	1
7	8	9					14	15								25	26				30	31	32	

CONT		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE						REPORT DATE													
0	1	M	1	L	L	0	5	0	-	0	2	2	0	0	2	0	7	7	6	0	3	0	3	7	6						
7	8	57	58	59	60	61							68	69										74	75						80

EVENT DESCRIPTION

02	During routine surveillance testing RE-04A, 'high drywell pressure indicator (1 of 4)	80
03	tripped at 3.35 psig rather than 3.5 \pm .053 psig.	80
04		80
05		80
06	RO 76-03	80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION		
0	7	I A	E	I	N	S	T	R	U	N	B	0	8	0	N
7	8	9	10	11	12				17	43	44				48

CAUSE DESCRIPTION

08	Set point drift. Redundant sensors operable therefore no hazard to general public.	80
09		80
10		80

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
11		E		090																				b																																																	
FACILITY STATUS				% POWER		OTHER STATUS																		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION																																															
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
12		Z		Z		N/A																		N/A		N/A																																															
FORM OF ACTIVITY RELEASED				CONTENT OF RELEASE		AMOUNT OF ACTIVITY																				LOCATION OF RELEASE																																															
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	3	0	0	0	Z N/A

PERSONNEL INJURIES

NUMBER				DESCRIPTION
1	4	0	0	N/A

OFFSITE CONSEQUENCES	probable
1	NONE

1	5	NONE
7	8	9

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
16	3		N/A

PUBLICITY

17	NONE	80
----	------	----

ADDITIONAL FACTORS

18	NONE	
7 8 9		80

19

NAME: T. Dente

315-343-2110
PHONE: _____



LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE										EVENT TYPE												
01	N	Y	N	M	P	1													4				1				1				1				0				1			
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40									

CATEGORY										REPORT TYPE										REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE																																
01	CON'T		M	I	L	L					0				5				0				0				2				2				0				0				2				0				7				6				0				3				0				3				7				6			
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40																																																	

EVENT DESCRIPTION

02	During surveillance testing found AE-18C, Reactor Lo-Lo-Lo level indicator,																																							80
03	actuated at 131" rather than 129.7" max.																																							80
04																																								80
05																																								80
06	R076-04																																							80

SYSTEM CODE										CAUSE CODE										COMPONENT CODE										PRIME COMPONENT SUPPLIER										COMPONENT MANUFACTURER										VIOLATION									
07	I	B					D					I	N	S	T	R	U					N					B	0	8	0					N																								
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40																										

CAUSE DESCRIPTION

08	Set point drift. Redundant components operable. No hazard presented to general																																							80
09	public.																																							80
10																																								80

FACILITY STATUS										% POWER										OTHER STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION									
11	E					0	9	0									b																																
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40																

FORM OF ACTIVITY RELEASED										CONTENT OF RELEASE										AMOUNT OF ACTIVITY										LOCATION OF RELEASE									
12	Z					Z	N/A																																
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40						

PERSONNEL EXPOSURES

NUMBER										TYPE										DESCRIPTION													
13	0	0	0					Z	N/A																								
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40

PERSONNEL INJURIES

NUMBER										DESCRIPTION																							
14	0	0	0					N/A																									
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40

OFF-SITE CONSEQUENCES Probable
NONE

15																																								80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE										DESCRIPTION																							
16	Z					N/A																											
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40

PUBLICITY

17	NONE																																							80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	NONE																																							80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																																								80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: T. Dente

PHONE: 315-343-2110

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1					-						4	1	1	1	1	0	1			
7	8	9				14	15										25	26				30	31	32		

CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER					EVENT DATE					REPORT DATE									
01	CONT	M	I	L	L	0	5	0	-	0	2	2	0	0	2	1	0	7	6	0	3	0	3	7	6
7	8			57	58	59	60	61					68	69					74	75				80	

EVENT DESCRIPTION

02	During Routine Surveillance, R015C, a refuel platform high range monitor/calibration																								
7	8	9																							
03	calibration indicated a response of 350 mr/hr rather than 800 mr/hr. No irradiated																								
7	8	9																							
04	fuel movement or cast handling was taking place. Therefore, no hazard was presented																								
7	8	9																							
05	to the General Public.																								
7	8	9																							
06	RO 76-05																								
7	8	9																							

SYSTEM CODE				CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	B	A	D	I	N	S	T	R	U	W	G	0	8	0	N			
7	8	9	10	11	12				17	43	44			47	48			

CAUSE DESCRIPTION

08	Detector has failed and has been replaced.																								
7	8	9																							
09	Part Number - 5481718																								
7	8	9																							
10																									
7	8	9																							

FACILITY STATUS			% POWER			OTHER STATUS					METHOD OF DISCOVERY		DISCOVERY DESCRIPTION									
11	E	0	9	0						b												
7	8	9	10	12	13					44	45	46										

FORM OF ACTIVITY RELEASED			CONTENT OF RELEASE			AMOUNT OF ACTIVITY					LOCATION OF RELEASE									
12	Z	Z	N/A																	
7	8	9	10	11					44	45										

PERSONNEL EXPOSURES

NUMBER			TYPE		DESCRIPTION																		
13	0	0	0	Z	N/A																		
7	8	9	11	12	13																		

PERSONNEL INJURIES

NUMBER			DESCRIPTION																					
14	0	0	0	N/A																				
7	8	9	11	12																				

OFF-SITE CONSEQUENCES

15	Probable NONE																								
7	8	9																							

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION																				
16	Z	N/A																					
7	8	9	10																				

PUBLICITY

17	NONE																								
7	8	9																							

ADDITIONAL FACTORS

18	NONE																								
7	8	9																							

19																									
7	8	9																							

NAME: T. Dente

315-343-2110
PHONE:



LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	1	0	1									
7	8	9				14	15										25	26					30	31	32					

CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER										EVENT DATE					REPORT DATE				
01	CON'T	M	I	L	L	0	5	0	-	0	2	2	0	0	2	1	5	7	6	0	3	0	3	7	6
7	8	57	58	59	60	61							68	69						74	75				80

EVENT DESCRIPTION

02	Loss of HPCI Component due to apparent failure of a pump suction pressure switch.																								80
03	Component is F12 F.W. pump, one of two HPCI used pumps.																								80
04																									80
05																									80
06	R076-06																								80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER					VIOLATION	
07	I	B	A	2	9	9	9	9	9	-	Z	9	9	9	9	N	
7	8	9	10	11	12				17	43	44				47	48	

CAUSE DESCRIPTION

08	Linkage arm on mercoid was disconnected for no apparent reason. Reconnected arm,																								80
09	switch tested properly. Redundent component operable.																								80
10																									80

FACILITY STATUS		% POWER		OTHER STATUS					METHOD OF DISCOVERY		DISCOVERY DESCRIPTION									
11	E	0	9	0						a										
7	8	9	10	12	13					44	45	46				80				
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY					LOCATION OF RELEASE											
12	Z	Z	N/A					N/A												
7	8	9	10	11					44	45			80							

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION												
13	0	0	0	Z	N/A											
7	8	9	11	12	13											80

PERSONNEL INJURIES

NUMBER		DESCRIPTION													
14	0	0	0	N/A											
7	8	9	11	12											80

OFFSITE CONSEQUENCES Probable

15	None																								80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION												
16	Z	N/A												
7	8	9	10											80

PUBLICITY

17	NONE																								80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	NONE																								80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																									80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: T. Dente

PHONE: 315-343-2110



25

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 1289

FILE: INCIDENT FILE

FROM: Niagara Mohawk Power Corp. Syracuse, N.Y. R.R. Schneider			DATE OF DOC 2-3-76	DATE REC'D 2-9-76	LTR XXX	TWX	RPT	OTHER
TO: J.P.O'Reilly			ORIG None	CC 30	OTHER	SENT NRC PDR <u>XXX</u> SENT LOCAL PDR <u>XXX</u>		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 30		DOCKET NO: 50-220		

DESCRIPTION:
Letter trans the following.....

ENCLOSURES:
Reportable Occurrence # 76-01, on 1-17-76,
Concerning Setpoint drift in the conservative
direction.....

(1 Copy Received)

ACKNOWLEDGED

PLANT NAME: Nine Mile Pt # 1

DO NOT REMOVE

FOR ACTION/INFORMATION

SAB 2-10-76

BRANCH CHIEF Lear W/3

LIC. ASST. K. Parrish W/16 cys ACRS

INTERNAL DISTRIBUTION

REG FILE

NRC PDR
ISE (2)
MIPC (3)
SCHRODER/IPPOLITO
HOUSTON
NOVAK/CHECK
GRIMES/SCHWENCER
CASE
F. WILLIAMS
HANAUER
TEDESCO/MACCARY
EISENHUT
BAER
SHAO

VOLLMER/BUNCH
KREGER/J. COLLINS

NOTE: IF PERSONEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

LOCAL PDR Oswego, N.Y.
TIC
NSIC

DISTRIBUTION REVISED 1-19-76 by D. CRUTCHFIELD, TECH REVIEW COORDINATOR



LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME								LICENSE NUMBER								LICENSE TYPE					EVENT TYPE			
01	N	Y	N	M	P	1				-								4	1	1	1	1	0	4
7	8	9				14	15								25	26					30	31	32	

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE				REPORT DATE												
01	CON'T	M	I	T	L	0	5	0	-	0	2	2	0	0	5	0	8	7	6	0	5	1	1	7	6	
7	8	57	58	59	60	61							68	69						74	75					80

EVENT DESCRIPTION.

02	Fish impingement on traveling screens was determined to be in excess of 20,000/24 hr.	80
03	on 05/03-04/76. This situation continued until 05/07-08/76. The numbers on these	80
04	dates exceeded ETS limits. (Sect. 3!1.2.a2)	80
05	See attachment.	80
06		80
	PRIME	80

7 8 9 SYSTEM CODE CAUSE CODE COMPONENT CODE PRIME COMPONENT SUPPLIER COMPONENT MANUFACTURER VIOLATION

07 H F F Z Z Z Z Z Z 9 9 9 -

7 8 9 10 11 12 17 43 44 47 48

CAUSE DESCRIPTION

08	There was no apparent cause for this occurrence related to changes in plant operation.	80
09	The influx of the principle species (alewives, rainbow smelt) occurs annually at this	80
10	time of year.	80

11	F	% POWER	089	OTHER STATUS	N/A	METHOD OF DISCOVERY	a	DISCOVERY DESCRIPTION	
7 8	9	10	12	13	44	45	46	80	
12	Z	FORM OF ACTIVITY RELEASED	Z	CONTENT OF RELEASE	N/A	AMOUNT OF ACTIVITY	N/A	LOCATION OF RELEASE	
7 8	9	10	11	44	45			80	

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
13	0	0	2	N/A

PERSONNEL INJURIES

NUMBER			DESCRIPTION
14	0	0	N/A

QUESTIONS CONSEQUENCES probable
NONE

15	NONE												
7	8	9											80

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
16	Z		N/A

PUBLICITY

17	N/A
----	-----

ADDITIONAL FACTORS

18 Contractor personnel continued sampling until numbers fell below 20,000/24 hr. as per

19 ETS. 789 80

NAME.

M. Hedrick

315-343-2110 Ext. 1310

IMPINGEMENT NUMBERS

5/3-4/76	1000-1000	298,079
5/4-5/76	1000-1000	97,617
5/5-6/76	1000-1000	91,156
5/6-7/76	1000-1000	28,311
5/7-8/76	1000-1000	11,637

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

February 3, 1976

Regulatory

File Cr.

Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pa. 19406


RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1
Technical Specification 6.9, we hereby submit Licensee Event Report
76-01 which documents the Reportable Occurrences for January 1976.

This report conforms to the requirements of Regulatory
Guide 1.16, Revision 2 and was completed within the intent of the
Licensee Event Report Instruction Booklet 00E-SS-001, dated
October 1974, revised December 24, 1974. Due to the minimal
significance category of the report, no supplemental report is
included.

Very truly yours,


R.R. Schneider
Vice President -
Electric Operations

TJD/mm

Enc. 3 copies

cc: K.R. Goller (30 copies)



LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME														LICENSE NUMBER												LICENSE TYPE				EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	1	0	1										
7	8	9				14	15							25	26					30	31	32									

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE												
01	CON'T	M	I	L	L	0	5	0	0	2	2	0	0	1	1	7	7	6	0	2	0	3	7	6
7	8	57	58	59	60	61						68	69					74	75					80

EVENT DESCRIPTION

02	During routine surveillance testing, RV-30 A&B Core Spray ΔP Instrumentation																							80
03	indicated out of the normal range at 2.8 psid and 3.5 psid respectively 5±1 psid																							80
04	required. This instrument is alarm only and serves no automatic initiation. Drift																							80
05	was in conservative direction and safety and health of general public was not in																							80
06	jeopardy. RO 76-1																							80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION		
07	I	B	E	I	N	S	T	R	U	N	B	0	8	0	N	
7	8	9	10	11	12	13	14	15	16	17	43	44	45	46	47	48

CAUSE DESCRIPTION

08	Set point drift in the conservative direction. Normal surveillance appears able																							80
09	to detect at the established frequency of surveillance.																							80
10																								80

FACILITY STATUS		% POWER		OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION			
11	E	0	9	4				b					
7	8	9	10	11	12	13	14	44	45	46		80	

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE			
12	Z	Z	N/A								
7	8	9	10	11	12	13	14	44	45		80

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION		
13	0	0	0	Z	N/A	
7	8	9	10	11	12	13

PERSONNEL INJURIES

NUMBER		DESCRIPTION			
14	0	0	0	N/A	
7	8	9	10	11	12

XXXXXX CONSEQUENCES Probable

15	None																							80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION	
16	Z	N/A	
7	8	9	10

PUBLICITY

17	N/A																							80
----	-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	N/A																							80
----	-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																								80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: T.J. Dente

PHONE: 315 343-2110



NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 242

FILE: INCIDENT REPORT FI

FROM: Niagara Mohawk Power Corp. Syracuse, N.Y. R.R. Schneider		DATE OF DOC 1-8-76	DATE REC'D 1-12-76	LTR XXX	TWX	RPT	OTHER
TO: J.P.O'Reilly		ORIG None	CC 30	OTHER	SENT AEC PDR XXX		XXX
CLASS XXX		UNCLASS	PROP INFO	INPUT	NO CYS REC'D 30		DOCKET NO: 50-220

DESCRIPTION:
Letter trans the following.....

ENCLOSURES:
Abnormal Occurrence # 75-38, on 12-12-76,
Concerning #.11 IRM 's failure to respond...
Abnormal Occurrence # 75-38, on 12-12-76;
Concerning RE-04C tripping...
(30 Cys. Received)

PLANT NAME: Nine Mile Pt. # 1

FOR ACTION/INFORMATION

SAB 1-13-76

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	REID W/ Copies

DO NOT REMOVE
ACKNOWLEDGED

INTERNAL DISTRIBUTION

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE {3} STEELE	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	<u>DENTON</u> **GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC ASST</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	<u>A/T IND.</u> BRAITMAN SALTZMAN MELTZ <u>PLANS</u> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
--	--	--	---	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR Oswego, N.Y.	1 - TIC (ABERNATHY) (1)(2)(10)	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - NSIC (BUCHANAN)	1 - ASLB	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - Newton Anderson	1 - CONSULTANTS	NEWMARK/BLUME/AGBABIAN	1 - G. ULRIKSON, ORNL
16 - ACRS SENT TO LIC ASST S. Teets	** SEND ONLY TEN DAY REPORTS		1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
			1 - J. D. RUNKLES, Rm E-201 GT

... ..


NIAGARA MOHAWK POWER CORPORATION

Regulatory

File C-1

NIAGARA  MOHAWK

300 Erie Boulevard, West
Syracuse, New York 13202



Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pa. 19406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Reports 75-37 and 75-38 which document the Abnormal Occurrences for the month of December 1975.

These reports conform to the requirements of Regulatory Guide 1.16, Rev. 2 and were completed within the intent of the Licensee Event Report Instruction Booklet 00E-SS-001, dated October 1974 and revised December 24, 1974.

Very truly yours,

R.R. Schneider
Vice President - Electric Operations

TJD/mm

Enc. (3 copies)

cc: K.R. Goller (30 copies)



LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME														LICENSE NUMBER												LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	1	0	1											
7	8	9				14	15								25	26				30	31	32										

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE					REPORT DATE										
01	CONT	M	I	L	L	0	5	0	0	2	2	0	1	2	0	3	7	5	10	1	0	7	7	6
7	8	57	58	59	60	61						68	69					74	75					80

EVENT DESCRIPTION

02	During plant startup, #11 IRM failed to respond. Remaining channels of IRM																						
03	were determined to be operable, therefore, startup continued.																						
04																							
05																							
06	AOR 75-37																						

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER			VIOLATION	
07	I	E	E	I	N	S	T	R	U	N	G	0	8	0	N
7	8	9	10	11	12				17	43	44			47	48

CAUSE DESCRIPTION

08	Subsequent checks of the detector showed low resistance. Further investigation																						
09	will be performed next drywell entry.																						
10																							

FACILITY STATUS		% POWER			OTHER STATUS					METHOD OF DISCOVERY		DISCOVERY DESCRIPTION												
11	H	0	0	0						b														
7	8	9	10	11	12	13				44	45	46												80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY										LOCATION OF RELEASE										
12	Z	Z																						
7	8	9	10	11	12																			80

PERSONNEL EXPOSURES													
NUMBER			TYPE		DESCRIPTION								
13	0	0	0			N/A							
7	8	9	10	11	12	13							

PERSONNEL INJURIES													
NUMBER			DESCRIPTION										
14	0	0	0	N/A									
7	8	9	10	11	12								

CONSEQUENCES Probable

15	None																						
7	8	9																					

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																					
16	Z	N/A																					
7	8	9																					

PUBLICITY

17	None																						
7	8	9																					

ADDITIONAL FACTORS

18	None																						
7	8	9																					

19																							
7	8	9																					

NAME: T.J. Dente

PHONE: (315) 343-2110



LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

<p>LICENSEE NAME</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 01 N Y N M P 1 </div> <p style="font-size: small;">7 8 9 14 15 25</p>	<p>LICENSE NUMBER</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> - - </div> <p style="font-size: small;">26 30</p>	<p>LICENSE TYPE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 4 1 1 1 1 </div> <p style="font-size: small;">31 32</p>
--	---	---

<p>01 CONT</p> <p style="font-size: small;">7 8</p>	<p>CATEGORY</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> M I </div> <p style="font-size: small;">57 58</p>	<p>REPORT TYPE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> L </div> <p style="font-size: small;">59</p>	<p>REPORT SOURCE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> L </div> <p style="font-size: small;">60</p>	<p>DOCKET NUMBER</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 0 5 0 - 0 2 2 0 </div> <p style="font-size: small;">61 68</p>	<p>EVENT DATE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 1 2 1 2 7 5 </div> <p style="font-size: small;">69 74</p>	<p>REPORT DATE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 0 1 0 7 7 5 </div> <p style="font-size: small;">75 80</p>
---	---	--	--	---	--	---

EVENT DESCRIPTION

02 During routine surveillance testing, RE-04C indicated a trip at 3.25 psig rather

03 than 3.5 ± .053 psig.

04

05

06 AOR 75-38

7 8 9 80

<p>07</p> <p style="font-size: small;">7 8 9 10</p>	<p>SYSTEM CODE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> I A </div> <p style="font-size: small;">11</p>	<p>CAUSE CODE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> E </div> <p style="font-size: small;">12</p>	<p>COMPONENT CODE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> I N S T R U </div> <p style="font-size: small;">17</p>	<p>PRIME COMPONENT SUPPLIER</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> N </div> <p style="font-size: small;">43</p>	<p>COMPONENT MANUFACTURER</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> B 0 8 0 </div> <p style="font-size: small;">44 47</p>	<p>VIOLATION</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> N </div> <p style="font-size: small;">48</p>
---	---	---	---	---	--	--

CAUSE DESCRIPTION

08 Could find no apparent reason for the drift, however, routine surveillance is

09 sufficient to locate these problems.

10

7 8 9 80

<p>11</p> <p style="font-size: small;">7 8 9</p>	<p>FACILITY STATUS</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> E </div> <p style="font-size: small;">10</p>	<p>% POWER</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 0 5 0 </div> <p style="font-size: small;">12 13</p>	<p>OTHER STATUS</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> </div> <p style="font-size: small;">44</p>	<p>METHOD OF DISCOVERY</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> b </div> <p style="font-size: small;">45 46</p>	<p>DISCOVERY DESCRIPTION</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> </div> <p style="font-size: small;">80</p>
--	--	---	--	---	---

<p>12</p> <p style="font-size: small;">7 8 9</p>	<p>FORM OF ACTIVITY RELEASED</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> Z </div> <p style="font-size: small;">10</p>	<p>CONTENT OF RELEASE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> Z </div> <p style="font-size: small;">11</p>	<p>AMOUNT OF ACTIVITY</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> </div> <p style="font-size: small;">44 45</p>	<p>LOCATION OF RELEASE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> </div> <p style="font-size: small;">80</p>
--	--	---	---	---

PERSONNEL EXPOSURES

<p>13</p> <p style="font-size: small;">7 8 9</p>	<p>NUMBER</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 0 0 0 </div> <p style="font-size: small;">11</p>	<p>TYPE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> Z </div> <p style="font-size: small;">12</p>	<p>DESCRIPTION</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> </div> <p style="font-size: small;">13 80</p>
--	---	---	--

PERSONNEL INJURIES

<p>14</p> <p style="font-size: small;">7 8 9</p>	<p>NUMBER</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 0 0 0 </div> <p style="font-size: small;">11 12</p>	<p>DESCRIPTION</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> </div> <p style="font-size: small;">80</p>
--	--	---

OFFENSE CONSEQUENCES Probable

<p>15</p> <p style="font-size: small;">7 8 9</p>	<p>None</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> </div> <p style="font-size: small;">80</p>
--	--

LOSS OR DAMAGE TO FACILITY

<p>16</p> <p style="font-size: small;">7 8 9</p>	<p>TYPE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> Z </div> <p style="font-size: small;">10</p>	<p>DESCRIPTION</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> </div> <p style="font-size: small;">80</p>
--	---	---

PUBLICITY

<p>17</p> <p style="font-size: small;">7 8 9</p>	<p>None</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> </div> <p style="font-size: small;">80</p>
--	--


ADDITIONAL FACTORS

<p>18</p> <p style="font-size: small;">7 8 9</p>	<p>None</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> </div> <p style="font-size: small;">80</p>
--	--

<p>19</p> <p style="font-size: small;">7 8 9</p>	<p></p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> </div> <p style="font-size: small;">80</p>
--	--

NAME: T.J. Dente

PHONE: (315) 343-2110



NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 14351

FILE: INCIDENT REPORT FILE

FROM: Niagara Mohawk Pwr Corp Syracuse, NY R R Schneider			DATE OF DOC 12-17-75	DATE REC'D 12-31-75	LTR XXX	TWX	RPT	OTHER
TO: Mr O'Reilly			ORIG one signed	CC	OTHER	SENT AEC PDR <u>xx</u> SENT LOCAL PDR <u>xx</u>		
CLASS	UNCLASS XXXXX	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-220		

DESCRIPTION:
Ltr trans the following:

ACKNOWLEDGED

PLANT NAME: Nine Mile Point

ENCLOSURES:
Licensee Event Rpt 75-33A on 11-21-75 concerning tripping of the high drywell pressure sensor.....

FOR ACTION/INFORMATION 1-6-76 ehf

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	REID W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE {3} STEELE	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	<u>DENTON</u> **GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC ASST</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	<u>A/T IND.</u> BRAITMAN SALTZMAN MELTZ <u>PLANS</u> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
--	--	--	---	--

EXTERNAL DISTRIBUTION K. PARRISH (L)

1 - LOCAL PDR <u>Dsweso, NY</u>	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
16 - ACRS SENT TO LIC ASST <u>Teets</u>		
** SEND ONLY TEN DAY REPORTS		



.....

33

.....


NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

December 17, 1975

Mr. James P. O'Reilly
Directorate of Regulatory Operations
Region I
United States Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406




RE: Docket No. 50-220


Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Report 75-33A.

This report conforms to the requirements of Regulatory Guide 1.16, Revision 2 and was completed within the intent of the Licensee Event Report instruction book 00E-SS-001, dated October, 1974, revised December 24, 1974. Due to the minimal significance category of the report, no supplemental report is included.

Very truly yours,


R.R. Schneider
Vice President
Electric Operations



TJD/mm

Enc. 3 copies

cc: 30 copies to Mr. K.R. Goller

14351

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE				EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	1	0	1								
7	8	9				14	15										25	26					30	31	32				

CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER						EVENT DATE				REPORT DATE									
01	CONT	M	I	L	L	0	5	0	-	0	2	2	0	1	1	2	1	7	5	1	2	1	7	7	5
7	8			57	58	59	60	61					68	69					74	75					80

EVENT DESCRIPTION

02	During routine surveillance testing, RE-04D, high drywell pressure sensor (1 of 4)																							80
03	was found to trip at 3.4 psi rather than 3.5 ± .053 psi. The device is a Barton																							80
04	Model #289.																							80
05																								80
06	AOR 75-33A																							80

SYSTEM CODE				CAUSE CODE		COMPONENT CODE						PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	I	A	E	I	N	S	T	R	U	N	B	0	8	0	N				
7	8	9	10	11	12				17	43	44			47	48				

CAUSE DESCRIPTION

08	Could find no apparent reason for the .047 psi drift, however, routine surveillance																							80
09	is sufficient to locate these drifting problems.																							80
10																								80

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION									
11	H	0	0	0	b															
7	8	9	10	12	13	44	45	46	80											

FORM OF ACTIVITY RELEASED			CONTENT OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE									
12	Z	Z	N/A															
7	8	9	10	11	44	45	80											

PERSONNEL EXPOSURES

NUMBER			TYPE		DESCRIPTION										
13	0	0	0	Z	N/A										
7	8	9	11	12	13	80									

PERSONNEL INJURIES

NUMBER			DESCRIPTION											
14	0	0	0	N/A										
7	8	9	11	12	80									

~~XXXXXX~~ CONSEQUENCES Probable

15	None - Drift in more conservative direction																							80
----	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION										
16	Z	N/A											
7	8	9	10	80									

PUBLICITY

17	None																							80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	None																							80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																								80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: T.J. Dente

PHONE: 315 - 343-2110

RECEIVED
U.S.N.R.C.
DEC 24 1975
KING OF PRUSSIA, PA.

**NRC CONTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 14076

FILE: INCIDENT REPORT FI

FROM: Niagara Mohawk Power Corp. Syracuse, N.Y. R.R. Schneider		DATE OF DOC 12-17-75	DATE REC'D 12-24-75	LTR XXX	TWX	RPT	OTHER
TO: J.P. O'Reilly		ORIG None	CC 30	OTHER	SENT AEC PDR XXX SENT LOCAL PDR XXX		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 30	DOCKET NO: 50-220		

DESCRIPTION: Letter trans the following.....	ENCLOSURES: Licensee Event Report # 75-33 A, on 11-21-75, Concerning the high drywell pressure sensor tripping (30 Cys. Received)
---	---

PLANT NAME: Nine Mile Pt. # 1

FOR ACTION/INFORMATION

SAB 12-29-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	REID W/ Copies

**DO NOT REMOVE
ACKNOWLEDGED**

INTERNAL DISTRIBUTION

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	<u>DENTON</u> **GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC ASST</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	<u>A/T IND.</u> BRAITMAN SALTZMAN MELTZ <u>PLANS</u> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
--	--	--	---	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR Oswego, N.Y.	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRICKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson	S. Teets	1 - J. D. RUNKLES, Rm E-201 GT
16 ACRS SENT TO LIC ASST		
** SEND ONLY TEN DAY REPORTS		

DO NOT REMOVE
UNCLASSIFIED

NIAGARA MOHAWK POWER CORPORATION


NIAGARA MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

Regulatory

File 57

December 17, 1975



Mr. James P. O'Reilly
Directorate of Regulatory Operations
Region 1
United States Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1
Technical Specification 6.9, we hereby submit Licensee Event Report
75-33A.

This report conforms to the requirements of Regulatory Guide
1.16, Revision 2 and was completed within the intent of the Licensee
Event Report instruction book 00E-SS-001, dated October, 1974,
revised December 24, 1974. Due to the minimal significance category
of the report, no supplemental report is included.

Very truly yours,

ORIGINAL SIGNED BY R.R. SCHNEIDER

R.R. Schneider
Vice President
Electric Operations

TJD/mm

Enc. 3 copies

cc: 30 copies to Mr. K.R. Goller

14076

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE					EVENT TYPE						
0	1	N	Y	N	M			-					-			4	1	1	1	1	0	1	
7	8	9			14	15									25	26					30	31	32

01		CONT		CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER						EVENT DATE						REPORT DATE					
7	8	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80		
		M	I	L	KL	0	5	0	-	0	2	2	0	1	1	2	1	7	5	1	2	1	7	7	5		

EVENT DESCRIPTION

02	During routine surveillance testing, RE-04D, high drywell pressure sensor (1 of 4)	80
03	was found to trip at 3.4 psi rather than 3.5 ± .053 psi. The device is a Barton	80
04	Model #289.	80
05		80
06	AOR 75-33A	80

8 9 SYSTEM CODE CAUSE CODE COMPONENT CODE PRIME COMPONENT SUPPLIER COMPONENT MANUFACTURER VIOLATION

07 I A E I N S T R U N B 0 8 0 N

7 8 9 10 11 12 17 43 44 47 48

CAUSE DESCRIPTION

09	Could find no apparent reason for the .047 psi drift, however, routine surveillance	
09	is sufficient to locate these drifting problems.	80
10		80
		80

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	1	H	0	0	0		b			
7	8	9	10	11	12	13	44	45	46	80
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY			LOCATION OF RELEASE			
1	2	Z	Z	N/A						
7	8	9	10	11	44	45				80

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
13	0	0	0	Z N/A

PERSONNEL INJURIES

NUMBER			DESCRIPTION	
14	0	0	0	N/A

~~XXXXXX~~ CONSEQUENCES Probable

15	None - Drift in more conservative direction
----	---

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
15	Z	N/A

PUBLICITY

17	None
----	------

ADDITIONAL FACTORS

18	None
----	------

19

NAME: T.J. Dente

PHONE. 315 - 343-2110

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 13949

FILE: INCIDENT REPORT FI

FROM: NIAGARA MOHAWK POWER CORP. Syracuse, N.Y. R. R. Schneider			DATE OF DOC 12-5-75	DATE REC'D 12-16-75	LTR XXX	TWX	RPT	OTHER
TO: H.P. O'Reilly			ORIG None	CC 30	OTHER	SENT AEC PDR XXX SENT LOCAL PDR XXX		
CLASS	UNCLASS	PROP INFO	INPUT	NO CYS REC'D 30		DOCKET NO: 50-220		
XXX-								

DESCRIPTION:
Letter trans the following.....

ENCLOSURES:
A/O # 75-31, on 11-14-75, Concerning mis-adjustment on both Emergency Vent Radiation m monitors
A/O # 75-32, on 11-17-75, Concerning water being inadvertently discharged to the lake...
A/O # 75-33, on 11-21-75, Concerning # 13 SRM Failed to signal...
A/O # 75-34, on 11-22-75, Concerning 68-12A Torus Vacuum Relief Valve operating beyond normal setpoint deviation...

PLANT NAME: Nine Mile Pt # 1

FOR ACTION/INFORMATION

SAB 12-17-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	PEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	REID W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC ASST</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	<u>A/T IND.</u> BRAITMAN SALTZMAN MELTZ <u>PLANS</u> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	--	--	---	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR Oswego, N.Y.	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
16 ACRS SENT TO LIC ASST	S. Teets	
** SEND ONLY TEN DAY REPORTS		

SECRET

REF ID: A66272

SECRET

SECRET
REF ID: A66272
SECRET

SECRET

SECRET

A/O 75-35, on 11-29-75, Concerning the chlorides increasing.....

A/O 75-36, on 11-29-75, Concerning Leakage of water, around the CleanUp System area.....

(30 Cys. Received)

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

Regulatory

File Cy

December 5, 1975

Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, Pa. 19406


RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Reports 75-31 through 75-36 which document the Abnormal Occurrences for the month of November 1975.

These reports conform to the requirements of Regulatory Guide 1.16, Revision 2 and were completed within the intent of the Licensee Event Report Instruction Booklet 00E-SS-001, dated October 1974, and revised December 24, 1974.


Very truly yours,


R.R. Schneider
Vice President
Electric Operations

TJD/mm

Enc. 3 copies

cc: Mr. K.R. Goller (30 copies)



13949

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	1	0	1									
7	8	9				14	15								25	26			30	31	32									

CATEGORY			REPORT TYPE		REPORT SOURCE		DOCKET NUMBER						EVENT DATE					REPORT DATE								
01	CONT		D	I	T	L	0	5	0	-	0	2	2	0	1	1	1	4	7	5	1	1	1	7	7	5
7	8		57	58	59	60	61					68	69		74	75										80

EVENT DESCRIPTION

02	Upscale trip points on both Emergency Vent Radiation monitors found to trip at																			80
03	20 and 30 mr/hr rather than 5 mr/hr + 100% - 50%.																			80
04																				80
05																				80
06	AOR 75-31																			80

SYSTEM CODE			CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	I	B	E	-	I	N	S	T	R	U	N	G	0	8	0	N	
7	8	9	10	11	12					17	43	44		47		48	

CAUSE DESCRIPTION

08	The investigation revealed no reason for the mis-adjustment. These instruments																			80
09	will be carefully monitored during subsequent checks.																			80
10																				80

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
11	H	0	0	0	N/A										
7	8	9	10	12	13			44	45	46				80	

FORM OF ACTIVITY RELEASED			CONTENT OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE				
12	Z	Z	N/A										
7	8	9	10	11			44	45				80	

PERSONNEL EXPOSURES

NUMBER			TYPE		DESCRIPTION	
13	0	0	0	Z	N/A	
7	8	9	11	12	13	

PERSONNEL INJURIES

NUMBER			DESCRIPTION	
14	0	0	0	N/A
7	8	9	11	12

EXISTING CONSEQUENCES Probable

15	None																			80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION																
16	Z	N/A																	
7	8	9	10																

PUBLICITY

17	None																			80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	None																			80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																				80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: T.J. Dente

PHONE: (315) 343-2110

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE										EVENT TYPE									
01		N		Y		N		M		P		1		15		-		-		4		1		1		1		1		0		1							
7	8	9																																					

CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER										EVENT DATE										REPORT DATE																									
01		CONT		M		I		L		L		0		5		0		-		0		2		2		0		1		1		1		7		7		5		1		1		3		0		7		5	
7	8																																																		

EVENT DESCRIPTION

02		An acid leak was experienced in the Make-Up Demin. acid storage tank. During																																																																																80	
03		neutralizing, the make-up demin. regen. waste tank, the discharge valve to the																																																																																80	
04		lake (BV 69-05) was found partically opened and resulted in approx. 16,000 gals																																																																																80	
05		of (ph~12.4 and high SO ₄ content) water being inadvertantly discharged to the																																																																																80	
06		lake. AOR 75-32																																																																																80	

SYSTEM CODE		CAUSE CODE		COMPONENT CODE										PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER										VIOLATION			
07		Z		Z		Z		Z		Z		Z		Z		Z		Z		Z		Z		Z		N			
7	8	9																											

CAUSE DESCRIPTION

08		Valve was repaired and should not allow this incident to occur.																																																																																80	
09																																																																																		80	
10																																																																																		80	

FACILITY STATUS		% POWER										OTHER STATUS										METHOD OF DISCOVERY		DISCOVERY DESCRIPTION									
11		H		0		0		0		12		13		44		45		46		80													
7	8	9																															

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY										LOCATION OF RELEASE									
12		Z		Z		N/A		44		45		80											
7	8	9																					

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION											
13		0		0		0		11		12		13		80	
7	8	9													

PERSONNEL INJURIES

NUMBER		DESCRIPTION											
14		0		0		0		11		12		80	
7	8	9											

OFFSITE CONSEQUENCES Probable

15		None																																																																																80	
7	8	9																																																																																	

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION									
16		Z		N/A		10		80			
7	8	9									

PUBLICITY

17		None																																																																																80	
7	8	9																																																																																	

ADDITIONAL FACTORS

18		None																																																																																80	
7	8	9																																																																																	

19																																																																																		80	
7	8	9																																																																																	

NAME: T.J. Dente

PHONE: (315) 343-2110

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER											LICENSE TYPE				EVENT TYPE	
01	N	Y	N	M	P	1	-								4	1	1	1	0	3										
7	8	9				14	15							25	26			30	31	32										
CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER								EVENT DATE				REPORT DATE												
01	CONT	M	I	L	L	0	5	0	-	0	2	2	0	1	1	2	1	7	5	1	2	0	3	7	5					
7	8		57	58	59	60	61					68	69					74	75					80						

EVENT DESCRIPTION

02	During reactor shutdown, #13 SRM failed to provide an adequate signal to the																			80
03	monitor. Indication was downscale. Bypass was available for the system and																			80
04	three SRM's were operable.																			80
05																				80
06	AOR-75-33																			80

SYSTEM CODE				CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	I	E	E	I	N	S	T	R	U	N	G	O	8	0	N		
7	8	9	10	11	12				17	43	44			47	48		

CAUSE DESCRIPTION

08	Failed capacitor in the pre-amplifier unit.																			80
09																				80
10																				80

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
11	H	0	0	0				A						
7	8	9	10	11	12	13		44	45	46				80
FORM OF ACTIVITY RELEASED			CONTENT OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE					
12	Z	Z	N/A			N/A								
7	8	9	10	11				44	45			80		

PERSONNEL EXPOSURES

NUMBER			TYPE		DESCRIPTION	
13	0	0	0	Z	N/A	
7	8	9	11	12	13	80

PERSONNEL INJURIES

NUMBER			DESCRIPTION	
14	0	0	0	N/A
7	8	9	11	12

PRESENT CONSEQUENCES Probable

15	None																			80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																		
16	Z	N/A																		
7	8	9	10																	80

PUBLICITY

17	None																			80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	None																			80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																				80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: T.J. Dente

PHONE: (315) 343-2110

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1			-						-		4	1	1	1	1	0	1			
7	8	9				14	15									25	26				30	31	32			

CON'T		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE					REPORT DATE								
01		M	I	L	L	0	5	0	-	0	2	2	0	1	1	2	2	7	5	1	2	0	3	7	5
7	8	57	58	59	60	61							68	69					74	75					80

EVENT DESCRIPTION

02	During surveillance testing, found 68-12A Torus Vacuum Relief Valve to operate	
7 8 9		80
03	at 3.5" H ₂ O rather than 6.8" H ₂ O (more conservative but beyond normal set point	
7 8 9		80
04	deviation). Other valves operated satisfactorily (Serial #P064756)	
7 8 9		80
05		
7 8 9		80
06		AOR 75-34
7 8 9		80
	PREME	

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					SUPPLIER	COMPONENT MANUFACTURER				VIOLATION
07	I E	E	I	N	S	T	R	U	N	M	2	3	5	N
7	8 9 10	11	12	17					43	44	47			48

CAUSE DESCRIPTION

08	Recalibrated to acceptable values - set point drift.	80
09		80
10		80

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	H	0	0	0			B			

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	2	Z		N/A		N/A	
7	8	9	10	11	44	45	80

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
13	0	0	0	Z N/A

PERSONNEL INJURIES

NUMBER			DESCRIPTION
1	4		N/A

DESIRE CONSEQUENCES Probable

1	5	None	
7	8	9	80

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
16	Z	N/A

PUBLICITY

17	None	80
----	------	----

ADDITIONAL FACTORS

18	None	89	80
----	------	----	----

19 89 (117) 515 0120 80

NAME: T.J. Dente

PHONE: (315) 343-2110

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1			-					-		4	1	1	1	1	0	1				
7	8	9				14	15								25	26					30	31	32			

CON'T		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE					REPORT DATE									
01		M	I	1	L	0	5	0	-	0	2	2	0	1	1	2	9	7	5	1	2	0	5	7	5
7	8	57	58	59	60	61							68	69					74	75					80

EVENT DESCRIPTION

[02]	During an inspection of the Clean-Up System area, water was seen to be leaking	
7-89		80
[03]	thru the pipe insulation leading to the regenerative heat exchanger. The in-	
7-89		80
[04]	sulation was removed showing a 4" longitudinal crack.	
7-89		80
[05]		
7-89		80
[06]		AOR 75-36
7-89		80
	PRIME	

SYSTEM CODE: 07 C G
 CAUSE CODE: F
 COMPONENT CODE: _____
 PRIME COMPONENT SUPPLIER: N
 COMPONENT MANUFACTURER: _____
 VIOLATION: N

CAUSE	DESCRIPTION
1	1.1
2	2.1
3	3.1
4	4.1
5	5.1
6	6.1
7	7.1
8	8.1
9	9.1
10	10.1
11	11.1
12	12.1
13	13.1
14	14.1
15	15.1
16	16.1
17	17.1
18	18.1
19	19.1
20	20.1
21	21.1
22	22.1
23	23.1
24	24.1
25	25.1
26	26.1
27	27.1
28	28.1
29	29.1
30	30.1
31	31.1
32	32.1
33	33.1
34	34.1
35	35.1
36	36.1
37	37.1
38	38.1
39	39.1
40	40.1
41	41.1
42	42.1
43	43.1
44	44.1
45	45.1
46	46.1
47	47.1
48	48.1
49	49.1
50	50.1
51	51.1
52	52.1
53	53.1
54	54.1
55	55.1
56	56.1
57	57.1
58	58.1
59	59.1
60	60.1
61	61.1
62	62.1
63	63.1
64	64.1
65	65.1
66	66.1
67	67.1
68	68.1
69	69.1
70	70.1
71	71.1
72	72.1
73	73.1
74	74.1
75	75.1
76	76.1
77	77.1
78	78.1
79	79.1
80	80.1
81	81.1
82	82.1
83	83.1
84	84.1
85	85.1
86	86.1
87	87.1
88	88.1
89	89.1
90	90.1
91	91.1
92	92.1
93	93.1
94	94.1
95	95.1
96	96.1
97	97.1
98	98.1
99	99.1
100	100.1

08 The section of pipe will be replaced and the defective piping examined to
7 8 9 80
09 determine its exact cause of failure. This will probably be available in early
7 8 9 80
10 1976 and will be filed at the Site for your inspection.
7 8 9 80

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	C	0	1	5			a			

		FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
7	8	9	10	11	44
1	2	Z	Z	N/A	
					45
					80

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION	
13	0	0	0	Z	

PERSONNEL INJURIES

NUMBER			DESCRIPTION	
14	0	0	0	N/A

UNUSUAL CONSEQUENCES Probable

1	5	None
7	8	9
		80

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
1	5	Z	None

PUBLICITY

17	None
----	------

ADDITIONAL FACTORS

19	None	80
----	------	----

19 89 80

NAME: T.J. Dente

PHONE: (315) 343-2110

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1						4	1	1	1	1	0	1
7	8	9				14	15				25	26				30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE									
01	CON'T	M	I	L				0	5	0		1	1	2	9	1	2	0	3	7	5
7	8	57	58	59	60	61	68	69	74	75	80										

EVENT DESCRIPTION

02	During reactor heat-up, chlorides increased from 80 ppb to 160 ppb. The reactor	80
03	was shutdown, and in cold shutdown within 10 hours. (Technical Specifications	80
04	3.3.3.a).	80
05		80
06	AOR 75-35	80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VOLATION			
07	H	C	E	H	T	E	X	C	H	A	M	1	2	0	N	
7	8	9	10	11	12	13	14	15	16	17	43	44	45	46	47	48

CAUSE DESCRIPTION

08	Leak in condenser tube produced higher chloride levels. Tube was plugged.	80
09		80
10		80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION			
11	C	0	0	0		a					
7	8	9	10	11	12	13	44	45	46	47	48

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
12	Z	Z		N/A					
7	8	9	10	11	12	13	44	45	48

PERSONNEL EXPOSURES

NUMBER		TYPE	DESCRIPTION	
13	0	0	Z	N/A
7	8	9	11	12

PERSONNEL INJURIES

NUMBER		DESCRIPTION	
14	0	Z	N/A
7	8	9	11

OFFSITE CONSEQUENCES Probable

15	None	80
----	------	----

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION		
16	Z	N/A	
7	8	9	10

PUBLICITY

17	None	80
----	------	----

ADDITIONAL FACTORS

18	None	80
----	------	----

19		80
----	--	----

NAME: T.J. Dente

PHONE: (315) 343-2110

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 13538

FILE: INCIDENT REPORT FI

FROM: Niagara Mohawk Power Corp. 300 Erie Blvd, West R.R. Schneider			DATE OF DOC 11-28-75	DATE REC'D 12-3-75	LTR XXX	TWX	RPT	OTHER
TO: James P.O'Reilly			ORIG None	CC 30	OTHER	SENT AEC PDR XXX SENT LOCAL PDR XXX		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 30		DOCKET NO: 50-220		
DESCRIPTION: Letter trans the following.....				ENCLOSURES: A20 # 75-31, on 11-14-75, Concerning Failure of radiation monitors..... A/O # 75-32, on 11-17-75, Concerning Specification level of ETS 2.33 and 2.34 exceed on SO ₄ and pH (Table 2.3-1)..... (30 Cys. Received)				
PLANT NAME: Nine Mile Pt. # 1								

FOR ACTION/INFORMATION

SAB 12-4-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	REID W/ Copies

**ACKNOWLEDGED
DO NOT REMOVE**

INTERNAL DISTRIBUTION

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO	<u>DENTON</u> **GRIMES GAMMILL KASTNER BALLARD SPANGLER	<u>LIC ASST</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	<u>A/T IND</u> BRAITMAN SALTZMAN MELTZ <u>PLANS</u> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	**STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	<u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS		

EXTERNAL DISTRIBUTION

1 - LOCAL PDR Oswego, N.Y.	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
16 ACRS SENT TO LIC ASST S. Teets		
** SEND ONLY TEN DAY REPORTS		

[Handwritten signature]

NOTICE OF THE
FEDERAL BUREAU OF INVESTIGATION
UNITED STATES DEPARTMENT OF JUSTICE

WASHINGTON, D. C. 20535

DATE OF BIRTH

30

10

.....

ALL INFORMATION CONTAINED
HEREIN IS UNCLASSIFIED
DATE 11-11-00 BY 60322
EXCEPT WHERE SHOWN
OTHERWISE

(S. 102, 103)

11-11-00

11-11-00

11-11-00

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

Regulatory

File C-1

November 28, 1975

Mr. James P. O'Reilly
Directorate of Regulatory Operations
Region I
United States Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

Enclosed please find Abnormal Occurrence Reports 75-31 and 75-32 for Nine Mile Point Nuclear Plant Unit #1. These reports are submitted in accordance with Regulatory Guide 1.16 and constitute fulfillment of the fifteen (15) day letter requirements. The Licensee Event Reports forms will be submitted by the 10th of December, 1975.



Very truly yours,



R.R. Schneider
Vice President
Electric Operations

TJD/mm

Enc.



13538

Conditions Prior to
Occurrence:

_____	Steady State Power	_____	Routine Shutdown
_____	Hot Standby	_____	
_____	Cold Shutdown	_____	Load Changes
X	Refueling Shutdown	_____	
_____	Routine Startup	_____	Other

Description of the Occurrence:

During routine radiation protection surveillance testing, both radiation monitors in the Reactor Building Ventilation Duct failed to provide transfer to Emergency Ventilation System until 20 mr/hr and 30 mr/hr respectively was applied to the sensors. The electronic calibration had just previously been performed.

Apparent Cause of the Occurrence:

_____	Design	X	Procedure
_____	Manufacture	_____	Unusual Service Condition
_____	Installation/	_____	
_____	Const.	_____	
X	Operator	_____	Component Failure
		_____	Other (Specify)

Analysis of Occurrence:

During refueling operation, the radiation monitor located on the refueling platform will also cause a transfer to Emergency Ventilation. The plant has been in refueling since September 11, 1975. Thus protection for the public was adequately supplied by this monitor in the event of a dropped fuel assembly.

Corrective Action:

The investigation revealed that an inadvertant adjustment was made to these instruments prior to their calibration. Better coordination between the verification of trip point and the electronic alignment will be implemented, and should prevent this in the future. Additional administrative controls will be imposed for this type of calibration.

Failure Data:

None

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

DATE: November 26, 1975

SUBJECT: Abnormal Occurrence Report No. 50- 220 75- 31
(10 Day Letter)

The enclosed Abnormal Occurrence Report is being submitted in accordance with Technical Specification Section 6.

TO: James P. O'Reilly
Directorate of Regulatory Operations
Region 1
631 Park Avenue
King of Prussia, Pa. 19406

FROM: Niagara Mohawk Power Corporation
Nine Mile Point - James A. FitzPatrick Site

P.O. Box #32
Lycoming, New York 13093

Docket No. 50- 220

REFERENCE: License DPR- 63

Report No.: 50- 220/75- 31

Report Date: 11/26/75

Occurrence Date: 11/14/75

Facility: NY NMP #1

Identification of Occurrence:

Failure of both radiation monitors located in the Reactor Building Ventilation Duct to provide a transfer to Emergency Ventilation System at 5 mr/hr.

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

DATE: November 28, 1975

SUBJECT: Abnormal Occurrence Report No. 50- 220 75- 32
(10 Day Letter)

The enclosed Abnormal Occurrence Report is being submitted in accordance with Technical Specification Section 6.

TO: James P. O'Reilly
Directorate of Regulatory Operations
Region 1
631 Park Avenue
King of Prussia, Pa. 19406

FROM: Niagara Mohawk Power Corporation
Nine Mile Point - James A. FitzPatrick Site

P.O. Box #32
Lycoming, New York 13093

Docket No. 50- 220

REFERENCE: License DPR- 63

Report No.: 50- 220 /75-32

Report Date: 11/28/75

Occurrence Date: 11/17/75

Facility: NY NMP #1

Identification of Occurrence:

Specification level of ETS 2.33 and 2.34 exceed on SO₄ and pH
(Table 2.3-1).

Conditions Prior to
Occurrence:

_____	Steady State Power	_____	Routine Shutdown
_____	Hot Standby	_____	
_____	Cold Shutdown	_____	Load Changes
X _____	Refueling Shutdown	_____	
_____	Routine Startup	_____	Other

Description of the Occurrence:

During shutdown for refueling, an acid leak was experienced in the Make-up Demin. acid storage tank. During neutralizing, the Make-up Demin. Regen. Waste Tank, the discharge valve to the lake (BV-69-05), was found partially opened and resulted in approximately 16,000 gals. of (pH ~ 12.4 and high SO_4 content) water being inadvertantly discharged to the lake.

Apparent Cause of the Occurrence:

_____	Design	_____	Procedure
_____	Manufacture	X _____	Unusual Service Condition
_____	Installation/	_____	
_____	Const.	_____	
_____	Operator	_____	Component Failure
		_____	Other (Specify)

Analysis of Occurrence:

It is estimated that the pH in the discharge canal during this discharge would be a maximum of 9.1, it was probably less than this since a small amount of acid was added after the last pH reading of 12.4 was taken on the tank. The SO_4^{2-} concentration in the discharge canal is estimated to be 17 ppm above the ambient concentration of approx. 30 ppm. It is felt that the above levels would not have had a significant impact on the lake water environment since the lake ambient conditions vary from pH 7.2 to pH 9.1 and 13 ppm to 50 ppm for SO_4^{2-} based on data in the Nine Mile Point Environmental Report.

Corrective Action:

Valve was repaired and should not allow this incident to occur.

Failure Data:

None

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

DATE: November 18, 1975

SUBJECT: Abnormal Occurrence Report No. 50-220 75- 32
(24 hour Notification)

The enclosed preliminary AOR is being submitted in accordance with Technical Specification Section 6.

Confirming T.J. Perkins phone conversation
with Mr. Gallina AEC RO-1 office on
11-18-75

TO: James P. O'Reilly
Directorate of Regulatory Operations
Region 1
631 Park Avenue
King of Prussia, Pa. 19406

FROM: Niagara Mohawk Power Corporation
Mine Mile Point - James A. FitzPatrick Site
P.O. Box #32
Lycoming, New York 13093
Docket No. 50- 220

REFERENCE: License DPR- 63

Report No.: 50-220 /75- 32

Report Date 11-18-75

Occurrence Date 11-17-75

Facility: NY NMP #1

Identification of Occurrence:

Specification level of ETS 2.33 & 2.54 exceed on SO₄ & pH (Table 2.5-1)

Conditions Prior to
Occurrence:

_____	Steady State Power	_____	Routine Shutdown
_____	Hot Standby	_____	
_____	Cold Shutdown	_____	Load Changes
X _____	Refueling Shutdown	_____	
_____	Routine Startup	_____	Other

Description of the Occurrence:

During shutdown for refueling, an acid leak was experienced in the Make-Up Demin. acid storage tank. During neutralizing, the Make Up Demin. regen. waste tank, BV-69-05, was found failed partially opened and resulted in approx. 16,000 gals. of (ph ~12.4 and high SO₄ content) water being inadvertently discharged to the Inke.

Apparent Cause of the Occurrence:

_____	Design	_____	Procedure
_____	Manufacture	X _____	Unusual Service Condition.
_____	Installation/	_____	
_____	Const.	_____	
_____	Operator	_____	Component Failure
		_____	Other (Specify)

Analysis of Occurrence:

Presently under investigation.

D FILES

Corrective Action:

Valve will be repaired

Failure Data:

None

To: T.J. Shedlosky (MRC)

4/18/75

4:20 pm

RR. Schneider

From: T.J. Perkins

O. Files

NIAGARA MOHAWK POWER CORPORATION



DATE: November 17, 1975

SUBJECT: Abnormal Occurrence Report No. 50- 220 75- 31
(24 hour Notification)

The enclosed preliminary AOR is being submitted in accordance with Technical Specification Section 6.

Confirming T.J. Perkins phone conversation
with T. Shedlosky AEC RO:I office on
November 14, 1975

TO: James P. O'Reilly
Directorate of Regulatory Operations
Region 1
631 Park Avenue
King of Prussia, Pa. 19406

FROM: Niagara Mohawk Power Corporation
Nine Mile Point - James A. FitzPatrick Site

P.O. Box 652
Lynchburg, New York 15095

Docket No. 50-220

REFERENCE: License DPR- 63

Report No. 50-220-75-31

Report Date: 11-17-75

Occurrence Date: 11-14-75

Facility: NMP #1

Identification of Occurrence:

Failure of both radiation monitors located in the Reactor Building Ventilation Duct to provide a transfer to Emergency Ventilation system at 5 Hr/hr.

Description of the Occurrence:

During routine radiation protection surveillance testing, both radiation monitors in the Reactor Building Ventilation Duct failed to provide transfer to Emergency Ventilation System until 20 Mr/hr and 30 Mr/hr was applied to the sensor. The electronic calibration had just previously been performed.

Apparent Cause of the Occurrence:

Design	<input checked="" type="checkbox"/>	Procedure
Manufacture	<input type="checkbox"/>	Unusual Service/Condition
Installation	<input type="checkbox"/>	
Const.	<input type="checkbox"/>	
Operator	<input checked="" type="checkbox"/>	Component Failure
		Other (Specify)

Analysis of Occurrence:

During refueling operation, the radiation monitor located on the refueling platform will also cause a transfer to Emergency Ventilation. The plant has been in refueling since September 11, 1975. Thus protection for the public was adequately supplied by this monitor in the event of a dropped fuel assembly.

Corrective Action:

The monitors were recalibrated to proper levels. An investigation into the event surrounding the Abnormal Occurrence has been initiated by SORC and it is expected that the report of that investigation will be included in the 15-day report.

Reference Data:

None

Theresa L. J. Skidley (WEC)
T. J. Perkins

Tom R.R. Schneider
(WEC)

11/17/75

3:00 p.m.

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 12806

FILE: INCIDENT REPORT FILE

FROM: Niagara Mohawk power Co. Syracuse, N.Y. R.R. Schneider		DATE OF DOC 11-4-75	DATE REC'D 11-8-75	LTR XXX	TWX	RPT	OTHER
TO: Mr. James O'Reilly		ORIG None	CC 30	OTHER	SENT AEC PDR XXX		
					SENT LOCAL PDR XXX		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 30	DOCKET NO: 50-220		

DESCRIPTION:
Letter trans the following.....

ENCLOSURES:
Licensee Event Report Event # 75-29, on 10-1-75 and 75-30, on 10-1-75, Concerning a Main Steam Line Temperatur switch that was found to actuate the required isolation.....

(30 Copies Received)

PLANT NAME: Nine Mile Pt.# 1

FOR ACTION/INFORMATION

SAB 11-10-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	REID W/ Copies

ACKNOWLEDGED

DO NOT REMOVE

INTERNAL DISTRIBUTION

REG FILE NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	TECH REVIEW SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC ASST R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	A/T IND. BRAITMAN SALTZMAN MELTZ PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	--	--	---	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR, Oswego, N.Y.	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
1 - ACRS SENT TO LIC ASST S. Teets		
** SEND ONLY TEN DAY REPORTS		

OFFICE OF THE ATTORNEY GENERAL

100

● 1997年12月1日

NIAGARA MOHAWK POWER CORPORATION

Regulatory

File CY

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

November 4, 1975

Mr. James P. O'Reilly
Directorate of Regulatory Operations
Region I
United States Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1
Technical Specification 6.9, we hereby submit Licensee Event Reports
75-29 and 75-30 which document the Abnormal Occurrences for October, 1975.

These reports conform to the requirements of Regulatory Guide
1.16, Revision 2 and were completed within the intent of the Licensee
Event Report Instruction Booklet 00E-SS-001, dated October 1974, revised
December 24, 1974. Due to the minimal significance category of the reports,
no supplemental report is included.

Very truly yours,


Original signed by R.R. Schneider

R.R. Schneider
Vice President
Electric Operations

TJD/mm

Enc. 3 copies

cc: K.R. Goller (30 copies)



12806



7 2 2
X

200, 200

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	1	0	1									
7	8	9				14	15										25	26				30	31	32						

CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER						EVENT DATE				REPORT DATE										
01	CONT	M	I	L	L	0	5	0	-	0	2	2	0	1	0	0	1	7	5	1	1	0	3	7	5	
7	8			57	58	59	60	61					68	69					74		75					80

EVENT DESCRIPTION

02	During routine surveillance testing involving a calibration check, a Main Steam																								80
03	Line Temperature switch was found to actuate at 216°F rather than <200°F required																								80
04	EP # IB-10P - Bi-metallic thermal switches - Part Number 17002-40																								80
05	Range -100 to +600°F																								80
06	AOR 75-29																								80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	I	G	E	I	N	S	T	R	U	N	F	0	8	0	N
7	8	9	10	11	12				17	43	44			47	48

CAUSE DESCRIPTION

08	Set point drift. The instrument was recalibrated to trip at 199°F.																								80
09																									80
10																									80

FACILITY STATUS		% POWER			OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION														
11	D	0	0	0					b	N/A															
7	8	9	10	11	12	13			44	45	46														80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY						LOCATION OF RELEASE														
12	0	Z																						
7	8	9	10	11					44	45														80

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION																			
13	0	0	0	Z																			
7	8	9	11	12	13																		80

PERSONNEL INJURIES

NUMBER		DESCRIPTION																					
14	0	0	0	N/A																			
7	8	9	11	12																			80

OFFSITE CONSEQUENCES Probable

15	None																								80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																							
16																									80

PUBLICITY

17																									80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	Sufficient temperature switches were functional to provide the required isolation																								80
19	if required.																								80

NAME: T.J. Dente

PHONE: (315) 343-2110

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	1	0	1									
7	8	9				14	15											26						31	32					

CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER						EVENT DATE					REPORT DATE									
01	CONT	M	I	L	L	0	5	0	-	0	2	2	0	1	0	0	1	7	5	1	1	0	3	7	5	
7	8			57	58	59	60	61					68	69							74	75				80

EVENT DESCRIPTION

02	During routine surveillance testing involving a calibration check, a Main Steam																								80
03	Line Temperature Switch was found to actuate at 212°F rather than < 200°F required																								80
04	EP # IB-10P Bi-metallic thermal switches - Part Number 17002-40																								80
05	Range -100 to + 600°F																								80
06																									80
	AOR 75-30																								80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	I	G	E	I	N	S	T	R	U	N	F	0	8	0	N
7	8	9	10	11	12				17	43	44			47	48

CAUSE DESCRIPTION

08	Set point drift. The instrument was recalibrated to trip at 199°F.																								80
09																									80
10																									80

FACILITY STATUS		% POWER		OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION															
11	D	0	0	0					b	N/A															
7	8	9	10	12	13				44	45	46														80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE																	
12	0	2																							
7	8	9	10	11																					80

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION																					
13	0	0	0	Z																					
7	8	9	11	12	13																				80

PERSONNEL INJURIES

NUMBER		DESCRIPTION																							
14	0	0	0	N/A																					
7	8	9	11	12																					80

SEVERE CONSEQUENCES Probable

15	None																								80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																								
16																									80	
7	8	9	10																							80

PUBLICITY

17																									80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	Sufficient temperature switches were functional to provide the required isolation																								80
19	if required.																								80

NAME: T.J. Dente

PHONE: (315) 343-2110

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 10771

FILE: INCIDENT REPORT FILE

FROM: Niagara Mohawk Power Corp. Syrachse, N.Y. R.R. Schneider		DATE OF DOC 10-3-75	DATE REC'D 10-9-75	LTR XXX	TWX	RPT	OTHER
TO:	Mr. James P. O'Neill	ORIG None	CC 33	OTHER	SENT AEC PDR XXX		
				SENT LOCAL PDR XXX			
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 33	DOCKET NO: 50-220		

DESCRIPTION:
Letter trans the following.....

ENCLOSURES:

A/O # 75-24, on 9-11-75; Concerning the APRM to the APRM, losing their power.....
A/O # 75-25, on 9-13-75, Concerning inoperable feedwater pump # 12....
A/O # 75-26, on 9-13-75, Concerning the Drywell Floor Drain leakage increasing above 5 gpm...
A/O # 75-27, on 9-16-75, Concerning Failure of power supply for radiation
A/O # 75-28, on 9-22-75, Concerning a Main Steam

PLANT NAME: Nine Mile Pt.

FOR ACTION/INFORMATION

(Cont) SAB 10-10-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	

DO NOT REMOVE
ACKNOWLEDGED

INTERNAL DISTRIBUTION

REG FILE NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	TECH REVIEW SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC ASST R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	A/T IND. BRAITMAN SALTZMAN MELTZ PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
--	--	--	--	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR Oswego, N.Y.	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
5 - ACRS SENT TO LIC ASST S. Teets		
** SEND ONLY TEN DAY REPORTS		

451

And

Line Temperature Switch which was found acutuate
(33 Copies Enclosure Received)

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

Regulatory

File Cyt

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

October 3, 1975

Mr. James P. O'Reilly
Directorate of Regulatory Operations
Region I
United States Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406


RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Reports 75-24 thru 75-28 which document the Abnormal Occurrences for September, 1975.

These reports conform to the requirements of Regulatory Guide 1.16, Revision 2 and were completed within the intent of the Licensee Event Report Instruction Booklet 00E-SS-001, dated October 1974, revised December 24, 1974. Due to the minimal significance category of the reports, no supplemental report is included.



Very truly yours,


R.R. Schneider
Vice President -
Electric Operations

TJD/mm

Enc. 3 copies

cc: K.R. Goller (30 copies)



10771

LICENSEE EVENT REPORT

CONTROL BLOCK: _____

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER												LICENSE TYPE				EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	1	0	1										
7	8	9				14	15							25	26					30	31	32									

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE												
01	CON'T	M	I	L	L	0	5	0	0	2	2	0	0	9	1	1	7	5	1	0	0	1	7	5
7	8	57	58	59	60	61						68	69					74	75					80

EVENT DESCRIPTION

02 During normal power operation, one APRM (#14) went downscale. Investigation showed																							
03 that the LPRM inputs to the APRM had lost their power supply. APRM was bypassed.																							
04 Redundant componetns fully operable.																							
05																							
06																							
AOR 75-24																							

SYSTEM CODE				CAUSE CODE		COMPONENT CODE						PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	I	A		E		I	N	S	T	R	U	N		G	0	8	0	N	
7	8	9	10	11		12					17	43		44			47	48	

CAUSE DESCRIPTION

08 Problem with loose component in power supply. Corrected and returned to service.																							
09																							
10																							

FACILITY STATUS		% POWER		OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION														
11	E	0	8	1				a																
7	8	9	10	12	13			44	45	46														80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY										LOCATION OF RELEASE										
12	Z	0		N/A																				
7	8	9	10	11																				80

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION																				
13	0	0	0	Z		N/A																		
7	8	9	11	12	13																			80

PERSONNEL INJURIES

NUMBER		DESCRIPTION																						
14	0	0	0	N/A																				
7	8	9	11	12																				80

DESTRUCTIVE CONSEQUENCES Probable

15 None																							
7 8 9																							

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																						
16	Z	N/A																						
7	8	9	10																					80

PUBLICITY

17 None																							
7 8 9																							

ADDITIONAL FACTORS

18 None																							
7 8 9																							

19																							
7 8 9																							

NAME: Thomas J. Dente

PHONE: (315) 343-2110



LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE					EVENT TYPE							
01	N	Y	N	M	P	1			-					-			4	1	1	1	1	0	1	
7	8	9				14	15									25	26					30	31	32

CONT		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE												
0	1	M	I	L	L	0	5	0	-	0	2	2	0	0	9	1	3	7	5	1	0	0	1	7	5	
7	8	57	58	59	60	61							68	69						74	75					80

EVENT DESCRIPTION

02 During process of shutdown, #12 feedwater pump would not start when given a signal

03 | to do so. #11 feedwater pump was operational for HPCI. Problem isolated to oil.

04 pump motor breaker.

05 _____

7 8 9
06 | AOR 75-25 80 |

7 8 9 SYSTEM CODE CAUSE CODE COMPONENT CODE PRIME COMPONENT SUPPLIER COMPONENT MANUFACTURER VIOLATION
 07 11 E 12 17 43 A 44 47 Z Z Z Z 48 N

CAUSE DESCRIPTION

08 Found loose 120 V control fuse holder on terminal block. Apparent vibration caused

09 | the loosening and interruption of control voltage.

10

7	8	9	FACILITY	METHOD OF	80
---	---	---	----------	-----------	----

11		STATUS	% POWER			OTHER STATUS	DISCOVERY	DISCOVERY DESCRIPTION	
7	8	9	10	11	12	13	14	15	16
		H	0	2	2		a	Attempt to start.	

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
1	2	0	N/A	

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION	
13	0	0	0	Z	N/A

PERSONNEL INJURIES

NUMBER			DESCRIPTION	
14	0	0	0	N/A

~~OFFSIDE~~ CONSEQUENCES PROBABLE

15	None
----	------

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
16	Z	N/A

PUBLICITY

17	None
----	------

ADDITIONAL FACTORS

18 Lock washers or appropriate fix action will be reviewed to eliminate this problem.

19

NAME: Thomas J. Dente PHONE: (315) 343-2110



[PLEASE PRINT ALL REQUIRED INFORMATION]

EVENT DESCRIPTION

SYSTEM CODE		CAUSE CODE
I	B	E
10		11

COMPONENT CODE
I N S T R
12

PRIME
COMPONENT
SUPPLIER
[N]
43

COMPONENT
MANUFACTURER

G	0	8	0
---	---	---	---

44 47

VIOLATION
[N]
48

08	The power supply was replaced returning system to normal. Bad power supply:	
7 8 9		80
09	component will be replaced.	
7 8 9		80
10		
7 8 9		80

7 8		9		10 11 12			13 14 15			16 17		18 19		20 21 22		
FACILITY STATUS		% POWER			OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION						
1	1	0	0	0				a								

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
1	2	0	N/A	

NUMBER			TYPE	DESCRIPTION	
13	0	0	0	Z	N/A

NUMBER				DESCRIPTION	
1	4	0	0	0	N/A

15	None
----	------

TYPE			DESCRIPTION	
1	6	Z	N/A	

17	None
----	------

18	None
----	------

19

PHONE: (315) 343-2110

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 01 N Y N M P 1 LICENSE NUMBER: 15 - 25 26 30 31 32 LICENSE TYPE: 4 1 1 1 1 EVENT TYPE: 0 1

CATEGORY: 01 CONT REPORT TYPE: M I REPORT SOURCE: L L DOCKET NUMBER: 0 5 0 0 2 2 0 EVENT DATE: 0 9 1 3 7 5 REPORT DATE: 1 0 0 1 7 5

EVENT DESCRIPTION

02 During a routine reactor shutdown for refueling and with 200 psig reactor pressure,
03 the Drywell Floor Drain leakage increased above .5 gpm. An operator was sent
04 into the drywell to investigate and found a leak on #15 Reactor Recirculation
05 Pump Motor Cooling Line (Not a part of the Reactor Coolant Boundary).
06 AOR 75-26

SYSTEM CODE: 07 W G CAUSE CODE: E COMPONENT CODE: Z Z Z Z Z Z PRIME COMPONENT SUPPLIER: N COMPONENT MANUFACTURER: Z Z Z Z VIOLATION: N

CAUSE DESCRIPTION

08 Leak to be repaired. Insulated bushing in pump oil cooling system was the cause
09 of leak. Part will be replaced.
10

FACILITY STATUS: 11 G % POWER: 0 0 0 OTHER STATUS: 380°F Shutting down METHOD OF DISCOVERY: a DISCOVERY DESCRIPTION: Rate of rise instrument (Analog)
12 FORM OF ACTIVITY RELEASED: Z CONTENT OF RELEASE: 0 AMOUNT OF ACTIVITY: N/A LOCATION OF RELEASE:

PERSONNEL EXPOSURES

13 NUMBER: 0 0 0 TYPE: Z DESCRIPTION: N/A

PERSONNEL INJURIES

14 NUMBER: 0 0 0 DESCRIPTION: N/A

DEVELOPING CONSEQUENCES Probable

15 None

LOSS OR DAMAGE TO FACILITY

16 TYPE: Z DESCRIPTION: N/A

PUBLICITY

17 None

ADDITIONAL FACTORS

18 None

19

NAME: Thomas J. Dente

PHONE: (315) 343-2110

LICENSEE' EVENT REPORT

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER								LICENSE TYPE					EVENT TYPE	
0	1	N	Y	N	M	P	1			-					-		4	1	1	1	1	0	1					
7	8	9					14	15								25	26				30	31	32					

CONT		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER							EVENT DATE					REPORT DATE							
0	1	M	I	L	L	0	5	0	-	0	2	2	0	0	9	2	2	7	5	1	0	0	1	7	5
7	8	57	58	59	60	61							68	69					74	75					80

EVENT DESCRIPTION

02	During routine surveillance involving calibration check, a Main Steam Line Temperature	80
03	Switch was found to actuate at 173°F or more conservative than the - 200.±10°F.	80
04	Readjusted to required limits.	80
05		80
06	AOR 75-28	80
PRMF		80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION			
0	7	I	B	E	I	N	S	T	R	U	N	F	0	8	0	N
7	8	9	10	11	12					17	43	44			47	48

CAUSE DESCRIPTION

08	Set point drift.	
7 8 9		80
09		
7 8 9		80
10		
7 8 9		80

	FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION	80
[1][1]	[D]	[0][0][0]	N/A	[b]	N/A	
7 8	9 FORM OF	10 .12	13	44 45	46 _____ <div style="float:right; width: 30px;">80</div>	

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	2	0		N/A			
7	8	9	10	11	44	45	80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	2	N/A

PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	N/A

GRAVE CONSEQUENCES Probable

1	5	None	
7	8	9	80

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
18	Z	N/A

PUBLICITY

17	None
----	------

ADDITIONAL FACTORS

18	None
----	------

19

NAME: Thomas J. Dente PHONE: (315) 343-2110



**NEED DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 9534

FILE: INCIDENT REPORT FILE

FROM: Niagara Mohawk Power Corp. Syracuse, N.Y. R.R. Schneider			DATE OF DOC 9-3-75	DATE REC'D 9-8-75	LTR	TWX	RPT XX	OTHER
TO: NRC			ORIG None	CC	OTHER	SENT AEC PDR SENT LOCAL PDR		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-220		

DESCRIPTION:

Letter trans the following.....

PLANT NAME: Nine Mile Pt. # 1

ENCLOSURES:

A/O # 75-21, on 8-2-75, Concerning Core Spray Sparger tripped 6.4 psid instead of required 5 psid, during surveillance testing....
A/O # 75-22, on 8-14-75, Concerning inoperable Reactor Building Vent Monitor.....
A/O # 75-23, on 8-26-75, Concerning Iodine sensitivity in milk sample inadequate, per Appendix B 4.3.3.....
(1 Copy Enclosure Received)

FOR ACTION/INFORMATION

SAB 9-9-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

**ACKNOWLEDGED
DO NOT REMOVE**

INTERNAL DISTRIBUTION

REG FILE NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MPC/PE (3) STEELE	TECH REVIEW SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC ASST R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	A/T IND. BRAITMAN SALTZMAN MELTZ PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
--	--	--	--	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR Oswego, N.Y.	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
1 - ACRS SENT TO LIC ASST L.A. S. Teets		
** SEND ONLY TEN DAY REPORTS		

000000

NIAGARA MOHAWK POWER CORPORATION

Regulatory


File Cy.

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

September 3, 1975

Mr. James P. O'Reilly
Directorate of Regulatory Operations
Region I
United States Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406



RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Report 75-21, 75-22 and 75-23 which document the Abnormal Occurrences for August, 1975.

These reports conform to the requirements of Regulatory Guide 1.16, Revision 2 and were completed within the intent of the Licensee Event Report instruction booklet 00E-SS-001, dated October, 1974, revised December 24, 1974.

Very truly, yours,




R.R. Schneider
Vice President
Electric Operations

TJD/mm

Enc. 3 copies

cc: 30 copies to K.R. Goller



9534



LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1					1	-			-		4	1	1	1	1	0	1			
7	8	9				14	15									25	26					30	31	32		

CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER					EVENT DATE					REPORT DATE									
01	CONT	M	I	L	L	0	5	0	-	0	2	2	0	0	8	0	2	7	5	0	9	0	3	7	5
7	8	57	58	59	60	61					68			69					74		75			80	

EVENT DESCRIPTION

02	During routine surveillance testing, RV-30A, Core Spray Sparger ΔP tripped at																							80
03	6.4 psid instead of required 5 psid.																							80
04																								80
05																								80
06	AOR 75-21																							80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER			VIOLATION		
07	I	E	E	I	N	S	T	R	U	N	B	0	8	0	N
7	8	9	10	11	12				17	43	44			47	48

CAUSE DESCRIPTION

08	Set point drift. Redundant component operable. Recalibrated instrument to																							80
09	required value.																							80
10																								80

FACILITY STATUS		% POWER		OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
11	E	0	8	4					b					
7	8	9	10	12	13			44	45	46				80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE				
12	Z	Z	N/A									
7	8	9	10	11			44	45				80

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION	
13	0	0	0	Z	N/A
7	8	9	11	12	13

PERSONNEL INJURIES

NUMBER		DESCRIPTION	
14	0	0	0
7	8	9	11. 12

ON SITE CONSEQUENCES Probable

15	None																							80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION	
16	Z	N/A	
7	8	9	10

PUBLICITY

17	None																							80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	None																							80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																								80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----


NAME: T.J. Dente

PHONE: (315) 343-2110



[PLEASE PRINT ALL REQUIRED INFORMATION]

GPO 881-667



LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	1	0	1									
7	8	9				14	15											25	26			30	31	32						

CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER										EVENT DATE					REPORT DATE				
01	CONT	M	I	L	I	0	5	0	-	0	2	2	0	0	8	2	6	7	5	0	9	0	3	7	5
7	8	57	58	59	60	61							68	69					74	75				80	

EVENT DESCRIPTION

02	Iodine detection sensitivity in milk sample inadequate, per Appendix B 4.3.3.																							80
03	Milk sample from location #1 collected 7/22/75 showed activity of I 131 = 0.78 ±																							80
04	0.38 pCi/l which has an associated error of ± 49% rather than required ±25%.																							80
05																								80
06	AOR 75-23																							80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER					VIOLATION	
07	Z	Z	Z	Z	9	9	9	9	9	Z	Z	9	9	9	9	N	
7	8	9	10	11	12				17	43		44			47	48	

CAUSE DESCRIPTION

08	Procedural requirements were placed upon the contractor which he did not fulfill.																							80
09	The contractor has been informed as to the absolute necessity to follow these																							80
10	procedures.																							80

FACILITY STATUS		% POWER		OTHER STATUS					METHOD OF DISCOVERY		DISCOVERY DESCRIPTION													
11	E	0	8	2								Inspection by NRC												
7	8	9	10	12	13					44	45	46												80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY					LOCATION OF RELEASE														
12	Z	Z																					
7	8	9	10	11					44	45													80

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION											
13	0	0	0	Z											
7	8	9	11	12	13										

PERSONNEL INJURIES

NUMBER		DESCRIPTION												
14	0	0	0											
7	8	9	11	12										

OFFSITE CONSEQUENCES PROBABLE

15	None																							80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION											
16	Z												
7	8	9	10										

PUBLICITY

17	None																							80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----


ADDITIONAL FACTORS

18	None																							80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																								80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: T.J. Dente

PHONE: (315) 343-2110



NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

DATE: August 29, 1975

SUBJECT: Abnormal Occurrence Report No. 50-220 75- 23
(24 hour Notification)

The enclosed preliminary AOR is being submitted in accordance with Technical Specification Section 6.

Confirming R.A. Burns phone conversation
with T. Shedlosky AEC RG:I office on
August 27, 1975

TO: James P. O'Reilly
Directorate of Regulatory Operations
Region 1
631 Park Avenue
King of Prussia, Pa. 19406

FROM: Niagara Mohawk Power Corporation
Nine Mile Point - James A. FitzPatrick Site

P.O. Box #32
Lycoming, New York 13893

Docket No. 50-220

REFERENCE: License DPR- 63

Report No.: 50- 220 /75- 23

Report Date August 29, 1975

Occurrence Date August 26, 1975

Facility: NY ^{NMP} ~~1~~ #1

Identification of Occurrence:

Iodine detection sensitivity in milk sample

dupe

NIAGARA MOHAWK POWER CORPORATION

NIAGARA MOHAWK

Conditions Prior to Occurrence:

<u>X</u>	Steady State Power	<u> </u>	Routine Shutdown
<u> </u>	Hot Standby	<u> </u>	<u> </u>
<u> </u>	Cold Shutdown	<u> </u>	Load Changes
<u> </u>	Refueling Shutdown	<u> </u>	<u> </u>
<u> </u>	Routine Startup	<u> </u>	Other

Description of the Occurrence:

During an audit by NRP/JAF staff personnel of contractor's facility used in analyzing milk samples, it was discovered that required sensitivity per Appendix B 3.2.C was not met. Milk sample from location #1 collected 7/22/75 showed activity of $I_{131} = 0.78 \pm 0.38$ pCi/l which has an associated error in the analysis of $\pm 49\%$ rather than the required $\pm 25\%$.

Apparent Cause of the Occurrence:

<u> </u>	Design	<u>X</u>	Procedure
<u> </u>	Manufacture	<u> </u>	Unusual Service Condition
<u> </u>	Installation	<u> </u>	<u> </u>
<u> </u>	Cost	<u> </u>	<u> </u>
<u> </u>	Operator	<u> </u>	Component Failure
<u> </u>	<u> </u>	<u> </u>	Other (Specify)

Analysis of Occurrence:

No effect on the environmental because of failure to meet this required sensitivity.

Corrective Action:

Contractor has been informed that, in order to meet the required sensitivity he must increase the milk sample counting time.

Failure Date:

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 9360

FILE: INCIDENT REPORT FILE

FROM: Niagara Mohawk Power Corp Syracuse, N.Y. R.R. Schneider			DATE OF DOC 8-4-75	DATE REC'D 9-3-75	LTR xxx	TWX	RPT	OTHER
TO: Mr. James P. O'Reilly			ORIG not- signed	CC	OTHER	SENT AEC PDR xxx		
						SENT LOCAL PDR xx		
CLASS xxxx	UNCLASS	PROP INFO	INPUT	NO CYS REC'D		DOCKET NO: 50-220		

DESCRIPTION:

Ltr trans the following:

ACKNOWLEDGED
DO NOT REMOVE

PLANT NAME:

Nine Mile Point #1

ENCLOSURES:

License, Event Report #75-18-#75-20
 #75-18 on 7-4-75 concerning emergency condenser
 vent radiation monitor went upscale isolating
 the system as designed
 #75-19 on 7-22-75 concerning the surveillance
 test on Torus Vacuum Relief to Atmosphere.
 Switches was not completed
 #75-20 on 7-25-75 concerning Mile Sample analysis
 was not completed until 9 days following collec

FOR ACTION/INFORMATION 9-3-75 JGB

BUTLER (L)	SCHWENCER (L)	ZIEMANN (L)	REGAN (E)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
CLARK (L)	STOLZ (L)	DICKER (E)	LEAR (L)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
PARR (L)	VASSALLO (L)	KNIGHTON (E)	SPELS
W/ Copies	W/ Copies	W/ Copies	W/ Copies
KNIEL (L)	PURPLE (L)	YOUNGBLOOD (E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u>	<u>TECH REVIEW</u>	<u>DENTON</u>	<u>LIC ASST</u>	<u>A/T IND.</u>
NRC PDR	SCHROEDER	**GRIMES	R. DIGGS (L)	BRAITMAN
OGC, ROOM P-506A	MACCARY	GAMMILL	H. GEARIN (L)	SALTZMAN
GOSSICK/STAFF	KNIGHT	KASTNER	E. GOULBOURNE (L)	MELTZ
CASE	PAWLICKI	BALLARD	P. KREUTZER (E)	
GIAMBUSO	SHAO	SPANGLER	J. LEE (L)	<u>PLANS</u>
BOYD	**STELLO		M. RUSHBROOK (L)	MCDONALD
MOORE (L)	**HOUSTON	<u>ENVIRO</u>	S. REED (E)	CHAPMAN
DEYOUNG (L)	**NOVAK	MULLER	M. SERVICE (L)	DUBE (Ltr)
SKOVHOLT (L)	ROSS	DICKER	S. SHEPPARD (L)	E. COUPE
GOLLER (L) (Ltr)	IPPOLITO	KNIGHTON	M. SLATER (E)	PETERSON
P. COLLINS	TEDESCO	YOUNGBLOOD	H. SMITH (L)	HARTFIELD (2)
DENISE	J. COLLINS	REGAN	S. TEETS (L)	KLECKER
REG OPR	LAINAS	PROJECT LDR	G. WILLIAMS (E)	EISENHUT
FILE & REGION (2)	BENAROYA		V. WILSON (L)	*WIGGINTON
MIPC/PE (3)	VOLLMER	<u>HARLESS</u>	R. INGRAM (L)	F. WILLIAMS
STEELE			M. DUNCAN (E)	HANAUER

EXTERNAL DISTRIBUTION

1 - LOCAL PDR Oswego, N.Y.	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN)
1 - Newton Anderson		Rm B-127 GT
1 - ACRS SENT TO LIC ASST		1 - J. D. RUNKLES, Rm E-201
** SEND ONLY TEN DAY REPORTS		GT

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

August 4, 1975

Mr. James P. O'Reilly
Directorate of Regulatory Operations
Region I
United States Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1
Technical Specification 6.9, we hereby submit Licensee Event Reports
75-18 thru 75-20 which document the Abnormal Occurrences for July 1975.

These reports conform to the requirements of Regulatory
Guide 1.16, Revision 2 and were completed within the intent of the
Licensee Event Report Instruction Booklet 00E-SS-001, dated October, 1974,
revised December 24, 1974. Due to the minimal significance category
of the reports, no supplemental report is included.

Very truly yours,




R.R. Schneider
Vice President
Electric Operations

TJD/mm

Enc. 3 copies

cc: K.R. Goller (30 copies)



9360

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 01 N Y N M P 1 14 15 25 26 30 31 32

CATEGORY: 01 CON'T M I 57 58 59 60 61 68 69 74 75 80

EVENT DESCRIPTION

02 Due to a recent revision in the Technical Specifications, a change in testing re-
03 quirements went unnoted and a surveillance test on Torus Vacuum Relief to Atmosphere
04 Switches was not completed. The review of the specifications was in progress at
05 that time and since has been completed.
06 AOR 75-19

SYSTEM CODE: 07 Z Z 11 12 17 43 44 47 48

CAUSE DESCRIPTION

08 Upon review completion of the Technical Specifications, the requirement was noted.
09
10

FACILITY STATUS: 11 F 9 10 12 13 44 45 46 80

FORM OF ACTIVITY RELEASED: 12 Z 9 10 11 44 45 80

PERSONNEL EXPOSURES

NUMBER: 13 0 0 0 11 12 13 80

PERSONNEL INJURIES

NUMBER: 14 0 0 0 11 12 80

CONSEQUENCES Probable

15 None 80

LOSS OR DAMAGE TO FACILITY

TYPE: 16 Z 10 80

PUBLICITY

17 None 80

ADDITIONAL FACTORS

18 The test performed met all required limits for operation. 80

19 80

NAME: T.J. Dente

PHONE: (315) 343-2110

LICENSEE EVENT REPORT

***CONTROL BLOCK:**

--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME							LICENSE NUMBER							LICENSE TYPE					EVENT TYPE					
0	1	N	Y	N	M	P	1			-					-		4	1	1	1	1	0	1	
7	8	9					14	15								25	26					30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE					REPORT DATE										
01	CONT	M	I	L	L	0	5	0	-	0	2	2	0	0	7	2	5	7	5	0	8	0	4	7	5
7	8	57	58	59	60	61							68	69					74	75					80

EVENT DESCRIPTION

02	Environmental Technical Specifications requires an Environmental Sample (Milk Sample)	80
03	be collected and analysed within 8 days of collection. Analysis was not completed	80
04	until 9 days following collection.	80
05		80
06		80
		80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION	
0	7	Z	Z	d	Z	Z	Z	Z	Z	Z	9	9	9	N
7	8	9	10	11	12			17	43	44			47	48

CAUSE, DESCRIPTION

08	The sample was sent to the lab via ground transportation. In the future, it will	80
09	be sent by air. Eberline Corporation contacted and told of speed requirements.	80
10		80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	E	0	8	0		a		Review by Supervisor	
7	8	9	10	11	12	13	14	15	16

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
12	Z	Z		N/A			
7	8	9	10	11	12	13	14

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION	
13	0	0	0	Z	N/A

PERSONNEL INJURIES

NUMBER				DESCRIPTION
1	4	0	0	N/A

XXXXXX CONSEQUENCES Probable

15	None
----	------

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
16	Z		N/A

PUBLICITY

17	None
7 8 9	

ADDITIONAL FACTORS

18 The results of the analysis indicated I-131 well below limits.

19

NAME: T.J. Dente

PHONE: (315) 343-2110

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 8639

FILE: INCIDENT REPORT FILE

FROM: Niagara Mohawk Power Corp Syracuse, N.Y. R.R. Schneider			DATE OF DOC 8-4-75	DATE REC'D 8-14-75	LTR XXX	TWX	RPT	OTHER
TO: NRC			ORIG 1 Signed	CC	OTHER	SENT AEC PDR <u>XXX</u> SENT LOCAL PDR <u>XXX</u>		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-220			

DESCRIPTION:

letter Trans the following

PLANT NAME: Nine Mile Pt.#1

ENCLOSURES:

Abnormal Occurance #75-18 on 7-4-75, Concerning the failure component in the condenser vent radiation monitor.....
A/O #75-19 on 7-22-75, Concerning a surveillance test on Torus Vacuum Relief to Atmosphere Switches was not completed, do to a change in testing requirements.....
A/O #75-20 on 7-25-75, Advising of Analysis that won't be completed until 9 days following milk sample.....

FOR ACTION/INFORMATION

SAB 8-18-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	✓ REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	✓ LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

**DO NOT REMOVE
ACKNOWLEDGED**

INTERNAL DISTRIBUTION

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (2) STEELE	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO ** STELLO ** HOUSTON ** NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	<u>ENVIRO</u> DENTON ** GRIMES GAMMILL KASTNER BALLARD SPANGLER MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR B. VAN HARLESS	<u>LIC ASST</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	<u>A/T IND.</u> BRAITMAN SALTZMAN MELTZ <u>PLANS</u> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	---	--	---	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR <u>Onwego, NY.</u>	1 - NATIONAL LABS <u>ANL</u>	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASI	NEWMARK/BEUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm 8-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
1 - ACRS SENT TO LIC ASST Teets		
** SEND ONLY TEN DAY REPORTS		



1. The first part of the document
describes the general situation
of the country.



Regulatory

File Cy.

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202



August 4, 1975

Mr. James P. O'Reilly
Directorate of Regulatory Operations
Region I
United States Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Reports 75-18 thru 75-20 which document the Abnormal Occurrences for July 1975.

These reports conform to the requirements of Regulatory Guide 1.16, Revision 2 and were completed within the intent of the Licensee Event Report Instruction Booklet OOE-SS-001, dated October, 1974, revised December 24, 1974. Due to the minimal significance category of the reports, no supplemental report is included.

Very truly yours,



R.R. Schneider
Vice President
Electric Operations

TJD/mm

Enc. 3 copies

cc: K.R. Goller (30 copies)

dupe

8639



12-12-12

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME							LICENSE NUMBER							LICENSE TYPE					EVENT TYPE					
0	1	N	Y	N	M	P	1			-					-			4	1	1	1	1	0	1
7	8	9					14	15								25	26					30	31	32

		CATEGORY	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE					REPORT DATE								
<u>0</u>	<u>1</u>	M	L	L	0	5	0	-	0	2	2	0	0	7	0	4	7	5	0	8	0	4	7	5
7	8	57	58	59	60	61						68	69						75					80

EVENT DESCRIPTION

02	During routine operations, the emergency condenser vent radiation monitor went	80
03	upscale isolating the system as designed. Investigation revealed no high radiation	80
04	zone and a failed component in the monitor.	80
05		80
06	AOR 75-18	80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE						PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
0	7	S	H	E	I	N	S	T	R	U	N	G	0	8	0	N	
7	8	9	10	11	12					17	43	44			47	48	

CAUSE DESCRIPTION

08	Apparently the high temperature environment caused the failure of a component in	80
09	the monitor. The monitor was replaced. Redundant loop verified operational.	80
10		80

11		E		080				a			
7	8	9		10	12	13		44	45	46	80
12		Z		Z		N/A					
7	8	9		10	11		44	45			80

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
13	0	0	Z	N/A

PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	N/A

DEFENSE CONSEQUENCES Probable

1	5	None	
7	8	9	80

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
16	Z	N/A

PUBLICITY

17	None	
----	------	--


ADDITIONAL FACTORS

18	None	
----	------	--

19 7 8 9 80

NAME: T.J. Dente

PHONE: (315) 343-2110



Journal of Management Inquiry 18(6)

[illegible][illegible]

Figure 1. The effect of the number of trials on the number of correct responses. The number of correct responses was significantly higher than the number of incorrect responses in all cases. The number of correct responses was significantly higher than the number of incorrect responses in all cases. The number of correct responses was significantly higher than the number of incorrect responses in all cases.

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE					EVENT TYPE			
01	N	Y	N	M	P	1								4	1	1	1	1	0	1
7	8	9				14	15							25	26			30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE					REPORT DATE										
01	CONT	M	I	L	L	0	5	0	-	0	2	2	0	0	7	2	2	7	5	0	8	0	4	7	5
7	8	57	58	59	60	61				68	69			74	75									80	

EVENT DESCRIPTION

02	Due to a recent revision in the Technical Specifications, a change in testing re-																				80
03	quirements went unnoted and a surveillance test on Torus Vacuum Relief to Atmosphere																				80
04	Switches was not completed. The review of the specifications was in progress at																				80
05	that time and since has been completed.																				80
06	AOR 75-19																				80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE						PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOLATION		
07	Z	Z	d	Z	Z	Z	Z	Z	Z	--	Z	9	9	9	N
7	8	9	10	11	12			17	43	44		47		48	

CAUSE DESCRIPTION

08	Upon review completion of the Technical Specifications, the requirement was noted.																				80
09																					80
10																					80

FACILITY STATUS		% POWER	OTHER STATUS						METHOD OF DISCOVERY	DISCOVERY DESCRIPTION					
11	E	0	8	0					b	Review of revision to Tech. Spec.					
7	8	9	10	12	13			44	45	46				80	

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE	AMOUNT OF ACTIVITY						LOCATION OF RELEASE					
12	Z	Z	N/A											
7	8	9	10	11			44	45					80	

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
13	0	0
7	8	9

PERSONNEL INJURIES

NUMBER	DESCRIPTION
14	0
7	8

OFFENSE CONSEQUENCES Probable

15	None																				80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION
16	Z
7	8

PUBLICITY

17	None																				80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	The test performed met all required limits for operation.																				80
19																					80

NAME: T.J. Dente

PHONE: (315) 343-2110

1. The first part of the document discusses the importance of maintaining accurate records of all activities. It emphasizes that this is essential for ensuring the integrity and reliability of the information collected.

2. The second part of the document outlines the procedures for collecting and analyzing data. It describes the various methods used to gather information and the steps involved in processing and interpreting the results.

3. The third part of the document provides a detailed account of the findings of the study. It presents the data in a clear and concise manner, highlighting the key trends and patterns observed.

4. The fourth part of the document discusses the implications of the findings and offers recommendations for future research. It suggests that further studies should be conducted to explore the underlying causes of the observed phenomena.

5. The fifth part of the document concludes the report and summarizes the main points. It reiterates the importance of accurate record-keeping and the need for ongoing research in this field.

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1														4	1	1	1	1	0	1
7	8	9				14	15													25	26			30	31	32

CATEGORY			REPORT TYPE		REPORT SOURCE		DOCKET NUMBER						EVENT DATE					REPORT DATE									
01	CONT		M	I	L	L	0	5	0	-	0	2	2	0	0	7	2	5	7	5	0	8	0	4	7	5	
7	8		57	58	59	60	61							68	69							75					80

EVENT DESCRIPTION

02	Environmental Technical Specifications requires an Environmental Sample (Milk Sample)	80
03	be collected and analysed within 8 days of collection. Analysis was not completed	80
04	until 9 days following collection.	80
05		80
06	AOR 75-20	80

SYSTEM CODE			CAUSE CODE		COMPONENT CODE						PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	Z	Z	d		Z	Z	Z	Z	Z	Z	Z		Z	9	9	9	N	
7	8	9	10	11	12					17	43		44			47	48	

CAUSE DESCRIPTION

08	The sample was sent to the lab via ground transportation. In the future, it will	80
09	be sent by air. Eberline Corporation contacted and told of speed requirements.	80
10		80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	E	0	8	0			a		Review by Supervisor
7	8	9	10	12	13	44	45	46	80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
12	Z	Z		N/A			
7	8	9	10	11	44	45	80

PERSONNEL EXPOSURES

NUMBER			TYPE		DESCRIPTION	
13	0	0	0	Z		N/A
7	8	9	11	12	13	80

PERSONNEL INJURIES

NUMBER			DESCRIPTION		
14	0	0	0	N/A	
7	8	9	11	12	80

OPPOSITE CONSEQUENCES Probable

15	None	80
----	------	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION		
16	Z		N/A	
7	8	9	10	80

PUBLICITY

17	None	80
----	------	----

ADDITIONAL FACTORS

18	The results of the analysis indicated I-131 well below limits.	80
----	--	----

19		80
----	--	----

NAME: T.J. Dente

PHONE: (315) 343-2110

RECEIVED

U.S.N.R.C

AUG - 7 1974

KING OF PRUSSIA, PA.

REPORT OF ABNORMAL OCCURRENCE AND/OR INCIDENT
NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY-FORM)

CONTROL NO: 7222

FILE: INCIDENT REPORT FILE

FROM: Niagra Mohawk Power Corp Syracuse, N.Y. R R Schneider			DATE OF DOC 7-2-75	DATE REC'D 7-7-75	LTR XX	TWX	RPT	OTHER
TO: Mr. James O'Reilly			ORIG none signed	CC	OTHER	SENT AEC PDR XXXX SENT LOCAL PDR1 XXXX		
CLASS	UNCLASS XXXX	PROP INFO	INPUT	NO CYS REC'D 40		DOCKET NO: 50-220		

DESCRIPTION: Ltr trans the following:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: Nine Mile Point

ENCLOSURES: Licensee Event Report no. AOR 75-14 on 6-18-75, during testing, #11 Standby Liquid Control pump would not start....
AOR 75-15 on 6-26-75, during inspection it was noted that 10 KW heater test on emergency ventilation system was not being performed per Tech Spec.....

see attached paper

FOR ACTION/INFORMATION wtm 7-8-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ 3 Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	

INTERNAL DISTRIBUTION

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	<u>DENTON</u> **GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC ASST</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. MAIGRET (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L)	<u>A/T IND.</u> BRAITMAN SALTZMAN MELTZ <u>PLANS</u> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	--	--	--	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR <u>OSWEGO, N.Y.</u>	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT.
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
1 - ACRS SENT TO LIC ASST		
** SEND ONLY TEN DAY REPORTS		




.....

100

1972

NIAGARA MOHAWK POWER CORPORATION


NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

Regulatory Docket File

July 2, 1975

Mr. James P. O'Reilly
Directorate of Regulatory Operations
Region 1
United States Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406



RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Reports 75-14 thru 75-17 which document the Abnormal Occurrences for June 1975.

These reports conform to the requirements of Regulatory Guide 1.16, Revision 2 and were completed within the intent of the Licensee Event Report Instruction Booklet 00E-SS-001, dated October 1974, revised December 24, 1974. Due to the minimal significance category of the reports, no supplemental report is included.

Very truly yours,

Original signed by R.R. Schneider

R.R. Schneider
Vice President
Electric Operations

TJD/mm

Enc. 3 copies

cc: Mr. K.R. Goller (30 copies)



1222

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER												LICENSE TYPE						EVENT TYPE			
01 N Y N M P 1																										4 1 1 1 1						0 1			
7 8 9 14 15 25 26 30 31 32																																			
01		CONT		CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER						EVENT DATE						REPORT DATE													
01		M I		L		L		0 5 0 - 0 2 2 0						0 6 2 8 7 5						0 7 0 1 7 5															
7 8		57 58		59 60		61 68 69 74 75 80																													

EVENT DESCRIPTION

02 During routine surveillance testing RE-04c, high drywell pressure tripped at														80	
03 3.7 psig and RE-04d tripped at 3.75 psig. Required trip is 3.5 ± .053 psig.														80	
04 Intermediate break (LOCA) analysis (FSAR) indicates that the drift would not have														80	
05 affected the design transient due to the rapid pressure build-up. The small break														80	
06 uses low water level as primary scram and high drywell as back-up. AOR 75-17														80	
														80	

SYSTEM CODE		CAUSE CODE		COMPONENT CODE						PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07 I A		E		I N S T R U						N		B 0 8 0				N	
7 8 9 10		11		12 17						43		44 47				48	

CAUSE DESCRIPTION

08 Minor set point drift. The instruments were recalibrated to required trip point.														80	
09														80	
10														80	

FACILITY STATUS		% POWER		OTHER STATUS						METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
11 E		0 9 2								b		Surveillance Testing					
7 8 9		10 12 13		44 45 46						80							
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY						LOCATION OF RELEASE							
12 Z		Z		N/A													
7 8 9		10 11		44 45						80							

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION					
13 0 0 0		Z		N/A					
7 8 9 11		12 13		80					

PERSONNEL INJURIES

NUMBER		DESCRIPTION					
14 0 0 0		N/A					
7 8 9 11 12		80					

CONSEQUENCES Probable

15 The health and safety of the public was not jeopardized														80	
--	--	--	--	--	--	--	--	--	--	--	--	--	--	----	--

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION					
16 Z		0					
7 8 9 10		80					

PUBLICITY

17 None														80	
---------	--	--	--	--	--	--	--	--	--	--	--	--	--	----	--

ADDITIONAL FACTORS

18 An investigation into 1) replacement of the sensors or 2) relaxation of the														80	
19 ± .053 psi allowable range in the Technical Specifications														80	

NAME: T.J. Dente

PHONE: (315) 343-2110

PLEASE PRINT ALL REQUIRED INFORMATION)

EVENT DESCRIPTION

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					POWER COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOlation	
07	I B	E	I	N	S	T	R	U	N	B	0	8	0	N
7	8 9 10	11	12					17	43	44			47	48

08	Minor set point drift. The instruments were recalibrated to required set points.	80
09		80
10		80

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	E	0	9	2			b	Surveillance testing		
7	8	9	10	12	13		44	45	46	80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	2	Z	N/A				
7	8	9	10	11	44	45	80

NUMBER			TYPE	DESCRIPTION	
13	0	0	0	Z	N/A

NUMBER				DESCRIPTION	
1	4	0	0	0	N/A

~~DRISSEX~~ CONSEQUENCES Probable

15 | The health and safety of the public was not jeopardized .

TYPE		DESCRIPTION
16	Z	0

17	None	80
----	------	----

18 7 8 9 80

19 | _____

NAME: T.J. Dente

PHONE: (315) 343-2110

[PLEASE PRINT ALL REQUIRED INFORMATION]

01		CONT		CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER						EVENT DATE					REPORT DATE				
7	8	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
		M	I	L	I	0	5	0	-	0	2	2	0	0	6	2	6	7	5	0	7	0	1	7	5

02	During NRC inspection, inspector noted that 10 KW heater test on Emergency	7	8	9	80
03	Ventilation System was not being performed per Technical Specification 4.4.4a.2.	7	8	9	80
04	Test on 6/27 indicated 10.18 KW (acceptable). This is an annual test. Based	7	8	9	80
05	upon test results, no hazard was presented to the general public.	7	8	9	80
06		7	8	9	80
		7	8	9	80

7	8	9	SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER			VIOLATION	
0	7		M	B	D	Z	Z	Z	Z	Z	Z	L	Z	9	9	9	N	
7	8	9	10		11	12					17	43	44			47	48	

08	Due to an oversight, the test had not been performed. A review of all surveillance	80
09	requirements is underway to assure compliance with Technical Specifications.	80
10		80

7		8		9		FACILITY STATUS						% POWER				OTHER STATUS										METHOD OF DISCOVERY		DISCOVERY DESCRIPTION													
11						E		0		9		0												d		NRC Inspector															
7		8		9		10		11		12		13		44										45		80															
7		8		9		FORM OF ACTIVITY RELEASED						CONTENT OF RELEASE				AMOUNT OF ACTIVITY												LOCATION OF RELEASE													
12						Z		Z		N/A																															
7		8		9		10		11		12		44										45		80																	

NUMBER				TYPE	DESCRIPTION	
1	3	0	0	0	Z	N/A

NUMBER			DESCRIPTION
1	4	0 0 0	N/A

15 | No hazard was presented to the general public. 80

TYPE			DESCRIPTION
1	5	7	0

17	None	80
----	------	----

A number line starting at 7 and ending at 80. A box with the number 18 is placed above the line, and a vertical tick mark is drawn at the position of 18. The numbers 7, 8, 9, and 80 are labeled below the line.

19 | _____ 80

PHONE: (315) 343-2710

AOR 75-16 on 6-28-75, 3 of 4 reactor water IO-IO-IO Level sensors were found out of calibration....

AOR 75-17 on 6-28-75, high drywell pressure tripped at 3.7 psig and RE-04d tripped at 3.75 psig....

40 copies encl rec'd



1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

1

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 6190

FILE: INCIDENT REPORT FILE

FROM: Niagara Mohawk Power Corp. Syracuse, N Y 13202 R R Schneider			DATE OF DOC 6-3-75	DATE REC'D 6-6-75	LTR XX	TWX	RPT	OTHER
TO: Mr. James O'Reilly			ORIG no original	CC	OTHER	SENT AEC PDR XXX SENT LOCAL PDR XXX		
CLASS	UNCLASS XXXXXX	PROP INFO	INPUT	NO CYS REC'D 40		DOCKET NO: 50-220		

DESCRIPTION: Ltr trans the following:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: Nine Mile Point # 1

ENCLOSURES: Abnormal Occurrence Report
75-10, on 5-20-75, 18 APRM failed to provide a trip during flow bias trip weekly functional testing at the 20% flow test
Abnormal Occurrence Report 75-11 on 5-22-75, Minor set point drift on 1B-05C Emergency Condenser High Flow...

FOR ACTION/INFORMATION wtm 6-6-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/3 Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	

INTERNAL DISTRIBUTION

REG FILE NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	TECH REVIEW SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO LONG LAINAS BENAROYA VOLLMER	DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC ASST R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. MAIGRET (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L)	A/T IND. BRAITMAN SALTZMAN MELTZ PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
--	--	--	--	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR Oswego, N Y	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
5 - ACRS SENT TO LIC ASST		
** SEND ONLY TEN DAY REPORTS		

Abnormal Occurrence Report 75-12 on 5-29-75 Minor set point drift on RE-04A, B, & d
Hi Drywell Pressure Sensors...

Abnormal Occurrence Report No. 75-13 on 5-29-75, During routine surveillance testing, ...
minor set point drift was detected on RE-18D, A & C (10-10-10- water level) 124.5,"
132", 124" respectively...



RECEIVED
NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

June 3, 1975

Mr. James P. O'Reilly
Directorate of Regulatory Operations
Region 1
United States Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Reports 75-10, 75-11, 75-12 and 75-13 which document the Abnormal Occurrences for May 1975.

These reports conform to the requirements of Regulatory Guide 1.16, Revision 2 and were completed within the intent of the Licensee Event Report Instruction Booklet 00E-SS-001, dated October 1974, revised December 24, 1974. Due to the minimal significance category of the reports, no supplemental report is included.

Very truly yours,


Original signed by R.R. Schneider

R.R. Schneider
Vice President - Electric Operations

TJD/vmm

Enc. 3 copies

cc: 30 copies to K.R. Goller



6190

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME: 01 N Y N M P 1 LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 LICENSE TYPE: 4 1 1 1 1 EVENT TYPE: 0 1

CATEGORY: 01 CONT REPORT TYPE: M I REPORT SOURCE: L L DOCKET NUMBER: 0 5 0 - 0 2 2 0 EVENT DATE: 0 5 2 0 7 5 REPORT DATE: 0 6 0 3 7 5

EVENT DESCRIPTION

02 18 APRM failed to provide a trip during flow bias trip weekly functional testing at
03 the 20% flow test. Redundant systems available and fully operable, therefore, no
04 hazard presented to the general public.
05 _____
06 _____ AOR 75-10

SYSTEM CODE: 07 1 A CAUSE CODE: E COMPONENT CODE: I n s t r u PRIME COMPONENT SUPPLIER: N COMPONENT MANUFACTURER: G 0 8 0 VIOLATION: N

CAUSE DESCRIPTION

08 Set point drift which was corrected with a recalibration of the instrument.
09 _____
10 _____

FACILITY STATUS: 11 E % POWER: 0 9 4 OTHER STATUS: _____ METHOD OF DISCOVERY: B DISCOVERY DESCRIPTION: Weekly Functional Testing
 FORM OF ACTIVITY RELEASED: 12 Z CONTENT OF RELEASE: Z AMOUNT OF ACTIVITY: N/A LOCATION OF RELEASE: N/A

PERSONNEL EXPOSURES

NUMBER: 13 0 0 0 TYPE: Z DESCRIPTION: N/A

PERSONNEL INJURIES

NUMBER: 14 0 0 0 DESCRIPTION: N/A

OFFSITE CONSEQUENCES Probable

15 None

LOSS OR DAMAGE TO FACILITY

TYPE: 16 Z DESCRIPTION: N/A

PUBLICITY

17 None

ADDITIONAL FACTORS

18 None

19 _____

NAME: T.J. Dente

PHONE: (315) 343-2110

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 01 N Y N M P 1 LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 LICENSE TYPE: 4 1 1 1 1 EVENT TYPE: 0 1

CATEGORY: 01 CONT REPORT TYPE: M I REPORT SOURCE: L L DOCKET NUMBER: 0 5 0 - 0 2 2 0 EVENT DATE: 0 5 2 2 7 5 REPORT DATE: 0 6 0 3 7 5

EVENT DESCRIPTION

02 Minor set point drift on 1B-05C Emergency Condenser High Flow. Required set point
03 19 ± 1 psid - tripped at 17.5 psid. Redundant sensor was operable.
04
05
06 AOR 75-11

SYSTEM CODE: 07 1 B CAUSE CODE: E COMPONENT CODE: I n s t r u PRIME COMPONENT SUPPLIER: A COMPONENT MANUFACTURER: B 0 8 0 VIOLATION: N

CAUSE DESCRIPTION

08 Instrument recalibrated to provide required trip within Technical Specification
09 limits. No hazard was presented to the general public.
10

FACILITY STATUS: 11 E % POWER: 0 9 4 OTHER STATUS: METHOD OF DISCOVERY: B DISCOVERY DESCRIPTION: Routine Surveillance Testing
 FORM OF ACTIVITY RELEASED: 12 Z CONTENT OF RELEASE: Z AMOUNT OF ACTIVITY: N/A LOCATION OF RELEASE: N/A

PERSONNEL EXPOSURES

13 NUMBER: 0 0 0 TYPE: Z DESCRIPTION: N/A

PERSONNEL INJURIES

14 NUMBER: 0 0 0 DESCRIPTION: N/A

CONSEQUENCES Probable

15 None

LOSS OR DAMAGE TO FACILITY

16 TYPE: Z DESCRIPTION: N/A

PUBLICITY

17 None

ADDITIONAL FACTORS

18 None

19

NAME: T.J. Dente

PHONE: (315) 343-2110

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE		
01 N Y N M P 1										0 0 - 0 0 0 0 0 - 0 0										4 1 1 1 1					0 3		
7	8	9								14	15									25	26	27	28	29	30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE					REPORT DATE											
01 CONT M I		L	L	0 5 0 - 0 2 2 0					0 5 2 9 7 5					0 6 0 3 7 5											
7	8	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80

EVENT DESCRIPTION

02	7	8	9	During routine surveillance testing, minor set point drift was detected on																				80
03	7	8	9	RE-18D, A & C (Lo-Lo-Water Level) 124.5", 132", and 124" respectively. Should																				80
04	7	8	9	be 128" water column. Instruments were recalibrated to required set point.																				80
05	7	8	9	Three of the four instruments would actuate sooner than required, thus providing																				80
06	7	8	9	the required function.																				80
AOR 75-13																								

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER					VIOLATION	
07 I A		B		I n s t r u					N		B 0 8 0					N	
7	8	9	10	11	12	13	14	15	16	17	43	44	45	46	47	48	

CAUSE DESCRIPTION

08	7	8	9	Minor set point drift which would cause the desired action within the established																				80
09	7	8	9	time frame for analyzed sequence operation of ADS. Therefore, no hazard was																				80
10	7	8	9	presented to the general public.																				80

FACILITY STATUS		% POWER		OTHER STATUS					METHOD OF DISCOVERY		DISCOVERY DESCRIPTION									
11 E		0 9 2							B		Routine Testing									
7	8	9	10	11	12	13	14	15	16	17	44	45	46							80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY					LOCATION OF RELEASE											
12 Z		Z		N/A					N/A											
7	8	9	10	11	12	13	14	15	16	17	44	45	46							80

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION														
13 0 0 0	Z	N/A														
7	8	9	11	12	13											80

PERSONNEL INJURIES

NUMBER	DESCRIPTION														
14 0 0 0	N/A														
7	8	9	11	12											80

~~XXXXXX~~ CONSEQUENCES Probable

15	7	8	9	None																				80
----	---	---	---	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION													
16 Z	N/A													
7	8	9	10											80

PUBLICITY

17	7	8	9	None																				80
----	---	---	---	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	7	8	9	The existing surveillance testing and procedures are adequate to detect the																				80
				set point drift and therefore, no changes on frequency or method are contemplated.																				80
19	7	8	9																					80

NAME: T.J. Dente

PHONE: (315) 343-2110

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 (PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME 01 N Y N M P 1														LICENSE NUMBER 0 0 - 0 0 0 0 0 - 0 0														LICENSE TYPE 4 1 1 1 1										EVENT TYPE 0 3																	
CATEGORY 01 CONT M I														REPORT TYPE L				REPORT SOURCE L				DOCKET NUMBER 0 5 0 - 0 2 2 0														EVENT DATE 0 5 2 9 7 5										REPORT DATE 0 6 0 2 7 5									

EVENT DESCRIPTION

02 Minor set point drift on RE-04A, B, & D Hi Drywell Pressure Sensors. Technical																																																																															
03 Specifications require a trip at 3.5 psig and the sensor provided a trip at 3.7 psig,																																																																															
04 which would have been sufficient to cause the required action within the time frame																																																																															
05 reference as established in the FSAR.																																																																															
06 AOR 75-12																																																																															

SYSTEM CODE 07 I A										CAUSE CODE E		COMPONENT CODE I N S T R U										PRIME COMPONENT SUPPLIER N				COMPONENT MANUFACTURER B O 8 0										VIOLATION N			
-----------------------	--	--	--	--	--	--	--	--	--	-----------------	--	-------------------------------	--	--	--	--	--	--	--	--	--	-------------------------------	--	--	--	-----------------------------------	--	--	--	--	--	--	--	--	--	----------------	--	--	--

CAUSE DESCRIPTION

08 Minor set point drift which was immediately corrected to Technical Specification																																																																															
09 limits. The event occurred during routine surveillance testing. The allowable																																																																															
10 limits for drift on these instrument is $\pm .053$ psi which is quite restrictive.																																																																															

FACILITY STATUS 11 E										% POWER 0 9 3										OTHER STATUS										METHOD OF DISCOVERY B										DISCOVERY DESCRIPTION Routine Surveillance Testing.									
FORM OF ACTIVITY RELEASED 12 Z										CONTENT OF RELEASE Z										AMOUNT OF ACTIVITY N/A										LOCATION OF RELEASE N/A																			

PERSONNEL EXPOSURES

NUMBER 13 0 0 0										TYPE Z										DESCRIPTION N/A									
--------------------	--	--	--	--	--	--	--	--	--	-----------	--	--	--	--	--	--	--	--	--	--------------------	--	--	--	--	--	--	--	--	--

PERSONNEL INJURIES

NUMBER 14 0 0 0										DESCRIPTION N/A									
--------------------	--	--	--	--	--	--	--	--	--	--------------------	--	--	--	--	--	--	--	--	--

OFFSITE CONSEQUENCES Probable Consequences

15 None																																																																															
---------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

LOSS OR DAMAGE TO FACILITY

TYPE 16 Z										DESCRIPTION N/A									
--------------	--	--	--	--	--	--	--	--	--	--------------------	--	--	--	--	--	--	--	--	--

PUBLICITY

17 None																																																																															
---------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

ADDITIONAL FACTORS

18 None																																																																															
---------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

19																																																																															
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

NAME: T.J. Dente

PHONE: (315) 343-2110

NRC DISTRIBUTION FOR PART 50 DOCKET SERIAL (TEMPORARY FORM)

CONTROL NO: 5522FILE: INCIDENT REPORT FILE

FROM: Niagara Mohawk Pwr. Co. Syracuse, N.Y. R.R. Schneider			DATE OF DOC 5-6-75	DATE REC'D 5-20-75	LTR XXX	TWX	RPT	OTHER
TO: James P. O'Reilly			ORIG 1 Signed	CC	OTHER	SENT AEC PDR <u>XXXX</u> SENT LOCAL PDR <u>XXXX</u>		
CLASS	UNCLASS XXXX	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-220		

DESCRIPTION:

Ltr. trans the following....

ENCLOSURES:

Reporting 4 Abnormn. Occurrs. as follows:

75-6-on 4-5-75-concern. Instrument appears to have drifted..... to

75-7-on 4-12-75, concern. E.C.IV#11(AC) failed open

75-8-on 4-14-75-concern. Relay coil in RPS relay 12K30 shorted.....

75-9-on 4-14-75-concern. APRM #11 failed to provide high alarm

PLANT NAME: Nine Mile Pt. # 1

FOR ACTION/INFORMATION

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	

INTERNAL DISTRIBUTION

REG FILE NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	TECH REVIEW SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO LONG LAINAS BENAROYA VOLLMER	DENTON GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC ASST R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. MAIGRET (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L)	A/T IND. BRAITMAN SALTZMAN MELTZ PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	--	---	--	---

EXTERNAL DISTRIBUTION

1 - LOCAL PDR <i>Oswego N.Y.</i>	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
5 - ACRS SENT TO LIC ASST		
** SEND ONLY TEN DAY REPORTS	<i>Teets</i>	



41 31 20 00

•

Regulatory

File 674

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

May 6, 1975



Mr. James P. O'Reilly
Directorate of Regulatory Operations
Region I
United States Nuclear Regulatory Commission
631 Park Avenue
King of Prussia. 19406


RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Report 75-6, 75-7, 75-8, and 75-9 which document the Abnormal Occurrences for April 1975.

These reports conform to the requirements of Regulatory Guide 1.16, Revision 2 and were completed within the intent of the Licensee Event Report instruction booklet 00E-SS-001, dated October, 1974, revised December 24, 1974. Due to the Minimal significance category of the reports, no supplemental report is included.

Very truly yours,


R.R. Schneider
Vice President
Electric Operations

TJD/mm

Enc. 3 copies

cc: 30 copies to K.R. Goller

5552

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1											4	1	1	1	1	0	1			
7	8	9				14	15							25			26					30	31	32		

CONT		CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER								EVENT DATE					REPORT DATE							
01	CONT	M	I	L	L			0	5	0		0	2	2	0		0	4	0	5	7	5	0	5	0	3	7	5
7	8	57	58	59	60			61						68		69						74	75					80

EVENT DESCRIPTION

02 During surveillance testing, RE-18A Rx Level Lo-Lo-Lo was found to actuate at 131 inches
03 of H₂O rather than 128.5 inches of water. Redundant sensors available and operable.
04 Instrument appears to have drifted - Instrument recalibrated to 128.5" of water and
05 tested.
06 AOR 75-06

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER			VIOLATION		
07	I	B	E	I	N	S	T	R	U	A	B	O	8	0	N
7	8	9	10	11	12			17	43		44		47		48

CAUSE DESCRIPTION

08 Set Point Drift
09
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
00
01
02
03
04
05
06
07
08
09
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
00
01
02
03
04
05
06
07
08
09
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
00
01
02
03
04
05
06
07
08
09
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME														LICENSE NUMBER											LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	1	0	1										
7	8	9				14	15										25	26					30	31	32						

CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER											EVENT DATE					REPORT DATE				
01	CONT	M	I	L	L	0	5	0	-	0	2	2	0	0	4	1	2	7	5	0	5	0	3	7	5	
7	8	57	58	59	60	61							68	69					74	75					80	

EVENT DESCRIPTION

02	During quarterly testing, E.C. IV #11 (A.C.) failed to open. E.P. # 39-09 part																								80
03	NM-86A. Redundant system operable and available. Loose connection found in control																								80
04	circuit terminal block 1S 65 cabinet "M" block.																								80
05																									80
06	AOR 75-07																								80

SYSTEM CODE				CAUSE CODE		COMPONENT CODE											PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	I	B	E	I	N	S	T	R	U	A	Z	9	9	9	N									
7	8	9	10	11	12				17	43	44			47	48									

CAUSE DESCRIPTION

08	Loose connection was found in the remote manual wiring terminal block. Connection																								80
09	tightened, valve operated properly.																								80
10																									80

FACILITY STATUS			% POWER			OTHER STATUS								METHOD OF DISCOVERY		DISCOVERY DESCRIPTION										
11	G	0	0	0									b	Z												
7	8	9	10	12	13								44	45	46										80	

FORM OF ACTIVITY RELEASED			CONTENT OF RELEASE			AMOUNT OF ACTIVITY											LOCATION OF RELEASE										
12	0	0	0	Z												Z											
7	8	9	10	11									44	45											80		

PERSONNEL EXPOSURES

NUMBER			TYPE		DESCRIPTION																				
13	0	0	0	Z	Z																				
7	8	9	11	12	13																				80

PERSONNEL INJURIES

NUMBER			DESCRIPTION																						
14	0	0	0	Z																					
7	8	9	11	12																					80

CONSEQUENCES Probable

15	None as redundant component available and operable.																								80
----	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION																						
16	Z	None																							
7	8	9	10																						80

PUBLICITY

17	None																								80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	None																								80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																									80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: T.J. Dente

PHONE: (315) 343-2110

LICENSEE EVENT REPORT

CONTROL BLOCK:

1					6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE					EVENT TYPE							
0	1	N	Y	N	M	P	1			-					-			4	1	1	1	1	0	1
7	8	9					14	15								25	26					30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE					REPORT DATE								
01	CON'T	M I	L	0	5	0	-	0	2	2	0	0	4	1	4	7	5	0	5	0	3	7	5
7	8	57	58	59	60	61					68	69					74	75					80

EVENT DESCRIPTION

02	During normal power operation, the relay coil in RPS relay 12K30 (turbine trip	80
03	1 out of 2 twice) shorted. EP# GEH-2024, part.no. GEF-2757. Redundant relays were	80
04	fully operable. Relay assumed tripped condition upon failure. Relay coil was	80
05	replaced and unit tested.	80
06	AOR 75-08	80

7 8 9 SYSTEM CODE CAUSE CODE COMPONENT CODE PRIME COMPONENT SUPPLIER COMPONENT MANUFACTURER VIOLATION

07 I A E I N S T R U N G O 8 0 N

7 8 9 10 11 12 13 14 15 16 17 43 44 45 46 47 48

CAUSE DESCRIPTION

08	Appears to be normal failure, the result of the environment and high usage. Coil	
7 8 9		80
09	is always energized.	
7 8 9		80
10		
7 8 9		80

7 8		9		10 11 12			13 14		15 16		17 18		19 20	
FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
1	1	C	0	5	5			a						

		FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
7	8	9	10	11		44	45		80
1	2	Z	Z	Z					

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
13	000	0	Z	

PERSONNEL INJURIES

NUMBER				DESCRIPTION
14	0	0	0	Z

~~OFFICIAL~~ CONSEQUENCES Probable

15 None as redundant component available and operable.

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
16	Z		Z

PUBLICITY

17	None
----	------

ADDITIONAL FACTORS

18	None	
7	8	9
		80

19 7 8 9 80

NAME: T.J. Dente

PHONE: (315) 343-2110

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME				LICENSE NUMBER								LICENSE TYPE					EVENT TYPE						
01	N	Y	N	M	P	1			-				-			4	1	1	1	1	0	1	
7	8	9				14	15								25	26					30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE					REPORT DATE										
01	CON'T	M	I	L	L	0	5	0	-	0	2	2	0	0	4	1	4	7	5	0	5	0	4	7	5
7	8	57	58	59	60	61							68	69						74	75				80

EVENT DESCRIPTION

02	During weekly functional test of APRM's, APRM #11 failed to provide high alarm when	80
03	required to do so. The scram function tested satisfactory. Six APRM's are required	80
04	for operation, 7 were operable and available. Electronic failure with affected parts	80
05	replaced in kind.	80
06	AOR 75-09	80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION			
0	7	I	A	E	I	N	S	T	R	U	N	G	0	8	0	N
7	8	9	10	11	12					17	43	44				48

CAUSE DESCRIPTION

08	Open transistor (Q4) in dual alarm unit (194X382G1). Transistor replaced, unit	80
09	tested satisfactory.	80
10		80

11	FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
7	8	9	10	12	13	44	45	46	80	
		C	0	5	5	Z	b	Z		
12	FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
7	8	9	10	11	44	45	80			
		Z	Z	Z		Z				

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	3	0	0	0	Z

PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	Z

~~XXXXXX~~ OFFSITE CONSEQUENCES Probable

15 No consequences as redundant system were operable and available.

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
1	6	Z	Z

PUBLICITY

17	None	
----	------	--

ADDITIONAL FACTORS

18	None	
----	------	--

19 89 89

NAME: T.J. Dente

PHONE: (315) 343-2110

RECEIVED
U.S. AIR FORCE
MAY 12 1961

REPORT OF ABNORMAL OCCURRENCE AND/OR INCIDENT

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL (TEMPORARY FORM)

CONTROL NO: 5281

FILE: INCIDENT REPORT FILE

FROM: Niagara Mohawk Pwr. Co. Syracuse, N.Y. R.R. Schneider		DATE OF DOC 5-6-75	DATE REC'D 5-13-75	LTR XX	TWX	RPT	OTHER
TO: James P. O'Reilly,		ORIG 1 Signed	CC	OTHER	SENT AEC PDR <u>XXXXXX</u> SENT LOCAL PDR <u>XXXXX</u>		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-220		

DESCRIPTION:

Ltr. trans the following...

ENCLOSURES: Reporting Abnorm. Occurrs. (4)
75-06-on 4-5-75-Set Point Drift.....
75-07-on 4-12-75-E.C.1V#11 failure.....
75-08-on 4-14-75-Relay Coil in RPS relay, 12K30
shorted.....
75-09-on 4-14-75-APRM#11 failed to provide high
alarm.....

PLANT NAME: Nine Mile Pt. # 1

FOR ACTION/INFORMATION

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	FEAR (I) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	

INTERNAL DISTRIBUTION

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO LONG LAINAS BENAROYA VOLLMER	<u>DENTON</u> **GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC ASST</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. MAIGRET (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L)	<u>A/T IND.</u> BRAITMAN SALTZMAN MELTZ <u>PLANS</u> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	--	--	--	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR <u>One-90-11-22</u>	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
1 - ACRS SENT TO LIC ASST		
** SEND ONLY TEN DAY REPORTS		

dup

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD WEST
SYRACUSE, N. Y. 13202

May 6, 1975

Mr. James P. O'Reilly
Directorate of Regulatory Operations
Region I
United States Nuclear Regulatory Commission
631 Park Avenue
King of Prussia. 19406


RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Report 75-6, 75-7, 75-8, and 75-9 which document the Abnormal Occurrences for April 1975.

These reports conform to the requirements of Regulatory Guide 1.16, Revision 2 and were completed within the intent of the Licensee Event Report instruction booklet 00E-SS-001, dated October, 1974, revised December 24, 1974. Due to the Minimal significance category of the reports, no supplemental report is included.

Very truly yours,


R.R. Schneider
Vice President
Electric Operations

TJD/mm

Enc. 3 copies

cc: 30 copies to K.R. Goller

5281

LICENSEE EVENT REPORT

CONTROL BLOCK

PLEASE PRINT ALL REQUIRED INFORMATION

LICENSEE NAME														LICENSE NUMBER												LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	1	0	1											
7	8	9				14	15							25	26					30	31	32										

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE					REPORT DATE										
01	CONT	M	I	L	L	0	5	0	0	2	2	0	0	4	0	5	7	5	0	5	0	3	7	5
7	8	57	58	59	60	61						68	69					74	75					80

EVENT DESCRIPTION

02	During surveillance testing, RE-18A Rx Level Lo-Lo-Lo was found to actuate at 131 inches																						
03	of H ₂ O rather than 128.5 inches of water. Redundant sensors available and operable.																						
04	Instrument appears to have drifted - Instrument recalibrated to 128.5" of water and																						
05	tested.																						
06	AOR 75-06																						

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	I	B	E	I	N	S	T	R	U	A	B	O	8	0	N
7	8	9	10	11	12				17	43	44			47	48

CAUSE DESCRIPTION

08	Set Point Drift																						
09																							
10																							

FACILITY STATUS		% POWER		OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION														
11	E	0	9	4					b															
7	8	9	10	12	13				44	45				46										80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE															
12	Z	Z						Z															
7	8	9	10	11				44	45														80

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION																			
13	0	0	0	Z	Z																		
7	8	9	11	12	13																		80

PERSONNEL INJURIES

NUMBER		DESCRIPTION																					
14	0	0	0	Z																			
7	8	9	11	12																			80

CONSEQUENCES Probable

15	None as redundant component available and operable.																						
----	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																						
16	Z	None																						
7	8	9	10																					80

PUBLICITY

17	None																						
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

ADDITIONAL FACTORS

18	None																						
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

19																							
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

NAME: T.J. Dento

PHONE: (315) 343-2110

LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME [01] N Y N M P 1 14														LICENSE NUMBER 15 25											LICENSE TYPE 4 1 1 1 1 30					EVENT TYPE 0 1 31 32	
[01] CONT 7 8		CATEGORY M I 57 58		REPORT TYPE L 59		REPORT SOURCE L 60		DOCKET NUMBER 0 5 0 - 0 2 2 0 68										EVENT DATE 0 4 1 2 7 5 74					REPORT DATE 0 5 0 3 7 5 80								

EVENT DESCRIPTION

[02] During quarterly testing, E.C. IV #11 (A.C.) failed to open. E.P. # 39-09 part																																																																															
[03] NM-86A. Redundant system operable and available. Loose connection found in control																																																																															
[04] circuit terminal block 1S 65 cabinet "M" block.																																																																															
[05]																																																																															
[06] AOR 75-07																																																																															

SYSTEM CODE I B 7 8 9 10				CAUSE CODE E 11		COMPONENT CODE I N S T R U 12 17							PRIME COMPONENT SUPPLIER A 43		COMPONENT MANUFACTURER Z 9 9 9 44 47					VIOLATION N 48	
-----------------------------	--	--	--	--------------------	--	-------------------------------------	--	--	--	--	--	--	----------------------------------	--	---	--	--	--	--	-------------------	--

CAUSE DESCRIPTION

[08] Loose connection was found in the remote manual wiring terminal block. Connection																																																																															
[09] tightened, valve operated properly.																																																																															
[10]																																																																															

FACILITY STATUS G 7 8 9		% POWER 0 0 0 10 12 13			OTHER STATUS			METHOD OF DISCOVERY b 44 45		DISCOVERY DESCRIPTION Z 46																											
FORM OF ACTIVITY RELEASED 0 7 8 9		CONTENT OF RELEASE 0 10 11			AMOUNT OF ACTIVITY Z 44			LOCATION OF RELEASE Z 45																													

PERSONNEL EXPOSURES

NUMBER 0 0 0 7 8 9		TYPE Z 11 12		DESCRIPTION Z 13															
-----------------------	--	-----------------	--	---------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

PERSONNEL INJURIES

NUMBER 0 0 0 7 8 9		DESCRIPTION Z 11 12															
-----------------------	--	------------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

CONSEQUENCES Probable

[15] None as redundant component available and operable.																																																																															
--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

LOSS OR DAMAGE TO FACILITY

TYPE Z 7 8 9		DESCRIPTION None 10																																																																													
-----------------	--	------------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

PUBLICITY

[17] None																																																																															
-----------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

ADDITIONAL FACTORS

[18] None																																																																															
-----------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

[19]																																																																															
------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

NAME: T.J. Dente

PHONE: (315) 343-2110

LICENSEE EVENT REPORT

CONTROL BLOCK

PLEASE PRINT ALL REQUIRED INFORMATION

LICENSEE NAME: 01 N Y N M P 1 LICENSE NUMBER: 15 LICENSE TYPE: 4 1 1 1 1 EVENT TYPE: 0 1

CON'T: 01 CATEGORY: M I REPORT TYPE: L REPORT SOURCE: L DOCKET NUMBER: 0 5 0 - 0 2 2 0 EVENT DATE: 0 4 1 4 7 5 REPORT DATE: 0 5 0 3 7 5

EVENT DESCRIPTION

02 During normal power operation, the relay coil in RPS relay 12K30 (turbine trip
03 1 out of 2 twice) shorted. EP# GEH-2024, part no. GEF-2757. Redundant relays were
04 fully operable. Relay assumed tripped condition upon failure. Relay coil was
05 replaced and unit tested.
06 AOR 75-08

SYSTEM CODE: 07 I A CAUSE CODE: E COMPONENT CODE: I N S T R U PRIME COMPONENT SUPPLIER: N COMPONENT MANUFACTURER: G O 8 0 VIOLATION: N

CAUSE DESCRIPTION

08 Appears to be normal failure, the result of the environment and high usage. Coil
09 is always energized.
10

FACILITY STATUS: 11 C % POWER: 0 5 5 OTHER STATUS: METHOD OF DISCOVERY: a DISCOVERY DESCRIPTION:

FORM OF ACTIVITY RELEASED: 12 Z CONTENT OF RELEASE: Z AMOUNT OF ACTIVITY: Z LOCATION OF RELEASE:

PERSONNEL EXPOSURES

NUMBER: 13 0 0 0 TYPE: 0 DESCRIPTION: Z

PERSONNEL INJURIES

NUMBER: 14 0 0 0 DESCRIPTION: Z

CONSEQUENCES Probable

15 None as redundant component available and operable.

LOSS OR DAMAGE TO FACILITY

TYPE: 16 Z DESCRIPTION: Z

PUBLICITY

17 None

ADDITIONAL FACTORS

18 None

19

NAME: T.J. Dente

PHONE: (315) 343-2110



NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 4437

FILE: INCIDENT REPORT FILE

FROM: Niagara Mohawk Power Corp. Syracuse, N.Y. 13202 R.R. Schneider		DATE OF DOC 4-14-75	DATE REC'D 4-23-75	LTR XX	TWX	RPT	OTHER
TO: Mr. J. P. O'Reilly		ORIG 1 signed	CC	OTHER	SENT AEC PDR XX SENT LOCAL PDR XX		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-220	
DESCRIPTION: Ltr trans the following:				ENCLOSURES: Licensee Event Report No. AOR-75-5 on 4-1-75 re failure of the RPS solenoids to function thus not allowing AOV-202-36 to open.... (1 cy encl rec'd)			
PLANT NAME: Nine Mile Pt. Unit 1				<div style="border: 1px solid black; padding: 5px; display: inline-block;"> ACKNOWLEDGED Do Not Remove </div>			

FOR ACTION/INFORMATION

DHL 4-24-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	

INTERNAL DISTRIBUTION

REG FILE NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	TECH REVIEW SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO LONG LAINAS BENAROYA VOLLMER	DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC ASST R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. MAIGRET (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L)	A/T IND. BRAITMAN SALTZMAN MELTZ PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	--	--	---	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR Oswego, N.Y.	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRICKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
5 - ACRS SENT TO LIC ASST S. Teets 4-24-75		
** SEND ONLY TEN DAY REPORTS		



... ..
... ..
... ..

...

... ..
... ..
... ..
... ..
... ..

... ..

... ..

...


... ..

... ..

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202



April 14, 1975

Mr. James P. O'Reilly
Directorate of Regulatory Operations
Region 1
United States Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406




RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Report 75-5 which documents the Abnormal Occurrence Report for April 1, 1975.

This report conforms to the requirements of Regulatory Guide 1.16, Revision 2 and was completed with the intent of the Licensee Event Report instruction booklet 00E-SS-001, dated October, 1974, revised December 24, 1974.

Very truly yours,


R.R. Schneider
Vice President
Electric Operations

TJD/mm

Enc. (3 copies)

cc: 30 copies to Mr. K.R. Goller

REGISTERED MAIL
RETURN RECEIPT REQUEST

4437



LICENSEE EVENT REPORT Regulatory Docket File

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 01 N Y N M P 1 14
 LICENSE NUMBER: 15 16 17 18 19 20 21 22 23 24 25
 LICENSE TYPE: 26 4 1 1 1 0 30
 EVENT TYPE: 31 0 1 32

01 CONT CATEGORY M I 57 58 REPORT TYPE T 59 REPORT SOURCE L 60 DOCKET NUMBER 0 5 0 0 2 2 0 61 68 69 74 75 80
 EVENT DATE: 0 4 0 1 7 5
 REPORT DATE: 0 4 1 4 7 5

EVENT DESCRIPTION

02 During testing of the Emergency Ventilation System, the system failed to operate
 03 due to a failure of the RPS solenoids to function thus not allowing AOV-202-36 to
 04 open. The valve was immediately hand opened. SORC review indicated that further
 05 inspection of this type of solenoid was in order. A further report will be made
 06 on this item. AOR 75-5

SYSTEM CODE: 07 S H 10 CAUSE CODE: E 11 COMPONENT CODE: V A L V O P 17 PRIME COMPONENT SUPPLIER: A 43 COMPONENT MANUFACTURER: A 63 1 0 47 VIOLATION: N 48

CAUSE DESCRIPTION

08 The solenoid valves (SN-831630) failed due to (1) broken stem and (2) metal oxide
 09 not allowing the valve to open. The SOV's were repaired and the system test completed
 10 No hazard was presented to the general public as indicated in FSAR Supplement 1 VI-II.

11 FACILITY STATUS: E 9 % POWER: 0 9 2 12 13 OTHER STATUS: 44 METHOD OF DISCOVERY: b 45 DISCOVERY DESCRIPTION: 46
 12 FORM OF ACTIVITY RELEASED: Z 9 CONTENT OF RELEASE: Z 10 AMOUNT OF ACTIVITY: N/A 44 LOCATION OF RELEASE: N/A 45

PERSONNEL EXPOSURES

13 NUMBER: 0 0 0 11 TYPE: Z 12 DESCRIPTION: N/A 13

PERSONNEL INJURIES

14 NUMBER: 0 0 0 11 DESCRIPTION: N/A 12

CONSEQUENCES Probable

15 None

LOSS OR DAMAGE TO FACILITY

16 TYPE: Z 10 DESCRIPTION: N/A

PUBLICITY

17 N/A

ADDITIONAL FACTORS

18 SORC ordered a review of the system operation be conducted, however, due to the 14
 day requirements on LER's, the review which is not ready, will be submitted as a
 19 supplement.

NAME: T.J. Dente

PHONE: (315) 343-2110

40

RECEIVED
U.S.N.R.C.
APR 17 1975

REPORT OF ABNORMAL OCCURRENCE AND/OR INCIDENT

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 4208

FILE: INCIDENT REPORT FILE

FROM: Niagara Mohawk Power Corp Syracuse, N.Y. R.R. Schneider			DATE OF DOC 4-14-75	DATE REC'D 4-17-75	LTR xxx	TWX	RPT	OTHER
TO: Mr. James P. O'Reilly			ORIG no	CC 30	OTHER	SENT AEC PDR <u>xxx</u> SENT LOCAL PDR <u>xxx</u>		
CLASS	UNCLASS xxxx	PROP INFO	INPUT	NO CYS REC'D 30		DOCKET NO: 50-220		

DESCRIPTION: Ltr trans the following: PLANT NAME <u>Nine Mile Pt #1</u>	ENCLOSURES: Abnormal Occurrence on 4-1-75 concerning failure of the RPS solenoids to function thus not allowing AOV-202-36 to open
--	--

FOR ACTION/INFORMATION 4-18-75 JGB

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	✓ LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

REG FILE NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) T.R. WILSON (3) STEELE	TECH REVIEW SCHROEDER MACCARY KNIGHT PAWLICKI SHAO ** STELLO ** HOUSTON ** NOVAK ROSS IPPOLITO TEDESCO LONG LAINAS BENAROYA VOLLMER	DENTON ** GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC ASST R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. MAIGRET (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) ✓ S. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L)	A/T IND. BRAITMAN SALTZMAN MELTZ PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
--	--	---	---	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR <u>Oswego, N.Y.</u> 1 - TIC (ABERNATHY) (1)(2)(10) 1 - NSIC (BUCHANAN) 1 - ASLB 1 - Newton Anderson 1 - ACRS SENT TO LIC ASST ** SEND ONLY TEN DAY REPORTS	NATIONAL LABS 1 - W. PENNINGTON, Rm E-201 GT 1 - CONSULTANTS NEWMARK/BLUME/AGBABIAN	1 - PDR-SAN/LA/NY 1 - BROOKHAVEN NAT LAB 1 - G. ULRIKSON, ORNL 1 - AGMED (RUTH GUSSMAN) Rm B-127 GT 1 - J. D. RUNKLES, Rm E-201 GT
--	--	---

1944

1. The first part of the report is a general statement of the purpose and scope of the study. It is followed by a brief review of the literature on the subject. The second part of the report is a description of the methods used in the study. This is followed by a description of the results of the study. The third part of the report is a discussion of the results and their implications. The fourth part of the report is a conclusion.

2. The first part of the report is a general statement of the purpose and scope of the study. It is followed by a brief review of the literature on the subject. The second part of the report is a description of the methods used in the study. This is followed by a description of the results of the study. The third part of the report is a discussion of the results and their implications. The fourth part of the report is a conclusion.

3. The first part of the report is a general statement of the purpose and scope of the study. It is followed by a brief review of the literature on the subject. The second part of the report is a description of the methods used in the study. This is followed by a description of the results of the study. The third part of the report is a discussion of the results and their implications. The fourth part of the report is a conclusion.

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

April 14, 1975

Mr. James P. O'Reilly
Directorate of Regulatory Operations
Region 1
United States Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1
Technical Specification 6.9, we hereby submit Licensee Event Report
75-5 which documents the Abnormal Occurrence Report for April 1, 1975.

This report conforms to the requirements of Regulatory
Guide 1.16, Revision 2 and was completed with the intent of the
Licensee Event Report instruction booklet 00E-SS-001, dated October,
1974, revised December 24, 1974.

Very truly yours,

Original signed by R.R. Schneider

R.R. Schneider
Vice President
Electric Operations

TJD/mm

Enc. (3 copies)

cc: 30 copies to Mr. K.R. Goller

REGISTERED MAIL
RETURN RECEIPT REQUEST

4208

SENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE					EVENT TYPE				
01	N	Y	N	M	P	1			-				-		4	1	1	1	0	0	1
7	8	9				14	15							25	26				30	31	32

CON'T		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE					REPORT DATE								
01		M	I	T	L	0	5	0	-	0	2	2	0	0	4	0	1	7	5	0	4	1	4	7	5
7	8	57	58	59	60	61							68	69					74	75					80

EVENT DESCRIPTION

02	During testing of the Emergency Ventilation System, the system failed to operate	80
03	due to a failure of the RPS solenoids to function thus not allowing AOV-202-36 to	80
04	open. The valve was immediately hand opened. SORC review indicated that further	80
05	inspection of this type of solenoid was in order. A further report will be made	80
06	on this item. AOR 75-5	80

CAUSE DESCRIPTION

08 The solenoid valves (SN-831630) failed due to (1) broken stem and (2) metal oxide
7 8 9 80
09 not allowing the valve to open. The SOV's were repaired and the system test completed
7 8 9 80
10 No hazard was presented to the general public as indicated in FSAR Supplement I VI-II
7 8 9 80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	1	E	0	9	2		b		
7	8	9	10	12	13	44	45	46	80
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	2	Z	Z	N/A			N/A		
7	8	9	10	11	44	45			80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION	
1	3	0	0	0	Z	N/A

PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	N/A

~~XOFFSNE~~ CONSEQUENCES Probable

1	5	None
7	8	9
		80

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
16	Z		N/A

PUBLICITY

17	N/A
----	-----

ADDITIONAL FACTORS

[18] | SORC ordered a review of the system operation be conducted, however, due to the 14
7 8 9 | day requirements on LER's, the review which is not ready, will be submitted as a
[19] | supplement.
7 8 9 |

NAME: T.J. Dente

PHONE: (315) 343-2110



REPORT OF ABNORMAL OCCURRENCE AND/OR INCIDENT

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 2702

FILE: INCIDENT REPORT FILE

FROM: Niagara Mohawk Power Corp Syracuse, N.Y. R.R. Schneider			DATE OF DOC 3-5-75	DATE REC'D 3-11-75	LTR xxx	TWX	RPT	OTHER
TO: Mr. James P. O'Reilly			ORIG Designed	CC	OTHER	SENT AEC PDR <u>xxxx</u> SENT LOCAL PDR <u>xxx</u>		
CLASS	UNCLASS xxxxx	PROP INFO	INPUT	NO CYS REC'D 80		DOCKET NO: 50-220		

DESCRIPTION:

Ltr trans the following:

ENCLOSURES:

Abnormal Occurrence on 2-12-75 concerning
thru wall leakage was found along a horizontal
line

PLANT NAME: Nine Mile Point Pt #1

FOR ACTION/INFORMATION 3-12-75 JGB

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u> - NRC PDR OGC, ROOM P-506A GOSSICK/STAFF - CASE GIAMBUSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR - FILE & REGION (2) - T.R. WILSON (3) STEELE	<u>TECH REVIEW</u> - SCHROEDER MACCARY KNIGHT PAWLICKI SHAO ** STELLO ** HOUSTON ** NOVAK - ROSS - IPPOLITO TEDESCO LONG LAINAS BENAROYA - VOLLMER	DENTON GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC ASST</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. MAIGRET (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) - S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L)	<u>A/T IND.</u> BRAITMAN SALTZMAN MELTZ <u>PLANS</u> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) - KLECKER EISENHUT WIGGINTON - F. WILLIAMS - HANAUER
--	---	---	--	--

EXTERNAL DISTRIBUTION

- 1 - LOCAL PDR Oswego, N.Y.	- 1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
- 1 - TIC (ABERNATHY) (1)(2)(10)	- 1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
- 1 - NSIC (BUCHANAN)	- 1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
- 5 - ACRS SENT TO LIC ASST		
** SEND ONLY TEN DAY REPORTS		

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

March 5, 1975




Mr. James P. O'Reilly
Directorate of Regulatory Operations
Region 1
United States Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Report 75-3 and 75-4 which document the Abnormal Occurrences for February 1975.

These reports conform to the requirements of Regulatory Guide 1.16, Revision 2 and was completed within the intent of the Licensee Event Report instruction booklet 00E-SS-001, dated October, 1974, revised December 24, 1974. Due to the Minimal significance category of the report, no supplemental report is included.

Very truly yours,


R.R. Schneider
Vice President
Electric Operations

TJD/mm.

Enc. (3 copies)

cc: 30 copies to Mr. K.R. Goller

REGISTERED MAIL
RETURN RECEIPT REQUEST

2702

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

<p>LICENSEE NAME</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 01 N Y N M P 1 </div> <p style="font-size: small;">7 8 9 14 15 25</p>	<p>LICENSE NUMBER</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 15 - </div> <p style="font-size: small;">26 30 31 32</p>	<p>LICENSE TYPE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 4 1 1 1 1 </div>	<p>EVENT TYPE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 01 </div>
--	--	--	--

<p>CATEGORY</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 01 CON'T </div> <p style="font-size: small;">7 8</p>	<p>REPORT TYPE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> M I </div> <p style="font-size: small;">57 58</p>	<p>REPORT SOURCE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> L </div> <p style="font-size: small;">59 60</p>	<p>DOCKET NUMBER</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 0 5 0 - 0 2 0 </div> <p style="font-size: small;">61 68</p>	<p>EVENT DATE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 0 2 1 2 7 5 </div> <p style="font-size: small;">69 74</p>	<p>REPORT DATE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 0 3 0 4 7 5 </div> <p style="font-size: small;">75 80</p>
--	--	---	---	--	---

EVENT DESCRIPTION

02

7 8 9

During plant startup, thru wall leakage was found along a horizonatal line

80

03

7 8 9

approx. 1/2 inch below the circumferential weld between tank shell and tank

80

04

7 8 9

head on Waste Evaporator Concentrator. In addition, corroded areas were found

80

05

7 8 9

on the tank bottom. An evaluation is presently underway to determine feasibility

80

06

7 8 9

of repair or just scraping of this concentrator. AOR 75-3

80

<p>SYSTEM CODE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> M A </div> <p style="font-size: small;">7 8 9 10</p>	<p>CAUSE CODE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> E </div> <p style="font-size: small;">11</p>	<p>COMPONENT CODE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> Z Z Z Z Z Z </div> <p style="font-size: small;">12 17</p>	<p>PRIME COMPONENT SUPPLIER</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> L </div> <p style="font-size: small;">43</p>	<p>COMPONENT MANUFACTURER</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 2 9 9 9 </div> <p style="font-size: small;">44 47</p>	<p>VIOLATION</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> N </div> <p style="font-size: small;">48</p>
---	---	--	---	--	--

CAUSE DESCRIPTION

08

7 8 9

Failure of the concentrator resulted from gross corrosion and pitting

80

09

7 8 9

caused by sulfuric acid contamination.

80

10

7 8 9

80

<p>FACILITY STATUS</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> C </div> <p style="font-size: small;">7 8 9</p>	<p>% POWER</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 0 2 0 </div> <p style="font-size: small;">10 12 13</p>	<p>OTHER STATUS</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> </div> <p style="font-size: small;">44</p>	<p>METHOD OF DISCOVERY</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> a </div> <p style="font-size: small;">45 46</p>	<p>DISCOVERY DESCRIPTION</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> </div> <p style="font-size: small;">80</p>
<p>FORM OF ACTIVITY RELEASED</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> Z </div> <p style="font-size: small;">7 8 9</p>	<p>CONTENT OF RELEASE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> Z </div> <p style="font-size: small;">10 11</p>	<p>AMOUNT OF ACTIVITY</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> N/A </div> <p style="font-size: small;">44 45</p>	<p>LOCATION OF RELEASE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> N/A </div> <p style="font-size: small;">80</p>	

PERSONNEL EXPOSURES

<p>NUMBER</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 0 0 0 </div> <p style="font-size: small;">7 8 9 11</p>	<p>TYPE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> Z </div> <p style="font-size: small;">12</p>	<p>DESCRIPTION</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> N/A </div> <p style="font-size: small;">13 80</p>
---	---	---

PERSONNEL INJURIES

<p>NUMBER</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 0 0 0 </div> <p style="font-size: small;">7 8 9 11</p>	<p>DESCRIPTION</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> N/A </div> <p style="font-size: small;">12 80</p>
---	---

OFFSITE CONSEQUENCES PROBABLE

15

7 8 9

N/A

80

LOSS OR DAMAGE TO FACILITY

<p>TYPE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> Z </div> <p style="font-size: small;">7 8 9 10</p>	<p>DESCRIPTION</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> N/A </div> <p style="font-size: small;">80</p>
---	--

PUBLICITY

17

7 8 9

N/A

80

ADDITIONAL FACTORS

18

7 8 9

N/A

80

19

7 8 9

80

NAME: T.J. Dente

PHONE: (315) 343-2110

AEC DISSEMINATION FOR PART 50 DOCKET NO. [REDACTED] (TEMPORARY FORM)

CONTROL NO: 1440

FILE: INCIDENT REPORT

FROM: Niagara Mohawk Power Corp. Syracuse, N.Y. 13202 R.R. Schneider		DATE OF DOC 2-3-75	DATE REC'D 2-7-75	LTR XX	TWX	RPT	OTHER
TO: Mr. J. P. O'Reilly		ORIG	CC 30	OTHER	SENT AEC PDR XX SENT LOCAL PDR XX		
CLASS	UNCLASS XXXX	PROP INFO	INPUT	NO CYS REC'D 30	DOCKET NO: 50-220		

DESCRIPTION: Ltr trans the following:

ENCLOSURES: Licensee Event Report 75-1 & 75-2 which document the AO for Jan. 1975 re failure(open) of level control valve to Emergency condensers & failure of raw water valve #121 to open:...

(30 cys encl rec'd)

ACKNOWLEDGED

PLANT NAME: Nine Mile Pt. Unit 1

Do Not Remove

FOR ACTION/INFORMATION DHL 2-8-75

BUTLER (S) W/ Copies	SCHWENCER (S) W/ Copies	ZIEMANN (S) W/ Copies	REGAN (E) W/ Copies
CLARK (S) W/ Copies	STOLZ (S) W/ Copies	DICKER (E) W/ Copies	LEAR (S) W/ Copies
PARR (S) W/ Copies	VASSALLO (S) W/ Copies	KNIGHTON (E) W/ Copies	SPEIS (S) W/ Copies
KNIEL (S) W/ Copies	PURPLE (S) W/ Copies	YOUNGBLOOD (E) W/ Copies	

INTERNAL DISTRIBUTION

<u>REG FILE</u> AEC PDR OGC, ROOM P-506-A GOSSICK /STAFF CASE GIAMBUSSO BOYD MOORE (S) (BWR) DEYOUNG (S) (PWR) SKOVHOLT (S) GOLLER (S) P. COLLINS DENISE REG OPR FILE & REGION T.R. WILSON	<u>TECH REVIEW</u> SCHROEDER MACCARRY KNIGHT PAWLICKI SHAO STELLO HOUSTON NOVAK ROSS IPPOLITO TEDESCO LONG LAINAS BENAROYA STEELE VOLIMER	<u>DENTON</u> GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC. ASST.</u> DIGGS (S) GEARIN (S) GOULBOURNE (S) KREUTZER (E) LEE (S) MAIGRET (S) REED (E) SERVICE (S) SHEPPARD (S) SLATER (E) SMITH (S) TEETS (S) WILLIAMS (E) WILSON (S) INGRAM (S)	<u>A/T IND</u> BRAITMAN SALTZMAN B. HURT <u>PLANS</u> MCDONALD CHAPMAN DUBE w/input E. COUPE R. Hartfield (2) KLEGKER F. WILLIAMS
---	---	--	---	--

EXTERNAL DISTRIBUTION

1-LOCAL PDR Oswego, N.Y. 1-TIC (ABERNATHY) 1-NSIC (BUCHANAN) 1-ASLB 1-NEWTON ANDERSON 5-ACRS SENT TO LIC. ASST. S. Teets 2-8-75	(1) (2) (10) -NATIONAL LABS 1-W. PENNINGTON, RM E-201 G.T. 1-CONSULTANTS NEWMARK/BLUME/AGBABIAN	1-PDR SAN/LA/N 1-BROOKHAVEN NAT LAB 1-G. ULRIKSON, ORNL 1-AGMED (RUTH GUSSMAN) RM B-127 G.T. 1-J. RUNKLES, RM E-201 G.T.
---	--	--

[illegible]

•

• • • • •

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

Regulatory Docket File

February 3, 1975

50-220


Mr. James P. O'Reilly
Directorate of Regulatory Operations
Region 1
United States Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1
Technical Specification 6.9, we hereby submit Licensee Event Report
75-1 and 75-2 which document the Abnormal Occurrences for January, 1975.

This report conforms to the requirements of Regulatory
Guide 1.16, Revision 2 and was completed within the intent of the
Licensee Event Report instruction booklet OOE-SS-001, dated October, 1974,
revised December 24, 1974. Due to the Minimal significance category
of the report, no supplemental report is included.

Very truly yours,




R.R. Schneider
Vice President
Electric Operations

TJD/mm

Enc. (3 copies)

cc: 30 copies to Mr. K.R. Goller



1440

(PLEASE PRINT ALL REQUIRED INFORMATION)

GPO 881-667

CONTROL BLOCK: 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE						EVENT TYPE					
01	N	Y	N	M	P	1										4	1	1	1	1	0	1	
7	8	9				14	15									25	26				30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE						REPORT DATE									
01	CONT	M	I	L	0	5	0		0	2	2	0	0	1	0	9	7	5	0	2	0	3	7	5	
7	8	57	58	59	60	61						68	69										74	75	80

EVENT DESCRIPTION

02	Failure (open) of level control valve to Emergency condensers causing high																							80
03	water level alarm. Failure was in safe condition. Spare controller installed.																							80
04	Other system fully operable. Each set of E.C. has own make-up level control																							80
05	from M.V. Tank.																							80
06	AOR 75-1																							80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE						PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION	
07	C	F	E	I	N	S	T	R	U	N	G	0	8	0	N
7	8	9	10	11	12				17	43	44			47	48

CAUSE DESCRIPTION

08	Make-up tank alarmed on low level operator attempted to close valve could not.																							80
09	Maintained level with manual valve (RMV).																							80
10																								80

FACILITY STATUS	% POWER	OTHER STATUS						METHOD OF DISCOVERY	DISCOVERY DESCRIPTION						
11	E	0	8	2				a	Operator noted alarm.						
7	8	9	10	11	12	13		44	45				46		80

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY						LOCATION OF RELEASE							
12	Z	Z	N/A						N/A						
7	8	9	10	11				44	45						80

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION			
13	0	0	0	Z	N/A
7	8	9	11	12	13

PERSONNEL INJURIES

NUMBER	DESCRIPTION			
14	0	0	0	N/A
7	8	9	11	12

OFFSITE CONSEQUENCES PROBABLE

15	None Failure was in safe direction																							80
----	------------------------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION		
16	Z	N/A	
7	8	9	10

PUBLICITY

17	N/A																							80
----	-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18																								80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																								80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: T.J. Dente

PHONE: (315) 343-2110 ext. 1309

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: **NY N M P I** LICENSE NUMBER: **15** LICENSE TYPE: **4 1 1 1 1** EVENT TYPE: **0 1**

CONT: **MI** CATEGORY: **MI** REPORT TYPE: **L** REPORT SOURCE: **L** DOCKET NUMBER: **0 5 0 - 0 2 2 0** EVENT DATE: **0 2 1 2 7 5** REPORT DATE: **0 3 0 4 7 5**

EVENT DESCRIPTION

02 During plant startup, in run mode, #12 F.W. Pump failed to start (HPCI component)
03 due to broken linkage on suction pressure switch. Redundant pump was fully
04 operable. Switch linkage replaced. The pump was started not for HPCI but as
05 normal operation. (ANA-240941)
06 AOR 75-4

SYSTEM CODE: **S F** CAUSE CODE: **E** COMPONENT CODE: **I N S T R U** PRIME COMPONENT SUPPLIER: **A** COMPONENT MANUFACTURER: **M 2 3 5** VIOLATION: **N**

CAUSE DESCRIPTION

08 Due to vibration the linkage between the bourdon tube and the Mercoid switch
09 became disconnected. This will be rechecked periodically when pump is operating.
10

FACILITY STATUS: **C** % POWER: **0 1 7** OTHER STATUS: **N/A** METHOD OF DISCOVERY: **a** DISCOVERY DESCRIPTION: **N/A**
 FORM OF ACTIVITY RELEASED: **Z** CONTENT OF RELEASE: **Z** AMOUNT OF ACTIVITY: **N/A** LOCATION OF RELEASE: **N/A**

PERSONNEL EXPOSURES

13 NUMBER: **0 0 0** TYPE: **Z** DESCRIPTION: **N/A**

PERSONNEL INJURIES

14 NUMBER: **0 0 0** DESCRIPTION: **N/A**

OFFSITE CONSEQUENCES Probable

15 No consequences due to available redundant component.

LOSS OR DAMAGE TO FACILITY

16 TYPE: **Z** DESCRIPTION: **N/A**

PUBLICITY

17 N/A

ADDITIONAL FACTORS

18 No previous failures

19

NAME: **T.J. Dente**

PHONE: **(315) 343-2110**

**AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 326

FILE: INCIDENT REPORT

FROM: Niagara Mohawk Power Corp. Syracuse, N.Y. 13202 R.R. Schneider			DATE OF DOC 1-6-75	DATE REC'D 1-13-75	LTR XXXX	TWX	RPT	OTHER
TO: Mr. Karl R. Goller			ORIG 1 signed	CC 39	OTHER	SENT AEC PDR <u>XX</u> SENT LOCAL PDR <u>XX</u>		
CLASS XXXX	UNCLASS	PROP INFO	INPUT	NO CYS REC'D 40		DOCKET NO: 50-220		

DESCRIPTION: Ltr trans the following:	ENCLOSURES: Abnormal Occurrence Report No. 50-220/74-17 (10 cya letter) on 12-27-74 re one inoperable SRM(14).... (40 cys encl rec'd)
---------------------------------------	--

PLANT NAME: Nine Mile Pt. 1

FOR ACTION/INFORMATION

DHL 1-14-75

BUTLER (S) W/ Copies	SCHWENCER (S) W/ Copies	ZIEMANN (S) W/ Copies	REGAN (E) W/ Copies
CLARK (S) W/ Copies	STOLZ (S) W/ Copies	DICKER (E) W/ Copies	LEAR (S) W/4 Copies
PARR (S) W/ Copies	VASSALLO (S) W/ Copies	KNIGHTON (E) W/ Copies	SPEIS (S) W/ Copies
KNIEL (S) W/ Copies	PURPLE (S) W/ Copies	YOUNGBLOOD (E) W/ Copies	

INTERNAL DISTRIBUTION

REG FILE	TECH REVIEW	DENTON	LIC. ASST.	A/T IND
AEC PDR	SCHROEDER	GRIMES	DIGGS (S)	BRAITMAN
EOGC, ROOM P-506-A	MACCARRY	GAMMILL	GEARIN (S)	SALTZMAN
MUNIZING/STAFF	KNIGHT	KASTNER	GOULBOURNE (S)	B. HURT
CASE	AWLICKI	BALLARD	KREUTZER (E)	
GIAMBUSSO	SHAO	SPANGLER	LEE (S)	PLANS
BOYD	STELLO		MAIGRET (S)	MCDONALD
MOORE (S) (BWR)	HOUSTON	ENVIRO	REED (E)	CHAPMAN
DEYOUNG (S) (PWR)	NOVAK	MULLER	SERVICE (S)	DUBE w/input
SKOVHOLT (S)	CROSS	DICKER	SHEPPARD (S)	E. COUPE
GOLLER (S)	PIPPOLITO	KNIGHTON	SLATER (E)	D. THOMPSON (2)
P. COLLINS	TEDESCO	YOUNGBLOOD	SMITH (S)	KLEGKER
DENISE	LONG	REGAN	FEETS (S)	F. WILLIAMS
REG OPR	LAINAS	PROJECT LDR	WILLIAMS (E)	
FILE & REGION	BENAROYA		WILSON (S)	
T.R. WILSON	STEELE	HARLESS	INGRAM (S)	
	VOLIMER			

EXTERNAL DISTRIBUTION

1-LOCAL PDR Oswego, N.Y.	(1) (2) (10) -NATIONAL LABS	1-PDR SAN/LA/NY
1-TIC (ABERNATHY)	1-H. PENNINGTON, RM E-201 G.T.	1-BROOKHAVEN NAT LAB
1-NSIC (BUCHANAN)	1-CONSULTANTS	1-G. ULRIKSON, ORNL
1-ASLB	NEWMARK/BLUME/ARBABIAN	1-AGMED (RUTH GUSSMAN) RM B-127 G.T.
1-NEWTON ANDERSON		1-J. RUNKLES, RM E-201 G.T.
5-ACRS SENT TO LIC. ASST. S. Teet 1-14-75		



[The body of the document contains extremely faint, illegible text that appears to be a series of lines and paragraphs. Due to the low contrast and quality of the scan, the specific content cannot be transcribed.]

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

00-239

January 6, 1975

Mr. Karl R. Goller
Assistant Director of Operating Reactors
Directorate of Licensing
United States Atomic Energy Commission
Washington, D.C. 20545

Dear Mr. Goller:

In accordance with the Technical Specifications for the
Nine Mile Point Nuclear Station, Unit #1, the enclosed Abnormal
Occurrence Report (74-17) is being submitted. This is in the
accepted format as detailed in Regulatory Guide 1.16, Rev. 1.


Very truly yours,



R.R. Schneider
Vice President - Electric Operations

TJD/mm

Enc.



326



1. The first part of the document is a list of names and addresses. The names are listed in the first column, and the addresses are listed in the second column. The names are: John Doe, Jane Smith, and Bob Johnson. The addresses are: 123 Main St, 456 Elm St, and 789 Oak St.

2. The second part of the document is a list of names and addresses. The names are listed in the first column, and the addresses are listed in the second column. The names are: John Doe, Jane Smith, and Bob Johnson. The addresses are: 123 Main St, 456 Elm St, and 789 Oak St.

3. The third part of the document is a list of names and addresses. The names are listed in the first column, and the addresses are listed in the second column. The names are: John Doe, Jane Smith, and Bob Johnson. The addresses are: 123 Main St, 456 Elm St, and 789 Oak St.

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

DATE: January 6, 1975

SUBJECT: Abnormal Occurrence Report No. 50-220 /74-17

The enclosed Abnormal Occurrence Report is being submitted in accordance with Technical Specifications Section 6.

TO: James P. O'Reilly
Directorate of Regulatory Operations
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

FROM: Niagara Mohawk Power Corporation
Nine Mile Point - James A. FitzPatrick Site

Nine Mile Point Nuclear Station

P.O. Box #32
Lycoming, New York 13093

Docket 50-220



NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

SUBJECT: Abnormal Occurrence 10 Day Letter

REFERENCE: License DPR 17.

Report No.: 50- 220 /74- 17

Report Date: 12/30/74

Occurrence Date: 12/27/74

Facility: NMPP#1

Identification of Occurrence:

One inoperable SRM (14)

Conditions Prior to
Occurrence:

<u> </u>	Steady State Power	<u> </u>	Routine Shutdown
<u> </u>	Hot Standby	<u> </u>	
<u> X </u>	Cold Shutdown	<u> </u>	Load Changes
<u> </u>	Refueling Shutdown	<u> </u>	
<u> </u>	Routine Startup	<u> </u>	Other

Description of the Occurrence:

During shutdown surveillance testing, it was found that SRM (14) was inoperable. Technical Specifications Sec. 3.1.1b (4) requires 3 operable Instrument Channels for startup. This LCO was satisfied as the other 3 SRM's were operable.



Apparent Cause of the Occurrence:

_____ Design
_____ Manufacture
_____ Installation/Const.
_____ Operator

_____ Procedure
_____ Unusual Service
_____ Condition
X _____ Component Failure
_____ Other (Specify)

Detector failure

Analysis of Occurrence:

The source range monitor (SRM) system performs no automatic safety function. It does provide the operator with a visual indication of neutron level which is needed for knowledgeable and efficient reactor startup at low neutron levels and it also provides rod withdrawal blocks to the Rod Control System. The results of reactivity accidents are functions of the initial neutron flux. One operable SRM channel would be adequate to monitor the approach to critical using homogeneous patterns of scattered control rods. A minimum of three operable SRM's is required as an added conservatism.

Therefore, it can be concluded that one SRM being inoperable would not have prevented the performance of the intended function of the SRM system. Further, no hazard would have been presented to the plant safety or health and welfare of the general public from this event.

Corrective Action:

Detector was replaced with spare and system response to neutrons was verified.

[illegible][illegible][illegible]

1. The first group of people who are interested in the study of the history of the United States are the people who are interested in the history of the United States.

[illegible]

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104. 105. 106. 107. 108. 109. 110. 111. 112. 113. 114. 115. 116. 117. 118. 119. 120. 121. 122. 123. 124. 125. 126. 127. 128. 129. 130. 131. 132. 133. 134. 135. 136. 137. 138. 139. 140. 141. 142. 143. 144. 145. 146. 147. 148. 149. 150. 151. 152. 153. 154. 155. 156. 157. 158. 159. 160. 161. 162. 163. 164. 165. 166. 167. 168. 169. 170. 171. 172. 173. 174. 175. 176. 177. 178. 179. 180. 181. 182. 183. 184. 185. 186. 187. 188. 189. 190. 191. 192. 193. 194. 195. 196. 197. 198. 199. 200. 201. 202. 203. 204. 205. 206. 207. 208. 209. 210. 211. 212. 213. 214. 215. 216. 217. 218. 219. 220. 221. 222. 223. 224. 225. 226. 227. 228. 229. 230. 231. 232. 233. 234. 235. 236. 237. 238. 239. 240. 241. 242. 243. 244. 245. 246. 247. 248. 249. 250. 251. 252. 253. 254. 255. 256. 257. 258. 259. 260. 261. 262. 263. 264. 265. 266. 267. 268. 269. 270. 271. 272. 273. 274. 275. 276. 277. 278. 279. 280. 281. 282. 283. 284. 285. 286. 287. 288. 289. 290. 291. 292. 293. 294. 295. 296. 297. 298. 299. 300. 301. 302. 303. 304. 305. 306. 307. 308. 309. 310. 311. 312. 313. 314. 315. 316. 317. 318. 319. 320. 321. 322. 323. 324. 325. 326. 327. 328. 329. 330. 331. 332. 333. 334. 335. 336. 337. 338. 339. 340. 341. 342. 343. 344. 345. 346. 347. 348. 349. 350. 351. 352. 353. 354. 355. 356. 357. 358. 359. 360. 361. 362. 363. 364. 365. 366. 367. 368. 369. 370. 371. 372. 373. 374. 375. 376. 377. 378. 379. 380. 381. 382. 383. 384. 385. 386. 387. 388. 389. 390. 391. 392. 393. 394. 395. 396. 397. 398. 399. 400. 401. 402. 403. 404. 405. 406. 407. 408. 409. 410. 411. 412. 413. 414. 415. 416. 417. 418. 419. 420. 421. 422. 423. 424. 425. 426. 427. 428. 429. 430. 431. 432. 433. 434. 435. 436. 437. 438. 439. 440. 441. 442. 443. 444. 445. 446. 447. 448. 449. 450. 451. 452. 453. 454. 455. 456. 457. 458. 459. 460. 461. 462. 463. 464. 465. 466. 467. 468. 469. 470. 471. 472. 473. 474. 475. 476. 477. 478. 479. 480. 481. 482. 483. 484. 485. 486. 487. 488. 489. 490. 491. 492. 493. 494. 495. 496. 497. 498. 499. 500. 501. 502. 503. 504. 505. 506. 507. 508. 509. 510. 511. 512. 513. 514. 515. 516. 517. 518. 519. 520. 521. 522. 523. 524. 525. 526. 527. 528. 529. 530. 531. 532. 533. 534. 535. 536. 537. 538. 539. 540. 541. 542. 543. 544. 545. 546. 547. 548. 549. 550. 551. 552. 553. 554. 555. 556. 557. 558. 559. 560. 561. 562. 563. 564. 565. 566. 567. 568. 569. 570. 571. 572. 573. 574. 575. 576. 577. 578. 579. 580. 581. 582. 583. 584. 585. 586. 587. 588. 589. 590. 591. 592. 593. 594. 595. 596. 597. 598. 599. 600. 601. 602. 603. 604. 605. 606. 607. 608. 609. 610. 611. 612. 613. 614. 615. 616. 617. 618. 619. 620. 621. 622. 623. 624. 625. 626. 627. 628. 629. 630. 631. 632. 633. 634. 635. 636. 637. 638. 639. 640. 641. 642. 643. 644. 645. 646. 647. 648. 649. 650. 651. 652. 653. 654. 655. 656. 657. 658. 659. 660. 661. 662. 663. 664. 665. 666. 667. 668. 669. 670. 671. 672. 673. 674. 675. 676. 677. 678. 679. 680. 681. 682. 683. 684. 685. 686. 687. 688. 689. 690. 691. 692. 693. 694. 695. 696. 697. 698. 699. 700. 701. 702. 703. 704. 705. 706. 707. 708. 709. 710. 711. 712. 713. 714. 715. 716. 717. 718. 719. 720. 721. 722. 723. 724. 725. 726. 727. 728. 729. 730. 731. 732. 733. 734. 735. 736. 737. 738. 739. 740. 741. 742. 743. 744. 745. 746. 747. 748. 749. 750. 751. 752. 753. 754. 755. 756. 757. 758. 759. 760. 761. 762. 763. 764. 765. 766. 767. 768. 769. 770. 771. 772. 773. 774. 775. 776. 777. 778. 779. 780. 781. 782. 783. 784. 785. 786. 787. 788. 789. 790. 791. 792. 793. 794. 795. 796. 797. 798. 799. 800. 801. 802. 803. 804. 805. 806. 807. 808. 809. 810. 811. 812. 813. 814. 815. 816. 817. 818. 819. 820. 821. 822. 823. 824. 825. 826. 827. 828. 829. 830. 831. 832. 833. 834. 835. 836. 837. 838. 839. 840.

3. *Chlorophyll content* was determined by the method of Arar and Cook (1987) using a spectrophotometer (Shimadzu 1601) at 663 nm and 646 nm. The absorbance values were converted to chlorophyll content using the following equation:

2000年12月22日 星期日

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 99

FILE: INCIDENT REPORT

| | | | | | | | | |
|---|---------------|-----------|-------------------------|----------------------|----------------------|--------------------------------------|-----|-------|
| FROM: Niagara Mohawk Power Corp
Lycoming, New York 13093 | | | DATE OF DOC
12/30/74 | DATE REC'D
1/6/75 | LTR
XX | TWX | RPT | OTHER |
| TO: James P. O'Reilly, Reg. 1 | | | ORIG | CC
1 | OTHER | SENT AEC PDR XX
SENT LOCAL PDR XX | | |
| CLASS | UNCLASS
XX | PROP INFO | INPUT | NO CYS REC'D
1 | DOCKET NO:
50-220 | | | |

DESCRIPTION:
Ltr w/attach. Abnormal occurrence report No. 50-220/74-17; occurrence date 12/27/74, SRM (14) was found inoperable during shutdown surveillance testing (a component failure).

ENCLOSURES:

ACKNOWLEDGED
DO NOT REMOVE

PLANT NAME: Nine Mile Point

FOR ACTION/INFORMATION

LDM 1/8/75

| | | | |
|-------------------------|----------------------------|-----------------------------|-------------------------|
| BUTLER (S)
W/ Copies | SCHWENCER (S)
W/ Copies | ZIEMANN (S)
W/ Copies | REGAN (E)
W/ Copies |
| CLARK (S)
W/ Copies | STOLZ (S)
W/ Copies | DICKER (E)
W/ Copies | ✓ LEAR (S)
W/ Copies |
| PARR (S)
W/ Copies | VASSALLO (S)
W/ Copies | KNIGHTON (E)
W/ Copies | SPEIS (S)
W/ Copies |
| KNIEL (S)
W/ Copies | PURPLE (S)
W/ Copies | YOUNGBLOOD (E)
W/ Copies | |

INTERNAL DISTRIBUTION

| | | | | |
|--|---|--|---|---|
| <u>REG FILE</u>
✓ AEC PDR
✓ COCC, ROOM P-506-A
✓ MUNTZING/STAFF
✓ CASE
GIAMBUSSO
BOYD
MOORE (S) (BWR)
DEYOUNG (S) (PWR)
SKOVHOLT (S)
GOLLER (S)
P. COLLINS
DENISE
REG OPR
✓ FILE & REGION
✓ T.R. WILSON | <u>TECH REVIEW</u>
✓ SCHROEDER
✓ MACCARRY
✓ KNIGHT
✓ PAWLICKI
✓ SHAO
✓ STELLO
✓ HOUSTON
✓ NOVAK
✓ ROSS
✓ IPPOLITO
✓ TEDESCO
✓ LONG
✓ LAINAS
✓ BENAROYA
✓ STEELE
✓ VOLIMER | <u>DENTON</u>
GRIMES
GAMMILL
✓ KASTNER
BALLARD
SPANGLER

<u>ENVIRO</u>
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR

HARLESS | <u>LIC. ASST.</u>
DIGGS (S)
GEARIN (S)
✓ GOULBOURNE (S)
KREUTZER (E)
LEE (S)
MAIGRET (S)
REED (E)
SERVICE (S)
SHEPPARD (S)
SLATER (E)
SMITH (S)
✓ TEETS (S)
WILLIAMS (E)
WILSON (S)
INGRAM (S) | <u>A/T IND</u>
BRAITMAN
SALTZMAN
B. HURT

<u>PLANS</u>
MCDONALD
CHAPMAN
DUBE w/input
E. COUPE
✓ D. THOMPSON (2)
✓ KLEGGER
✓ F. WILLIAMS |
|--|---|--|---|---|

EXTERNAL DISTRIBUTION

| | | |
|---|---|---|
| 1-LOCAL PDR Oswego, N.Y.
1-TIC (ABERNATHY)
1-NSIC (BUCHANAN)
1-ASLB
1-NEWTON ANDERSON
5-ACRS SENT TO LIC. ASST.
Teets sent 1/8/75 | (1) (2) (10) - NATIONAL LABS
1-M. PENNINGTON, RM E-201 G.T.
1-CONSULTANTS
NEWMARK/BLUME/AGBABIAN | 1-PDR SAN/LA/NY
1-BROOKHAVEN NAT LAB
1-G. ULRIKSON, ORNL
1-AGMED (RUTH GUSSMAN)
RM B-127 G.T.
1-J. RUNKLES, RM E-201
G.T. |
|---|---|---|

dupe

NIAGARA MOHAWK POWER CORPORATION

NIAGARA MOHAWK

DATE: December 30, 1974

SUBJECT: Abnormal Occurrence Report No. 50-220 /74-17


The enclosed preliminary AOR is being submitted in accordance with Technical Specifications Section 6.

TO: James P. O'Reilly
Directorate of Regulatory Operations
Region 1
681 Park Avenue
King of Prussia, Pennsylvania 19406

Regulatory

File cy.

FROM: Niagara Mohawk Power Corporation
Nine Mile Point - James A. FitzPatrick Site
Nine Mile Point Nuclear Station.
P.O. Box #32
Lycoming, New York. 13003
Docket 50-220





[The body of the document contains several paragraphs of text that are extremely faint and illegible due to the quality of the scan. The text appears to be organized into multiple sections, possibly separated by headings or subheadings, but the specific content cannot be discerned.]

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

SUBJECT: Abnormal Occurrence 24 hour Notification

Confirming Mr. C. Stuart phone conversation
with Mr. T. Shodlosky ABC ROY office on
12/27/74

REFERENCE: License DPR 17

Report No.: 50- 220 /74-17

Report Date: 12/30/74

Occurrence Date: 12/27/74

Facility: NKP # 1

Identification of Occurrence:

One inoperable SRM (14)

Conditions Prior to
Occurrence:

| | |
|--------------------------------------|------------------------------------|
| <u> </u> Steady State Power | <u> </u> Routine Shutdown |
| <u> </u> Hot Standby | <u> </u> |
| <u> X </u> Cold Shutdown | <u> </u> Load Changes |
| <u> </u> Refueling Shutdown | <u> </u> |
| <u> </u> Routine Startup | <u> </u> Other |

Description of the Occurrence:

During shutdown surveillance testing, it was found that SRM (14) was inoperable. Technical Specifications Sec. 3.1.1b (4) requires 3 operable Instrument channels for startup. This LCO was satisfied as the other 3 SRM's were operable.



12

Apparent Cause of the Occurrence:

_____ Design
_____ Manufacture
_____ Installation/Const.
_____ Operator

_____ Procedure
_____ Unusual Service
_____ Condition
_____ X Component Failure
_____ Other (Specify)

Detector Failure

Analysis of Occurrence:

The source range monitor (SRM) system performs no automatic safety function. It does provide the operator with a visual indication of neutron level which is needed for knowledgeable and efficient reactor startup at low neutron levels and it also provides rod withdrawal blocks to the Rod Control System. The results of reactivity accidents are functions of the initial neutron flux. One operable SRM channel would be adequate to monitor the approach to critical using homogeneous patterns of scattered control rods. A minimum of three operable SRM's is required as an added conservatism.

Therefore, it can be concluded that one SRM being inoperable would not have prevented the performance of the intended function of the SRM system. Further, no hazard would have been presented to the plant safety or health and welfare of the general public from this event.

Corrective Action:

Detector replaced.

Failure Data:

Later



AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 12926

FILE: INCIDENT REPORT

| | | | | | | | |
|--|-----------------|-------------------------|------------------------|-------------------|--------------------------------------|-----|-------|
| FROM: Niagara Mohawk Power Corp.
Syracuse, N.Y. 13202
R.R. Schneider | | DATE OF DOC
12-19-74 | DATE REC'D
12-23-74 | LTR
X | TWX | RPT | OTHER |
| TO:
Mr. Karl R. Goller | | ORIG
1 signed | CC
39 | OTHER | SENT AEC PDR XX
SENT LOCAL PDR XX | | |
| CLASS | UNCLASS
XXXX | PROP INFO | INPUT | NO CYS REC'D
1 | DOCKET NO:
50-220 | | |

DESCRIPTION: Ltr trans the following:

ENCLOSURES: Abnormal Occurrence A0-50-220/74-16
on 12-10-74 involving one inoperable IRM
(12) in Safety System 11.....

(1 Orig & 39 CC rec'd)

ACKNOWLEDGE

Do Not Remove

PLANT NAME: Nine Mile Pt. Unit 1

FOR ACTION/INFORMATION

DHL 12-24-74

| | | | |
|-------------------------|----------------------------|-----------------------------|------------------------|
| BUTLER (S)
W/ Copies | SCHWENCER (S)
W/ Copies | ZIEMANN (S)
W/ Copies | REGAN (E)
W/ Copies |
| CLARK (S)
W/ Copies | STOLZ (S)
W/ Copies | DICKER (E)
W/ Copies | LEAR (S)
W/ Copies |
| PARR (S)
W/ Copies | VASSALLO (S)
W/ Copies | KNIGHTON (E)
W/ Copies | SPEIS (S)
W/ Copies |
| KNIEL (S)
W/ Copies | PURPLE (S)
W/ Copies | YOUNGBLOOD (E)
W/ Copies | |

INTERNAL DISTRIBUTION

| | | | | |
|--------------------|--------------------|---------------|-------------------|-----------------|
| <u>REG FILE</u> | <u>TECH REVIEW</u> | <u>DENTON</u> | <u>LIC. ASST.</u> | <u>A/T IND</u> |
| AEC PDR | SCHROEDER | GRIMES | DIGGS (S) | BRAITMAN |
| DOCC, ROOM P-506-A | MACCARRY | GAMMILL | GEARIN (S) | SALTZMAN |
| MUNIZING/STAFF | KNIGHT | KASTNER | GOULBOURNE (S) | B. HURT |
| CASE | PAWLICKI | BALLARD | KREUTZER (E) | |
| GIAMBUSSO | SHAO | SPANGLER | LEE (S) | <u>PLANS</u> |
| BOYD | STELLO | | MAIGRET (S) | MCDONALD |
| MOORE (S) (BWR) | HOUSTON | <u>ENVIRO</u> | REED (E) | CHAPMAN |
| DEYOUNG (S) (PWR) | NOVAK | MULLER | SERVICE (S) | DUBE w/input |
| SKOVHOLT (S) | ROSS | DICKER | SHEPPARD (S) | E. COUPE |
| GOLLER (S) | IPPOLITO | KNIGHTON | SLATER (E) | D. THOMPSON (2) |
| P. COLLINS | TEDESCO | YOUNGBLOOD | SMITH (S) | KLEGKER |
| DENISE | LONG | REGAN | TEETS (S) | EISENHUT |
| <u>REG OPR</u> | LAINAS | PROJECT LDR | WILLIAMS (E) | |
| FILE & REGION | BENAROYA | | WILSON (S) | |
| T.R. WILSON | STEELE | HARLESS | INGRAM (S) | |
| | VOLIMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|----------------------------|--------------------------------|------------------------|
| 1-LOCAL PDR. Oswego, N.Y. | (1) (2) (10) -NATIONAL LABS | 1-PDR SAN/LA/NY |
| 1-TIC (ABERNATHY) | 1-W. PENNINGTON, RM E-201 G.T. | 1-BROOKHAVEN NAT LAB |
| 1-NSIC (BUCHANAN) | 1-CONSULTANTS | 1-G. ULRIKSON, ORNL |
| 1-ASLB | NEWMARK/BLUME/AGBABIAN | 1-AGMED (RUTH GUSSMAN) |
| 1-NEWTON ANDERSON | | RM B-127 G.T. |
| 5-ACRS, SENT TO LIC. ASST. | | 1-J. RUNKLES, RM E-201 |
| S. Teets 12-24-74 | | G.T. |

... ..

(12-2)

... ..

... ..

... ..

... ..

... ..

NIAGARA MOHAWK POWER CORPORATION

NIAGARA




MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

December 19, 1974

50 - 220


Mr. Karl R. Goller
Assistant Director of Operating Reactors
Directorate of Licensing
United States Atomic Energy Commission
Washington, D.C. 20545



Dear Mr. Goller:


In accordance with the Technical Specifications for the Nine Mile Point Nuclear Station, Unit #1, the enclosed Abnormal Occurrence Report (74-16) is being submitted. This is in the accepted format as detailed in Regulatory Guide 1.16, Rev. 1.

Very truly yours,


R.R. Schneider
Vice President
Electric Operations

mm

Enc.
REGISTERED MAIL
RETURN RECEIPT REQUEST



12926

NIAGARA MOHAWK POWER CORPORATION

NIAGARA



MOHAWK

Received w/ Lit Dated 12-19-74DATE: December 16, 1974SUBJECT: Abnormal Occurrence Report No. 50-220 /74-16

The enclosed Abnormal Occurrence Report is being submitted in accordance with Technical Specifications Section 6.

TO: James P. O'Reilly
Directorate of Regulatory Operations
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

FROM: Niagara Mohawk Power Corporation
Nine Mile Point - James A. FitzPatrick Site

P.O. Box #32
Lycoming, New York 13093

Docket 50-220



THE UNITED STATES OF AMERICA

DEPARTMENT OF JUSTICE

OFFICE OF THE ATTORNEY GENERAL

WASHINGTON, D. C. 20530

MEMORANDUM FOR THE ATTORNEY GENERAL

RE: [Illegible text]

DATE: [Illegible text]

BY: [Illegible text]

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

SUBJECT: Abnormal Occurrence 10 Day Letter

REFERENCE: License DPR 17.

Report No.: 50-220 /74-16

Report Date: 12/10/74

Occurrence Date: 12/10/74

Facility: NY NMP #1

Identification of Occurrence:


One inoperable IRM (12), in Safety System 11

Conditions Prior to
Occurrence:

| | | | |
|----------------------|--------------------|-------------------|------------------|
| <u> </u> | Steady State Power | <u> </u> | Routine Shutdown |
| <u> </u> | Hot Standby | <u> </u> | |
| <u> </u> | Cold Shutdown | <u> </u> | Load Changes |
| <u> </u> | Refueling Shutdown | <u> </u> | |
| <u> X </u> | Routine Startup | <u> </u> | Other |

Description of the Occurrence:

During routine surveillance it was found that IRM (12) was inoperable. Technical Specifications Table 3.6.2a requires 3 operable Instrument Channels per trip system. This LCO was satisfied as the other 3 IRM's in safety system 11 were operable.



1. The first part of the document discusses the importance of maintaining accurate records of all transactions and activities. It emphasizes the need for transparency and accountability in financial reporting.

2. The second part of the document outlines the various methods and techniques used to collect and analyze data. It includes a detailed description of the experimental procedures and the statistical analysis performed.

3. The third part of the document presents the results of the study, showing the trends and patterns observed in the data. It includes several tables and graphs to illustrate the findings.

4. The fourth part of the document discusses the implications of the results and the potential applications of the findings. It highlights the need for further research and the importance of sharing the results with the relevant stakeholders.

5. The fifth part of the document provides a conclusion and a summary of the key points discussed throughout the document. It also includes a list of references and a bibliography.

Apparent Cause of the Occurrence:

| | |
|---------------------------------------|-----------------------------------|
| <u> </u> Design | <u> </u> Procedure |
| <u> </u> Manufacture | <u> </u> Unusual Service |
| <u> </u> Installation/Const. | <u> </u> Condition |
| <u> </u> Operator | <u> X </u> Component Failure |
| | <u> </u> Other (Specify) |

Cable or detector failure

Analysis of Occurrence:

The IRM system is used to detect and indicate neutron flux level between the source range and the power range instrumentation. Trip signals are provided to the RPS in a one out of two twice logic. It is possible to bypass an inoperative IRM channel from the RPS. The switches for this function are arranged so that only one channel in a safety system bus can be bypassed at one time. The number and locations of the IRM detectors have been analytically and experimentally determined to provide sufficient intermediate range flux level information under the worst permitted bypass or detector failure conditions. A range of rod withdrawal accidents has been analyzed. In the most severe case the reactor is just sub-critical with one fourth of the control rods plus done more rod removed in the normal operating sequence. The error is the removal of the control rod adjacent to the last rod withdrawn. This location is chosen to maximize the distance to the second nearest detector for each RPS trip system. The nearest detector in each trip system is assumed to be bypassed. The rod withdrawal is "seen" and a trip initiated.

Therefore, it can be concluded that one IRM being inoperable would not have prevented the performance of the intended safety function of the IRM system. Further, no hazard would have been presented to the plant safety or health and welfare of the general public from this event.

Corrective Action:

The failure is apparently in either the cable or the detector itself. Therefore, a power reduction and de-inertion of the drywell would be required to repair the IRM. This repair will be undertaken during a refueling shutdown and the nature of repair included in the annual report.

Conclusion:

The IRM will remain bypassed or in a tripped condition until repairs can be made. The LCO Table 3.6.2a is satisfied. Therefore, it is concluded that no hazard is presented to the general public.

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 12788

FILE: INCIDENT REPORT

| | | | | | | | |
|--|-----------------|-------------------------|------------------------|--------------------|--|-----|-------|
| FROM: Niagara Mohawk Power Corp.
Syracuse, N.Y. 13202
R.R. Schneider | | DATE OF DOC
12-17-74 | DATE REC'D
12-19-74 | LTR
X | TWX | RPT | OTHER |
| TO:
Mr. Karl R. Goller | | ORIG
1 signed | CC
39 | OTHER | SENT AEC PDR <u>XX</u>
SENT LOCAL PDR <u>XX</u> | | |
| CLASS | UNCLASS
XXXX | PROP INFO | INPUT | NO CYS REC'D
40 | DOCKET NO:
50-220 | | |

DESCRIPTION: Ltr trans the following:

ENCLOSURES: Abnormal Occurrence AO-74-15 on 11-26-74 involving operator error resulting in an inadvertent trip of power board #167...

(1 Orig & 39 CC rec'd)

Do Not Remove

ACKNOWLEDGED

PLANT NAME: Nine Mile Pt. 1

FOR ACTION/INFORMATION

DHL 12-21-74

| | | | |
|-------------------------|----------------------------|-----------------------------|------------------------|
| BUTLER (S)
W/ Copies | SCHWENCER (S)
W/ Copies | ZIEMANN (S)
W/ Copies | REGAN (E)
W/ Copies |
| CLARK (S)
W/ Copies | STOLZ (S)
W/ Copies | DICKER (E)
W/ Copies | LEAR (S)
W/ Copies |
| PARR (S)
W/ Copies | VASSALLO (S)
W/ Copies | KNIGHTON (E)
W/ Copies | SPEIS (S)
W/ Copies |
| KNIEL (S)
W/ Copies | PURPLE (S)
W/ Copies | YOUNGBLOOD (E)
W/ Copies | |

INTERNAL DISTRIBUTION

| | | | | |
|-------------------|--------------------|---------------|-------------------|-----------------|
| <u>REG FILE</u> | <u>TECH REVIEW</u> | <u>DENTON</u> | <u>LIC. ASST.</u> | <u>A/T IND</u> |
| AEC PDR | SCHROEDER | GRIMES | DIGGS (S) | BRATMAN |
| DGC, ROOM P-506-A | MACCARRY | GAMMILL | GEARIN (S) | SALTZMAN |
| MUNIZING/STAFF | KNIGHT | KASTNER | GOULBOURNE (S) | B. HURT |
| CASE | PAWLICKI | BALLARD | KREUTZER (E) | |
| GIAMBUSSO | SHAO | SPANGLER | LEE (S) | <u>PLANS</u> |
| BOYD | STELLO | | MAIGRET (S) | MCDONALD |
| MOORE (S) (BWR) | HOUSTON | <u>ENVIRO</u> | REED (E) | CHAPMAN |
| DEYOUNG (S) (PWR) | NOVAK | MULLER | SERVICE (S) | DUBE w/input |
| SKOVHOLT (S) | CROSS | DICKER | SHEPPARD (S) | E. COUPE |
| GOLLER (S) | IPPOLITO | KNIGHTON | SLATER (E) | D. THOMPSON (2) |
| P. COLLINS | TEDESCO | YOUNGBLOOD | SMITH (S) | KLEGGER |
| DENISE | LONG | REGAN | TEETS (S) | EISENHUT |
| REG OPR | LAINAS | PROJECT LDR | WILLIAMS (E) | |
| FILE & REGION | BENAROYA | | WILSON (S) | |
| T.R. WILSON | STEELE | HARLESS | INGRAM (S) | |
| | VOLIMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|---------------------------|--------------------------------|------------------------|
| 1-LOCAL PDR Oswego, N.Y. | (1) (2) (10) -NATIONAL LABS | 1-PDR SAN/LA/NY |
| 1-TIC (ABERNATHY) | 1-H. PENNINGTON, RM E-201 G.T. | 1-BROOKHAVEN NAT LAB |
| 1-NSIC (BUCHANAN) | 1-CONSULTANTS | 1-G. ULRIKSON, ORNL |
| 1-ASLB | NEWMARK/BLUME/AGBABIAN | 1-AGMED (RUTH GUSSMAN) |
| 1-NEWTON ANDERSON | | RM B-127 G.T. |
| 5-ACRS SENT TO LIC. ASST. | | 1-J. RUNKLES, RM E-201 |
| S. Teets 12-21-74 | | G.T. |

5

(14)

... ..
... ..
... ..

(15)

... ..

...

...

...

NIAGARA MOHAWK POWER CORPORATION

NIAGARA




MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

50-220

December 17, 1974

Mr. Karl R. Goller
Assistant Director of Operating Reactors
Directorate of Licensing
United States Atomic Energy Commission
Washington, D.C. 20545



Dear Mr. Goller:


In accordance with the Technical Specifications for
the Nine Mile Point Nuclear Station, Unit #1, the enclosed
Abnormal Occurrence Report (74-15) is being submitted.
This is in the accepted format as detailed in Regulatory
Guide 1.16, Rev. 1.

Very truly yours,

R.R. Schneider
Vice President
Electric Operations

mm

Enc.



12788

W. H. L. 1913

Regulatory

File Cy.

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

Received w/ Mr. Bates 12-17-74

DATE: December 17, 1974

SUBJECT: Abnormal Occurrence Report No. 50-220 /74-15

The enclosed Abnormal Occurrence Report is being submitted in accordance with Technical Specifications Section 6.

TO: James P. O'Reilly
Directorate of Regulatory Operations
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

FROM: Niagara Mohawk Power Corporation
Nine Mile Point P

P.O. Box #32
Lycoming, New York 13093

Docket 50-220

THE

OF THE

AND

THE

THE

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWKSUBJECT: Abnormal Occurrence 10 Day LetterREFERENCE: License DPR 17.

Report No.: 50-220 /74-15

Report Date: 12/5/74Occurrence Date: 11/26/74Facility: NY NMP #1

Identification of Occurrence:

An operator error resulting in an inadvertent trip of
power board #167

Conditions Prior to
Occurrence:

| | | | |
|----------------------|--------------------|-------------------|------------------|
| <u> X </u> | Steady State Power | <u> </u> | Routine Shutdown |
| <u> </u> | Hot Standby | <u> </u> | |
| <u> </u> | Cold Shutdown | <u> </u> | Load Changes |
| <u> </u> | Refueling Shutdown | <u> </u> | |
| <u> </u> | Routine Startup | <u> </u> | Other |

1708 MWt 580 MWe

Description of the Occurrence:

During a process of Marking up MG Set #167 the operator inadvertently tripped the supply breaker for power board #167. This power board supplies certain components of the ECCS system with motive valve energy as well as indicating lights for valve position. This event was discovered during a weekly management review of plant operations and further reviewed during a SORC meeting to determine the significance of this event. The powerboard was de-energized for 15 minutes..

1. The first part of the report

is the title page

2. The second part of the report

is the abstract

3. The third part of the report

is the introduction

4. The fourth part of the report

is the literature review

5. The fifth part of the report

is the methodology

6. The sixth part of the report

is the results

7. The seventh part of the report

is the discussion

8. The eighth part of the report

is the conclusion

9. The ninth part of the report

is the references

10. The tenth part of the report
is the appendix
11. The eleventh part of the report
is the bibliography
12. The twelfth part of the report
is the list of figures
13. The thirteenth part of the report
is the list of tables
14. The fourteenth part of the report
is the list of abbreviations
15. The fifteenth part of the report
is the list of symbols
16. The sixteenth part of the report
is the list of units
17. The seventeenth part of the report
is the list of definitions
18. The eighteenth part of the report
is the list of acronyms
19. The nineteenth part of the report
is the list of initialisms
20. The twentieth part of the report
is the list of terms

Apparent Cause of the Occurrence:

_____ Design
_____ Manufacture
_____ Installation/Const.
 X Operator

_____ Procedure
_____ Unusual Service
_____ Condition
_____ Component Failure
_____ Other (Specify)

Analysis of Occurrence:


All redundant components in the ECCS system were in an operable condition and therefore, no hazard would be presented to the general public.

Corrective Action:

The operator has been warned that procedures and orders must be carefully followed. This will be followed up in training sessions for all operators.

Failure Data:

N/A



1. The first part of the document is a list of names and addresses. The names are written in a cursive script, and the addresses are written in a more formal, printed style. The list is organized into two columns, with names on the left and addresses on the right.

2. The second part of the document is a list of names and addresses. The names are written in a cursive script, and the addresses are written in a more formal, printed style. The list is organized into two columns, with names on the left and addresses on the right.

3. The third part of the document is a list of names and addresses. The names are written in a cursive script, and the addresses are written in a more formal, printed style. The list is organized into two columns, with names on the left and addresses on the right.

4. The fourth part of the document is a list of names and addresses. The names are written in a cursive script, and the addresses are written in a more formal, printed style. The list is organized into two columns, with names on the left and addresses on the right.

5. The fifth part of the document is a list of names and addresses. The names are written in a cursive script, and the addresses are written in a more formal, printed style. The list is organized into two columns, with names on the left and addresses on the right.

6. The sixth part of the document is a list of names and addresses. The names are written in a cursive script, and the addresses are written in a more formal, printed style. The list is organized into two columns, with names on the left and addresses on the right.

7. The seventh part of the document is a list of names and addresses. The names are written in a cursive script, and the addresses are written in a more formal, printed style. The list is organized into two columns, with names on the left and addresses on the right.

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 12750

FILE: INCIDENT REPORT

| | | | | | | | |
|--|-----------------|-------------------------|------------------------|-------------------|--------------------------------------|-----|-------|
| FROM: Niagara Mohawk Power Corp.
Lycoming, N.Y. 13093 | | DATE OF DOC
12-10-74 | DATE REC'D
12-18-74 | LTR
X | TWX | RPT | OTHER |
| TO:
Mr. J.P. O'Reilly | | ORIG | CC
1 | OTHER | SENT AEC PDR XX
SENT LOCAL PDR XX | | |
| CLASS | UNCLASS
XXXX | PROP INFO | INPUT | NO CYS REC'D
1 | DOCKET NO:
50-220 | | |

DESCRIPTION: Ltr trans the following:

ENCLOSURES: Abnormal Occurrence AO-50-220/74-16 on 12-10-74 involving one inoperable IRM (12) in Safety System II....

(1 cy encl rec'd)

ACKNOWLEDGED

Do Not Remove

PLANT NAME: Nine Mile Pt. Unit 1

FOR ACTION/INFORMATION

DHL 12-23-74

| | | | |
|-------------------------|----------------------------|-----------------------------|------------------------|
| BUTLER (S)
W/ Copies | SCHWENCER (S)
W/ Copies | ZIEMANN (S)
W/ Copies | REGAN (E)
W/ Copies |
| CLARK (S)
W/ Copies | STOLZ (S)
W/ Copies | DICKER (E)
W/ Copies | LEAR (S)
W/4 Copies |
| PARR (S)
W/ Copies | VASSALLO (S)
W/ Copies | KNIGHTON (E)
W/ Copies | SPEIS (S)
W/ Copies |
| KNIEL (S)
W/ Copies | PURPLE (S)
W/ Copies | YOUNGBLOOD (E)
W/ Copies | |

INTERNAL DISTRIBUTION

| | | | | |
|---|---|--|---|--|
| <u>REG FILE</u>
AEC PDR
OGC, ROOM P-506-A
MUNIZING/STAFF
CASE
GIAMBUSSO
BOYD
MOORE (S) (BWR)
DEYOUNG (S) (PWR)
SKOVHOLT (S)
GOLLER (S)
P. COLLINS
DENISE
REG OPR
FILE & REGION
T.R. WILSON | <u>TECH REVIEW</u>
SCHROEDER
MACCARRY
KNIGHT
PAWLICKI
SHAO
STELLO
HOUSTON
NOVAK
ROSS
IPPOLITO
TEDESCO
LONG
LAINAS
BENAROYA
STEELE
VOLIMER | <u>DENION</u>
GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

<u>ENVIRO</u>
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR
HARLESS | <u>LIC. ASST.</u>
DIGGS (S)
GEARIN (S)
GOULBOURNE (S)
KREUTZER (E)
LEE (S)
MAIGRET (S)
REED (E)
SERVICE (S)
SHEPPARD (S)
SLATER (E)
SMITH (S)
TEETS (S)
WILLIAMS (E)
WILSON (S)
INGRAM (S) | <u>A/T IND</u>
BRAITMAN
SALTZMAN
B. HURT

<u>PLANS</u>
MCDONALD
CHAPMAN
DUBE w/input
E. COUPE
D. THOMPSON (2)
KLECKER
EISENHUT |
|---|---|--|---|--|

EXTERNAL DISTRIBUTION

| | | |
|---|---|---|
| 1-LOCAL PDR Oswego, N.Y.
1-TIC (ABERNATHY)
1-NSIC (BUCHANAN)
1-ASLB
1-NEWTON ANDERSON
5-ACRS SENT TO LIC. ASST.
S. Teets 12-23-74 | (1) (2) (10) - NATIONAL LABS
1-M. PENNINGTON, RM E-201 G.T.
1-CONSULTANTS
NEWMARK/BLUME/AGBABIAN | 1-PDR SAN/LA/NY
1-BROOKHAVEN NAT LAB
1-G. ULRIKSON, ORNL
1-AGMED (RUTH GUSSMAN)
RM B-127 G.T.
1-J. RUNKLES, RM E-201
G.T. |
|---|---|---|

... ..

...

(222)

... ..
... ..
... ..

...

... ..)

...

...

...

...

NIAGARA MOHAWK POWER CORPORATION

Reg. No.

By

NIAGARA MOHAWK

DATE: December 10, 1974

SUBJECT: Abnormal Occurrence Report No. 50-220 /74-16


The enclosed preliminary AOR is being submitted in accordance with Technical Specifications Section 6.

TO: James P. O'Reilly
Directorate of Regulatory Operations
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

FROM: Niagara Mohawk Power Corporation
Nine-Mile Point - James A. FitzPatrick Site

P.O. Box #32
Lycoming, New York 13093

Docket 50-220



NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

Received by 12-10-74

SUBJECT: Abnormal Occurrence 24 hour Notification

Confirming Mr. T. Perkins phone conversation
with Mr. T. Shediowsky AEC RO:1 office on
12/10/74

REFERENCE: License DPR 17

Report No.: 50-220 /74-16

Report Date: 12/10/74

Occurrence Date: 12/10/74

Facility: NY NPP #1

Identification of Occurrence:

One inoperable IRM (12), in Safety System II

**Conditions Prior to
Occurrence:**

| | | | |
|------------------------------|--------------------|-----------------------------|------------------|
| <u> </u> | Steady State Power | <u> </u> | Routine Shutdown |
| <u> </u> | Hot Standby | <u> </u> | |
| <u> </u> | Cold Shutdown | <u> </u> | Load Changer |
| <u> </u> | Refueling Shutdown | <u> </u> | |
| <u> X </u> | Routine Startup | <u> </u> | Other |

Description of the Occurrence:

During routine surveillance it was found that IRM (12) was inoperable. Technical Specifications Table 3.6.2a requires 3 operable Instrument channels per trip system. This LCO was satisfied as the other 3 IRM's in safety system II were operable.



100-100



Apparent Cause of the Occurrence:

_____ Design
_____ Manufacture
_____ Installation/Const.
_____ Operator

_____ Procedure
_____ Unusual Service
_____ Condition
X _____ Component Failure
_____ Other (Specify)

Cable or detector failure.

Analysis of Occurrence:

The IRM System is used to detect and indicate neutron flux level between the source range and the power range instrumentation. Trip signals are provided to the RPS in a one out of two twice logic. It is possible to bypass an inoperative IRM channel from the RPS. The switches for this function are arranged so that only one channel in a safety system bus can be bypassed at one time. The number and locations of the IRM detectors have been analytically and experimentally determined to provide sufficient intermediate range flux level information under the worst permitted bypass or detector failure conditions. A range of rod withdrawal accidents has been analyzed. In the most severe case the reactor is just sub-critical with one fourth of the control rods plus one more rod removed in the normal operating sequence. The error is the removal of the control rod adjacent to the last rod withdrawn. This location is chosen to maximize the distance to the second nearest detector for each RPS trip system. The nearest detector in each trip system is assumed to be bypassed. The rod withdrawal is "seen" and a trip initiated.

Therefore, it can be concluded that one IRM being inoperable would not have prevented the performance of the intended safety function of the IRM system. Further, no hazard would have been presented to the plant safety or health and welfare of the general public from this event.

Corrective Action:

Later

Failure Data:

Later



AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 12527

FILE: INCIDENT REPORT

| | | | | | | | |
|--|---------|-------------------------|------------------------|-------------------|--|-----|-------|
| FROM: Niagara Mohawk Power Corp.
Syracuse, N.Y. 13202
R.R. Schneider | | DATE OF DOC
12-10-74 | DATE REC'D
12-12-74 | LTR
X | TWX | RPT | OTHER |
| TO:
Mr. Karl Goller | | ORIG
1 signed | CC | OTHER | SENT AEC PDR <u>XX</u>
SENT LOCAL PDR <u>XX</u> | | |
| CLASS
XXXX | UNCLASS | PROP INFO | INPUT | NO CYS REC'D
1 | DOCKET NO:
50-220 | | |

DESCRIPTION: Ltr trans the following:

ENCLOSURES: Unusual Event on 11-10-74 involving calculations of fuel channel deflections indicate an increase in core bypass flow over that assumed on the original design..

Do Not Remove
ACKNOWLEDGED

PLANT NAME: Nine Mile Pt. Unit 1

(1 cy encl rec'd)

FOR ACTION/INFORMATION

DHL 12-13-74

| | | | |
|-------------------------|----------------------------|-----------------------------|-------------------------|
| BUTLER (S)
W/ Copies | SCHWENCER (S)
W/ Copies | ZIEMANN (S)
W/ Copies | REGAN (E)
W/ Copies |
| CLARK (S)
W/ Copies | STOLZ (S)
W/ Copies | DICKER (E)
W/ Copies | LEAR (S)
W/ 4 Copies |
| PARR (S)
W/ Copies | VASSALLO (S)
W/ Copies | KNIGHTON (E)
W/ Copies | SPEIS (S)
W/ Copies |
| KNIEL (S)
W/ Copies | PURPLE (S)
W/ Copies | YOUNGBLOOD (E)
W/ Copies | |

INTERNAL DISTRIBUTION

| | | | | |
|---|--|--|---|---|
| <u>REG FILE</u>
AEC PDR
OGC, ROOM P-506-A
MUNTING/STAFF
CASE
GIAMBUSO
BOYD
MOORE (S) (BWR)
DEYOUNG (S) (PWR)
SKOVHOLT (S)
GOLLER (S)
P. COLLINS
DENISE
REG OPR
FILE & REGION
T.R. WILSON | <u>TECH REVIEW</u>
SCHROEDER
MACCARRY
KNIGHT
AWLICKI
SHAO
STELLO
HOUSTON
NOVAK
ROSS
IPPOLITO
TEDESCO
LONG
LAINAS
BENAROYA
STEELE
VOLIMER | <u>DENTON</u>
GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

<u>ENVIRO</u>
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR
HARLESS | <u>LIC. ASST.</u>
DIGGS (S)
GEARIN (S)
GOULBOURNE (S)
KREUTZER (E)
LEE (S)
MAIGRET (S)
REED (E)
SERVICE (S)
SHEPPARD (S)
SLATER (E)
SMITH (S)
TEETS (S)
WILLIAMS (E)
WILSON (S)
INGRAM (S) | <u>A/T IND.</u>
BRAITMAN
SALTZMAN
B. HURT

<u>PLANS</u>
MCDONALD
CHAPMAN
DUBE w/input
E. COUPE
D. THOMPSON (2)
KLECKER
EISENHUT |
|---|--|--|---|---|

EXTERNAL DISTRIBUTION

| | | |
|---|--|---|
| 1-LOCAL PDR Oswego, N.Y.
1-TIC (ABERNATHY)
1-NSIC (BUCHANAN)
1-ASLB
1-NEWTON ANDERSON
1-ACRS SENT TO LIC. ASST.
S. Teets 12-13-74 | (1) (2) (10) -NATIONAL LABS
1-M. PENNINGTON, RM E-201 G.T.
1-CONSULTANTS
NEWMARK/BLUME/AEBABIAN | 1-PDR SAN/LA/NY
1-BROOKHAVEN NAT LAB
1-G. ULRIKSON, ORNL
1-AGMED (RUTH GUSSMAN)
RM B-127 G.T.
1-J. RUNKLES, RM E-201
G.T. |
|---|--|---|

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000


1000

50-220

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202




~~Regulatory~~

~~File Cy.~~

December 10, 1974


Mr. Karl R. Goller
Assistant Director of Operating Reactors
Directorate of Licensing
U.S. Atomic Energy Commission
Washington, D.C. 20545



Dear Mr. Goller:

In accordance with the Technical Specifications
for the Nine Mile Point Nuclear Station Unit #1, the enclosed
Unusual Event is being submitted. This is in the accepted
format as detailed in Regulatory Guide 1.16, Rev. 1.

Very truly yours,


R.R. Schneider
Vice President
Electric Operations

TJD/mm

Enc.

12527.

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

NINE MILE POINT NUCLEAR PLANT

Received w/ Ltr. Dated 12-10-74

UNUSUAL EVENT

1. Docket No. 50-220 DPR-17
- 2a. Date December 10, 1974
- 2b. Occurrence Date November 10, 1974
3. Facility NY NMP #1
4. Identification of Occurrence

Nine Mile Point Unit 1 has been informed by General Electric Co., our fuel supplier, that their calculations of fuel channel deflections indicate an increase in core bypass flow over that assumed on the original design.

5. Conditions of Plant

The reactor is presently 2200 MWD/ST into the operating cycle with a targeted cycle exposure potential of 5500 MWD/ST.

6. Description of Occurrence

Nine Mile Point Unit #1 has had a channel measuring and evaluation program for the past several years. Primarily the interested channel deflections are (1) elastic deflection due to differential pressure across the channel wall and (2) permanent deflection due to relaxation of fabricated stresses and inservice creep of irradiated zircalog.

These deflections could potentially cause three problems: (1) an increase in core leakage flow (less water flow thru the fuel assembly) (2) less clearance between the channel and the control rod (control rod interference) (3) less clearance between the corner fuel rod and the inside channel wall. The results of the studies and measurements indicated no control rod interference or corner rod to channel decrease clearance. The channel deflection study did show that an increase in bypass leakage flow has occurred. This concurs with a letter from Mr. J.A. Hinds (G.E. Co.) to the Atomic Energy Commission dated November 28, 1973. In this letter, it was stated that the major effect of channel deformation is a decrease in in-channel flow.



Unusual Event
NY NMP #1

7. Analysis and Corrective Action

Changes in core bypass flow only slightly affect the void coefficient and operational transient analyses. Because a boundary analysis approach was taken in performing the transient analysis, the affects of increased core bypass flow are well within the applicability of the transient analyses and will remain so throughout this cycle. In the future, channels will be replaced on an accelerated schedule and finger springs will be used on reload fuel to control leakage.

The thermal margins during normal operation will be maintained. Minimum critical heat flux ratio will be maintained above 1.9 for all fuel and the minimum critical power racks will be maintained above 1.24 and 1.29 for 7x7 and 8x8 fuel respectively. Conservative adjustments will be applied to our calculational procedures to account for reductions in in-channel flow.

The locus of operating conditions for which the most limiting rod has a minimum critical heat flux ratio equal to 1.0 as described by Figure 2.1.1 of the Technical Specifications is essentially unaffected. That curve assumes an initial MCHFR of 1.9 at rated power and total core flow conditions. Because the reduction in in-channel flow is accounted for in the calculations of operation conditions, the initial MCHFR remains at 1.9 (rated power and core flow) and the effect on the safety limit line is insignificant.

Another potential effect of channel bowing is the possibility of fuel channel-control rod interference. Any interference would be gradual and channels will be replaced well before any expected problems. Scram times and other parameters will be monitored to detect any onset of fuel channel-control rod interference.

NIAGARA MOHAWK POWER CORPORATION

NIAGARA MOHAWK

DATE: December 4, 1974

DK Central Files

SUBJECT:

Abnormal Occurrence Report No. 50- 220 /74- 15

The enclosed preliminary AOR is being submitted in accordance with Technical Specifications Section 6.

TO:

James P. O'Reilly
Directorate of Regulatory Operations
Region 1
651 Park Avenue
King of Prussia, Pennsylvania 19406

FROM:

Niagara Mohawk Power Corporation
Nine Mile Point - James A. FitzPatrick Site

P.O. Box #32
Lycoming, New York 13093

Docket 50- 220

NIAGARA MOHAWK POWER CORPORATION

NIAGARA MOHAWK

SUBJECT: Abnormal Occurrence 24 hour Notification

Confirming Mr. C.L. Stuart phone conversation
with Mr. T. Shedlosky ABC RO:1 office on
12/4/74

REFERENCE: License DPR 17

Report No.: SO- 220 /74- 15

Report date: 12/5/74

Occurrence Date: 11/26/74

Facility: NY NMP # 1

Identification of Occurrence:

On operator error resulting in an inadvertent trip of
power board #167

Conditions Prior to Occurrence:

| | |
|--|---|
| <input checked="" type="checkbox"/> Steady State Power | <input type="checkbox"/> Routine Shutdown |
| <input type="checkbox"/> Hot Standby | <input type="checkbox"/> Load Changes |
| <input type="checkbox"/> Cold Shutdown | <input type="checkbox"/> Other |
| <input type="checkbox"/> Refueling Shutdown | |
| <input type="checkbox"/> Routine Startup | |

1700 MW 500 MW

Description of the Occurrence:

During a process of "Marking Up" MG Set #167 the operator inadvertently tripped the supply breaker for power board 167. This power board supplies certain components of the ECCS system with motive valve energy as well as indicating lights for valve position. This event was discovered during a weekly management review of plant operations and further reviewed during a SORC meeting to determine the significance of this event. The powerboard was de-energized for 15 minutes.



11/11/11

Apparent Cause of the Occurrence:

_____ Design
_____ Manufacture
_____ Installation/Const.
X _____ Operator

_____ Procedure
_____ Unusual Service
_____ Condition
_____ Component Failure
_____ Other (Specify)

Analysis of Occurrence:

All redundant components in the ECCS system were in an operable condition and therefore, no hazard would be presented to the general public.

Corrective Action:

The operator has been warned that procedures and orders must be carefully followed. This will be followed up in training sessions for all operators.

Failure Data:

N/A

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 12148

FILE: _____

| | | | | | | | |
|--|----------------|-------------------------|------------------------|--------------------|--|-----|-------|
| FROM: Niagara Mohawk Power Corp.
Syracuse, N.Y. 13202
R.R. Schneider | | DATE OF DOC
11-27-74 | DATE REC'D
11-29-74 | LTR
X | TWX | RPT | OTHER |
| TO:
Mr. Donald J. Skovholt | | ORIG
1 signed | CC
39 | OTHER | SENT AEC PDR <u>XX</u>
SENT LOCAL PDR <u>XX</u> | | |
| CLASS | UNCLASS
XXX | PROP INFO | INPUT | NO CYS REC'D
40 | DOCKET NO:
50-220 | | |

DESCRIPTION: Ltr trans the following:

ENCLOSURES: Abnormal Occurrence 50-220/74-14 which occurred on 11-20-74 involving failure to perform required surveillance frequency on battery tests.....

Do Not Remove

(40 cys encl rec'd)

ACKNOWLEDGED

PLANT NAME: Nine Mile Pt. Unit 1

FOR ACTION/INFORMATION

DHL 11-30-74

| | | | |
|------------|---------------|----------------|-----------|
| BUTLER (L) | SCHWENCER (L) | ZIEMANN (L) | REGAN (E) |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| CLARK (L) | STOLZ (L) | DICKER (E) | LEAR (L) |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| PARR (L) | VASSALLO (L) | KNIGHTON (E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| KNIEL (L) | PURPLE (L) | YOUNGBLOOD (E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|--------------------------------|------------------------|----------------|-----------------|---------------------------|
| REG FILE | <u>TECH REVIEW</u> | <u>DENTON</u> | <u>LIC ASST</u> | <u>A/T IND</u> |
| ✓ AEC PDR | ✓ SCHROEDER | GRIMES | | BRAITMAN |
| ✓ GGC, ROOM P-506A | ✓ MACCARY | GAMMILL | DIGGS (L) | SALTZMAN |
| ✓ MUNTZING/STAFF | ✓ KNIGHT | CASTNER | GEARIN (L) | B. HURT |
| ✓ CASE | ✓ AWLICKI | BALLARD | GOULBOURNE (L) | |
| GIAMBUSSO | ✓ SHAO | SPANGLER | KREUTZER (E) | <u>PLANS</u> |
| BOYD | ✓ STELLO | | LEE (L) | MCDONALD |
| MOORE (L) (BWR) | ✓ HOUSTON | <u>ENVIRO</u> | MAIGRET (L) | CHAPMAN |
| DEYOUNG (L) (PWR) | ✓ KOVAK | MULLER | REED (E) | DUBE w/input |
| SKOVHOLT (L) | ✓ ROSS | DICKER | SERVICE (L) | E. COUPE |
| GOLLER (L) | ✓ PROLITO | KNIGHTON | SHEPPARD (L) | |
| P. COLLINS | ✓ TEDESCO | YOUNGBLOOD | SLATER (E) | ✓ THOMPSON (2) |
| DENISE | ✓ LONG | REGAN | SMITH (L) | ✓ LECKER |
| ✓ REG OPR | ✓ MAINAS | PROJECT LDR | TEETS (L) | ✓ EISENHUT |
| ✓ FILE & REGION (3) | ✓ ENAROYA | | WILLIAMS (E) | |
| ✓ MORRIS | ✓ VOLIMER | <u>HARLESS</u> | WILSON (L) | |
| ✓ STEELE | | | | |

EXTERNAL DISTRIBUTION

| | | |
|--|---------------------------------|--------------------------------|
| ✓ LOCAL PDR Oswego, N.Y. | | |
| ✓ TIC (ABERNATHY) (1)(2)(10) | 1 - NATIONAL LABS | 1 - PDR SAN/LA/NY |
| ✓ 1 - NSIC (BUCHANAN) | 1 - ASLBPIE/V Bldg, Rm 529) | 1 - BROOKHAVEN NAT LAB |
| 1 - ASLB | 1 - W. PENNINGTON, Rm E-201 GT | 1 - G. ULRIKSON, ORNL |
| 1 - Newton Anderson | 1 - B&M SWINEBROAD, Rm E-201 GT | 1 - AGMED (RUTH GUSSMAN) |
| 1 - ACRS HOLDING | 1 - CONSULTANTS | Rm B-127 GT |
| ✓ 5 Sent to Lic Asst. S. TEETS 11-30-74 | NEWARK BLUME/AGBABIAN | 1 - R. D. MUELLER, Rm E-201 GT |

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

Regulatory

File-Cy

November 27, 1974

50 - 220

Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D.C. 20545




Dear Mr. Skovholt:

In accordance with the Technical Specifications for the Nine Mile Point Nuclear Station, Unit #1, the enclosed Abnormal Occurrence is submitted. The report is in the format detailed in Regulatory Guide 1.16 Rev. 1.

Very truly yours,


R.R. Schneider
Vice President
Electric Operations



TJD/nmm

Enc.

12148

Wm. H. Miller

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

NINE MILE POINT - J.A. FITZPATRICK

Resolved By/Ltr Dated 11-27-74

1. Report No. 50-220/74-14

2a. Date November 21, 1974

2b. Occurrence Date November 20, 1974

3. Facility NY NMP # 1

4. Identification of Occurrence

Failure to perform required surveillance frequency on battery tests. Specification 4.6.3b.

5. Condition Prior to Occurrence

During the period the unit was operated at a peak load of 1830 mwt, this load was maintained until October when a pattern swap at low power was completed and reactor power decreased to 0.

6. Description of Occurrence

During management review of monthly surveillance tests, it was found that the station batteries were not tested as required by specification 4.6.3b. (Specific gravity of each cell on monthly basis). The October readings were taken on November 5, the July readings on August 1 and the September readings on October 2. The maximum time between tests occurred between 8/26 and 10/2, 37 days.

7. Designation of Apparent Cause of the Occurrence

Misinterpretation of the requirements as related by Operations Department to the Maintenance Department.

8. Analysis of Occurrence

The station battery, two independent systems, is used as a power source for breaker operation and instrumentation and control. Certain plant emergency systems (lighting, bearing oil pumps, etc.) are powered from the battery, in the event of loss of AC power. The battery, therefore, could prevent serious equipment damage and excessive maintenance. The monthly checks of the battery are provided to assure that all cells will satisfactorily handle full-rated current if necessary. By extending the surveillance frequency to 37 days in one case does not reduce the capability of the system to function as required, however, it does complicate the process of logically determining whether or not a trendable discharge is in progress. Pilot cells are checked each day and the battery is floating across a battery charger which would maintain the battery in full readiness.




8. Continued

During review of the test no degradation of the cells was noted, therefore, no hazard would have been presented the general public.

9. Corrective Action

The maintenance foreman was notified of the requirement for monthly tests. In addition, management controls in this area of surveillance testing are being reviewed and methods are being evaluated. A change will be made to assure that this event does not happen again.

10. N/A



NIAGARA MOHAWK POWER CORPORATION

NIAGARA MOHAWK

NINE MILE POINT - J.A. FITZPATRICK

1. Report No. 50-220/74-14

2a. Date 11-21-74

2b. Occurrence Date 11-20-74

3. Facility NY NMP #1

4. Identification of Occurrence

Failure to perform required surveillance frequency on battery tests.
Specification 4.6.5b.

5. Condition Prior to Occurrence

During the period the unit was operated at a peak load of 1050 mwt, this load was maintained until October when a pattern swap at low power was completed and reactor power decreased to 0.

6. Description of Occurrence

During management review of monthly surveillance tests, it was found that the station batteries were not tested as required by specification 4.6.5b. (Specific gravity of each cell on monthly basis). The October readings were taken on November 5, the July readings on 1 August and the September readings on October 2. The maximum time between tests occurred between 8/26 and 10/2, 37 days.

7. Designation of Apparent Cause of the Occurrence

Misinterpretation of the requirements as related by Operations department to the Maintenance department.

8. Analysis of Occurrence

The station battery, two independent systems, is used as a power source for breaker operation and instrumentation and control. Certain plant emergency systems (lighting, bearing oil pumps, etc.) are powered from the battery, in the event of loss of AC power. The battery, therefore, could prevent serious equipment damage and excessive maintenance. The monthly checks of the battery are provided to assure that all cells will satisfactorily handle full-rated current if necessary. By extending the surveillance frequency to 37 days in one case does not reduce the capability of the system to function as required, however, it does complicate the process of logically determining whether or not a credible discharge is in progress. Pilot cells are checked each day and the battery is floating across a battery charger which would maintain the battery in full readiness. During review of the test no degradation of the cells was noted, therefore, no hazard would have been presented to the general public.

A104

July

9. Corrective Action.

The maintenance foreman was notified of the requirement for monthly tests. In addition, management controls in this area of surveillance testing are being reviewed and methods are being evaluated. A change will be made to assure that this event does not happen again.

10. N/A



Handwritten scribble or signature in the top right corner.

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 11261

FILE: _____

| | | | | | | | | |
|---|-----------------------|-----------|-------------------------|-----------------------|------------|--|-----|-------|
| FROM: Niagara Mohawk Power Corp
Syracuse, N.Y.
R.R. Schneider | | | DATE OF DOC
10-31-74 | DATE REC'D
11-4-74 | LTR
xxx | TWX | RPT | OTHER |
| TO:
Mr. Donald J. Skovholt | | | ORIG
1-signed | CC | OTHER | SENT AEC PDR <u>XXXXXXXXXXXX</u>
SENT LOCAL PDR <u>XXXXXX</u> | | |
| CLASS | UNCLASS
XXXXXXXXXX | PROP INFO | INPUT | NO CYS REC'D | | DOCKET NO:
50-220 | | |

DESCRIPTION:

Ltr Trans the Following:

ACKNOWLEDGED
DO NOT REMOVE

PLANT NAME: Nine Mile Point Unit #1

ENCLOSURES:

Abnormal Occurrence on 10-1-74 concerning
Variance from performance specifications
contained in the Tech-Specs.....

FOR ACTION/INFORMATION 11-7-74 JGB


| | | | |
|-------------------------|----------------------------|-----------------------------|-------------------------|
| BUTLER (L)
W/ Copies | SCHWENCER (L)
W/ Copies | ZIEMANN (L)
W/ Copies | REGAN (E)
W/ Copies |
| CLARK (L)
W/ Copies | STOLZ (L)
W/ Copies | DICKER (E)
W/ Copies | ✓ LEAR (L)
W/ Copies |
| PARR (L)
W/ Copies | VASSALLO (L)
W/ Copies | KNIGHTON (E)
W/ Copies | W/ Copies |
| KNIEL (L)
W/ Copies | PURPLE (L)
W/ Copies | YOUNGBLOOD (E)
W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|---|---|----------------|-----------------|---|
| <input checked="" type="checkbox"/> REG FILE | TECH REVIEW | DENTON | LIC ASST | A/T IND |
| <input checked="" type="checkbox"/> AEC PDR | <input checked="" type="checkbox"/> SCHROEDER | GRIMES | | BRAITMAN |
| <input checked="" type="checkbox"/> OGC, ROOM P-506A | <input checked="" type="checkbox"/> MACCARY | GAMMILL | DIGGS (L) | SALTZMAN |
| <input checked="" type="checkbox"/> MUNTZING/STAFF | <input checked="" type="checkbox"/> KNIGHT | KASTNER | GEARIN (L) | B. HURT |
| <input checked="" type="checkbox"/> CASE | <input checked="" type="checkbox"/> PAWLICKI | BALLARD | GOULBOURNE (L) | PLANS |
| GIAMBUSSO | <input checked="" type="checkbox"/> SHAO | SPANGLER | KREUTZER (E) | MCDONALD |
| BOYD | <input checked="" type="checkbox"/> STELLO | ENVIRO | LEE (L) | CHAPMAN |
| MOORE (L) (BWR) | <input checked="" type="checkbox"/> HOUSTON | MULLER | MAIGRET (L) | DUBE w/input |
| DEYOUNG (L) (PWR) | <input checked="" type="checkbox"/> NOVAK | DICKER | REED (E) | E. COUPE |
| SKOVHOLT (L) | <input checked="" type="checkbox"/> ROSS | KNIGHTON | SERVICE (L) | |
| <input checked="" type="checkbox"/> GOLLER (L) | <input checked="" type="checkbox"/> IPPOLITO | YOUNGBLOOD | SHEPPARD (L) | <input checked="" type="checkbox"/> D. THOMPSON (2) |
| P. COLLINS | <input checked="" type="checkbox"/> TEDESCO | REGAN | SLATER (E) | <input checked="" type="checkbox"/> KLECKER |
| DENISE | <input checked="" type="checkbox"/> LONG | PROJECT LDR | SMITH (L) | <input checked="" type="checkbox"/> EISENHUT |
| <input checked="" type="checkbox"/> REG OPR | <input checked="" type="checkbox"/> LAINAS | HARLESS | ✓ TEETS (L) | |
| <input checked="" type="checkbox"/> FILE & REGION (3) | <input checked="" type="checkbox"/> BENAROYA | | WILLIAMS (E) | |
| <input checked="" type="checkbox"/> MORRIS | <input checked="" type="checkbox"/> VOLIMER | | WILSON (L) | |
| <input checked="" type="checkbox"/> STEELE | | | | |

EXTERNAL DISTRIBUTION

| | | |
|---|---|--------------------------------|
| <input checked="" type="checkbox"/> 1 - LOCAL PDR <u>Oswego, N.Y.</u> | <input checked="" type="checkbox"/> 1 - NATIONAL LABS _____ | 1 - PDR-SAN/LA/NY |
| <input checked="" type="checkbox"/> 1 - TIC (ABERNATHY) (1)(2)(10) | 1 - ASLBP(E/W Bldg, Rm 529) | 1 - BROOKHAVEN NAT LAB |
| <input checked="" type="checkbox"/> 1 - NSIC (BUCHANAN) | 1 - W. PENNINGTON, Rm E-201 GT | 1 - G. ULRIKSON, ORNL |
| 1 - ASLB | 1 - B&M SWINEBROAD, Rm E-201 GT | 1 - AGMED (RUTH GUSSMAN) |
| 1 - Newton Anderson | 1 - CONSULTANTS | Rm B-127 GT |
| <input checked="" type="checkbox"/> 5 - ACRS HOLDING | NEWMARK/BLUME/AGBABIAN | 1 - R. D. MUELLER, Rm E-201 GT |



NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202



October 31, 1974

Regulatory

File Cy.

Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D.C. 20545

50-220

Dear Mr. Skovholt:

In accordance with Technical Specifications for
Nine Mile Point Unit 1, the enclosed Unusual Event Report
is submitted. This report is in accordance with the format
set forth in Regulatory Guideline 1.16.


Very truly yours,



R.R. Schneider
Vice President -
Electric Operations

TJD/MM
Enc.

registered mail
return receipt requested



11261

Handwritten signature or scribble.

UNUSUAL EVENT REPORT

- | | | |
|-----|-------------------------------------|-------------------------|
| 1. | <u>Report No.</u> | Unusual Event |
| 2a. | <u>Date</u> | October 30, 1974 |
| 2b. | <u>Occurrence Date</u> | October 1, 1974 |
| 3. | <u>Facility</u> | Nine Mile Point Unit #1 |
| 4. | <u>Identification of Occurrence</u> | |

Variance from performance specifications contained in the Technical Specifications.

5. Condition Prior to Occurrence

Unit steady state 97%-98% power.

6. Description of Occurrence

During testing on the containment spray raw water pumps, it was revealed that the installed, as built design, for flow measurement was not adequate to determine performance as established in the Technical Specifications.

The existing flow instrumentation ranges from 0 to 150,000 lbs/hr (0-3000 gpm). During surveillance testing the indicated flow has generally indicated greater than the 150,000 lb/hr upper point, or off scale. Testing was then conducted, over and above surveillance requirements, to establish a reasonable range for the instrumentation in which the indicated flow would not exceed the upper readable point. During this testing, it was discovered that the precision required for system performance as established in the Technical Specifications could not be obtained on the flow measurements. This is due to the piping design of the system which does not permit the flow orifice to determine, within required accuracy, the raw flow parameter. Thus correlation to the certified pump curve cannot be made with both the Total Developed Head (TDH) and pump flow.

The acceptable performance of the system as documented by the Final Safety Analysis Report (FSAR), requires a system flow of 3000 gpm and a minimum pressure on the raw water side of the heat exchanger of 160 psig. A variance, therefore, exists between the Technical Specifications and the FSAR. This is an Unusual Event as defined in Technical Specification 6.6.b(2)b.

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944

7. Designation of Apparent Cause of the Occurrence

Inability to adequately determine Laboratory pump curve flow at design TDH in the Station.

8. Analysis of Occurrence

Inspection of the vertical pump shows no unusual or unexpected condition. The shutoff head as measured compares favorably with the pump curve. The containment spray raw water system is a 400% redundant system designed to maintain containment spray water temperature no greater than 140 F under the most limiting operating conditions. A flow rate of 3000 gpm is used in the supporting safety analysis (FSAR) to maintain this temperature. A requirement to obtain a greater pressure on the raw water side of the heat exchanger is provided to maintain any leakage flow into the containment system. As indicated in the Safety Analysis (FSAR Vol. I VII-22), the containment side of the heat exchangers will operate at 123 psig, including containment pressure, under accident conditions. The design raw water side operating pressure is 160 psig. Presently, the raw water side operates at 180-185 psig with a pump total discharge head of 540 feet of water. This is considerably more than required.

9. Corrective Action

Each of the four (4) pumps were tested in accordance with the Hydraulic Institute Standard requirements before shipment from the factory in July 1969 and met or exceeded the specified design performance. During the course of the in-plant investigation it was decided to open up one of the pumps for inspection. This inspection revealed that little if any wear could be observed, or in other words the pump appeared to be in near new condition. This fact is further substantiated by operating reports that indicate total operating time on each pump since their original installation is less than 25 hours.

Because of the fact that these pumps did meet or exceed their design performance at the factory, have total operating time of less than 25 hours and recent inspection indicated like new condition, it is concluded that were the pumps subjected to a new test conducted in accord with the Hydraulic Institute Standards that they would meet their specified design performance.

Therefore, based on the above conclusion, the flow through each of the pumps will be adjusted such that the corrected TDH is 540 ft. of water. When operating at this TDH, the flow meter indication will be adjusted to read 3000 gpm. This activity will in effect calibrate the orifice plate and give a very accurate flow indication for that range of flows.

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

91

92

93

94

95

96

97

98

99

100

9. Continued

In addition, the performance specification as defined in the bases of the Technical Specification will be rewritten reflecting the safety analysis as presented in the FSAR. This change will rectify the existing variance. This change will be reviewed by the Safety Review and Audit Board at their next regular meeting and submitted in accordance with Section 6 of the Technical Specifications. The change will reflect a requirement to measure the pressure on the raw water side of the heat exchanger (minimum 160 psig) at an indicated flow of at least 3000 gpm on the flow meter. With this clarification of performance determination, the system flow and heat exchanger pressure will correlate directly to the required Safety Analysis and not a design point on a pump curve.

10. Conclusion

The investigative actions, results and conclusions meet with full approval of the SORC and that committee concludes that this event does not present a hazard to the health and safety to the general public.

Page 1 of 1

The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that proper record-keeping is essential for the integrity of the financial system and for the ability to detect and prevent fraud. The document also outlines the responsibilities of individuals involved in the process, including the need for transparency and accountability.

The second part of the document provides a detailed overview of the various methods used to collect and analyze data. It describes the different types of data sources, such as surveys, interviews, and focus groups, and explains how this information is used to identify trends and patterns. The document also discusses the challenges associated with data collection and analysis, such as ensuring the reliability and validity of the data.

The third part of the document focuses on the development of effective communication strategies. It discusses the importance of clear and concise communication and provides guidelines for writing reports and presentations. The document also outlines the different channels through which information can be disseminated, such as newsletters, websites, and social media.

Page 1 of 1

The final part of the document discusses the importance of ongoing evaluation and improvement. It emphasizes that the effectiveness of the system can only be ensured through regular monitoring and assessment. The document also outlines the different methods used to evaluate the system, such as self-assessments, external audits, and stakeholder feedback.

The document concludes by reiterating the importance of maintaining accurate records and the need for transparency and accountability. It also provides a list of resources for further information and a contact list for those who need assistance.

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 9916

FILE: _____

| | | | | | | | | |
|---|-------------------|-----------|------------------------|-----------------------|------------|--|-----|-------|
| FROM: Niagara Mohawk Power Co
Syracuse, NY 13202
RR Schneider | | | DATE OF DOC
9-20-74 | DATE REC'D
9-26-74 | LTR
XXX | TWX | RPT | OTHER |
| TO:
Mr Skovholt | | | ORIG
1 signed | CC | OTHER | SENT AEC PDR <u>XX</u>
SENT LOCAL PDR <u>XX</u> | | |
| CLASS | UNCLASS
XXXXXX | PROP INFO | INPUT | NO CYS REC'D
1 | | DOCKET NO:
50-220 | | |

DESCRIPTION:

Ltr trans the following:

DO NOT REMOVE

ACKNOWLEDGED

PLANT NAME: Nine Mile Pt #1

ENCLOSURES:

REPORT: Abnormal Occurrence #74-13 on
9-18-74 concerning inoperable containment spray
pump #122.....

FOR ACTION/INFORMATION 10-3-74 ehf

| | | | |
|------------|---------------|----------------|------------|
| BUTLER (L) | SCHWENCER (L) | ZIEMANN (L) | REGAN (E) |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| CLARK (L) | STOLZ (L) | DICKER (E) | ✓ LEAR (L) |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| PARR (L) | VASSALLO (L) | KNIGHTON (E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| KNIEL (L) | PURPLE (L) | YOUNGBLOOD (E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|---------------------|-------------|-------------|----------------|-------------------|
| REG FILE | TECH REVIEW | DENTON | LIC ASST | A/T IND |
| ✓ AEC PDR | ✓ SCHROEDER | GRIMES | | BRAITMAN |
| ✓ OGC, ROOM P-506A | ✓ MACCARY | G. MILL | DIGGS (L) | SALTZMAN |
| ✓ MUNTZING/STAFF | ✓ KNIGHT | K. MILLER | GEARIN (L) | B. HURT |
| ✓ CASE | ✓ PAWLICKI | BALLARD | GOULBOURNE (L) | |
| GIAMBUSSO | ✓ SHAO | SPANGLER | KREUTZER (E) | PLANS |
| BOYD | ✓ STELLO | | LEE (L) | MCDONALD |
| MOORE (L) (BWR) | ✓ HOUSTON | ENVIRO | MAIGRET (L) | CHAPMAN |
| DEYOUNG (L) (PWR) | ✓ NOVAK | MULLER | REED (E) | DUBE w/input |
| SKOVHOLT (L) | ✓ ROSS | DICKER | SERVICE (L) | E. COUPE |
| GOLLER (L) | ✓ IPPOLITO | KNIGHTON | SHEPPARD (L) | |
| P. COLLINS | ✓ TEDESCO | YOUNGBLOOD | SLATER (E) | ✓ D. THOMPSON (2) |
| DENISE | ✓ LONG | REGAN | SMITH (L) | ✓ KLECKER |
| ✓ REG OPR | ✓ LAINAS | PROJECT LDR | ✓ TEETS (L) | ✓ EISENHUT |
| ✓ FILE & REGION (3) | ✓ BENAROYA | | WILLIAMS (E) | |
| ✓ MORRIS | ✓ VOLIMER | HARLESS | WILSON (L) | |
| ✓ STEELE | | | | |

EXTERNAL DISTRIBUTION

| | | |
|-----------------------------------|---------------------------------|--------------------------------|
| ✓ 1 - LOCAL PDR <u>Oswego, NY</u> | 1 - NATIONAL LABS | 1 - PDR-SAN/LA/NY |
| ✓ 1 - TIC (ABERNATHY) (1)(2)(10) | 1 - ASLBP (E/W Bldg, Rm 529) | 1 - BROOKHAVEN NAT LAB |
| ✓ 1 - NSIC (BUCHANAN) | 1 - W. PENNINGTON, Rm E-201 GT | 1 - G. ULRIKSON, ORNL |
| 1 - ASLB | 1 - B&M SWINEBROAD, Rm E-201 GT | 1 - AGMED (RUTH GUSSMAN) |
| 1 - Newton Anderson | 1 - CONSULTANTS | Rm B-127 GT |
| ✓ 5-ACRS SENT TO LIC ASST | NEWMARK/BLUME/AGBABIAN | 1 - R. D. MUELLER, Rm E-201 GT |

Teets

NAME

ST. NAME

ST. NAME

ST. NAME

ST. NAME

ST. NAME

ST. NAME

ST. NAME

ST. NAME

ST. NAME

ST. NAME

ST. NAME

ST. NAME

ST. NAME

ST. NAME

Regulatory

File Cy.

NIAGARA MOHAWK POWER CORPORATION


NIAGARA  MOHAWK

300 ERIE BOULEVARD WEST
SYRACUSE, N. Y. 13202

50-220

September 20, 1974

Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D.C. 20545



Dear Mr. Skovholt:


In accordance with Technical Specifications 1.13d for Nine Mile Point Unit 1, the enclosed Abnormal Occurrence Report is submitted. This report is in accordance with the format set forth in Regulatory Guideline 1.16. This occurrence was reported to RO:I on September 18, 1974.

Very truly yours,


R.R. Schneider

Vice President - Electric Operations

TJD:mmm



9916



1. The first part of the document is a list of names and addresses.

2.

3. The second part of the document is a list of names and addresses.

4. The third part of the document is a list of names and addresses.

5.

6. The fourth part of the document is a list of names and addresses.

7.

8.

9.

10.

11.

ABNORMAL OCCURRENCE REPORT

1. Report No. 74-13
- 2a. Date September 18, 1974
- 2b. Occurrence Date September 18, 1974
3. Facility Nine Mile Point Unit 1
4. Identification of Occurrence

Inoperable containment spray pump #122.

5. Conditions Prior to Occurrence

Unit #1 at steady state 98% power.

6. Description of Occurrence

During routine testing following a recalibration of the flow transmitter on September 17, 1974, the performance of containment spray pump #122 was found to have varied from previously expected performance. The three redundant pumps showed expected performance. The pump curve for containment spray pump #122 sets design flow at 3000 gpm at a pump developed head of 375 ft. at 60°F. The test data indicated the required developed head but the flow indication was approximately 2600 gpm. The pump was taken out of service and the required surveillance performed on the redundant pump. Technical Specification 3.3.7.b provides 15 days to return the effected pump to service provided the additional surveillance is performed. Specification 3.3.7.b was satisfied, therefore, fulfilling the L.C?O. The pump was disassembled and a piece of wood was found wedged in the "eye" of the pump thus limiting its performance. Therefore, requiring the reporting of an abnormal occurrence pursuant to Technical Specification 1.13d.

7. Designation of Apparent Cause of the Occurrence

Restricted suction flow caused by foreign object. (1p3/4x 5 1/4" x 3 1/4" piece of wood)

8. Analysis of Occurrence

Operation of only one containment spray pump is sufficient to remove post accident core energy releases including a substantial chemical reaction involving hydrogen generation and will also limit pressure and temperature rises in the pressure suppression system to below design values. The containment spray system is designed with four (4) pumps, therefore, providing 400% redundancy. The other three (3) pumps satisfactorily meet the performance requirements, therefore, it can be concluded that no hazard would have been presneted to the general public or station had the containment spray system been required.



◀ ▶ 🔍 📄 📁 📂 📅 📆 📇 📈 📉 📊 📋 📌 📍 📎 📏 📐 📑 📒 📓 📔 📕 📖 📗 📘 📙 📚 📛 📜 📝 📞 📟 📠 📡 📢 📣 📤 📥 📦 📧 📨 📩 📪 📫 📬 📭 📮 📯 📰 📱 📲 📳 📴 📵 📶 📷 📸 📹 📺 📻 📼 📽 📾 📿 📻 📼 📽 📾 📿

१ १५ ४ ३ २ १ ०

8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

9. Corrective Action

The foreign object, a piece of wood 1 3/4" x 3 1/4" x 5 1/4" was removed from its lodged location in the "eye" of the pump. None of the redundant three pumps has shown any behavior, which would lead to the conclusion that similiar problems with foreign objects have occurred.

Following removal of the object and reassembly of the pump, its performance was measured and demonstrated the following:

1. Pump discharge pressure was 165 psig or 379 feet of developed head. (required 375 feet)
2. Pump discharge flow was 150 k lbs / hr or 3000 gpm (required 3000 gpm)

Containment spray pump #122, therefore, is returned to service.

10. Failure Data

No previous containment spray pump failures.



Handwritten marks and scribbles in the top right corner.

.....

.....

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 9047

FILE: _____

| | | | | | | | |
|---|-----------------------|-------------------------------|-----------------------------|---------------------------|--|------------|--------------|
| FROM:
Niagara Mohawk Power Corp.
Syracuse, NY
RRSchneider | | DATE OF DOC
8-28-74 | DATE REC'D
9-3-74 | LTR
X | TWX | RPT | OTHER |
| TO:
Donald J. Skovholt | | ORIG
1 signed | CC
39 | OTHER | SENT AEC PDR X
SENT LOCAL PDR X | | |
| CLASS | UNCLASS
XXX | PROP INFO | INPUT | NO CYS REC'D
40 | DOCKET NO:
50-220 | | |

DESCRIPTION:

Ltr trans the following.....

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: Nine Mile Point Unit #1

ENCLOSURES:

Abnormal occurrence rpt #50-220/72-12 of
8-24-74 re set point drift on drywell.
high pressure.....

(40 cys encl rec'd)

FOR ACTION/INFORMATION

9-4-74

GMC

| | | | |
|------------|---------------|----------------|-----------|
| BUTLER (L) | SCHWENCER (L) | ZIEMANN (L) | REGAN (E) |
| W/ CYS | W/ CYS | W/ CYS | W/ CYS |
| CLARK (L) | STOLZ (L) | DICKER (E) | ✓LEAR |
| W/ CYS | W/ CYS | W/ CYS | W/ 4 CYS |
| FAER (L) | MASALLO (L) | KNIGHTON (E) | |
| W/ CYS | W/ CYS | W/ CYS | W/ CYS |
| KNIEL (L) | PURPLE (L) | YOUNGBLOOD (E) | |
| W/ CYS | W/ CYS | W/ CYS | W/ CYS |

INTERNAL DISTRIBUTION

| | | | | |
|--------------------|--------------------|---------------|-----------------|------------------|
| ✓ <u>REG FILE</u> | <u>TECH REVIEW</u> | DENTON | <u>LIC ASST</u> | <u>A/T IND</u> |
| ✓AEC PDR | | GRIMES | DIGGS (L) | BRAITMAN |
| ✓OGC | ✓SCHROEDER | GAMMILL | GEARIN (L) | SALTZMAN |
| ✓MUNTZING/STAFF | ✓MACCARY | KASTNER | GOULBOURNE (L) | B. HURT |
| ✓CASE | ✓KNIGHT | BALLARD | KREUTZER (E) | |
| GIAMBUSSO | ✓PAWLICKI | SPANGLER | LEE (L) | <u>PLANS</u> |
| BOYD | ✓SHAO | | MAIGRET (L) | MCDONALD |
| MOORE (L)(LWR-2) | ✓STELLO | <u>ENVIRO</u> | REED (E) | CHAPMAN |
| DEYOUNG (L)(LWR-1) | ✓HOUSTON | MULLER | SERVICE (L) | DUBE w/input |
| SKOVHOLT (L) | ✓NOVAK | DICKER | SHEPPARD (L) | E. COUPE |
| GOLLER (L) | ✓ROSS | KNIGHTON | SLATER (E) | |
| P. COLLINS | ✓IPPOLITO | YOUNGBLOOD | SMITH (L) | ✓D. THOMPSON (2) |
| DENISE | ✓TEDESCO | REGAN | ✓TEETS (L) | ✓KLECKER |
| ✓ <u>REG OPR</u> | ✓LONG | PROJECT MGR | WILLIAMS (E) | ✓EISENHUT |
| ✓FILE & REGION (2) | ✓LAINAS | | WILSON (L) | |
| ✓MORRIS | ✓BENAROYA | HARLESS | | |
| ✓STEELE | ✓VOLLMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|---|-------------------------------|-------------------------|
| ✓1 - LOCAL PDR Oswego, NY | (1)(2)(10)-NATIONAL LABS | 1-PDR-SAN/LA/NY |
| ✓1 - TIC (ABERNATHY) | 1-ASLBP(E/W Bldg, Rm 529) | 1-BROOKHAVEN NAT LAB |
| ✓1 - NSIC (BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | 1-G. ULRIKSON, ORNL |
| 1 - ASLB | 1-B&M SWINEBROAD, Rm E-201 GT | 1-AGMED (RUTH GUSSMAN) |
| 1 - Newton Anderson | 1-CONSULTANTS | Rm B-127 GT |
| ✓5 - ACRS SENT TO LIC ASST Teets 9-4-74 | NEWMARK/BLUME/AGBABIAN | 1-RD..MUELLER, Rm F-303 |
| | | GT |

3b:

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

August 28, 1974

50 - 220

Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D.C. 20545



Dear Mr. Skovholt:


In accordance with Technical Specifications 1.13d for Nine Mile Point Unit 1, the enclosed Abnormal Occurrence Report is submitted. This report is in accordance with the format set forth in Regulatory Guideline 1.16. This occurrence was reported to RO:I on August 26, 1974.

Very truly yours,


R.R. Schneider

Vice President - Electric Operations

TJD:mm



REGULATORY DOCKET FILE COPY

9047

1000000

ABNORMAL OCCURRENCE REPORT

1. Report No. 50-220/74-12
- 2a. Date August 26, 1974
- 2b. Occurrence Date August 24, 1974
3. Facility Nine Mile Point Unit 1
4. Identification of Occurrence
Set point drift on Drywell High Pressure
5. Conditions Prior to Occurrence
Unit 1 was at steady state 98% power
6. Description of Occurrence
During routine surveillance testing on August 24, 1974 at approximately 1000 hours, one Barton Instrument used in the Drywell High Pressure (3.5 psig) RPS was found to have drifted .05 psi higher than required. The surveillance test consists of operating the switch thru regulated (mercury manometer) air signal to the sensor. The three other Barton instruments in the two trip systems actuated within the prescribed set point.
7. Designation of Apparent Cause of the Occurrence
Set point drift
8. Analysis of Occurrence
The high drywell pressure trip requires a one out of two twice logic to actuate the protective function. One channel in each trip system would have actuated at the required setpoint and thus produced the protective function. Therefore, no hazard would have been presented to the general public or station had the protective function been rerequired.
9. Corrective Action
The immediate corrective action involved recalibration of the Barton switch. The normal value of setpoint is $3.5 \pm .053$ psig. A modification had been made to the Barton switch. A new switch plate locking device to prevent setpoint drift had been installed. (AOR 74-8). This modification was installed to minimize set point drift in this model of Barton instruments and is currently being evaluated to its usefulness.
10. Failure Data
Previous set point drift occurred on May 31, 1974 - AOR-74-8

100-130

100-130

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 9048

FILE: _____

| | | | | | | | | |
|---|-----------------------|------------------|-------------------------------|-----------------------------|-----------------|--|------------|--------------|
| FROM:
Niagara Mohawk Power Corp.
Syracuse, NY
RRSchneider | | | DATE OF DOC
8-28-74 | DATE REC'D
9-3-74 | LTR
X | TWX | RPT | OTHER |
| TO:
Donald J. Skovholt | | | ORIG
1 signed | CC
39 | OTHER | SENT AEC PDR X
SENT LOCAL PDR X | | |
| CLASS | UNCLASS
XXX | PROP INFO | INPUT | NO CYS REC'D
40 | | DOCKET NO:
50-220 | | |

DESCRIPTION:

Ltr trans the following.....

ENCLOSURES:

Abnormal occurrence rpt #50-220/74-11 of
8-24-74 re set point drift.....

ACKNOWLEDGED
DO NOT REMOVE

PLANT NAME: NINE MILE POINT UNIT #1

(40 cys encl rec'd)

FOR ACTION/INFORMATION

9-4-74 GMC

| | | | |
|------------|---------------|----------------|-----------|
| BUTLER (L) | SCHWENCER (L) | ZIEMANN (L) | REGAN (E) |
| W/ CYS | W/ CYS | W/ CYS | N/ CYS |
| CLARK (L) | STOLZ (L) | DICKER (E) | LEAR |
| W/ CYS | W/ CYS | W/ CYS | W/4 CYS |
| FAIR (L) | VASSALLO (L) | KNIGHTON (E) | |
| W/ CYS | W/ CYS | W/ CYS | W/ CYS |
| KNIEL (L) | PURPLE (L) | YOUNGBLOOD (E) | |
| W/ CYS | W/ CYS | W/ CYS | W/ CYS |

INTERNAL DISTRIBUTION

| | | | | |
|--|--|----------------|--|--|
| <input checked="" type="checkbox"/> REG FILE | TECH REVIEW | DENTON | LIC ASST | A/T IND |
| <input checked="" type="checkbox"/> AEC PDR | | GRIMES | DIGGS (L) | BRAITMAN |
| <input checked="" type="checkbox"/> OGC | <input checked="" type="checkbox"/> SCHROEDER | GAMMILL | GEARIN (L) | SALTZMAN |
| <input checked="" type="checkbox"/> MUNTZING/STAFF | <input checked="" type="checkbox"/> MACCARY | KASTNER | GOULBOURNE (L) | B. HURT |
| <input checked="" type="checkbox"/> CASE | <input checked="" type="checkbox"/> KNIGHT | BALLARD | KREUTZER (E) | |
| GIAMBUSSO | <input checked="" type="checkbox"/> PAWLICKI | SPANGLER | LEE (L) | PLANS |
| BOYD | <input checked="" type="checkbox"/> SHAO | | MAIGRET (L) | MCDONALD |
| MOORE (L)(LWR-2) | <input checked="" type="checkbox"/> STELLO | ENVIRO | REED (E) | CHAPMAN |
| DEYOUNG (L)(LWR-1) | <input checked="" type="checkbox"/> HOUSTON | MULLER | SERVICE (L) | DUBE w/input |
| SKOVHOLT (L) | <input checked="" type="checkbox"/> NOVAK | DICKER | SHEPPARD (L) | E. COUPE |
| GOLLER (L) | <input checked="" type="checkbox"/> ROSS | KNIGHTON | SLATER (E) | |
| P. COLLINS | <input checked="" type="checkbox"/> IPPOLITO | YOUNGBLOOD | SMITH (L) | <input checked="" type="checkbox"/> D. THOMPSON (2) |
| DENISE | <input checked="" type="checkbox"/> TEDESCO | REGAN | <input checked="" type="checkbox"/> TEETS (L) | <input checked="" type="checkbox"/> KLECKER |
| <input checked="" type="checkbox"/> REG OPR | <input checked="" type="checkbox"/> LONG | PROJECT MGR | WILLIAMS (E) | <input checked="" type="checkbox"/> EISENHUT |
| <input checked="" type="checkbox"/> FILE & REGION (2) | <input checked="" type="checkbox"/> LAINAS | | WILSON (L) | |
| <input checked="" type="checkbox"/> MORRIS | <input checked="" type="checkbox"/> BENAROYA | HARLESS | | |
| <input checked="" type="checkbox"/> STEELE | <input checked="" type="checkbox"/> VOLLMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|--|-------------------------------|------------------------|
| <input checked="" type="checkbox"/> 1 - LOCAL PDR Oswego, NY | (1)(2)(10) - NATIONAL LABS | 1-PDR-SAN/LA/NY |
| <input checked="" type="checkbox"/> 1 - TIC (ABERNATHY) | 1-ASLBP(E/W Bldg, Rm 529) | 1-BROOKHAVEN NAT LAB |
| <input checked="" type="checkbox"/> 1 - NSIC (BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | 1-G. ULRIKSON, ORNL |
| 1 - ASLB | 1-B&M SWINEBROAD, Rm E-201 GT | 1-AGMED (RUTH GUSMAN) |
| 1 - Newton Anderson | 1-CONSULTANTS | 1-RD..MUELLER, Rm F-3. |
| <input checked="" type="checkbox"/> 5 - ACRS SENT TO LIC ASST Teets 9-4-74 | NEWARK/BLUME/AGBABIAN | GT |

RECEIVED W. M. W. W.
ST. LOUIS, MO.

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

50-220

August 28, 1974

Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D.C. 20545



Dear Mr. Skovholt:


In accordance with Technical Specifications 1.13d for Nine Mile Point Unit 1, the enclosed Abnormal Occurrence Report is submitted. This report is in accordance with the format set forth in Regulatory Guideline 1.16. This occurrence was reported to RO:I on August 26, 1974.

Very truly yours,


R.R. Schneider

Vice President - Electric Operations

TJD:mmn



REGULATORY DOCKET FILE COPY

REGULATORY DOCKET FILE COPY

9048



ABNORMAL OCCURRENCE REPORT

1. Report No. 50-220/74-11
- 2a. Date August 26, 1974
- 2b. Occurrence Date August 24, 1974
3. Facility Nine Mile Point Unit 1
4. Identification of Occurrence
Set point drift in RE-18C Rx Lo-Lo-Lo Level
5. Conditions Prior to Occurrence
Unit at steady state 98% full load
6. Description of Occurrence
During routine surveillance testing Barton instrument 288-3471 provided the desired trip action sooner than required.
7. Designation of Apparent Cause of the Occurrence
Set point drift.
8. Analysis of Occurrence
Each of two instruments provide inputs to one instrument channel in each trip system. RE-18C provided a trip in system 12 at 124.5" instead of 128 ± 2.6 ". (Technical Specifications 3.6.2) The signals for initiating automatic blowdown differ from other initiating signals in that only one of the two trip systems is required to start blowdown. This is due to the requirement that automatic depressurization be prevented unless A.C. power is available to the ECCS. In order to cause a trip both instrument channels in either trip system must be energized. With RE-18C tripping sooner than required, the desired action if required would still have occurred at the established set point. Therefore, no hazard was presented to the health and general welfare of the public.
9. Corrective Action
The immediate correction action was to recalibrate the instrument to the required set point.
10. Failure Data
Previous set point drift on this instrument occurred on Oct. 21, 1972.

- 2a. Date August 26, 1974
- 2b. Occurrence Date August 24, 1974
3. Facility Nine Mile Point Unit 1
4. Identification of Occurrence
Set point drift on Drywell High Pressure
5. Conditions Prior to Occurrence
Unit 1 was at steady state 98% power
6. Description of Occurrence
During routine surveillance testing on August 24, 1974 at approximately 1000 hours, one Barton Instrument used in the Drywell High Pressure (3.5 psig) RPS was found to have drifted .45 psi higher than required. The surveillance test consists of operating the switch thru regulated (mercury manometer) air signal to the sensor. The three other Barton instruments in the two trip systems actuated within the prescribed set point.
7. Designation of Apparent Cause of the Occurrence
Set point drift
8. Analysis of Occurrence
The high drywell pressure trip requires a one out of two twice logic to actuate the protective function. One channel in each trip system would have actuated at the required setpoint and thus produced the protective function. Therefore, no hazard would have been presented to the general public or station had the protective function been required.
9. Corrective Action
The immediate corrective action involved recalibration of the Barton switch. The normal value of setpoint is $3.5 + .053$ psig. A modification had been made to the Barton switch. A new switch plate locking device to prevent setpoint drift had been installed. (AOR 74-8). This modification was installed to minimize set point drift in this model of Barton instruments and is currently being evaluated to its usefulness.
10. Failure Data
Previous set point drift occurred on May 31, 1974 - AOR 74-8

2a. Date

August 26, 1974

2b. Occurrence Date

August 24, 1974

3. Facility

Nine Mile Point Unit 1

4. Identification of Occurrence

Set point drift in RE-18C Rx Lo-Lo-Lo Level

5. Conditions Prior to Occurrence

Unit at steady state 98% full load

6. Description of Occurrence

During routine surveillance testing Barton instrument 288-3471 provided the desired trip action sooner than required.

7. Designation of Apparent Cause of the Occurrence

Set point drift.

8. Analysis of Occurrence

Each of two instruments provide inputs to one instrument channel in each trip system. RE-18C provided a trip in system 12 at 124.5" instead of 128 ± 2.6 ". (Technical Specifications 3.6.2) The signals for initiating automatic blowdown differ from other initiating signals in that only one of the two trip systems is required to start blowdown. This is due to the requirement that automatic depressurization be prevented unless A.C. power is available to the ECCS. In order to cause a trip both instrument channels in either trip system must be energized. With RE-18C tripping sooner than required, the desired action if required would still have occurred at the established set point. Therefore, no hazard was presented to the health and general welfare of the public.

9. Corrective Action

The immediate correction action was to recalibrate the instrument to the required set point.

10. Failure Data

Previous set point drift on this instrument occurred on Oct. 21, 1972.

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 8857

FILE: _____

| | | | | | | | | |
|--|----------------|------------------|-------------------------------|------------------------------|-----------------|--|------------|--------------|
| FROM:
Niagara Mohawk Power Corp
Syracuse, NY
RRSchneider | | | DATE OF DOC
8-21-74 | DATE REC'D
8-28-74 | LTR
X | TWX | RPT | OTHER |
| TO:
Donald J. Skovholt | | | ORIG
1 signed | CC | OTHER | SENT AEC PDR XXX
SENT LOCAL PDR XXX | | |
| CLASS | UNCLASS | PROP INFO | INPUT | NO CYS REC'D
1 | | DOCKET NO:
50-220 | | |
| | XXX | | | | | | | |

DESCRIPTION:

Ltr trans the following.....

ENCLOSURES:

Abnormal occurrence rpt #74-10 of 8-17-74
re set point drift in Barton differential
pressure instrument 1 B05C

DO NOT REMOVE

ACKNOWLEDGED

PLANT NAME: NINE MILE POINT UNIT #1

(1 cy encl rec'd)

FOR ACTION/INFORMATION 8-30-74 GMC

| | | | |
|------------|---------------|----------------|-----------|
| BUTLER (L) | SCHWENCER (L) | ZIEMANN (L) | REGAN (E) |
| W/ CYS | W/ CYS | W/ CYS | W/ CYS |
| CLARK (L) | STOLZ (L) | DICKER (E) | ✓LEAR |
| W/ CYS | W/ CYS | W/ CYS | W/ 4 CYS |
| FAER (L) | MASALLO (L) | KNIGHTON (E) | |
| W/ CYS | W/ CYS | W/ CYS | W/ CYS |
| KNIEL (L) | PURPLE (L) | YOUNGBLOOD (E) | |
| W/ CYS | W/ CYS | W/ CYS | W/ CYS |

INTERNAL DISTRIBUTION

| | | | | |
|--------------------------------|--------------------|---------------|-----------------|------------------|
| ✓ <u>REG FILE</u> | <u>TECH REVIEW</u> | DENTON | <u>LIC ASST</u> | <u>A/T IND</u> |
| ✓ <u>AEC PDR</u> | | GRIMES | DIGGS (L) | BRAITMAN |
| ✓ <u>OGC</u> | ✓SCHROEDER | GAMMILL | GEARIN (L) | SALTZMAN |
| ✓ <u>MUNTZING/STAFF</u> | ✓MACCARY | KASTNER | GOULBOURNE (L) | B. HURT |
| ✓ <u>CASE</u> | ✓KNIGHT | BALLARD | KREUTZER (E) | |
| GIAMBUSSO | ✓PAWLICKI | SPANGLER | LEE (L) | <u>PLANS</u> |
| BOYD | ✓SHAO | | MAIGRET (L) | MCDONALD |
| MOORE (L)(LWR-2) | ✓STELLO | <u>ENVIRO</u> | REED (E) | CHAPMAN |
| DEYOUNG (L)(LWR-1) | ✓HOUSTON | MULLER | SERVICE (L) | DUBE w/input |
| SKOVHOLT (L) | ✓NOVAK | DICKER | SHEPPARD (L) | E. COUPE |
| GOLLER (L) | ✓ROSS | KNIGHTON | SLATER (E) | |
| P. COLLINS | ✓IPPOLITO | YOUNGBLOOD | SMITH (L) | ✓D. THOMPSON (2) |
| DENISE | ✓TEDESCO | REGAN | ✓TEETS (L) | ✓KLECKER |
| ✓ <u>REG OPR</u> | ✓LONG | PROJECT MGR | WILLIAMS (E) | ✓EISENHUT |
| ✓ <u>FILE & REGION (2)</u> | ✓LAINAS | | WILSON (L) | |
| ✓ <u>MORRIS</u> | ✓BENAROYA | HARLESS | | |
| ✓ <u>STEELE</u> | ✓VOLLMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|--|-------------------------------|------------------------|
| ✓1 - LOCAL PDR OSWEGO, NY | (1)(2)(10)-NATIONAL LABS | 1-PDR-SAN/LA/NY |
| ✓1 - TIC (ASERNATHY) | 1-ASLBP(E/W Bldg, Rm 529) | 1-BROOKHAVEN NAT LAB |
| ✓1 - NSIC (BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | 1-G. ULRIKSON, ORNL |
| 1 - ASLB | 1-B&M SWINEBROAD, Rm E-201 GT | 1-AGMED (RUTH GUSSMAN) |
| ✓1 - Newton Anderson | 1-CONSULTANTS | Rm B-127 GT |
| ✓5 - ACRS SENT TO LIC ASST TEETS 8-30-74 | NEWARK/BLUME/AGBABIAN | 1-RD..MUELLER, Em F-3. |
| | | GT |

[illegible]


50-220

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

August 21, 1974




Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D.C. 20545

Dear Mr. Skovholt:


In accordance with Technical Specifications 1.13d for Nine Mile Point Unit 1, the enclosed Abnormal Occurrence Report is submitted. This report is in accordance with the format set forth in Regulatory Guideline 1.16. This occurrence was reported to RO:I on August 19, 1974.

Very truly yours,


R.R. Schneider
Vice President - Electric Operations

TJD:mm

Enc.



REGULATORY DOCKET FILE COPY

8857

13-



ABNORMAL OCCURRENCE REPORT

1. Report No. 74-10
- 2a. Date August 19, 1974
- 2b. Occurrence Date August 17, 1974
3. Facility Nine Mile Point Unit 1
4. Identification of Occurrence

Set point drift in Barton differential pressure instrument 1 B05C (Emergency Cooling High Flow)
5. Conditions Prior to Occurrence

Unit at steady state 98% full load
6. Description of Occurrence

During routine surveillance testing Barton instrument 1 B05C provided the desired trip action at a lower than required value.
7. Designation of Apparent Cause of the Occurrence

Set point drift.
8. Analysis of Occurrence

Each of two differential pressure switches provided inputs to one instrument channel in each trip system. Therefore, with one instrument trip occurring at a lower than required value, the isolation of the emergency condensers would still have occurred at the desired set point. Based upon the fact that the redundant components actuated at the required set point as well as the fact that the set point drift was in the conservative direction it is concluded that at no time would a hazard be presented to the general public as a result of this set point drift.
9. Corrective Action

The instrument was recalibrated to required set point.
10. Failure Data
 - a. Type: Barton
 - b. No.: 289-793
 - c. Failures: First this instrument.

715 623

1. Report No.

74-9

Central files

2a. Date

July 7, 1974

2b. Occurrence Date

June 28, 1974

3. Facility

Nine Mile Point Unit 1

4. Identification of Occurrence

Failure of RE-23D relay (RPS) to return to normal (untripped)

5. Conditions Prior to Occurrence

Unit was being restarted following Spring Refueling Outage.

6. Description of Occurrence

During the heat-up phase of unit restart with reactor pressure increasing as planned device RE-23D failed to reset at 850 psig. The relay was replaced and performed its intended function.

7. Designation of Apparent Cause of the Occurrence

Investigation revealed an open relay coil.

8. Analysis of Occurrence

Pressure instrumentation (RE-23) trips when the main steam line pressure reaches or decends below 850 psig. This trip function is utilized in the "RUII" mode position only. Primarily this function is provided to protect against a pressure regulator malfunction or main steam line break which would cause a coolant loss, either thru the break or the turbine bypass valve system, from the reactor vessel. With the trip set at 850 psig coolant loss is limited so that the fuel is not uncovered and peak clad temperatures are limited. The system logic is a one out of two, twice requiring one trip on each of the trip systems to actuate the required function. With the relay failure; (In the RPS all relaying is designed Fail-Safe i.e. fail to the safeguard condition) one of the two trip systems was tripped. In this instrumentation system where two trip systems are required to initiate action, having one trip system already tripped does not decrease the reliability in terms of initiating the desired designed action. Therefore, with the relay failure, the system assumed the tripped condition as designed. Based upon the above logic and actions, it is concluded that at no time would a hazard be presented to the general public as a result of this failure.



Abnormal Occurrence Report

-2-

July 1, 1974

9. Corrective Action

The relay was replaced immediately to enable the sensor to perform its intended function.

10. Failure Data

- a. Type Potter & Brumfield AL100BH
- b. To. KR-4015-3
- c. Manufacture for-horo
- d. Failures First



AEC DISSEMINATION FOR PART 50 DOCKET MATERIALS
(TEMPORARY FORM)

CONTROL NO: 5217

FILE: A/D

| | | | | | | | | |
|--|-----------------|-----------|-----------------------|-----------------------|----------|--|-----|---|
| FROM: Niagara Mohawk Power Corp.
Syracuse, N. Y. 13202
R. R. Schneider | | | DATE OF DOC
6-3-74 | DATE REC'D
6-11-74 | LTR
X | MEMO | RPT | OTHER <input checked="" type="checkbox"/> |
| TO: Mr. Skovholt | | | ORIG
1 signed | CC | OTHER | SENT AEC PDR <input checked="" type="checkbox"/>
SENT LOCAL PDR <input checked="" type="checkbox"/> | | |
| CLASS | UNCLASS
XXXX | PROP INFO | INPUT | NO CYS REC'D
1 | | DOCKET NO:
50-220 | | |

DESCRIPTION:

Ltr trans the following:

ENCLOSURES:

Abnormal Occurrence Report No. 50-220/74-8
dtd 5-31-74, regarding setpoint drift on
Drywell High Pressure

Do Not Remove

ACKNOWLEDGED

PLANT NAME: Nine Mile Point Unit # 1

(40 cys rec'd)

FOR ACTION/INFORMATION

6-11-74

AB

| | | | |
|------------------------|---------------------------|-----------------------------|-----------------------|
| BUTLER(L)
W/ Copies | SCHWENCER(L)
W/ Copies | ✓ ZIEMANN(L)
W/ 7 Copies | REGAN(E)
W/ Copies |
| CLARK(L)
W/ Copies | STOLZ(L)
W/ Copies | DICKER(E)
W/ Copies | |
| PARR(L)
W/ Copies | VASSALLO(L)
W/ Copies | KNIGHTON(E) ..
W/ Copies | W/ Copies |
| KNIEL(L)
W/ Copies | PURPLE (L)
W/ Copies | YOUNGBLOOD(E)
W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|--|---|---|---|---|
| <u>REG FILE</u>
✓ AEC PDR
✓ OGC, ROOM P-506A
✓ MUNTZING/STAFF
✓ CASE
GIAMBUSSO
BOYD
MOORE (L) (BWR)
DEYOUNG (L) (PWR)
SKOVHOLT (L)
✓ GOLLER (L) (LTR)
P. COLLINS
DENISE
REG OPR
✓ FILE & REGION(3)
✓ MORRIS
✓ STEELE | <u>TECH REVIEW</u>
✓ HENDRIE
SCHROEDER
✓ MACCARY
✓ KNIGHT
✓ PAWLICKI
✓ SHAO
✓ STELLO
✓ HOUSTON
✓ NOVAK
✓ ROSS
✓ IPPOLITO
✓ TEDESCO
✓ LONG
✓ LAINAS
✓ BENAROYA
✓ VOLLMER | DENTON
GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

<u>ENVIRO</u>
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR

HARLESS | <u>LIC ASST</u>
✓ DIGGS (L)
GEARIN (L)
GOULBOURNE (L)
LEE (L)
MAIGRET (L)
REED (E)
SERVICE (L)
SHEPPARD (L)
SLATER (E)
SMITH (L)
TEETS (L)
WADE (E)
WILLIAMS (E)
WILSON (L) | <u>A/T IND</u>
BRAITMAN
SALTZMAN
B. HURT

<u>PLANS</u>
MCDONALD
DUBE w/Input

<u>INFO</u>
C. MILES
✓ KLECKER
EISENHUT

<u>AOR FILE</u>
✓ D. THOMPSON (2) |
|--|---|---|---|---|

EXTERNAL DISTRIBUTION

| | | |
|---|---------------------------------|------------------------|
| ✓ 1 - LOCAL PDR Oswego, N. Y. | (1) (2X10) NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| ✓ 1 - TIC (ABERNATHY) | 1-ASLBP (E/W Bldg, Rm 529) | 1-GERALD LELLOUCHE |
| ✓ 1 - NSIC (BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB | 1-CONSULTANT'S | 1-AGMED (Ruth Gussman) |
| 1 - P. R. DAVIS (AEROJET NUCLEAR) | NEWARK/BLUME/AGBABIAN | RM-B-127, GT. |
| ✓ 16 - CYS ACRS NOTING SENT TO LIC ASST. | 1-GERALD ULRIKSON...ORNL | 1-RD..MULLER..F-309 GT |
| R. DIGGS ON 6-11-74 | 1-B & M SWINEBROAD, Rm E-201 GT | |



100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100


Regulatory

Cy.

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD WEST
SYRACUSE, N. Y. 13202



June 3, 1974

50 - 220

Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D.C. 20545

Dear. Mr. Skovholt:


In accordance with Technical Specifications for Nine Mile Point Unit 1, 1.13d, the enclosed Abnormal Occurrence Report is submitted. This report is in accordance with the format set forth in Regulatory Guideline 1.16.

Very truly yours,


R.R. Schneider

Vice President - Electric Operations

RRS/bar



5217



1. The first part of the document is a list of names and addresses.

2. The second part of the document is a list of names and addresses.

3. The third part of the document is a list of names and addresses.

4. The fourth part of the document is a list of names and addresses.

5. The fifth part of the document is a list of names and addresses.

6. The sixth part of the document is a list of names and addresses.

7. The seventh part of the document is a list of names and addresses.

8. The eighth part of the document is a list of names and addresses.

9. The ninth part of the document is a list of names and addresses.

10. The tenth part of the document is a list of names and addresses.

ABNORMAL OCCURRENCE REPORT

1. Report No. 50-220/74-8
- 2a. Date June 3, 1974
- 2b. Occurrence Date May 31, 1974
3. Facility Nine Mile Point Nuclear Station Unit 1
4. Identification of Occurrence

Setpoint drift on Drywell High Pressure

5. Conditions Prior to Occurrence

Unit 1 was shutdown for annual refueling

6. Description of Occurrence

During routine surveillance testing on May 31, 1974 at approximately 1600 hours, two Barton Instruments used in the Drywell High Pressure (3.5 psig) RPS were found to have drifted .20 psi higher than required. The surveillance test consists of operating the switch thru regulated (mercury manometer) air signal to the sensor. The two Barton Instruments Model 289, E.P. #RE04A&D are in separate RPS trip systems.

With reactor in refuel mode and the drywell under atmospheric conditions no operator action was necessary, as the plant was in a safe condition.

7. Designation of Apparent Cause of the Occurrence

Setpoint drift

8. Analysis of Occurrence

The high drywell pressure trip requires a one out of two twice logic to actuate the protective function. One channel in each trip system would have actuated at the required setpoint and thus produced the protective function. Therefore, no hazard would have been presented to the general public or station had the protective function been required.

9. Corrective Action

The immediate corrective action involved recalibration of the Barton switch. The normal valve of setpoint is $3.5 \pm .053$ psig. A modification has been made to the Barton switch. A new switch plate locking device to prevent setpoint drift has been installed. (AOR 74-1). This modification should reduce setpoint drift problems with this switch.



10. Failure Data

No previous setpoint drifting has occurred on these switches this year. AOR 74-1 concerning a Barton switch setpoint drift is the only other drift in setpoint to date in 1974.



AEC INFORMATION FOR PART 50 DOCKET MATERIALS
(TEMPORARY FORM)

CONTROL NO: 4231

FILE: A10

| | | | | | | | | |
|---|----------------|-----------|-----------------------|-----------------------|----------|--|-----|-------|
| FROM:
Niagara Mohawk Power Corp.
Syracuse, N. Y.
R. R. Schneider | | | DATE OF DOC
5-3-74 | DATE REC'D
5-13-74 | LTR
X | MEMO | RPT | OTHER |
| TO:
Donald J. Skovholt | | | ORIG
1 signed | CC
39 | OTHER | SENT AEC PDR XXX
SENT LOCAL PDR XXX | | |
| CLASS | UNCLASS
XXX | PROP INFO | INPUT | NO CYS REC'D
40 | | DOCKET NO:
50-220 | | |

DESCRIPTION:

Ltr trans the following.....

PLANT NAME: NINE MILE POINT UNIT #1

ENCLOSURES:

Abnormal Occurrence Rpt #74-7 of 4-25-74
in which a control rod blade tube inversion
occurred

**ACKNOWLEDGED
DO NOT REMOVE**

(40 cys encl rec'd)

FOR ACTION/INFORMATION 5-13-74 GMC

| | | | |
|------------------------|---------------------------|----------------------------|-----------------------|
| BUTLER(L)
W/ Copies | SCHWENCER(L)
W/ Copies | ✓ZIEMANN(L)
W/7 Copies | REGAN(E)
W/ Copies |
| CLARK(L)
W/ Copies | STOLZ(L)
W/ Copies | DICKER(E)
W/ Copies | W/ Copies |
| PARR(L)
W/ Copies | VASSALLO(L)
W/ Copies | KNIGHTON(E)
W/ Copies | W/ Copies |
| KNIEL(L)
W/ Copies | PURPLE (L)
W/ Copies | YOUNGBLOOD(E)
W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|----------------------|--------------------|-------------|----------------|-------------------|
| ✓REG FILE | TECH REVIEW | DENTON | LIC ASST | A/T IND |
| ✓AEC PDR | ✓HENDRIE | GRIMES | | BRAITMAN |
| ✓OGC, ROOM P-506A | SCHROEDER | GAMMILL | ✓DIGGS (L) | SALTZMAN |
| ✓MUNIZING/STAFF | ✓MACCARY <i>tr</i> | KASTNER | GEARIN (L) | B. HURT |
| ✓CASE <i>tr</i> | ✓KNIGHT | BALLARD | GOULBOURNE (L) | PLANS |
| GIAMBUSO | ✓PAWLICKI | SPANGLER | LEE (L) | MCDONALD |
| BOYD | ✓SHAO | | MAIGRET (L) | DUBE w/Input |
| MOORE (L) (BWR) | ✓STELLO <i>tr</i> | ENVIRO | REED (E) | INFO |
| DEYOUNG(L) (PWR) | ✓HOUSTON | MULLER | SERVICE (L) | C. MILES |
| SKOVHOLT (L) | ✓NOVAK | DICKER | SHEPPARD (L) | B. KING (E/W-358) |
| ✓GOLLER(L) <i>tr</i> | ✓ROSS | KNIGHTON | SLATER (E) | ✓KLECKER |
| P. COLLINS | ✓IPPOLITO | YOUNGBLOOD | SMITH (L) | ✓EISENHUT |
| DENISE | ✓TEDESCO <i>tr</i> | REGAN | TEETS (L) | |
| ✓REG OPR | ✓LONG | PROJECT LDR | WADE (E) | |
| FILE & REGION(3) | ✓LAINAS | | WILLIAMS (E) | ✓D. THOMPSON (2) |
| ✓MORRIS | ✓BENAROYA | HARLESS | WILSON (L) | W/AOR FILE CY |
| STEELE | ✓VOLIMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|------------------------------------|---------------------------------|------------------------|
| ✓1 - LOCAL PDR OSWEGO, NY | (1) (2X10) NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| ✓1 - TIC (ABERNATHY) | 1-ASLBP (E/W Bldg, Rm 529) | 1-GERALD LELLOUCHE |
| ✓1 - NSIC (BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB | 1-CONSULTANT'S | 1-AGMED (Ruth Gussman) |
| ✓1 - P. R. DAVIS (AEROJET NUCLEAR) | NEWARK/BLUME/AGBABIAN | RM-B-127, GT. |
| ✓16 - CYS ACRS HOLDING | 1-GERALD ULRIKSON...ORNL | 1-RD..MULLER..F-309 GT |
| Sent to Lic Asst Diggs 5-13-74 | 1-B & M SWINEBROAD, Rm E-201 GT | |

NOV 28 1991

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD WEST
SYRACUSE, N. Y. 13202

May 3, 1974

50-220

30-220



Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D.C. 20545

Dear Mr. Skovholt:

In accordance with Technical Specifications for Nine Mile Point
Unit 1, the enclosed Abnormal Occurrence Report is submitted. This report
is in accordance with the format set forth in Regulatory Guideline 1.16.


Very truly yours,


R.R. Schneider

Vice President - Electric Operations

RRS/bar

REGISTERED MAIL - RETURN RECEIPT REQUEST



4231

REGULATORY DOCKET FILE COPY



10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

10-11-68

ABNORMAL OCCURRENCE REPORT

1. Report No. 74-7
- 2a. Date April 30, 1974
- 2b. Occurrence Date April 25, 1974
3. Facility Nine Mile Point Nuclear Station Unit 1
4. Identification of Occurrence

Control Rod Blade Tube Inversion

5. Conditions Prior to Occurrence

Unit 1 was shutdown for annual refueling

6. Description of Occurrence

During the previous operating cycle on September 25, 1973 you informed us of a possible problem involving inverted tubes in control rod blades. In our response to your letter and further communication we committed to:

1. A shutdown margin test on each control rod (completed in November 1973 with negative results).
2. An eddy current testing program on each control rod during the next refueling outage.
3. A change out of any affected control rod.

On April 24-25, 1974 the eddy current testing evaluation of individual control rod blades in the Nine Mile Point Unit 1 reactor core was completed. The eddy current test used was that as described in the General Electric submittal to your office on October 8, 1973. The results of the testing showed two control rod blades with possible inverted tubes. Immediate steps were taken to insure that the cells effected would be in a less reactive condition than that as experience during the previous cycle. The control rod would not be withdrawn and only two bundles were present in the cell affected. The control blades will be changed in these two cells later during the core refueling.

7. Designation of Apparent Cause of the Occurrence

Manufacturing Deficiency

8. Analysis of Occurrence

The inverted sheaths were found at core location 22-15 and 30-39 two widely dispensed locations. In addition shutdown margin demonstrations



in November 1973 showed no inadequacy in more than necessary shutdown margin. Based on this it is concluded that no hazard was presented to the general public.

9. Corrective Action

The two control blades will be changed. In addition the Site Quality Control Organization will prevent further manufacturing deficiency from being used. This organization was not in existence when the original control blades were obtained.

10. Failure Data

First Failure of this nature.

DK Central File

TUBE INVERSION IN TWO CONTROL BLADES

PURSUANT TO TECHNICAL SPECIFICATIONS T.13d WE ARE REPORTING AS AN ABNORMAL OCCURRENCE (AOR50-220/74-7) THE INVERSION OF TUBES IN TWO CONTROL ROD BLADES AT NINE MILE POINT NUCLEAR STATION UNIT 1.

DURING THE SPRING 1974 REFUELING OUTAGE AN EDDY CURRENT TEST WAS MADE OF EACH CONTROL BLADE IN THE REACTOR CORE. THE RESULTS WERE ANALYZED ON APRIL 24 AND INDICATED TUBE INVERSION IN CONTROL ROD BLADES, 30-39 AND 22-19.

THE EDDY CURRENT TESTING VERIFIES THE NON INVERSION OF INDIVIDUAL TUBES IN EACH KING OF THE CONTROL ROD BLADE. THEREFORE IT IS A CONSERVATIVE TEST IN THAT THE RESULTS INDICATE NON-INVERSION ONLY AND NOT INVERSION.

THE IMMEDIATE CORRECTIVE ACTION PERFORMED, WAS NOT LOADING THE CONTROL CELL TO ITS FINAL REACTIVE CONDITIONS DURING FUEL MOVEMENTS. THIS WILL INSURE THAT THE CONTROL BLADE "HOLDS DOWN" LESS REACTIVITY NOW THAN DURING ANY POINT IN THE PREVIOUS OPERATING CYCLE. DURING THE OPERATING CYCLE SHUTDOWN MARGIN TESTING WAS PERFORMED ON EACH CONTROL ROD IN THE REACTOR. THIS VERIFIED THAT MORE THAN ADEQUATE SHUTDOWN MARGIN EXISTED ON EVERY CONTROL BLADE IN THE CORE.

THE FINAL CORRECTIVE ACTION WILL BE TO REPLACE THE TWO CONTROL BLADES WITH BLADES VERIFIED TO BE NON-INVERTED.

BASED UPON THE FACT THAT MORE THAN ADEQUATE SHUTDOWN MARGIN EXISTED DURING THE OPERATING CYCLE AS DEMONSTRATED, NO HAZARD WAS PRESENTED TO THE GENERAL PUBLIC OR THE STATION DURING THE PREVIOUS OPERATING CYCLES.

THIS IS THE FIRST FAILURE OF THIS NATURE.

THOMAS J. PERKINS
STATION SUPERINTENDENT
NINE MILE POINT NUCLEAR STATION

afj



AEC T-11 BUTTON FOR PART 50 DOCKET M-111AL
(TEMPORARY FORM)

CONTROL NO: 4224

FILE: AJO

| | | | | | | | | |
|---|---------|-----------|----------------------------|---------------------------|--------------|--|-----|-------|
| FROM:
Niagara Mohawk Power Corp.
Syracuse, N. Y.
R. R. Schneider | | | DATE OF DOC

4-29-74 | DATE REC'D

5-13-74 | LTR

X | MEMO | RPT | OTHER |
| TO:

Donald J. Skovholt | | | ORIG

1 signed | CC

39 | OTHER | SENT AEC PDR: XXX
SENT LOCAL PDR: XXX | | |
| CLASS | UNCLASS | PROP INFO | INPUT | NO CYS REC'D

40 | | DOCKET NO:

50-220 | | |
| | XXX | | | | | | | |

DESCRIPTION:

Ltr trans the following.....

ENCLOSURES:

Abnormal Occurrence Rpt #74-6 of 4-19-74
in which excessive main steam line isolation
valve leakage was discovered :

**ACKNOWLEDGED
DO NOT REMOVE**

PLANT NAME: NINE MILE POINT UNIT #1

(40 cys encl rec'd)

FOR ACTION/INFORMATION 5-13-74 GMC

| | | | |
|-----------|--------------|---------------|-----------|
| BUTLER(L) | SCHWENCER(L) | ✓ZIEMANN(L) | REGAN(E) |
| W/ Copies | W/ Copies | W/7 Copies | W/ Copies |
| CLARK(L) | STOLZ(L) | DICKER(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| PARR(L) | VASSALLO(L) | KNIGHTON(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| KNIEL(L) | PURPLE (L) | YOUNGBLOOD(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|-------------------|--------------|-------------|----------------|-------------------|
| ✓REG FILE | ✓TECH REVIEW | DENTON | LIC ASST | A/T IND |
| ✓REG PDR | ✓HENDRIE | GRIMES | | BRAITMAN |
| ✓OGC, ROOM P-506A | ✓SCHROEDER | GAMMILL | ✓DIGGS (L) | SALTZMAN |
| ✓MUNTZING/STAFF | ✓MACCARY | KASTNER | GEARIN (L) | B. HURT |
| ✓CASE | ✓KNIGHT | BALLARD | GOULBOURNE (L) | PLANS |
| GIAMBUSO | ✓PAWLICKI | SPANGLER | LEE (L) | MCDONALD |
| BOYD | ✓SHAO | | MAIGRET (L) | DUBE w/Input |
| MOORE (L) (FWR) | ✓STELLO | ✓ENVIRO | REED (E) | INFO |
| DEYOUNG(L) (FWR) | ✓HOUSTON | MULLER | SERVICE (L) | C. MILES |
| SKOVHOLT (L) | ✓NOVAK | DICKER | SHEPPARD (L) | B. KING (E/W-358) |
| ✓GOLLER(L) | ✓ROSS | KNIGHTON | SLATER (E) | ✓KLECKER |
| P. COLLINS | ✓IPPOLITO | YOUNGBLOOD | SMITH (L) | ✓EISENHUT |
| DENISE | ✓TEDESCO | REGAN | TEETS (L) | |
| ✓REG OPR | ✓LONG | PROJECT LDR | WADE (E) | |
| ✓FILE & REGION(3) | ✓LAINAS | | WILLIAMS (E) | ✓D. THOMPSON (2) |
| ✓MORRIS | ✓BENAROYA | HARLESS | WILSON (L) | W/AOR FILE CY |
| ✓STEELE | ✓VOLMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|-----------------------------------|---------------------------------|------------------------|
| 1 - LOCAL PDR - OSWEGO, NY | (1) (2) (10) - NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| 1 - TIC (ABERNATHY) | 1-ASLBP (E/W Bldg, Rm 529) | 1-GERALD LELLOUCHE |
| 1 - NSIC (BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB | 1-CONSULTANT'S | 1-AGMED (Ruth Gussman) |
| 1 - P. R. DAVIS (AEROJET NUCLEAR) | NEWMARK/BLUME/AGBABIAN | RM-B-127, GT. |
| 6 - CYS ACRS HOLDING | 1-GERALD ULRIKSON...ORNL | 1-RD..MULLER..F-309 GT |
| Sent to Lic Asst Diggs 5-13-74 | 1-B & M SWINEBROAD, Rm E-201 GT | |



2

1. The first part of the document is a list of the names of the persons who were present at the meeting.

2. The second part of the document is a list of the names of the persons who were present at the meeting.

3. The third part of the document is a list of the names of the persons who were present at the meeting.

4. The fourth part of the document is a list of the names of the persons who were present at the meeting.

5. The fifth part of the document is a list of the names of the persons who were present at the meeting.

6. The sixth part of the document is a list of the names of the persons who were present at the meeting.

7. The seventh part of the document is a list of the names of the persons who were present at the meeting.

8. The eighth part of the document is a list of the names of the persons who were present at the meeting.

9. The ninth part of the document is a list of the names of the persons who were present at the meeting.

10. The tenth part of the document is a list of the names of the persons who were present at the meeting.

11. The eleventh part of the document is a list of the names of the persons who were present at the meeting.

12. The twelfth part of the document is a list of the names of the persons who were present at the meeting.

13. The thirteenth part of the document is a list of the names of the persons who were present at the meeting.

14. The fourteenth part of the document is a list of the names of the persons who were present at the meeting.

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD WEST
SYRACUSE, N. Y. 13202

April 29, 1974

50-220



Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D.C. 20545

Dear Mr. Skovholt:

In accordance with Technical Specifications 1.136 and 4.3.3e for
Nine Mile Point Unit 1, the enclosed Abnormal Occurrence Report is sub-
mitted. This report is in accordance with the format set forth in Regulatory
Guideline 1.16.


Very truly yours,


R.R. Schneider

Vice President - Electric Operations

RRS/bar

REGISTERED MAIL
RETURN RECEIPT REQUEST



4224

REGULATORY DOCKET FILE COPY



ABNORMAL OCCURRENCE REPORT

1. Report No. 74-6
- 2a. Date April 20, 1974
- 2b. Occurrence Date April 19, 1974
3. Facility Nine Mile Point Unit 1
4. Identification of Occurrence

Excessive Main Steam Line Isolation Valve Leakage.

5. Conditions Prior to Occurrence

Unit 1 was shutdown for annual refueling.

6. Description of Occurrence

During the process of re-leak testing the MSIV's (AOR 50-220/74-3) the procedure called for low leakage outside isolation valves and a retest of them. During the retest the outside valve leakage (approx. 95 SCFM) exceeded 12.9 SCFH limit. This valve had already satisfied the leakage test on April 2, 1974, therefore the reason for excessive leakage on April 19, 1974 could be attributed to a not fully closed valve or particles trapped under the seat of the valve. Since the unit was shutdown during this period no hazard was presented to the general public.

7. Designation of Apparent Cause of the Occurrence

Still under investigation.

8. Analysis of Occurrence

The Main Steam Line Isolation Valve leakage through the outside valve would not present a problem during a shutdown, however prior to returning the unit to service all valves will be retested.

9. Corrective Action

The valve will be inspected to determine the exact cause of excessive leakage. If in fact, particles were caught under the seat it may become necessary to relap the valve.



Handwritten notes in the top right corner, possibly a date or reference number.

First line of faint, illegible text.

Second line of faint, illegible text.

Third line of faint, illegible text.

Fourth line of faint, illegible text.

Fifth line of faint, illegible text.

Sixth line of faint, illegible text.

Seventh line of faint, illegible text.

Eighth line of faint, illegible text.

Ninth line of faint, illegible text.

Tenth line of faint, illegible text.

10. Failure Data

At least one of these valves has failed to achieve the necessary leak tightness during the annual test while the unit is shutdown. Therefore, an outside consultant has been retained to study, examine and recommend corrective action. Results of this study and corrective actions will be submitted when available. .



10-10-10

10-10-10

10-10-10

10-10-10

TO: MR. JAMES P. O'Rourke RO:I

● COPY

DK Central file

FROM: MR. THOMAS J. PERKINS - NINE MILE POINT

APRIL 20, 1974

ABNORMAL OCCURRENCE 50-220-74-6 MSIV LEAKAGE

PURSUANT TO TECHNICAL SPECIFICATIONS 1.13 e WE ARE REPORTING AS AN ABNORMAL OCCURRENCE THE FAILURE OF MSIV #112 TO PASS A LEAK RATE TEST AS ESTABLISHED IN TECHNICAL SPECIFICATION 4.3.3.e (4) NINE MILE POINT NUCLEAR STATION UNIT #1.

ON APRIL 2, 1974, IN ACCORDANCE WITH TECHNICAL SPECIFICATION 4.3.3.e (4) THIS VALVE WAS LEAK TESTED AND SUCCESSFULLY PASSED THE TEST WITH 7.85 SCFH LEAKAGE. THE LIMIT FOR INDIVIDUAL VALVE LEAKAGE HAS BEEN ESTABLISHED AS 12.9 SCFH. ON THAT SAME DAY, AS REPORTED, THE TWO INSIDE MSIV'S FAILED TO PASS THE LEAK RATE TEST. PRIOR TO RETESTING THE FAILED INSIDE VALVES A CHECK WAS MADE OF THE OUTSIDE VALVES. LEAKAGE THRU #112 WAS DISCOVERED TO BE EXCESSIVE (98.4 SCFH).

THE CAUSE FOR THIS CHANGE IS UNDER INVESTIGATION ALTHOUGH IT IS SUSPECTED THAT DIRT PARTICLES MAY HAVE BEEN TRAPPED UNDER THE SEAT OR THAT VALVE PACKING LEAKAGE MAY HAVE CAUSED THIS CHANGE.

THE UNIT WAS DOWN FOR REFUELING AT THE TIME SO NO HAZARD WOULD HAVE BEEN PRESENTED TO THE GENERAL PUBLIC. THE VALVE HAS BEEN DEMONSTRATED TO BE WITHIN SPECIFICATIONS IMMEDIATELY FOLLOWING SHUTDOWN.

THOMAS J. PERKINS
STATION SUPERINTENDENT

AV



AEC INFORMATION FOR PART 50 DOCKET MATERIALS
(TEMPORARY FORM)

CONTROL NO: 4223

FILE: A10

| | | | | | | | | |
|---|---------|-----------|----------------------------|---------------------------|--------------|---|-----|-------|
| FROM:
Niagara Mohawk Power Corp.
Syracuse, N. Y.
R. R. Schneider | | | DATE OF DOC

4-24-74 | DATE REC'D

5-13-74 | LTR

X | MEMO | RPT | OTHER |
| TO:

Donald J. Skovholt | | | ORIG

1 signed | CC

39 | OTHER | SENT AEC PDR <u>xxx</u>
SENT LOCAL PDR <u>xxxx</u> | | |
| CLASS | UNCLASS | PROP INFO | INPUT | NO CYS REC'D

40 | | DOCKET NO:

50-220 | | |
| | XXX | | | | | | | |

DESCRIPTION:

Ltr trans the following....

PLANT NAME: NINE MILE POINT #1

ENCLOSURES:

Abnormal Occurrence Rpt #74-5 of 4-15-74
in which a main steam line high temperature
sensor set point drift occurred

ACKNOWLEDGED
DO NOT REMOVE
(40 cys encl rec'd)

FOR ACTION/INFORMATION 5-13-74 GMC

| | | | |
|-----------|--------------|---------------|-----------|
| BUTLER(L) | SCHWENCER(L) | ✓ZIEMANN(L) | REGAN(E) |
| W/ Copies | W/ Copies | W/7 Copies | W/ Copies |
| CLARK(L) | STOLZ(L) | DICKER(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| PARR(L) | VASSALLO(L) | KNIGHTON(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| KNIEL(L) | PURPLE (L) | YOUNGBLOOD(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|-------------------|--------------------|---------------|-----------------|-------------------|
| ✓ <u>REG FILE</u> | <u>TECH REVIEW</u> | DENTON | <u>LIC ASST</u> | <u>A/T IND</u> |
| ✓AEC PDR | ✓HENDRIE | GRIMES | | BRAITMAN |
| ✓OGC, ROOM P-506A | ✓SCHROEDER | GAMMILL | ✓DIGGS (L) | SALTZMAN |
| ✓MUNTZING/STAFF | ✓MACCARY | KASTNER | GEARIN (L) | B. HURT |
| ✓CASE | ✓KNIGHT | BALLARD | GOULBOURNE (L) | <u>PLANS</u> |
| GIAMBUSO | ✓PAWLICKI | SPANGLER | LEE (L) | MCDONALD |
| BOYD | ✓SHAO | | MAIGRET (L) | DUBE w/Input |
| MOORE (L)(BWR) | ✓STELLO | <u>ENVIRO</u> | REED (E) | <u>INFO</u> |
| DEYOUNG(L)(FWR) | ✓HOUSTON | MULLER | SERVICE (L) | C. MILES |
| SKOVHOLT (L) | ✓NOVAK | DICKER | SHEPPARD (L) | B. KING (E/W-358) |
| ✓GOLLER(L) | ✓ROSS | KNIGHTON | SLATER (E) | ✓KLECKER |
| P. COLLINS | ✓IPPOLITO | YOUNGBLOOD | SMITH (L) | ✓EISENHUT |
| DENISE | ✓PEDESCO | REGAN | TEETS (L) | |
| <u>REG OPR</u> | ✓LONG | PROJECT LDR | WADE (E) | ✓D. THOMPSON (2) |
| ✓FILE & REGION(3) | ✓LAINAS | | WILLIAMS (E) | W/AOR FILE CY |
| ✓MORRIS | ✓BENAROYA | HARLESS | WILSON (L) | |
| ✓STEELE | ✓VOLLMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|------------------------------------|---------------------------------|------------------------|
| ✓1 - LOCAL PDR <u>OSWEGO, NY</u> | (1)(2X10)-NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| ✓1 - TIC (ABERNATHY) | 1-ASLBP(E/W Bldg, Rm 529) | 1-GERALD LELLOUCHE |
| ✓1 - NSIC(BUCHANAN) | 1-W, PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB | 1-CONSULTANT'S | 1-AGMED(Ruth Gussman) |
| ✓1 - P. R. DAVIS (AEROJET NUCLEAR) | NEWMARK/BLUME/AGBABIAN | RM-B-127, GT. |
| ✓16 - CYS ACRS <u>HOLDING</u> | 1-GERALD ULRICKSON...ORNL | 1-RD..MULLER..F-309 GT |
| Sent to Lic Asst Diggs 5-13-74 | 1-B & M SWINEBROAD, Rm E-201 GT | |



1. The first part of the document is a list of the names of the persons who were present at the meeting.

2. The second part of the document is a list of the names of the persons who were absent from the meeting.

3. The third part of the document is a list of the names of the persons who were present at the meeting.

4. The fourth part of the document is a list of the names of the persons who were present at the meeting.

5. The fifth part of the document is a list of the names of the persons who were present at the meeting.

6. The sixth part of the document is a list of the names of the persons who were present at the meeting.

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD WEST
SYRACUSE, N. Y. 13202

April 24, 1974

Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D.C. 20545

50-220

50-220



Dear Mr. Skovholt:

In accordance with Technical Specifications 1.136 and 3.6.2 for
Nine Mile Point Unit 1, the enclosed Abnormal Occurrence Report is sub-
mitted. This report is in accordance with the format set forth in Regulatory
Guideline 1.16.


Very truly yours,


R.R. Schneider

Vice President - Electric Operations

RRS/bar

REGISTERED MAIL
RETURN RECEIPT REQUEST



4223

REGULATORY DOCKET FILE COPY



ABNORMAL OCCURRENCE REPORT

1. Report No. 74-5
- 2a. Date April 25, 1974
- 2b. Occurrence Date April 15, 1974
3. Facility Nine Mile Point Nuclear Station Unit 1
4. Identification of Occurrence
Main Steam Line High Temperature Sensor Set Point Drift.
5. Conditions Prior to Occurrence
Unit 1 was shutdown for annual refueling.
6. Description of Occurrence
During routine surveillance testing three High Temperature Main Steam Line Tunnel Sensors were found to actuate at a lower temperature than required. These signals provide a closure of the Main Steam Line Isolation Valves upon reaching 200°F. However, since the isolation function requirement is $\leq 200^{\circ}\text{F}$ the necessary trip function would have been accomplished in the conservative direction. In as much as the set point drift was conservative no hazard would have been presented to the general public as a result of this drift.
7. Designation of Apparent Cause of the Occurrence
Set point Drift.
8. Analysis of Occurrence
The Technical Specifications require an isolation signal be sent to the Main Steam Isolation Line Valves, in the event the tunnel temperature reaches or exceeds 200°F. However, the basis for the Specification requires a deviation of $\pm 10^{\circ}\text{F}$. The as found trip point of these Fenwell Temperature Detectors is as follows:

| | |
|--------|-------|
| IB-10F | 187°F |
| IB-10G | 186°F |
| IB-10P | 185°F |
9. Corrective Action
The instrument was recalibrated to 200°F trip point.
10. Failure Data
1st Setpoint Drift on these detectors.



AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 3313

FILE:

| | | | | | | | |
|--|----------------|------------------------|-----------------------|--------------------|------------------------------------|-----|-------|
| FROM:
Niagara Mohawk Power Corp.
Lycoming, N. Y. 13202
P. A. Burt | | DATE OF DOC
4-11-74 | DATE REC'D
4-15-74 | LTR
X | MEMO | RPT | OTHER |
| TO:
D. J. Skovholt | | ORIG
1 signed | CC | OTHER | SENT AEC PDR X
SENT LOCAL PDR X | | |
| CLASS | UNCLASS
XXX | PROP INFO | INPUT | NO CYS REC'D
40 | DOCKET NO:
50-220 | | |

DESCRIPTION:
Ltr reporting abnormal occurrence 50-220-74-4 on 4-2-74, in which the four sensors NAMCO SNAP LOCK #D1200GU406 PTI and D1200GSR0423 PT1 were reported to RO:I as drifting beyond allowable limits on 4-2-74.....

ENCLOSURES:

DO NOT REMOVE

ACKNOWLEDGED

PLANT NAME: Nine Mile Point Unit #1

FOR ACTION/INFORMATION 4-16-74 GC

| | | | |
|------------------------|---------------------------|----------------------------|-----------------------|
| BUTLER(L)
W/ Copies | SCHWENCER(L)
W/ Copies | ZIEMANN(L)
W/7 Copies | REGAN(E)
W/ Copies |
| CLARK(L)
W/ Copies | STOLZ(L)
W/ Copies | DICKER(E)
W/ Copies | W/ Copies |
| PARR(L)
W/ Copies | VASSALLO(L)
W/ Copies | KNIGHTON(E)
W/ Copies | W/ Copies |
| KNIEL(L)
W/ Copies | PURPLE (L)
W/ Copies | YOUNGBLOOD(E)
W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|---|---|--|---|--|
| <u>REG FILE</u>
✓ AEC PDR
✓ OGC, ROOM P-506A
✓ MUNTZING/STAFF
✓ CASE
GIAMBUSO
BOYD
MOORE (L) (EWR)
DEYOUNG (L) (FWR)
SKOVHOLT (L)
✓ GOLLER (L)
P. COLLINS
DENISE
✓ REG OPR
FILE & REGION(3)
✓ MORRIS
✓ STEELE | <u>TECH REVIEW</u>
✓ HENDRIE
✓ SCHROEDER
✓ MACCARY
✓ KNIGHT
✓ PAWLICKI
✓ SHAO
✓ STELLO
✓ HOUSTON
✓ NOVAK
✓ ROSS
✓ IPPOLITO
✓ TEDESCO
✓ LONG
✓ LAINAS
✓ BENAROYA
✓ VOLLMER | DENTON
GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

ENVIRO
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR

HARLESS | <u>LIC ASST</u>
✓ DIGGS (L)
GEARIN (L)
GOULBOURNE (L)
LEE (L)
MAIGRET (L)
REED (E)
SERVICE (L)
SHEPPARD (L)
SLATER (E)
SMITH (L)
TEETS (L)
WADE (E)
WILLIAMS (E)
WILSON (L) | <u>A/T IND</u>
BRAITMAN
SALTZMAN
R. HURT

<u>PLANS</u>
MCDONALD
DUBE w/Input

<u>INFO</u>
C. MILES
✓ B. KING (E/W-358)
✓ KLECKER
✓ EISENHUT |
|---|---|--|---|--|

EXTERNAL DISTRIBUTION

| | | |
|--|---------------------------------|------------------------|
| ✓ 1 - LOCAL PDR Oswego, N. Y. | (1) (2X10) NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| ✓ 1 - TIC (ABERNATHY) | 1-ASLBP (E/W Bldg, Rm 529) | 1-GERALD LELLOUCHE |
| ✓ 1 - NSIC (BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB | 1-CONSULTANT'S | 1-AGMED (Ruth Gussman) |
| ✓ 1 - P. R. DAVIS (AEROJET NUCLEAR) | NEWMARK/BLUME/AGBABIAN | RM-B-127, GT. |
| ✓ 16 - CYS ACRS XXXXXX SENT TO LIC. ASST. | 1-GERALD ULRIKSON...ORNL | 1-RD..MULLER..F-309 GT |
| 4-16-74 DIGGS | 1-B & M SWINEBROAD, Rm E-201 GT | |



10

20

| Age Group | 1970 | 1980 | 1990 | 2000 | 2010 | 2020 |
|-----------|------|------|------|------|------|------|
| 0-14 | 25 | 22 | 18 | 15 | 12 | 10 |
| 15-24 | 15 | 16 | 17 | 18 | 19 | 20 |
| 25-34 | 10 | 11 | 12 | 13 | 14 | 15 |
| 35-44 | 10 | 11 | 12 | 13 | 14 | 15 |
| 45-54 | 10 | 11 | 12 | 13 | 14 | 15 |
| 55-64 | 10 | 11 | 12 | 13 | 14 | 15 |
| 65+ | 10 | 11 | 12 | 13 | 14 | 15 |

Figure 1 consists of three schematic diagrams labeled (a), (b), and (c). Diagram (a) shows a participant sitting at a desk with a computer monitor. The monitor displays a 'START' button and a 'STOP' button. The participant is shown pressing the 'START' button. Diagram (b) shows a participant sitting at a desk with a computer monitor. The monitor displays a 'START' button and a 'STOP' button. The participant is shown pressing the 'STOP' button. Diagram (c) shows a participant sitting at a desk with a computer monitor. The monitor displays a 'START' button and a 'STOP' button. The participant is shown pressing the 'STOP' button.

$\hat{\rho} = \frac{1}{n} \sum_{i=1}^n \hat{\rho}_i$

Figure 1. The effect of the concentration of the *Agrobacterium* suspension on the transformation efficiency of *Agrobacterium* strains. The *Agrobacterium* strains were grown in the YEA medium for 24 h at 28°C. The cell concentration of the strains was adjusted to 1.0 × 10⁸ cells/ml. The cell suspension was mixed with the plant tissue and the transformation efficiency was determined. The results were expressed as the mean ± SD of three independent experiments. The asterisk indicates a significant difference ($P < 0.05$) between the strains.

11

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

91

92

93

94

95

96

97

98

99

100

101

102

103

104

105

106

107

108

109

110

111

112

113

114

115

116

117

118

119

120

121

122

123

124

125

126

127

128

129

130

131

132

133

134

135

136

137

138

139

140

141

142

143

144

145

146

147

148

149

150

151

152

153

154

155

156

157

158

159

160

161

162

163

164

165

166

167

168

169

170

171

172

173

174

175

176

177

178

179

180

181

182

183

184

185

186

187

188

189

190

191

192

193

194

195

196

197

198

199

200

201

202

203

204

205

206

207

208

209

210

211

212

213

214

215

216

217

218

219

220

221

222

223

224

225

226

227

228

229

230

231

232

233

234

235

236

237

238

239

240

241

242

243

244

245

246

247

248

249

250

251

252

253

254

255

256

257

258

259

260

261

262

263

264

265

266

267

268

269

270

271

272

273

274

275

276

277

278

279

280

281

282

283

284

285

286

287

288

289

290

291

292

293

294

295

296

297

298

299

300

301

302

303

304

305

306

307

308

309

310

311

312

313

314

315

316

317

318

319

320

321

322

323

324

325

326

327

328

329

330

331

332

333

334

335

336

337

338

339

340

341

342

343

344

345

346

347

348

349

350

351

352

353

354

355

356

357

358

359

360

361

362

363

364

365

366

367

368

369

370

371

372

373

374

375

376

377

378

379

380

381

382

383

384

385

386

387

388

389

390

391

392

393

394

395

396

397

398

399

400

401

402

403

404

405

406

407

408

409

410

411

412

413

414

415

416

417

418

419

420

421

422

423

424

425

426

427

428

429

430

431

432

433

434

435

436

437

438

439

440

441

442

443

444

445

446

447

448

449

450

451

452

453

454

455

456

457

458

459

460

461

462

463

464

465

466

467

468

469

470

471

472

473

474

475

476

477

478

479

480

481

482

483

484

485

486

487

488

489

490

491

492

493

494

495

496

497

498

499

500

501

502

503

504

505

506

507

508

509

510

511

512

513

514

515

516

517

518

519

520

521

522

523

524

525

526

527

528

529

530

531


532

100

•

• • •

Regulatory Docket File



NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

Nine Mile Point Nuclear Station
Post Office Box 32
Lycoming, New York
April 11, 1974



Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545

Re: Provisional Operating License: DPR-17
Docket No.: 50-220
Abnormal Occurrence 50-220-74-4

Dear Mr. Skovholt:

On April 2, 1974 during the Spring 1974 refueling outage the low condenser vacuum sensors were tested as required by Technical Specification 3.6.2 Nine Mile Point Nuclear Station Unit #1. Pursuant to Technical Specifications 1.13b and 6.6.b.1 the four (4) sensors NAMCO SNAP LOCK #D1200GU406 PT1 and D1200GSR0423 PT1 were reported to RO:I as drifting beyond allowable limits on April 2, 1974.

The low condenser vacuum sensors provide a reactor scram of $23 \pm .5$ " of Hg. The primary reason for this trip is protection of the Turbine-Generator unit and does not have a nuclear related safety function.

With the drift in sensor switch settings a reactor scram would have occurred slightly later in time in the event of decreasing condenser vacuum. The following is a tabulation of the test results:

| Number | 6/11/73 | 4/2/74 |
|--------|---------|--------|
| #11 | 22.55 | 21.80 |
| #12 | 22.70 | 22.00 |
| #21 | 22.62 | 21.90 |
| #22 | 22.57 | 21.80 |

The immediate corrective action was to recalibrate the sensors switched to required actuation point. This is the first failure of this type on these sensors.


As these sensors are required only for Turbine Generator unit protection and that protective function would have occurred only slightly later in time, no hazard was presented to the general public.

Very truly yours,

P. Allister Burt

P. Allister Burt
General Superintendent
Nuclear Generation

3313



ABNORMAL OCCURRENCE 50-220-74-4

PERSUANT TO THE TECHNICAL SPECIFICATIONS 1.13b and 3.6.2, WE ARE REPORTING AS AN ABNORMAL OCCURRENCE THE DRIFT IN THE LOW CONDENSER VACUUM SENSORS.

THE LOW CONDENSER VACUUM SENSORS NORMALLY PROVIDE A REACTOR SCRAM AT $23 \pm .5$ " OF HG. THE PRIMARY REASON FOR THE TRIP IS PROTECTION OF THE TURBINE GENERATOR UNIT AND DOES NOT HAVE A NUCLEAR RELATED SAFETY FUNCTION.

THE FOUR SENSORS ACTUATED LOW WHICH WOULD CAUSE THE REACTOR SCRAM TO OCCUR SLIGHTLY LATER IN TIME IN THE EVENT OF DECREASING CONDENSER VACUUM. THE FOLLOWING IS A TABULATION OF THE TEST RESULTS:

| NUMBER | 6/11/73 | 4/2/74 | REQUIRED |
|--------|---------|--------|-------------|
| #11 | 22.55 | 21.8 | $23 \pm .5$ |
| #12 | 22.7 | 22.0 | " |
| #21 | 22.62 | 21.9 | " |
| #22 | 22.57 | 21.8 | " |

THE CORRECTIVE ACTION WAS TO RESET THE SENSORS, NAMCO SNAP-LOCK #D1200GU406PT1 + #D1200GSRU423PT1 TO THE REQUIRED TRIP POINT.

AS THE SENSORS PROVIDE TURBINE-GENERATOR PROTECTION ONLY AND WOULD HAVE CAUSED THAT PROTECTIVE FUNCTION ONLY SLIGHTLY LATER IN TIME NO HAZARD WAS PRESENTED TO THE STATION OR THE GENERAL PUBLIC.

T. J. PERKINS
STATION SUPERINTENDENT

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 3314

FILE: _____

| | | | | | | | | |
|--|----------------|-----------|-----------------------|-----------------------|----------|------------------------------------|-----|-------|
| FROM:
Niagara Mohawk Power Corp.
Syracuse, N. Y. 13202
P. A. Burt | | | DATE OF DOC
4-9-74 | DATE REC'D
4-15-74 | LTR
X | MEMO | RPT | OTHER |
| TO:
D. J. Skovholt | | | ORIG
1 signed | CC | OTHER | SENT AEC PDR X
SENT LOCAL PDR X | | |
| CLASS | UNCLASS
XXX | PROP INFO | INPUT | NO CYS REC'D
40 | | DOCKET NO:
50-220 | | |

DESCRIPTION:

Ltr reporting abnormal occurrence on 4-2-74, in which the inside valves in both line failed to meet the required limit of 12.9 SCFH.....

ENCLOSURES:

**DO NOT REMOVE
ACKNOWLEDGED**

PLANT NAME: Nine Mile Point Unit #1

FOR ACTION/INFORMATION 4-16-74 GC

| | | | |
|------------------------|---------------------------|----------------------------|-----------------------|
| BUTLER(L)
W/ Copies | SCHWENCER(L)
W/ Copies | ✓ZIEMANN(L)
W/ 7Copies | REGAN(E)
W/ Copies |
| CLARK(L)
W/ Copies | STOLZ(L)
W/ Copies | DICKER(E)
W/ Copies | W/ Copies |
| PARR(L)
W/ Copies | VASSALLO(L)
W/ Copies | KNIGHTON(E)
W/ Copies | W/ Copies |
| KNIEL(L)
W/ Copies | PURPLE (L)
W/ Copies | YOUNGBLOOD(E)
W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|--|---|---|--|---|
| <u>REG FILE</u>
✓AEC PDR
✓OGC, ROOM P-506A
✓MUNIZING/STAFF
✓CASE
GIAMBUSO
BOYD
MOORE (L)(BWR)
DEYOUNG(L)(PWR)
SKOVHOLT (L)
✓COLLER(L)
P. COLLINS
DENISE
REG OPR
FILE & REGION(3)
✓MORRIS
✓STEELE | <u>TECH REVIEW</u>
✓HENDRIE
✓SCHROEDER
✓MACCARY
✓KNIGHT
✓PAWLICKI
✓SHAO
✓STELLO
✓HOUSTON
✓NOVAK
✓ROSS
✓IPPOLITO
✓TEDESCO
✓LONG
✓LAINAS
✓BENAROYA
✓VOLLMER | DENTON
GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

<u>ENVIRO</u>
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR

HARLESS | <u>LIC ASST</u>
✓DIGGS (L)
GEARIN (L)
GOULBOURNE (L)
LEE (L)
MAIGRET (L)
REED (E)
SERVICE (L)
SHEPPARD (L)
SLATER (E)
SMITH (L)
TEETS (L)
WADE (E)
WILLIAMS (E)
WILSON (L) | <u>A/T IND</u>
BRAITMAN
SALTZMAN
B. HURT

<u>PLANS</u>
MCDONALD
DUBE w/Input

<u>INFO</u>
C. MILES
✓B. KING (E/W-358)
✓KLECKER
✓EISENHUT |
|--|---|---|--|---|

EXTERNAL DISTRIBUTION

| | | |
|---|---------------------------------|------------------------|
| ✓1 - LOCAL PDR Oswego, N. Y. | (1)(2)(10)-NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| ✓1 - TIC (ABERNATHY) | 1-ASLBP(E/W Bldg, Rm 529) | 1-GERALD LELLOUCHE |
| ✓1 - NSIC(BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB | 1-CONSULTANT'S | 1-AGMED(Ruth Gussman) |
| 1 - P. R. DAVIS (AEROJET NUCLEAR) | NEWMARK/BLUME/AGBABIAN | RM-B-127, GT. |
| ✓16 - CYS ACRS XXXXXX SENT TO LIC. ASST. | 1-GERALD ULRIKSON...ORNL | 1-RD..MULLER..F-309 GT |
| 4-16-74 DIGGS | 1-B & M SWINEBROAD, Rm E-201 GT | |

1944-1945

1946-1947

1948-1949

1950-1951

1952-1953

1954-1955

1956-1957


Regulatory Docket File

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD WEST
SYRACUSE, N. Y. 13202

April 9, 1974



Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545

Re: Provisional Operating License: DPR-17
Docket No.: 50-220
Abnormal Occurrence - 50-220-74-3



Dear Mr. Skovholt:

On April 2, 1974, in accordance with Technical Specification 4.3.3 e(4), the four (4) Main Steam Isolation Valves were leak tested. The outside MSIV's in each line successfully passed the leak rate test, however the inside valves in both lines failed to meet the required limit of 12.9 SCFH. Notification was made to RO:I on April 2, 1974 in accordance with Technical Specification 1.13e.

The Main Steam Flow from the reactor to the turbine is through two independent 24" lines. Each line contains two isolation valves, one inside the containment and one immediately outside the containment. The two failed valves, one in each line, were the valves inside the containment.

Under containment design basis accident conditions, both main steam lines would be essentially leak tight with low leakage through the outside valves and no hazard would be presented to the plant or the general public.

The primary corrective measure taken will depend upon the cause of leakage. It appears from preliminary results that one valve (#111) experienced a drift in the position switch on the valve controller to cause the valve not to fully close. The other valve #121, appears to require machine lapping of the valve seat. Such repairs have been made in the past and this is not the first of a kind failure.¹

The tabular results for each valve is indicated below:

| | |
|--------------|-----------|
| #111 Inside | 1400 SCFH |
| #112 Outside | 7.85 SCFH |
| #121 Inside | 120 SCFH |
| #122 Outside | 0.24 SCFH |

3314

3314



11/10/52

1. The first part of the report is a summary of the work done during the year.

2. The second part is a detailed account of the work done during the year.

3.

4.

5.

6.

7.

8.

9.

10.

11.

12.

13.

14.

15.

16.

17.

18.

19.

20.

21.

22.

23.

24.

25.

26.

27.

28.

29.

30.

31.

32.

33.

34.

35.

36.

37.

June 19, 1974

In the interest of maintaining an efficient refueling outage schedule, the repair and retesting of the inside valves has not been completed to this date, however, the results of the repair and retest will appear in the Semi-Annual report published in July, 1974.

Very truly yours,



P. Allister Burt
General Superintendent
Nuclear Generation

TJD:cm

¹Ltr. P.A. Burt - Skovholt - June 6, 1973.

**AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 3092

FILE: A/O

| | | | | | | | | |
|---|----------------|-----------|-----------------------|----------------------|----------|------------------------------------|-----|-------|
| FROM:
Niagara Mohawk Power Corp.
Syracuse, N. Y. 13202
R. R. Schneider | | | DATE OF DOC
4-1-74 | DATE REC'D
4-9-74 | LTR
X | MEMO | RPT | OTHER |
| TO:
D. J. Skovholt | | | ORIG
3 signed | CC | OTHER | SENT AEC PDR X
SENT LOCAL PDR X | | |
| CLASS | UNCLASS
XXX | PROP INFO | INPUT | NO CYS REC'D
40 | | DOCKET NO:
50-220 | | |

DESCRIPTION:
Ltr reporting abnormal occurrence 50-220-74-2
on 3-23-74, regarding a pipe crack in the
waste concentrator piping.....

ENCLOSURES:

DO NOT REMOVE

ACKNOWLEDGED

PLANT NAME: Nine Mile Point #1

FOR ACTION/INFORMATION 4-11-74 GC

| | | | |
|-----------|--------------|---------------|-----------|
| BUTLER(L) | SCHWENCER(L) | ✓ZIEMANN(L) | REGAN(E) |
| W/ Copies | W/ Copies | W/ 7Copies | W/ Copies |
| CLARK(L) | STOLZ(L) | DICKER(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| GOLLER(L) | VASSALLO(L) | KNIGHTON(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| KNIEL(L) | SCHEMEL(L) | YOUNGBLOOD(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|-------------------|--------------------|---------------|-----------------|----------------|
| <u>REG FILE</u> | <u>TECH REVIEW</u> | DENTON | <u>LIC ASST</u> | <u>A/T IND</u> |
| ✓AEC PDR | ✓HENDRIE | GRIMES | | BRAITMAN |
| ✓OGC, ROOM P-506A | SCHROEDER | GAMMILL | ✓DIGGS (L) | SALTZMAN |
| ✓MUNTZING/STAFF | ✓MACCARY | KASTNER | GEARIN (L) | B. HURT |
| ✓CASE | ✓KNIGHT | BALLARD | GOULBOURNE (L) | <u>PLANS</u> |
| GIAMBUSSO | ✓PAWLICKI | SPANGLER | LEE (L) | MCDONALD |
| BOYD | ✓SHAO | | MAIGRET (L) | DUBE w/Input |
| MOORE (L)(BWR) | ✓STELLO | <u>ENVIRO</u> | REED (E) | <u>INFO</u> |
| DEYOUNG(L)(PWR) | ✓HOUSTON | MULLER | SERVICE (L) | C. MILES |
| ✓SKOVHOLT (L) | ✓NOVAK | DICKER | SHEPPARD (L) | ✓B. KING(RO) |
| P. COLLINS | ✓ROSS | KNIGHTON | SLATER (E) | |
| DENISE | ✓APPOLITO | YOUNGBLOOD | SMITH (L) | |
| <u>REG OPR</u> | ✓TEDESCO | REGAN | TEETS (L) | |
| FILE & REGION(3) | ✓LONG | PROJECT LDR | WADE (E) | |
| ✓MORRIS | ✓LAINAS | | WILLIAMS (E) | |
| ✓STEELE | ✓BENAROYA | HARLESS | WILSON (L) | |
| | ✓VOLLMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|---|------------------------------|------------------------|
| ✓ - LOCAL PDR Oswego, N. Y. | (1) (2)(10)-NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| ✓ - DTIE(ABERNATHY) | 1-ASLBP(E/W Bldg, Rm 529) | 1-GERALD LELLOUCHE |
| ✓ - NSIC(BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB(YORE) | 1-CONSULTANT'S | 1-AGMED(Ruth Gussman) |
| ✓16 - CYS ACRS XXXXXXXX SENT TO LIC. ASST. | NEWMARK/BLUME/AGBABIAN | RM-B-127, GT. |
| 4-11-74 DIGGS | 1-GERALD ULRIKSON...ORNL | 1-RD..MULLER..F-309 GT |

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....


.....

.....

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD WEST
SYRACUSE, N.Y. 13202



April 1, 1974



Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545

Re: Provisional Operating License: DPR-17
Docket No.: 50-220

Dear Mr. Skovholt:

Persuant to Nine Mile Point Nuclear Station Unit #1 Technical Specifications 1.13 d, we are reporting Abnormal Occurrence 50-220-74-2 a pipe crack in the waste concentrator piping.

On March 23, 1974 during routine operation of the concentrator steam was observed coming through the insulation surrounding a 12" section of pipe leading from the side arm heater to the bottom of the concentrator. The concentrator was shut down and the insulation removed revealing cracks in the pipe.

The primary cause of the failure can be attributed to improper installation techniques during construction. Due to a problem with pipe fit certain forcing means were employed to position the pipe. These means weakened the pipe and caused its cracking. The pipe section will be replaced using approved methods. A section of the failed pipe will be examined to determine if any underlying cause for cracking was present.

The expanded Administrative Procedures and the expanded Quality Control Group will prevent reoccurrences of this failure in the future.

The cracking in the piping did not present a hazard to the Station Personnel or the General Public.

Very truly yours,



R. R. Schneider
Vice President - Electric Operations

TJD:cm

3092



12



UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

Central files

March 25, 1974

Distribution Code 2

Chief, Field Services and
Enforcement Branch, HQ

ABNORMAL OCCURRENCE

Licensee: Niagara Mohawk Power Corp.

Docket No.: 50-220

Abnormal Occurrence: 50-220-74-2 dated March 23, 1974

The attached report from the subject licensee is forwarded in accordance with RO Manual Chapter 1000. Follow-up will be performed during the next inspection, as appropriate. Copies of the report have been forwarded to the PDR, Local PDR, NSIC, DTIE, and State representatives. The licensee will submit a 10-day written report to Licensing.

A10

FROM: T.J. PERKINS - NINE MILE POINT NUCLEAR STATION

ABNORMAL OCCURRENCE 50-220-74-2

PERSUANT TO TECHNICAL SPECIFICATION 1.13d WE ARE REPORTING AS AN ABNORMAL OCCURRENCE CRACKING IN THE WASTE CONCENTRATOR PIPING FROM THE SIDE ARM HEATER.

ON MARCH 23, 1974 DURING ROUTINE OPERATION OF THE CONCENTRATOR A SLIGHT PUFF OF STEAM WAS SEEN TO BE EMITTED FROM A SECTION OF 12" PIPE LEADING FROM SIDE ARM HEATER TO THE BOTTOM OF THE CONCENTRATOR. FOLLOWING SHUTDOWN OF THE CONCENTRATOR AND REMOVAL OF THE INSULATION SURROUNDING THE PIPE, SEVERAL CRACKS WERE REVEALED IN (AND NEAR ONE WELD.

THE CAUSE OF THE FAILURE IS CURRENTLY UNDER INVESTIGATION AND WOULD OF COURSE DICTATE THE CORRECTIVE ACTION. NO HAZARD WAS PRESENTED TO THE GENERAL PUBLIC AS A RESULT OF THIS FAILURE.

T.J. PERKINS
STATION SUPERINTENDENT
NINE MILE POINT NUCLEAR STATION

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 2000

FILE: A10

| | | | | | | | | |
|--|---------|-----------|-----------------------|-----------------------|----------|--|-----|-------|
| FROM:
NiagaraMohawk Power Corporation
Syracuse, N. Y.
R. R. Schneider | | | DATE OF DOC
3-8-74 | DATE REC'D
3-11-74 | LTR
X | MEMO | RPT | OTHER |
| TO:
Donald J. Skovholt | | | ORIG
1 signed | CC
39 | OTHER | SENT AEC PDR XXX
SENT LOCAL PDR XXX | | |
| CLASS | UNCLASS | PROP INFO | INPUT | NO CYS REC'D
40 | | DOCKET NO:
50-220 | | |
| | XXX | | | | | | | |
| DESCRIPTION: | | | | ENCLOSURES: | | | | |

Ltr reporting abnormal occurrence of 2-25-74 in which pne core spray differential pressure ins instrument (Barton 288-4802, RV-30A) was found to actuate at a lower value than allowed

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: NINE MILE POINT UNIT #1

FOR ACTION/INFORMATION 3-12-74 GMC

| | | | |
|-----------|--------------|---------------|-----------|
| BUTLER(L) | SCHWENCER(L) | ✓ ZIEMANN(L) | REGAN(E) |
| W/ Copies | W/ Copies | W/ 7 Copies | W/ Copies |
| CLARK(L) | STOLZ(L) | DICKER(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| GOLLER(L) | VASSALLO(L) | KNIGHTON(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| KNIEL(L) | SCHEMEL(L) | YOUNGBLOOD(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|---------------------|----------------------|----------------|----------------|--------------------------|
| ✓ <u>REG FILE</u> | ✓ <u>TECH REVIEW</u> | DENTON | LIC ASST | A/T IND |
| ✓ AEC PDR | ✓ HENDRIE | GRIMES | ✓ DIGGS (L) | BRAITHAN |
| ✓ OGC, ROOM P-506A | ✓ SCHROEDER | GAMMILL | GEARIN (L) | SALTZMAN |
| ✓ MUNTZING/STAFF | ✓ MACCARY | KASTNER | GOULBOURNE (L) | B. HURT |
| ✓ CASE | ✓ KNIGHT | BALLARD | LEE (L) | <u>PLANS</u> |
| GIAMBUSO | ✓ PAWLICKI | SPANGLER | MAIGRET (L) | MCDONALD |
| BOYD | ✓ SHAO | | REED (L) | DUBE w/Input |
| MOORE (L) (EWR) | ✓ STELLO | <u>ENVIRO</u> | SERVICE (L) | <u>INFO</u> |
| ✓ DEYOUNG (L) (FWR) | ✓ HOUSTON | MULLER | SHEPPARD (E) | ✓ C. MILES |
| ✓ SKOVHOLT (L) | ✓ NOVAK | DICKER | SMITH (L) | ✓ B. KING <i>8/10/80</i> |
| P. COLLINS | ✓ ROSS | KNIGHTON | TEETS (L) | |
| DENISE | ✓ IPPOLITO | YOUNGBLOOD | WADE (E) | |
| ✓ <u>REG OPR</u> | ✓ TEDESCO | REGAN | WILLIAMS (E) | |
| ✓ FILE & REGION(3) | ✓ LONG | PROJECT LDR | WILSON (L) | |
| ✓ MORRIS | ✓ LAINAS | | | |
| ✓ STEELE | ✓ BENAROYA | <u>HARLESS</u> | | |
| | ✓ VOLLMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|------------------------------------|------------------------------|---------------------|
| ✓ 1 - LOCAL PDR OSWEGO, NY | 1-B & M SWINEBROAD | 1-P. R. DAVIS |
| ✓ 1 - DTIE(ABERNATHY) | (1)(2)(10)-NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| ✓ 1 - NSIC(BUCHANAN) | 1-ASLBP(E/W Bldg, Rm 529) | 1-GERALD LELLOUCHE |
| 1 - ASLB(YORE/SAYRE/ | 1-W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| WOODARD/"H" ST. | 1-CONSULTANT'S | 1-AGMED(Ruth Gussma |
| ✓ 16 - CYS ACRS <i>reverse</i> | NEWMARK/BLUME/AGBABIAN | RM- B-127, GT. |
| ... Sent to Lic Asst Diggs 3-12-74 | 1-GERALD ULRIKSON...ORNL | 1-RD..MULLER..F-309 |

...

...

...

...

... (...) ...

...


...

7

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK300 ERIE BOULEVARD WEST
SYRACUSE, N.Y. 13202

March 8, 1974



Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
U.S. Atomic Energy Commission
Washington, D. C. 20545

Re: Provisional Operating License: DPR-17
Docket No.: 50-220



Dear Mr. Skovholt:

Persuant to Nine Mile Point Nuclear Station Unit #1 Technical Specifications 1.13 d and 4.14 d we are reporting as an abnormal occurrence, an alarm limit drift on one core spray differential pressure instrument.

On February 25, 1974 during routine surveillance testing, one core spray differential pressure instrument (Barton 288-4802, RV-30A) was found to actuate at a lower value than that as set forth in the instrument surveillance checklist. This is the second drift in set point of this particular instrument¹. Notification was made to Region I, Division of Regulatory Operations on February 26, 1974.

The instrument surveillance checklist set point is 5 psid +0-1.0. The instrument actuated on alarm at 3.5 psid or at a lower differential than is required. However awareness of an abnormal condition in the core spray piping would have alarmed sooner than required thus the drift was in a safe direction. The instrument as designed is intended to provide an alarm only and serves no protective circuitry function.

The primary function of the core spray differential pressure indicators is to monitor the condition of the core spray piping between the reactor vessel. A loss of integrity would create a differential pressure in the range of 20-25 psid under normal operating conditions.

To prevent re-occurrence of this instrument set point drift a modification will be made to the Barton instrument to minimize if not eliminate the problem. This modification will be made during the upcoming Spring refueling outage scheduled to commence this month.



4

Mr. Donald J. Skovholt,
U.S. Atomic Energy Commission

March 6, 1974

Based upon the fact that the drift was in the safe direction,
no undue hazard was presented to the general public as a result of
this instrument drift.

Very truly yours,



R.R. Schneider

Vice President - Electric Operations

TJD:cm

¹ Ltr. Schneider - Skovholt July 6, 1973

AEC DISTRIBUTION FOR PART 50 DOCKET
(TEMPORARY FORM)

Regulatory File Cy.

CONTROL NO: 337

FILE:

| | | | | | | | | |
|--|---------|-----------|-----------------------|-----------------------|----------|--|-----|-------|
| FROM: Rudolph R. Schneider
Niagara Mohawk Power Corporation
300 Erie Boulevard West
Syracuse, N. Y. 13202 | | | DATE OF DOC
1-3-74 | DATE REC'D
1-11-74 | LTR
X | MEMO | RPT | OTHER |
| TO:
Mr. Donald J. Skovholt | | | ORIG
1 signed | CC
39 | OTHER | SENT AEC PDR <u>xxx</u>
SENT LOCAL PDR <u>xxx</u> | | |
| CLASS | UNCLASS | PROP INFO | INPUT | NO CYS REC'D
40 | | DOCKET NO:
50-220 | | |
| | xxx | | | | | | | |

DESCRIPTION:

Ltr furnishing the following info:

- 1) inspection of snubbers 1-2-74
- 2) filing of record of inspection
- 3) next inspection 2-1-74

ENCLOSURES:

DO NOT REMOVE
ACKNOWLEDGED

PLANT NAME: Nine Mile Point #1

FOR ACTION/INFORMATION 1-11-74 GMC

| | | | |
|-----------|--------------|---------------|-----------|
| BUTLER(L) | SCHWENCER(L) | ✓ ZIEMANN(L) | REGAN(E) |
| W/ Copies | W/ Copies | W/5 Copies | W/ Copies |
| CLARK(L) | STOLZ(L) | DICKER(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| GOLLER(L) | VASSALLO(L) | KNIGHTON(E) | ... |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| KNIEL(L) | SCHEMEL(L) | YOUNGBLOOD(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|-------------------|--------------------|----------------|-----------------|----------------|
| ✓ <u>REG FILE</u> | <u>TECH REVIEW</u> | DENTON | <u>LIC ASST</u> | <u>A/T IND</u> |
| ✓ AEC PDR | ✓ HENDRIE | GRIMES | ✓ DIGGS (L) | BRAITMAN |
| OGC, ROOM P-506A | SCHROEDER | GAMMILL | GEARIN (L) | SALTZMAN |
| MUNTZING/STAFF | ✓ MACCARY | KASTNER | GOULBOURNE (L) | B. HURT |
| CASE | KNIGHT | BALLARD | LEE (L) | <u>PLANS</u> |
| ✓ GIAMBUSSO | PAWLICKI | SPANGLER | MAIGRET (L) | ✓ MCDONALD |
| BOYD | SHAO | | SERVICE (L) | DUBE w/Input |
| MOORE (L) (BWR) | STELLO | <u>ENVIRO</u> | SHEPPARD (E) | <u>INFO</u> |
| DEYOUNG (L) (PWR) | HOUSTON | MULLER | SMITH (L) | C. MILES |
| SKOVHOLT (L) | NOVAK | DICKER | TEETS (L) | B. KING |
| P. COLLINS | ROSS | KNIGHTON | WADE (E) | |
| DENISE | IPPOLITO | YOUNGBLOOD | WILLIAMS (E) | |
| ✓ <u>REG OPR</u> | TEDESCO | REGAN | WILSON (L) | |
| FILE & REGION(3) | LONG | PROJECT LDR | | |
| MORRIS | LAINAS | | | |
| STEELE | BENAROYA | <u>HARLESS</u> | | |
| | VOLLMER | | | |


EXTERNAL DISTRIBUTION

- | | | |
|-------------------------------|------------------------------|------------------------|
| ✓ 1 - LOCAL PDR Oswego, N. Y. | (1) (2X10)-NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| 1 - DTIE (ABERNATHY) | 1-ASLBP (E/W Bldg, Rm 529) | 1-GERALD LELLOUCHE |
| 1 - NSIC (BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB (YORE/SAYRE/ | 1-CONSULTANT'S | 1-AGMED (Ruth Gussman) |
| WOODARD/"H" ST. | NEWMARK/BLUME/AGBABIAN | RM-B-127, GT. |
| ✓ 16 - CYS ACRS Sent to Lic | 1-GERALD ULRIKSON... ORNL | 1-RD..MULLER..F-309 C |
| Asst. R. Diggs | | |


NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK300 ERIE BOULEVARD WEST
SYRACUSE, N.Y. 13202

January 3, 1974



Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545




Re: Provisional Operating License: DPR-17
Docket No.: 50-220

Dear Mr. Skovholt:

In accordance with our commitment* to report the condition of Bergen-Paterson snubbers monthly the following information is furnished.

1. An inspection of all Bergen-Paterson snubbers was conducted on January 2, 1974.
2. All snubbers were found to be satisfactory and meet the criteria of the inspection as specified*.
3. A record of the inspection of each snubber has been made and filed as specified*.
4. The next inspection is scheduled for February 1, 1974.

Very truly yours,



Rudolph R. Schneider
Vice President - Electric Operations

TJD:cm

* Ltr. RRS to Skovholt - Dec. 5, 1973

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 10090

FILE: _____

| | | | | | | | | |
|---|----------------|-----------|-----------------------------|----------------------------|--------------|--|-----|-------|
| FROM:
Niagara Mohawk Power Corp.
Syracuse, N.Y. 13202
Mr. R.R. Schneider | | | DATE OF DOC

12-21-73 | DATE REC'D

12-28-73 | LTR

X | MEMO | RPT | OTHER |
| TO:

D.J. Skovholt | | | ORIG

1 signed | CC | OTHER | SENT AEC PDR XXX
SENT LOCAL PDR XXX | | |
| CLASS | UNCLASS
XXX | PROP INFO | INPUT | NO CYS REC'D
40 | | DOCKET NO:
50-220 | | |

DESCRIPTION:
Ltr re their 11-28-73 and 12-3-73 ltrs concern failures of 11 and 15 control rods to insert to 00 following a reactor scram at Nine Mile Point Unit #1.....submitting add'l info on the apparent cause of these abnormal occurrences....

ENCLOSURES:

ENCLOSURE
DO NOT REMOVE

PLANT NAME: Nine Mile Point #1

FOR ACTION/INFORMATION 1-8-74 JB

| | | | |
|-----------|--------------|---------------|-----------|
| BUTLER(L) | SCHWENCER(L) | ✓ ZIEMANN(L) | REGAN(E) |
| W/ Copies | W/ Copies | W/ 7 Copies | W/ Copies |
| CLARK(L) | STOLZ(L) | DICKER(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| GOLLER(L) | VASSALLO(L) | KNIGHTON(E) | ... |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| KNIEL(L) | SCHEMEL(L) | YOUNGBLOOD(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|--------------------|--------------------|---------------|-----------------|----------------|
| ✓ <u>REG FILE</u> | <u>TECH REVIEW</u> | DENTON | <u>LIC ASST</u> | <u>A/T IND</u> |
| ✓ AEC PDR | ✓ HENDRIE | GRIMES | | BRAITMAN |
| ✓ OGC, ROOM P-506A | SCHROEDER | GAMMILL | ✓ DIGGS (L) | SALTZMAN |
| ✓ MUNTZING/STAFF | ✓ MACCARY | KASTNER | GEARIN (L) | B. HURT |
| ✓ CASE | ✓ KNIGHT | BALLARD | GOULBOURNE (L) | <u>PLANS</u> |
| GIAMBUSSO | ✓ PAWLICKI | SPANGLER | LEE (L) | MCDONALD |
| BOYD | ✓ SHAO | | MAIGRET (L) | DUBE |
| MOORE (L)(FWR) | ✓ STELLO | <u>ENVIRO</u> | SERVICE (L) | <u>INFO</u> |
| DEYOUNG(L)(FWR) | ✓ HOUSTON | MULLER | SHEPPARD (E) | C. MILES |
| ✓ SKOVHOLT (L) | ✓ NOVAK | DICKER | SMITH (L) | ✓ B. King (RO) |
| P. COLLINS | ✓ ROSS | KNIGHTON | TEETS (L) | |
| | ✓ IPPOLITO | YOUNGBLOOD | WADE (E) | |
| ✓ <u>REG OPR</u> | ✓ TEDESCO | REGAN | WILLIAMS (E) | |
| FILE & REGION(3) | ✓ LONG | PROJECT LDR | WILSON (L) | |
| ✓ MORRIS | ✓ LAINAS | | | |
| ✓ STEELE | ✓ BENAROYA | HARLESS | | |
| | ✓ VOLLMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|---------------------------------------|------------------------------|------------------------|
| ✓ 1 - LOCAL PDR Oswego, N.Y. | (1) (2X10) NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| ✓ 1 - DTIE(ABERNATHY) | 1-ASLBP(E/W Bldg, Rm 529) | 1-GERALD LELLOUCHE |
| ✓ 1 - NSIC(BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB(YORE/SAYRE/ | 1-CONSULTANT'S | 1-AGMED(Ruth Gussman) |
| WOODARD/"H" ST. | NEWMARK/BLUME/AGBABIAN | RM-B-127, GT. |
| ✓ 16 - CYS ACRS HOLDING Sent to Diggs | 1-GERALD ULRIKSON...ORNL | 1-RD..MULLER..F-309 GT |
| 1-8-74 | | |

1. The first part of the report

2. The second part of the report

3.

4. The third part of the report

5.

6.

7. The fourth part of the report

8. The fifth part of the report

9.

10.


11.

12.


13.

14.

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK300 ERIE BOULEVARD WEST
SYRACUSE, N.Y. 13202

December 21, 1973



Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D.C. 20545

Re: Provisional Operating License: DPR-17
Docket No.: 50-220

Dear Mr. Skovholt:

This letter is to provide, as committed, additional clarifying information describing the apparent cause of the abnormal occurrences reported to you on November 28 and December 3, 1973, the failures of eleven (11) and fifteen (15), respectively, control rods to insert to 00 following a reactor scram at Nine Mile Point Nuclear Station 1 (NMPNS 1).

The control rod drives used at NMPNS 1 are the locking piston type using water as the hydraulic fluid. The assembly consists primarily of a stop piston and seals, which is fixed in position, a drive piston with seals, which is cylindrical around the stop piston and a collet-piston with rings, which locks the drive piston in an even notch position. The drive piston assembly has a subassembly, an index tube with 24 notches. The notches being similar to a right triangle cut, with the 90° angle at the notch top to prevent withdrawing of the control blade. The collet-piston has a latching mechanism made up of six fingers. Spring action in the fingers themselves hold them against the index tube. When these fingers are in a notch in the index tube the control blade cannot be withdrawn. Also if the fingers are not in a notch position but in contact with the index tube, the furthest the control rod can withdraw or settle is to the next notch position. In other words if a drive has been inserted beyond notch position 02 but not beyond position 00 the rod will settle back into notch position 02 and no further. The stop piston is a hollow assembly with two sets of seals and hydraulic ports (Buffer holes) between the above drive piston area and area between the two set of seals, and the scram exhaust valve. As pressure is increased under the drive piston the control rod tends to insert into the core. However the water above the drive piston must be evacuated as the drive piston assembly moves into this area. The water is exhausted through 8 ports in the stop piston assembly, (buffer holes). However as the drive piston moves closer to fully inserted position the holes are covered up by seals in the drive piston reducing the rate at which water may be evacuated from the over piston area. Thus on a scram this decreasing rate of water flow causes the drive to slow down once it passes the 02 notch position.

10090

Mr. Donald J. Skovholt
U.S. Atomic Energy Commission

December 21, 1973

As the rate of water flow decreases the pressure exerted must increase, however it remains much less than 1000 psi or reactor pressure. If the stop piston seals have become broken, scored or jammed and do not perform their function, reactor pressure water is introduced to the area between the two sets of seals. This excess water is carried away through the hydraulic port between the seals through the stop piston to the hollow interior. If the leakage is approximately 6 gpm past these seals it will force water at reactor pressure through the lower stop piston seal into the above drive piston area. Because of the number and size of the buffer holes available at notch 04 and notch 02 (Figure 1), no problem is presented to drive movement. However beyond the 02 notch position moving toward 00 the increased stop piston seal leakage becomes critical, such that the remaining buffer hole cannot vent the required water and the drive stops between position 01 and notch 00 (Figure 2). Upon resetting the scram signal, the scram dump valve closes. Pressure quickly builds up in the drive until reactor pressure is equalized. The drive then settles to notch 02. It can not proceed further to notch 04 because of the latching mechanism in the collet piston. Two important items which have been substantiated through testing by the General Electric Company can be drawn from the above sequence.

1. The drive slow down is not a problem until the drive has passed the 01 position. Sufficient buffer holes exist prior to this position.
2. The drive can only settle into the 02 notch position because of the latching mechanism in the collet-piston.


The drive design has been modified by the manufacturer (General Electric Company) to mount a .0012" mesh filter on the stop piston thus preventing the entry of dirt particles to the stop piston seals. These dirt particles cause the jamming and scoring of the stop piston seals. NMPNS.1 will start a conversion program at the Spring 1974 refueling outage.

Therefore having established that the only positions that the control rod with broken, jammed or scored stop piston seals can settle into is notch 00 or 02 consideration must be given to the shutdown margin with all control rods at notch 02. Calculations based upon shutdown margin tests and cold Xenon free criticals show a shutdown margin, with all rods at notch position 02 and the strongest control rod withdrawn, of 1.94% ΔK at Xenon free cold conditions.

In a random nine rod array (3x3) with the center rod withdrawn to 48 and adjacent rods at 02 notch position the shutdown margin is a minimum of 2.28% ΔK . If all rods were at notch 02 the shutdown margin would be 2.98% ΔK .

In conclusion, it has been established that adequate shutdown margin exists with all control rods at notch position 02. It has been further established that the possibility of even one rod settling in a notch position other than 00 or 02 is highly improbable if not impossible. Therefore it is concluded that no hazard exists to safe operation of the plant or to the general public during the remainder of this operating cycle as a result of this problem.

Very truly yours,



Rudolph R. Schneider

Vice President - Electric Operations


RRS:cm

Enclosures - 2 figures

REGISTERED MAIL - RETURN RECEIPT



RELATIONSHIP OF PARTS AT TIME
OF BUFFER ENTRY
FIG. 1



RELATIONSHIP OF PARTS WHEN
PISTON IS $1\frac{1}{4}$ " FROM POSITION "00"
FIG. 2

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 8914

FILE: A/6

| | | | | | | | | |
|--|---------|-----------|-------------------------|------------------------|----------|------------------------------------|-----|-------|
| FROM:
Niagara Mohawk Power Corporation
Syracuse, N. Y. 13202
Rudolph R. Schneider | | | DATE OF DOC
12-10-73 | DATE REC'D
12-14-73 | LTR
X | MEMO | RPT | OTHER |
| TO:
Mr. Skovholt | | | ORIG
1 signed | CC | OTHER | SENT AEC PDR X
SENT LOCAL PDR X | | |
| CLASS | UNCLASS | PROP INFO | INPUT | NO CYS REC'D
40 | | DOCKET NO:
50-220 | | |
| | XXX | | | | | | | |

DESCRIPTION:
Ltr reporting an incident on 12-1-73, in which the Scram Dump Volume Level system failed to operate during routine surveillance testing.....

ENCLOSURES:

ACKNOWLEDGED
Do Not Remove

PLANT NAME: Nine Mile Point Unit # 1

FOR ACTION/INFORMATION

12-15-73

AB

| | | | |
|-----------|--------------|---------------|-----------|
| BUTLER(L) | SCHWENCER(L) | ✓ ZIEMANN(L) | REGAN(E) |
| W/ Copies | W/ Copies | W/7 Copies | W/ Copies |
| CLARK(L) | STOLZ(L) | DICKER(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| GOLLER(L) | VASSALLO(L) | KNIGHTON(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| KNIEL(L) | SCHEMEL(L) | YOUNGBLOOD(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|--|---|---|---|---|
| <u>REG FILE</u>
✓ AEC PDR
✓ OGC, ROOM P-506A
✓ MUNTZING/STAFF
✓ CASE
GIAMBUSO
BOYD
MOORE (L) (BWR)
DEYOUNG (L) (FWR)
✓ SKOVHOLT (L)
P. COLLINS

<u>REG OPR</u>
✓ FILE & REGION(3)
✓ MORRIS
✓ STEELE | <u>TECH REVIEW</u>
✓ HENDRIE
SCHROEDER
✓ MACCARY
✓ KNIGHT
✓ PAWLICKI
✓ SHAO
✓ STELLO
✓ HOUSTON
✓ NOVAK
✓ ROSS
✓ IPPOLITO
✓ TEDESCO
✓ LONG
✓ LAINAS
✓ BENAROYA
✓ VOLLMER | DENTON
GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

<u>ENVIRO</u>
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR

HARLESS | <u>LIC ASST</u>
✓ DIGGS (L)
GEARIN (L)
GOULBOURNE (L)
LEE (L)
MAIGRET (L)
SERVICE (L)
SHEPPARD (E)
SMITH (L)
TEETS (L)
WADE (E)
WILLIAMS (E)
WILSON (L) | <u>A/T IND</u>
BRAITMAN
SALTZMAN
B. HURT

<u>PLANS</u>
MCDONALD
DUBE

<u>INFO</u>
C. MILES
✓ B. KING |
|--|---|---|---|---|

EXTERNAL DISTRIBUTION

| | | |
|--|--|---|
| ✓ 1 - LOCAL PDR Oswego, N. Y.
✓ 1 - DTIE (ABERNATHY)
✓ 1 - NSIC (BUCHANAN)
1 - ASLB (YORE/SAYRE/WOODARD/"H" ST.)
✓ 16 - CYS ACRS MODIFIED SENT TO LIC ASST.
R. DIGGS ON 12-15-73 | (1) (2) (10) - NATIONAL LAB'S
1 - ASLBP (E/W Bldg, Rm 529)
1 - W. PENNINGTON, Rm E-201 GT
1 - CONSULTANT'S
NEWMARK/BLUME/AGBABIAN
1 - GERALD ULRIKSON... ORNL | 1 - PDR-SAN/LA/NY
1 - GERALD LELLOUCHE
BROOKHAVEN NAT. LAB
1 - AGMED (Ruth Gussman)
RM-B-127, GT.
1 - RD..MULLER..F-309 GT |
|--|--|---|

[illegible]

$\frac{d}{dt} \left(\frac{\partial L}{\partial \dot{x}} \right) = \frac{\partial L}{\partial x}$

5

Regulatory


Cy.

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD WEST
SYRACUSE, N.Y. 13202

December 10, 1973



AOR 73-12-1

Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545

Re: Provisional Operating License: DPR-17
Docket No.: 50-220

Dear Mr. Skovholt:

On December 1, 1973 at 1300 hours at Nine Mile Point Nuclear Station Unit #1, a Magnetrol switch #352624 in the Scram Dump Volume level system failed to operate during routine surveillance testing. Pursuant to Technical Specification 1.13 d,:

- d. Failure of one or more components of an engineered safety feature or Station system that causes or threatens to cause the feature or system to be incapable of performing its intended function,

this is an abnormal occurrence and was reported by telephone on December 1, 1973 and photocopy on December 3, 1973 to Director of Regulatory Operations, Region I.


Prior to the occurrence the unit was operating at 1272 MWt with all plant systems normal. Routine surveillance testing was in progress.

The scram dump volume level switches (37 gal.) cause a reactor scram in a 1 out of 2 twice logic. RD08C failed to cause the required actuation of #12 trip channel. The remaining three instruments in this system performed as required.

The apparent cause of this occurrence was the result of oxidized mercury in the bulb of the switch. Although the switch carriage would rotate as required the mercury would not move out of contact with the switch wire inside the bulb. A pin hole leak was found in the bulb.

Since the redundant component was fully operable a scram would have been produced if required and no hazard would have been presented to the general public.

To correct this situation, the mercury bulb was replaced and in the future as much as possible all mercoids will be checked for this condition during surveillance testing. This is the first failure of this type.




8914

Mr. Donald J. Skovholt
U.S. Atomic Energy Commission

December 10, 1973

As the mercury starts to oxidize it loses its mirror shine and becomes increasingly dull. The Instrumentation and Control Technicians will be alerted to look for this condition.

Very truly yours,


Rudolph R. Schneider
Vice President - Electric Operations

RRS:cm

REGISTERED MAIL
RETURN RECEIPT REQUEST

AEC CONTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 8728

FILE:

| | | | | | | | | |
|---|----------------|-----------|------------------------|-----------------------|----------------------|------------------------------------|-----|-------|
| FROM:
Niagara Mohawk Power Corporation
Syracuse, New York 13202
Rudolph R. Schneider | | | DATE OF DOC
12-3-73 | DATE REC'D
12-7-73 | LTR
x | MEMO | RPT | OTHER |
| TO:
D. J. Skovholt | | | ORIG
1 signed | CC
39 | OTHER | SENT AEC PDR X
SENT LOCAL PDR X | | |
| CLASS | UNCLASS
XXX | PROP INFO | INPUT | NO CYS REC'D
40 | DOCKET NO:
50-220 | | | |

DESCRIPTION:

Ltr reporting abnormal occurrence on 11-26-73 regarding 15 control rod drives failed to insert to position 00 following a reactor scram.

ENCLOSURES:

ACKNOWLEDGED
DO NOT REMOVE

PLANT NAME: Nine Miles Point Unit # 1

FOR ACTION/INFORMATION 12-8-73 fod

| | | | |
|-----------|--------------|---------------|-----------|
| BUTLER(L) | SCHWENCER(L) | ✓ZIEMANN(L) | REGAN(E) |
| W/ Copies | W/ Copies | W/7 Copies | W/ Copies |
| CLARK(L) | STOLZ(L) | DICKER(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| GOLLER(L) | VASSALLO(L) | KNIGHTON(E) | W/ Copies |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| KNIEL(L) | SCHEMEL(L) | YOUNGBLOOD(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|-------------------|--------------------|----------------|-----------------|----------------|
| <u>REG FILE</u> | <u>TECH REVIEW</u> | DENTON | <u>LIC ASST</u> | <u>A/T IND</u> |
| ✓AEC PDR | ✓HENDRIE | GRIMES | | BRAITMAN |
| ✓OGC, ROOM P-506A | ✓SCHROEDER | GAMMILL | ✓DIGGS (L) | SALTZMAN |
| ✓MUNTZING/STAFF | ✓MACCARY | KASTNER | GEARIN (L) | B. HURT |
| ✓CASE | ✓KNIGHT | BALLARD | GOULBOURNE (L) | <u>PLANS</u> |
| GIAMBUSSO | ✓PAWLICKI | SPANGLER | LEE (L) | MCDONALD |
| BOYD | ✓SHAO | | MAIGRET (L) | DUBE |
| MOORE (L)(BWR) | ✓STELLO | <u>ENVIRO</u> | SERVICE (L) | <u>INFO</u> |
| DEYOUNG(L)(PWR) | ✓HOUSTON | MULLER | SHEPPARD (E) | C. MILES |
| ✓SKOVHOLT (L) | ✓NOVAK | DICKER | SMITH (L) | ✓B. KING (RO) |
| P. COLLINS | ✓ROSS | KNIGHTON | TEETS (L) | |
| | ✓IPPOLITO | YOUNGBLOOD | WADE (E) | |
| <u>REG OPR</u> | ✓TEDESCO | REGAN | WILLIAMS (E) | |
| ✓FILE & REGION(3) | ✓LONG | PROJECT LDR | WILSON (L) | |
| ✓MORRIS | ✓LAINAS | | | |
| ✓STEELE | ✓BENAROYA | <u>HARLESS</u> | | |
| | ✓VOLLMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|--|------------------------------|------------------------|
| ✓1 - LOCAL PDR Oswego, N. Y. | (1)(2)(10)-NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| ✓1 - DTIE(ABERNATHY) | 1-ASLBP(E/W Bldg, Rm 529) | 1-GERALD LELLOUCHE |
| ✓1 - NSIC(BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB(YORE/SAYRE/ | 1-CONSULTANT'S | 1-AGMED(Ruth Gussman) |
| WOODARD/"H" ST. | NEWMARK/BLUME/AGBABIAN | RM-B-127, GT. |
| ✓16 - CYS ACRS XXXXXX Sent 12-8-73 to | 1-GERALD ULRIKSON...ORNL | 1-RD..MULLER..F-309 GT |
| R. Diggs for Dist.. | | |

For the purpose of the present study, the following data were collected:

1. The first group of subjects

2. The second group of subjects

3. The third group of subjects

4. The fourth group of subjects

The results of the study are presented in the following table:

Table 1. Results of the study

Table 2. Results of the study

Table 3. Results of the study

Table 4. Results of the study

Table 5. Results of the study

Table 6. Results of the study

Table 7. Results of the study

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD WEST
SYRACUSE, N.Y. 13202

December 3, 1973

AOR 73-11-29

Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545

Re: Provisional Operating License: DPR-17
Docket No.: 50-220

Regulatory

File Cy.

Dear Mr. Skovholt:

On November 26, 1973 at 0330 hours at Nine Mile Point Nuclear Station Unit #1, fifteen (15) control rod drives failed to insert to position 00 following a reactor scram. Pursuant to Technical Specifications: 1.13 d,

- d. Failure of one or more components of an engineered safety feature or Station system that causes or threatens to cause the feature or system to be incapable of performing its intended function,

this is an abnormal occurrence and was reported by telephone and photocopy to Director of Regulatory Operations, Region I.


Prior to the occurrence the unit was being shutdown, mode switch in start-up and reactor pressure was less than 850 psig. A scram occurred on neutron instrumentation (IRM's) and upon resetting the scram fifteen (15) control rods showed position 02. Seven (7) of those were the subject of AOR 73-11-20. The operator immediately inserted these control rods to 00 using normal drive pressure and the manual control system.

The apparent cause of this occurrence following a review of testing by SORC has been identified as leakage past the stop piston seals.

The reactor was shutdown even with fifteen (15) control rods at 02 as indicated by decreasing neutron instrumentation therefore no hazard was presented to the general public nor was plant safety in jeopardy.



To correct this situation, the fifteen (15) control rods will be overhauled during the Spring 1974 refueling outage. This is the second incident of this nature (AOR 73-11-20) and appears to be a problem which occurs as a result of deteriorating stop piston seals causing a slowdown during the last 5% of drive travel.

Very truly yours,


Rudolph R. Schneider
Vice President - Electric Operations

RRS:cm

REGISTERED MAIL
RETURN RECEIPT REQUEST



8728

Mr. Donald J. Skovhove
U.S. Atomic Energy Commission

November 28, 1973


The apparent cause of this occurrence has been identified as damaged stop piston seals causing excessive leakage past these seals. This was determined from stall leakage flow tests and scram testing of each of the affected control rods prior to unit power generation on the succeeding start-up. Excessive flow past the stop piston seals instead of thru the buffer holes (the number of those holes decreases as the control rod is inserted) will result in slowing down of the control rod over the last 5% of its travel.

Throughout the preceding transient and during the period of time that the eleven (11) control rods were at position 02 no hazard was presented to the general public. The reactor was highly subcritical and could not have been made critical using these eleven control rods at position 02.

To correct this situation, the control rods affected will be overhauled during the Spring 1974 refueling outage as well as any others which indicate the high stall leakage flows.

In the past replacement of control rod drives during refueling outages has been determined in part by high stall leakage flows. The deterioration of the stop piston seals of the General Electric control rod drive mechanism appears to increase with increasing drive pressure required to operate the control rod. Orders have been issued to operations to maintain the drive pressure within normal limits during rod withdrawals. However those control rods with existing deteriorated seals will have to be moved using higher than normal pressure.

Very truly yours,



Rudolph H. Schneider
Vice President - Electric Operations

RRS:cm

cc: Mr. James O'Reilly
RO:I

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 8703

FILE: _____

| | | | | | | | | |
|---|----------------|-----------|-----------------------------|---------------------------|--------------|--|-----|-------|
| FROM:
Niagara Mohawk Power Corp;
Syracuse, N. Y. 13202
R. R. Schneider | | | DATE OF DOC

11-30-73 | DATE REC'D

12-6-73 | LTR

X | MEMO | RPT | OTHER |
| TO:
D. J. Skovholt | | | ORIG
1 signed | CC | OTHER | SENT AEC PDR <u>X</u>
SENT LOCAL PDR <u>X</u> | | |
| CLASS | UNCLASS
XXX | PROP INFO | INPUT | NO CYS REC'D
40 | | DOCKET NO:
50-220 | | |

DESCRIPTION:
Ltr reporting abnormal occurrence 73-11-2 in fall of 73, in which discrepancy was noted in the pressure set point trip of the re-circulation pumps for the analysis of transients without scram.....

ENCLOSURES:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: Nine Mile Point Unit #1

FOR ACTION/INFORMATION 12-7-73 GC

| | | | |
|-----------|--------------|---------------|-----------|
| BUTLER(L) | SCHWENCER(L) | ✓ZIEMANN(L) | REGAN(E) |
| W/ Copies | W/ Copies | W/ 7 Copies | W/ Copies |
| CLARK(L) | STOLZ(L) | DICKER(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| GOLLER(L) | VASSALLO(L) | KNIGHTON(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| KNIEL(L) | SCHEMEL(L) | YOUNGBLOOD(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|-------------------|--------------------|----------------|-----------------|----------------|
| <u>REG FILE</u> | <u>TECH REVIEW</u> | DENTON | <u>LIC ASST</u> | <u>A/T IND</u> |
| ✓AEC PDR | ✓HENDRIE | GRIMES | | BRAITMAN |
| ✓OGC, ROOM P-506A | SCHROEDER | GAMMILL | ✓DIGGS (L) | SALTZMAN |
| ✓MUNTZING/STAFF | ✓MACCARY | KASTNER | GEARIN (L) | B. HURT |
| ✓CASE | ✓KNIGHT | BALLARD | GOULBOURNE (L) | <u>PLANS</u> |
| GIAMBUSSO | ✓PAWLICKI | SPANGLER | LEE (L) | MCDONALD |
| BOYD | ✓SHAO | | MAIGRET (L) | DUBE |
| MOORE (L) (BWR) | ✓STELLO | <u>ENVIRO</u> | SERVICE (L) | <u>INFO</u> |
| DEYOUNG (L) (PWR) | ✓HOUSTON | MULLER | SHEPPARD (E) | C. MILES |
| ✓SKOVHOLT (L) | ✓NOVAK | DICKER | SMITH (L) | ✓B. KING (RO) |
| P. COLLINS | ✓ROSS | KNIGHTON | TEETS (L) | |
| | ✓IPPOLITO | YOUNGBLOOD | WADE (E) | |
| <u>REG OPR</u> | ✓TEDESCO | REGAN | WILLIAMS (E) | |
| FILE & REGION(3) | ✓LONG | PROJECT LDR | WILSON (L) | |
| ✓MORRIS | ✓LAINAS | | | |
| ✓STEELE | ✓BENAROYA | <u>HARLESS</u> | | |
| | ✓VOLLMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|---|------------------------------|------------------------|
| ✓1 - LOCAL PDR Oswego, NY. | (1) (2) (10) NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| ✓1 - DTIE (ABERNATHY) | 1-ASLBP (E/W Bldg, Rm 529) | 1-GERALD LELLOUCHE |
| ✓1 - NSIC (BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB (YORE/SAYRE/ | 1-CONSULTANT'S | 1-AGMED (Ruth Gussman) |
| WOODARD/"H" ST. | | RM-B-127, GT. |
| ✓16 - CYS ACRS XXXXXX SENT TO LIC. ASST. | NEWMARK/BLUME/AGBABIAN | 1-RD..MULLER..F-309 GT |
| 12-7-73 DIGGS | 1-GERALD ULRIKSON...ORNL | |

NIAGARA MOHAWK POWER CORPORATION


Regulatory Docket File



300 ERIE BOULEVARD WEST
SYRACUSE, N.Y. 13202

November 30, 1973

Mr. Donald J. Skovholt
Assistant Director For Reactor Operations
Division of Reactor Licensing
U. S. Atomic Energy Commission
Washington, D. C. 20545



Dear Mr. Skovholt:

Re: Provisional Operating License: DPR-17
Docket No.: 50-220

Unusual Event 73-11-2

In accordance with Section 6.6. b 2 of the Nine Mile Point Nuclear Station, Unit #1 Technical Specifications, the following information is forwarded concerning an unusual event occurring at the Nine Mile Point Nuclear Station, Unit #1.

During the Spring 1973 refueling outage, the circuitry to cause the trip of all recirculation pumps upon reaching a pre-established reactor pressure was installed in accordance with reviewed and approved design change drawings. The requirement for this change is discussed in detail in the "Technical Supplement To Petition For Conversion From Provisional Operating License To Full Term Operating License" page IV 39 - IV 47.

A review of the existing Technical Specification with regard to updating was conducted this Fall, when a discrepancy was noted in the pressure set point trip of the recirculation pumps for the Analysis of Transients without scram. A thorough review by the Site Operating Review Committee revealed that the pumps will be tripped at 1080 psig rather than the intended 1150 psig as stated in the above mentioned document. The effect of lowering this set point has no detrimental effect on the Analysis of Transients without scram. However, it does have an adverse effect on the margin between peak pressure reached in a transient involving scram with turbine trip and failure of the bypass system and the lowest safety valve setting. Although no safety limits are reached, the degradation of the pressure margin is of concern. General Electric Company has concluded that existing power operation is permissible with no infringement on the safe operation of the plant or safety of the general public. However, as stated in my letter of November 30, 1973, to Mr. Giambusso, the trip of recirculation pumps on high reactor pressure is being deleted from the protection system circuitry to prevent assumed aggravation of other transients.

8703

1

1000

1000

U. S. Atomic Energy Commission
Mr. Donald J. Skovholt
November 30, 1973

The General Electric Company is completing a review of safety analysis to determine the effect of this new parameter on performance on transient conditions. When their review is complete, design changes will be formulated, reviewed, approved and installed.

Very truly yours,



R. R. Schneider
Vice President - Electric Operations

cc Mr. James P. O'Reilly

REGISTERED MAIL
RETURN RECEIPT REQUEST

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 8604

FILE: _____

| | | | | | | | |
|---|-----------------|-------------------------|-----------------------|--------------------|------------------------------------|-----|-------|
| FROM:
Niagara Mohawk Power Corp.
Syracuse, N. Y. 13202
R. R. Schneider | | DATE OF DOC
11-28-73 | DATE REC'D
12-3-73 | LTR
X | MEMO | RPT | OTHER |
| TO:
D. J. Skovholt | | ORIG
1 signed | CC | OTHER | SENT AEC PDR X
SENT LOCAL PDR X | | |
| CLASS | UNCLASS
XXXX | PROP INFO | INPUT | NO CYS REC'D
40 | DOCKET NO:
50-220 | | |

DESCRIPTION:

Ltr reporting an abnormal occurrence on 11-20-73, in which 11 control rod drives failed to insert to notch position 00 following a Reactor Scram.....

ENCLOSURES:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: Nine Mile Point Unit 1

FOR ACTION/INFORMATION 12-3-73 GC

| | | | |
|------------------------|---------------------------|----------------------------|-----------------------|
| BUTLER(L)
W/ Copies | SCHWENCER(L)
W/ Copies | ZIEMANN(L)
W/ 7 Copies | REGAN(E)
W/ Copies |
| CLARK(L)
W/ Copies | STOLZ(L)
W/ Copies | DICKER(E)
W/ Copies | |
| GOLLER(L)
W/ Copies | VASSALLO(L)
W/ Copies | KNIGHTON(E)
W/ Copies | |
| KNIEL(L)
W/ Copies | SCHEMEL(L)
W/ Copies | YOUNGBLOOD(E)
W/ Copies | |

INTERNAL DISTRIBUTION

| | | | | |
|--|---|--|---|---|
| <u>REG FILE</u>
AEC PDR
OGC, ROOM P-506A
MUNTZING/STAFF
CASE
GIAMBUSSO
BOYD
MOORE (L)(BWR)
DEYOUNG(L)(PWR)
SKOVHOLT (L)
P. COLLINS | <u>TECH REVIEW</u>
HENDRIE
SCHROEDER
MACCARY
KNIGHT
PAWLICKI
SHAO
STELLO
HOUSTON
NOVAK
ROSS
IPPOLITO
TEDESCO
LONG
LAINAS
BENAROYA
VOLLMER | DENTON
GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

ENVIRO
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR

HARLESS | <u>LIC ASST</u>
DIGGS (L)
GEARIN (L)
GOULBOURNE (L)
LEE (L)
MAIGRET (L)
SERVICE (L)
SHEPPARD (E)
SMITH (L)
TEETS (L)
WADE (E)
WILLIAMS (E)
WILSON (L) | <u>A/T IND</u>
BRATTMAN
SALTZMAN
B. HURT

<u>PLANS</u>
MCDONALD
DUBE

<u>INFO</u>
C. MILES
B.KING (RO) |
| <u>REG OPR</u>
FILE & REGION(3)
MORRIS
STEELE | | | | |

EXTERNAL DISTRIBUTION

| | | |
|---|------------------------------|------------------------|
| 1 - LOCAL PDR Oswego, N. Y. | (1)(2)(10)-NATIONAL LAB'S | 1-PDR-SAN/LA/NY. |
| 1 - DTIE(ABERNATHY) | 1-ASLBP(E/W Bldg, Rm 529) | 1-GERALD LELLOUCHE |
| 1 - NSIC(BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB(YORE/SAYRE/
WOODARD/"H" ST. | 1-CONSULTANT'S | 1-AGMED(Ruth Gussman) |
| 16 - CYS ACRS XXXXXX SENT TO LIC. ASST. NEWMARK/BLUME/AGBABIAN | 1-GERALD ULRIKSON...ORNL | RM-B-127, GT. |
| 12-3-73 DIGGS | | 1-RD..MULLER..F-309 GT |

ACKNOWLEDGMENT

100


Regulatory Docket File

NIAGARA MOHAWK POWER CORPORATION


NIAGARA  MOHAWK

300 ERIE BOULEVARD WEST
SYRACUSE, N.Y. 13202

November 28, 1973



AOR 73-11-20



Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545

Re: Provisional Operating License: DPR-17
Docket No.: 50-220

Dear Mr. Skovholt:

On November 20, 1973 at approximately 0230 hours at Nine Mile Point Nuclear Station, Unit #1, eleven (11) control rod drives failed to insert to notch position 00 following a Reactor Scram. Pursuant to Technical Specification 1.13 d.,

Failure of one or more components of an engineered safety feature or Station system that causes or threatens to cause the feature or system to be incapable of performing its intended function,

this is an abnormal occurrence and was reported by telephone and photocopy to the Director of Regulatory Operations, Region Office I on November 20, 1973.

Prior to the occurrence a routine startup was in progress with reactor power being increased, using reactor recirculation flow, following a scheduled shutdown for Operator Demonstration criticals. Reactor power had reached the 77% level, water level was normal, reactor pressure was 988 psig, the generator was on line with all systems operating normally for a routine start-up.

A sudden increase in recirculation flow rate occurred at 77% power causing an increase in positive reactivity (the result of voids being "swept" more rapidly from the core i.e. better moderation) resulting in a high flux reactor scram and anticipatory turbine generator trip. The control room operator immediately decreased recirculation flow when it became obvious that recirculation flow was on an upward ramp and neutron instrumentation began steadily increasing, however his proper action could not prevent the high flux flow bias reactor scram. The recirculation flow ramp increase will be the subject of an unusual event letter before December 20, 1973. All systems operated normally for this transient except the control rod drive system. The operator noted that upon resetting of the scram eleven (11) control rods indicated position 02 instead of 00. The operator immediately inserted the control rods to 00 using the reactor manual control system with normal control rod drive pressure.

8604

— 42 —

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 8502

FILE:

| | | | | | | | | |
|---|----------------|-----------|-------------------------|------------------------|----------|--|-----|-------|
| FROM:
Niagara Mohawk Power Corporation
Syracuse, N.Y. 13202
Mr. R.R. Schneider | | | DATE OF DOC
11-21-73 | DATE REC'D
11-28-73 | LTR
X | MEMO | RPT | OTHER |
| TO:
D.J. Skovholt | | | ORIG
1 signed | CC | OTHER | SENT AEC PDR XXX
SENT LOCAL PDR XXX | | |
| CLASS | UNCLASS
XXX | PROP INFO | INPUT | NO CYS REC'D
40 | | DOCKET NO:
50-220 | | |

DESCRIPTION:
Ltr reporting an abnormal occurrence at the
Nine Mile Point facility Unit #1....concern...
loss of incoming 115 KV....

ENCLOSURES:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: Nine Mile Point

FOR ACTION/INFORMATION

11-28-73

JB

| | | | |
|-----------|--------------|---------------|-----------|
| BUTLER(L) | SCHWENCER(L) | ✓ ZIEMANN(L) | REGAN(E) |
| W/ Copies | W/ Copies | W/ 7 Copies | W/ Copies |
| CLARK(L) | STOLZ(L) | DICKER(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| GOLLER(L) | VASSALLO(L) | KNIGHTON(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| KNIEL(L) | SCHEMEL(L) | YOUNGBLOOD(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|--------------------|--------------------|----------------|-----------------|----------------|
| <u>REG FILE</u> | <u>TECH REVIEW</u> | DENTON | <u>LIC ASST</u> | <u>A/T IND</u> |
| ✓ AEC PDR | ✓ HENDRIE | GRIMES | | BRAITMAN |
| ✓ OGC, ROOM P-506A | SCHROEDER | GAMMILL | ✓ DIGGS (L) | SALTZMAN |
| ✓ MUNTZING/STAFF | ✓ MACCARY | KASTNER | GEARIN (L) | B. HURT |
| ✓ CASE | ✓ KNIGHT | BALLARD | GOULBOURNE (L) | <u>PLANS</u> |
| GIAMBUSSO | ✓ PAWLICKI | SPANGLER | LEE (L) | MCDONALD |
| BOYD | ✓ SHAO | | MAIGRET (L) | DUBE |
| MOORE (L) (BWR) | ✓ STELLO | <u>ENVIRO</u> | SERVICE (L) | <u>INFO</u> |
| DEYOUNG(L) (PWR) | ✓ HOUSTON | MULLER | SHEPPARD (E) | C. MILES |
| ✓ SKOVHOLT (L) | ✓ NOVAK | DICKER | SMITH (L) | ✓ B. King |
| P. COLLINS | ✓ ROSS | KNIGHTON | TEETS (L) | |
| | ✓ IPPOLITO | YOUNGBLOOD | WADE (E) | |
| ✓ REG OPR | ✓ TEDESCO | REGAN | WILLIAMS (E) | |
| FILE & REGION(3) | ✓ LONG | PROJECT LDR | WILSON (L) | |
| ✓ MORRIS | ✓ LAINAS | | | |
| ✓ STEELE | ✓ BENAROYA | <u>HARLESS</u> | | |
| | ✓ VOLLMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|---|------------------------------|------------------------|
| ✓ 1 - LOCAL PDR Oswego, N.Y. | (1) (2X10)-NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| ✓ 1 - DTIE(ABERNATHY) | 1-ASLB(E/W Bldg, Rm 529) | 1-GERALD LELLOUCHE |
| ✓ 1 - NSIC(BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB(YORE/SAYRE/
WOODARD/"H" ST. | 1-CONSULTANT'S | 1-AGMED(Ruth Gussman) |
| ✓ 16 - CYS ACRS XXXXXX Sent to Diggs | NEWMARK/BLUME/AGBABIAN | Rm-B-127, GT. |
| 11-28-73 | 1-GERALD ULRIKSON...ORNL | 1-RD..MULLER..F-309 GT |

TO THE HONORABLE

THE SECRETARY OF THE

...


...

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK300 ERIE BOULEVARD WEST
SYRACUSE, N.Y. 13202

November 21, 1973

Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
U. S. Atomic Energy Commission
Washington, D. C. 20545



Re: Provisional Operating License: DPR-17
Docket No.: 50-220


Dear Mr. Skovholt:

This is to report a condition relating to the operation of the Nine Mile Point Nuclear Station #1 (NMPNS) in which on November 17, 1973 at 1626 hours a loss of incoming 115 KV occurred.

Technical Specification 3.6.3.a states:

Specification:

- a. For all reactor operating conditions except cold shutdown, there shall normally be available two 115 KV external lines, two diesel-generator power systems and two battery systems.....



On November 17, 1973 the reactor was scheduled for AEC Operator Examination involving a critical demonstration. After the reactor was shutdown in the early morning (~2 a.m.) breaker R40 was opened to facilitate line work on the 115 KV line between James A. FitzPatrick Nuclear Power Plant (JAFNPP) and NMPNS #1. Breaker R10, the remaining 115 KV line breaker was closed and the station was operating on reserve power supplied by this line. Following the Reactor Operator critical demonstrations, the reactor was in the just critical condition, moderator temperature 207°F, mode switch in start-up and the JAFNPP-NMPNPS 115 KV line out of service. A plant electrician, working with the relay department in the auxiliary control room on the JAFNPP-NMPNPS 115 KV line relay accidentally bumped a relay (50 FDS/SI) causing Relay 945 to de-energize thus tripping the remaining 115 KV line. The plant remained without off-site power for 10 seconds until breaker R10 reclosed.

A reactor scram occurred within seconds (5.4) as M.G. Sets #131 and #141 (which supplies power to the scram pilot solenoids) upon loss of A.C. power, tripped at 55 hz. Within the allowable 10 seconds both diesel generator systems had started and energized the two control rod drive pumps to maintain reactor water within the normal expected range for this transient. As water level remained normal no other safeguard equipment was needed.

8502

1977



Mr. Donald J. Skovholt
U.S. Atomic Energy Commission

November 21, 1973


Restoration of normal reserve station power occurred within 10 seconds and upon resetting necessary plant feeders normal reserve A.C. was established to plant equipment and the diesel generators shutdown.

The reactor was restarted at approximately 2100 hours with both 115 KV lines in service and normal plant conditions.

All systems performed their designed function as required and no hazard was presented to the general public.

To prevent a reoccurrence of this incident the plant electricians were made aware of the need to be extra cautious when working around relaying in particular when one line is already de-energized.

Very truly yours,

A handwritten signature in cursive script, reading "Rudolph R. Schneider".

Rudolph R. Schneider
Vice President - Electric Operations

RRS:cm

My name
is [illegible]

[Illegible text block]

[Illegible text block]

[Illegible text block]

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 8423

FILE:

| | | | | | | | | |
|--|----------------|-----------|-------------------------|------------------------|----------|------------------------------------|-----|-------|
| FROM:
Niagara Mohawk Power Corporation
Syracuse, New York 13202
R. R. Schneider | | | DATE OF DOC
11-19-73 | DATE REC'D
11-23-73 | LTR
x | MEMO | RPT | OTHER |
| TO:
D. J. Skovholt | | | ORIG
1 signed | CC
39 | OTHER | SENT AEC PDR X
SENT LOCAL PDR X | | |
| CLASS | UNCLASS
XXX | PROP INFO | INPUT | NO CYS REC'D
40 | | DOCKET NO:
50-220 | | |

DESCRIPTION:
Ltr reporting a condition on 11-10-73....
a reactor low-low water level switch setting
was found to actuate above the normal set
point....

ENCLOSURES:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: Nine Mile Point Unit # 1

FOR ACTION/INFORMATION 11-24-73 fod

| | | | |
|------------------------|---------------------------|----------------------------|-----------------------|
| BUTLER(L)
W/ Copies | SCHVENCER(L)
W/ Copies | ZIEMANN(L)
W/ 7 Copies | REGAN(E)
W/ Copies |
| CLARK(L)
W/ Copies | STOLZ(L)
W/ Copies | DICKER(E)
W/ Copies | |
| GOLLER(L)
W/ Copies | VASSALLO(L)
W/ Copies | KNIGHTON(E)
W/ Copies | |
| KNIEL(L)
W/ Copies | SCHEMEL(L)
W/ Copies | YOUNGBLOOD(E)
W/ Copies | |

INTERNAL DISTRIBUTION

| | | | | |
|---|---|--|---|--|
| <u>REG FILE</u>
AEC PDR
OGC, ROOM P-506A
MUNTING/STAFF
CASE
GIAMBUSSO
BOYD
MOORE (L)(BWR)
DEYOUNG(L)(PWR)
SKOVHOLT (L)
P. COLLINS | <u>TECH REVIEW</u>
HENDRIE
SCHROEDER
MACCARY
KNIGHT
PAWLICKI
SHAO
STELLO
HOUSTON
NOVAK
ROSS
IPPOLITO
TEDESCO
LONG
LAINAS
BENAROYA
VOLLMER | DENTON
GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

ENVIRO
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR

HARLESS | <u>LIC ASST</u>
DIGGS (L)
GEARIN (L)
GOULBOURNE (L)
LEE (L)
MAIGRET (L)
SERVICE (L)
SHEPPARD (E)
SMITH (L)
TEETS (L)
WADE (E)
WILLIAMS (E)
WILSON (L) | <u>A/T IND</u>
BRATTMAN
SALTZMAN
B. HURT

<u>PLANS</u>
MCDONALD
DUBE

<u>INFO</u>
C. MILES
B. KING (RO) |
| <u>REG OPR</u>
FILE & REGION(3)
MORRIS
STEELE | | | | |

EXTERNAL DISTRIBUTION

| | | |
|--|------------------------------|------------------------|
| 1 - LOCAL PDR Oswego, N. Y. | (1) (2X10) NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| 1 - DTIE(ABERNATHY) | 1-ASLBP(E/W Bldg, Rm 529) | 1-GERALD LELLOUCHE |
| 1 - NSIC(BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB(YORE/SAYRE/
WOODARD/"H" ST. | 1-CONSULTANT'S | 1-AGMED(Ruth Gussman) |
| 16 - CYS ACRS Sent 11-24-73 to
R. Diggs for Dist. | NEWMARK/BLUME/AGBABIAN | RM-B-127, GT. |
| | 1-GERALD ULRIKSON...ORNL | 1-RD..MULLER..F-309 GT |

1947-1948


NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD WEST
SYRACUSE, N. Y. 13202

November 19, 1973

Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545



Dear Mr. Skovholt:

Regulatory

File Cy.

RE: Provisional Operating License: DPR-17
Docket No.: 50-220

This is to report a condition relating to the operation of the Nine Mile Point Nuclear Station Unit 1 in which on November 10, 1973 at 1509 hours a reactor low-low water level switch setting was found to actuate above the normal set point, which is allowable by Technical Specifications, but beyond the deviations as established in the basis for that specification. This condition was related to Region I Compliance by telephone and on November 12, 1973 by photocopy at 1508 hours.

During routine surveillance testing of the reactor low-low water level sensors (at 90% rated power) the set point of one of the Yarway sensors (RE02D) was found to have drifted to 4' 9" below minimum normal water level. A change of three (3) inches from the last inspection on October 13, 1973 at which time the sensor tripped as required at five (5) feet below minimum normal water level.

The basis of Technical Specification 3.6.2 call for a deviation of no more than 2.6".

The purpose of the sensor is to detect decreasing reactor water level and upon reaching a level of five (5) feet below minimum normal water level or higher, a Primary Coolant Isolation, Containment Isolation, Emergency Cooling Initiation and Start Core Spray Pumps permissive signal is initiated. Also, if high drywell pressure permissive signal is present, containment spray initiates. The electrical arrangement for the permissive logic is a one out of two in each trip system. It would require two sensors, one in each trip system, actuating higher than prescribed deviations to give a permissive start of those systems above the five (5) foot level.

Had plant conditions required the use of any of these mentioned safeguard systems they would have actuated at the five (5) foot level below minimum normal. However, since the set point of RE02D was three (3) inches high it would have initiated a permissive signal for trip system 12 at 4' 9" below minimum normal water level instead of five (5) foot below minimum normal water level. When water level reached the five (5) foot level, the other trip system would actuate causing the safeguard systems mentioned to function.

8423



11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

Mr. Donald J. Skovholt
U. S. Atomic Energy Commission

November 19, 1973
Page 2

The safety of the plant and general public was not jeopardized as the required systems would have functioned at the design set point.

The immediate corrective action was to recalibrate the sensor to read five (5) foot below minimum normal water level. The other three sensors all actuated at five (5) foot below minimum normal water level.

This is the first known malfunction of this type on this instrument. However, it will be closely watched for any further deviation and if a trend is established further corrective action will be taken.

Very truly yours,



R. R. Schneider
Vice President - Electrical Operations

RRS:pw

REGISTERED MAIL
RETURN RECEIPT REQUEST

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 7978

FILE:

| | | | | | | | | |
|---|----------------|-----------|-------------------------|-----------------------|----------------------|--|-----|-------|
| FROM:
Niagara Mohawk Power Corp.
Syracuse, N.Y. 13202
Mr. R.R. Schneider | | | DATE OF DOC
10-26-73 | DATE REC'D
11-2-73 | LTR
X | MEMO | RPT | OTHER |
| TO:
D.J. Skovholt | | | ORIG
1 signed | CC | OTHER | SENT AEC PDR XXX
SENT LOCAL PDR XXX | | |
| CLASS | UNCLASS
XXX | PROP INFO | INPUT | NO CYS REC'D
40 | DOCKET NO:
50-220 | | | |

DESCRIPTION:

Ltr submitting information concern an abnormal occurrence at the Nine Mile Point Unit #1.....unidentifiable leakage in the drywell.....trans the following.....

ENCLOSURES:

ATTACHMENTS 1, 2, and 3

ACKNOWLEDGED

(40 cys encls rec'd)

DO NOT REMOVE

PLANT NAME: Nine Mile Point

FOR ACTION/INFORMATION

11-2-73 JB

| | | | |
|-----------|--------------|---------------|-----------|
| BUTLER(L) | SCHWENCER(L) | ✓ ZIEMANN(L) | REGAN(E) |
| W/ Copies | W/ Copies | W/7 Copies | W/ Copies |
| CLARK(L) | STOLZ(L) | DICKER(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| GOLLER(L) | VASSALLO(L) | KNIGHTON(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| KNIEL(L) | SCHEMEL(L) | YOUNGBLOOD(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|--------------------|--------------------|----------------|-----------------|----------------|
| ✓ <u>REG FILE</u> | <u>TECH REVIEW</u> | DENTON | <u>LIC ASST</u> | <u>A/T IND</u> |
| ✓ AEC PDR | ✓ HENDRIE | GRIMES | | BRAITMAN |
| ✓ OGC, ROOM P-506A | SCHROEDER | GAMMILL | ✓ DIGGS (L) | SALTZMAN |
| ✓ MUNTZING/STAFF | ✓ MACCARY | KASTNER | GEARIN (L) | B. HURT |
| ✓ CASE | ✓ KNIGHT | BALLARD | GOULBOURNE (L) | <u>PLANS</u> |
| GIAMBUSO | ✓ PAWLICKI | SPANGLER | LEE (L) | MCDONALD |
| BOYD | ✓ SHAO | | MAIGRET (L) | DUBE |
| MOORE (L)(BWR) | ✓ STELLO | <u>ENVIRO</u> | SERVICE (L) | <u>INFO</u> |
| DEYOUNG(L)(FWR) | ✓ HOUSTON | MULLER | SHEPPARD (E) | C. MILES |
| ✓ SKOVHOLT (L) | ✓ NOVAK | DICKER | SMITH (L) | ✓ B. King |
| P. COLLINS | ✓ ROSS | KNIGHTON | TEETS (L) | |
| | ✓ IPPOLITO | YOUNGBLOOD | WADE (E) | |
| ✓ <u>REG OPR</u> | ✓ TEDESCO | REGAN | WILLIAMS (E) | |
| FILE & REGION(3) | ✓ LONG | PROJECT LDR | WILSON (L) | |
| ✓ MORRIS | ✓ LAINAS | | | |
| ✓ STEELE | ✓ BENAROYA | <u>HARLESS</u> | | |
| | ✓ VOLLMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|------------------------------|------------------------------|------------------------|
| ✓ 1 - LOCAL PDR Oswego, N.Y. | (1)(2)(10)-NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| ✓ 1 - DTIE(ABERNATHY) | 1-ASLBP(E/W Bldg, Rm 529) | 1-GERALD LELLOUCHE |
| ✓ 1 - NSIC(BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB(YORE/SAYRE/ | 1-CONSULTANT'S | 1-AGMED(Ruth Gussman) |
| WOODARD/"H" ST. | NEWMARK/BLUME/AGBABIAN | RM-B-127, GT. |
| ✓ 16 - CYS ACRS HOLDING | 1-GERALD ULRICKSON...ORNL | 1-RD..MULLER..F-309 GT |
| Sent to Diggs | | |
| 11-2-73 | | |

35

A 2

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....


.....

.....

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK300 ERIE BOULEVARD WEST
SYRACUSE, N.Y. 13202

October 26, 1973



Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545



Re: Provisional Operating License: DPR-17
Docket No.: 50-220

Dear Mr. Skovholt:

On October 18, 1973, the Nine Mile Point Unit #1 reactor was shut down, the result of an increasing rate of unidentifiable leakage in the drywell.

The shutdown, which occurred during the routine RO:I AEC Inspection, provided the opportunity to perform the following:

1. Shutdown Margin Demonstrations - in accordance with your letter¹ dated September 25, 1973.
2. Inspections of hydraulic shock suppressors in response to your request on October 1, 1973² and RO:I telephoned request³ on July 26, 1973.
3. The leak test of the manhole cover on the drywell which was committed in our letter of October 10, 1973⁴ in response to your letter of September 28, 1973⁵.

On August 17, 1973 leakage into the Drywell Floor Drain Tank (DWFDT) had increased to 2.5 gpm. Reactor Recirculation Pump 12 (RRP 12) was the immediate suspect as equalization was occurring between the low and high pressure seal. Once RRP 12 was secured the DWFDT leakage decreased to less than .25 gpm.

On October 1, 1973, with RRP 12 still secure leakage again was gradually increasing to the DWFDT. With leakage approaching 2.8 gpm on October 6, 1973 Station Supervision ordered increased surveillance on the DWFDT leakage. Although Technical Specifications call for a check of leakage only once per day, it was deemed necessary to continually plot leakage each hour to note trends or other indications which could provide an insight into the source of leakage. The Radiation Protection and Chemistry section had already determined that the major percentage of leaking liquid was not reactor coolant. On October 18, 1973 with DWFDT leakage indicating approximately 4.5 gpm, Plant Supervision ordered the reactor shutdown. During the subsequent drywell inspection the source of leakage was identified as steam leaks thru the valve packing on two electromatic relief systems blocking valves and a small leak on RRP 12 seal.

Mr. Donald J. Skovholt
U.S. Atomic Energy Commission


October 26, 1973

During the shutdown and at Xenon free condition, the shutdown margin demonstrations were performed. All control rods were verified to meet the minimum shutdown margin of 0.0075 delta k/k at cold, xenon free, operating samarium conditions. A complete report including responses to your question is being readied and will be sent to you prior to December 4, 1973 as outlined in your letter¹.

An inspection of the hydraulic shock suppressors was made during the shutdown. Enclosure 1 to this letter details the manufacturer, number of snubbers, identification of low fluid reservoirs, and corrective actions taken. In summary, no defective seals were found and no shock suppressors were found to be void of fluid. A certain amount of leakage was found from a few suppressors, the result of loose reservoir connections.

Also during the shutdown, the manhole cover on the drywell was leak tested. The penetration was pressurized to 35 psig and the decay in pressure noted over one half hour. No loss of pressure was observed.

Very truly yours,


Rudolph R. Schneider
Vice President - Electric Operations

RRS:cm

1. Ltr. Skovholt - Raymond Sept. 25, 1973
2. Ltr. Skovholt - Raymond Oct. 1, 1973
3. Tph. Cantrell - Perkins July 26, 1973
4. Ltr. Schneider- O'Reilly Oct. 10, 1973
5. Ltr. Skovholt - Schneider Sept. 28, 1973

THE
FEDERAL
BUREAU OF
INVESTIGATION
OF THE
DEPARTMENT OF JUSTICE
WASHINGTON, D. C.
20535

100-100000-100000


ENCLOSURE 1

HYDRAULIC SHOCK SUPPRESSOR

1. Manufacturer: All Grinnell Manufacturer
2. Number of Snubbers: 110 Fluid SF-96-1000
3. Where fluid was added the connection that was leaking was tightened.

| 4. | <u>Serial #</u> | <u>System</u> | <u>Condition</u> | <u>Corrective Action</u> |
|----|-----------------|-------------------|------------------|--------------------------|
| | 1367- D2 | * Elec.Vent Lines | Good | |
| | 1438- D2 | Elec.Vent Lines | Good | |
| | 1188- D2 | Elec.Vent Lines | Good | |
| | 1195- D2 | Elec.Vent Lines | Good | |
| | 1463- D2 | Elec.Vent Lines | Good | |
| | 1372- D2 | Elec.Vent Lines | Good | |
| | 1340- D2 | Elec.Vent Lines | Good | |
| | 1207- D2 | Elec.Vent Lines | Good | |
| | 1459- D2 | Elec.Vent Lines | Good | |
| | 1200- D2 | Elec.Vent Lines | Good | |
| | 1454- D2 | Elec.Vent Lines | Good | |
| | 1491- D3 | Elec.Vent Lines | Good | |
| | 1344 | Elec.Vent Lines | Good | |
| | 1450- D2 | Elec.Vent Lines | Good | |
| | 1488- D3 | Elec.Vent Lines | Good | |
| | 1495- D3 | Elec.Vent Lines | Low oil in Res. | Added Fluid |
| | 1026- D3 | Elec.Vent Lines | Good | |
| | 1028- D3 | Elec.Vent Lines | Good | |
| | 1494- D3 | Elec.Vent Lines | Low oil in Res. | Added Fluid |
| | 1217- D2 | Elec.Vent Lines | Good | |
| | 1350- D2 | Elec.Vent Lines | Good | |
| | 1379- D2 | Elec.Vent Lines | Good | |
| | 1215- D2 | Elec.Vent Lines | Good | |
| | 1349- D2 | Elec.Vent Lines | Good | |
| | 1359- D2 | Elec.Vent Lines | Good | |
| | 381 | Rx. Recir. System | Low oil in Res. | Added oil |
| | 373 | Rx. Recir. System | Good | |
| | 388 | Rx. Recir. System | Good | |
| | 384 | Rx. Recir. System | Low oil in Res. | Added oil |
| | 390 | Rx. Recir. System | Low Oil | Added oil |
| | 415 | Rx. Recir. System | Low oil | Added oil |
| | 413 | Rx. Recir. System | Low oil | Added oil |
| | 379 | Rx. Recir. System | Low oil | Added oil |
| | 392 | Rx. Recir. System | Low oil | Added oil |
| | 378 | Rx. Recir. System | Low oil | Added oil |
| | 1088 | Rx. Recir. System | Good | |
| | 1015 | Rx. Recir. System | Good | |
| | 1016 | Rx. Recir. System | Good | |
| | 1004 | Rx. Recir. System | Good | |
| | 1010 | Rx. Recir. System | Good | |
| | 1005 | Rx. Recir. System | Good | |

* Electromatic relief discharge piping to the Torus.



ENCLOSURE 1

| <u>Serial #</u> | <u>System</u> | <u>Condition</u> | <u>Corrective Action</u> |
|-----------------|--------------------|------------------|--------------------------|
| 124 | Rx. Recirc. System | Good | |
| 140 | Rx. Recirc. System | Good | |
| 118 | Rx. Recirc. System | Good | |
| 137 | Rx. Recirc. System | Good | |
| 86 | Rx. Recirc. System | Good | |
| 86 | Rx. Recirc. System | Good | |
| 101 | Rx. Recirc. System | Good | |
| 136 | Rx. Recirc. System | Good | |
| 120 | Rx. Recirc. System | Good | |
| 141 | Rx. Recirc. System | Good | |
| 383 | Rx. Recirc. System | Good | |
| 389 | Rx. Recirc. System | Good | |
| 375 | Rx. Recirc. System | Good | |
| 418 | Rx. Recirc. System | Good | |
| 391 | Rx. Recirc. System | Good | |
| 1017 | Rx. Recirc. System | Good | |
| 1006 | Rx. Recirc. System | Good | |
| 1007 | Rx. Recirc. System | Good | |
| 1014 | Rx. Recirc. System | Good | |
| 1012 | Rx. Recirc. System | Good | |
| 1011 | Rx. Recirc. System | Good | |
| | Rx. Recirc. System | Good | |
| 1008 | Rx. Recirc. System | Good | |
| 1025 | Rx. Recirc. System | Good | |
| 1022 | Rx. Recirc. System | Good | |
| 40-SC-47 | Core Spray System | Good | |
| 40-SC-10 | Core Spray System | Good | |
| 1760 | Core Spray System | Good | |
| 40-SC-8 | Core Spray System | Good | |
| 40-SC-7 | Core Spray System | Good | |
| 2582 | Core Spray System | Good | |
| 40-SC-28 | Core Spray System | Good | |
| 40-SC-27 | Core Spray System | Good | |
| 40-SC-26 | Core Spray System | Good | |
| 40-SC-25 | Core Spray System | Good | |
| 1368 | Main Steam | Good | |
| 1369 | Main Steam | Good | |
| | Main Steam | Good | |
| | Main Steam | Good | |
| 1367 | Main Steam | Good | |
| 1370 | Main Steam | Good | |
| | Main Steam | Good | |
| | Main Steam | Good | |
| 31-SC-6 | Feedwater System | Good | |
| 31-SC-3 | Feedwater System | Low oil | Added oil |
| 1760 | Feedwater System | Good | |
| 31-SC-5 | Feedwater System | Low oil | Added oil |
| 31-SC-4 | Feedwater System | Low oil | Added oil |
| 1761 | Feedwater System | Good | |
| 2189 | Clean-Up System | Good | |
| 2370 | Clean-Up System | Good | |
| 2293 | Clean-Up System | Good | |
| 1703 | Clean-Up System | Good | |
| 1789 | Clean-Up System | Good | |



11

11

ENCLOSURE 1

| <u>Serial #</u> | <u>System</u> | <u>Condition</u> | <u>Corrective Action</u> |
|-----------------|---------------------------|------------------|--------------------------|
| 2167 | Clean-Up Discharge | Low oil | Added oil |
| 29-SC-3 | Clean-Up Discharge | Good | |
| 2189 | Shutdown Cooling Suct. | Good | |
| 2164 | Shutdown Cooling Suct. | Good | |
| 2190 | Shutdown Cooling Disc. | Good | |
| 2176 | Emerg.Cond.Return | Low oil | Added oil |
| 2182 | Emerg.Cond.Return | Good | |
| 1219- D2 | Emerg.Cond.Return | Good | |
| 21-27 | Emerg.Cond.Return | Good | |
| 2129 | Emerg.Cond.Return | Good | |
| 2126 | Emerg.Cond.Return | Good | |
| 39-SC-15 | Emerg.Cond.Return | Good | |
| 2128 | Emerg.Cond.Return | Good | |
| 2227 | High Press Flange Leakoff | Good | |

5. Most of the leaks were found at the reservoir end caps. These were tightened and where necessary teflon tape was used in connections.

In general, there were no inoperable hydraulic shock suppressors.



11-11-11

11-11-11

11-11-11

11-11-11

11-11-11

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 6843

FILE: *Abn Dec*

| | | | | | | | | |
|---|----------------|-----------|-----------------------|-----------------------|----------|--|-----|-------|
| FROM:
Niagara Mohawk Power Corporation
Syracuse, N.Y. 13202
Mr. James Bartlett | | | DATE OF DOC
9-7-73 | DATE REC'D
9-10-73 | LTR
x | MEMO | RPT | OTHER |
| TO:
D.J. Skovholt | | | ORIG
1 | CC | OTHER | SENT AEC PDR <u>xxx</u>
SENT LOCAL PDR <u>xxx</u> | | |
| CLASS | UNCLASS
xxx | PROP INFO | INPUT | NO CYS REC'D
40 | | DOCKET NO:
50-220 | | |

DESCRIPTION:
Ltr reporting an abnormal occurrence at the Nine Mile Point Unit #1.....concerning the loss of stack gas monitors for a period of approx. 2 hours

ENCLOSURES:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: Nine Mile Point Unit #1

FOR ACTION/INFORMATION 9-11-73

JB

| | | | |
|------------------------|---------------------------|-----------------------------|-----------------------|
| BUTLER(L)
W/ Copies | SCHWENCER(L)
W/ Copies | ✓ ZIEMANN(L)
W/ 7 Copies | REGAN(E)
W/ Copies |
| CLARK(L)
W/ Copies | STOLZ(L)
W/ Copies | DICKER(E)
W/ Copies | W/ Copies |
| GOLLER(L)
W/ Copies | VASSALLO(L)
W/ Copies | KNIGHTON(E)
W/ Copies | W/ Copies |
| KNIEL(L)
W/ Copies | SCHEMEL(L)
W/ Copies | YOUNGBLOOD(E)
W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|--------------------|----------------------|---------------|----------------|----------------------|
| ✓ <u>REG FILE</u> | ✓ <u>TECH REVIEW</u> | DENTON | LIC ASST | A/T IND |
| ✓ AEC PDR | ✓ HENDRIE | GRIMES | ✓ DIGGS (L) | BRITMAN |
| ✓ OGC, ROOM P-506A | ✓ SCHROEDER | GAMMILL | GEARIN (L) | SALTZMAN |
| ✓ MUNTZING/STAFF | ✓ MACCARY | KASTNER | GOULBOURNE (L) | <u>PLANS</u> |
| ✓ CASE | ✓ KNIGHT | BALLARD | LEE (L) | MCDONALD |
| GIAMBUSSO | ✓ PAWLICKI | SPANGLER | MAIGRET (L) | DUBE |
| BOYD | ✓ SHAO | <u>ENVIRO</u> | SERVICE (L) | <u>INFO</u> |
| MOORE (L) (BWR) | ✓ STELLO | MULLER | SHEPPARD (E) | C. MILES |
| ✓ DEYOUNG(L) (PWR) | ✓ HOUSTON | DICKER | SMITH (L) | ✓ B. King (RO) (OOE) |
| ✓ SKOVHOLT (L) | ✓ NOVAK | KNIGHTON | TEETS (L) | |
| P. COLLINS | ✓ ROSS | YOUNGBLOOD | WADE (E) | |
| ✓ <u>REG. OPR</u> | ✓ IPPOLITO | REGAN | WILLIAMS (E) | |
| FILE & REGION(3) | ✓ TEDESCO | PROJECT LDR | WILSON (L) | |
| ✓ MORRIS | ✓ LONG | | | |
| ✓ STEELE | ✓ LAINAS | HARLESS | | |
| | ✓ BENAROYA | | | |
| | ✓ VOLIMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|--|--|---------------------------------------|
| ✓ 1 - LOCAL PDR Oswego, N.Y. | (1)(2)(10)-NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| ✓ 1 - DTIE(ABERNATHY) | 1-R.Schoonmaker, OC, GT, D-323. | 1-GERALD LELLOUCHE |
| ✓ 1 - NSIC(BUCHANAN) | 1-R. CATLIN, E-256-GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB(YORE/SAYRE/
WOODARD/"H" ST. | 1-CONSULTANT'S
NEWMARK/BLUME/AGBABIAN | 1-AGMED(WALTER KOESTER
RM-C-427-GT |
| ✓ 16 - CYS ACRS NSIC Sent to Diggs
9-11-73 | 1-GERALD ULRIKSON...ORNL | 1-RD..MULLER..F-309.GT |

... ..
... ..
... ..
... ..

... ..
... ..
... ..
... ..

... ..

... ..

... ..

Regulatory


File Cy.

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD WEST
SYRACUSE, N.Y. 13202

September 7, 1973



Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545

Re: Provisional Operating License: DPR-17
Docket No.: 50-220

Dear Mr. Skovholt:

Pursuant to your request, we are reporting as an abnormal occurrence the loss of the stack gas monitors for a period of approximately 2 hours on June 26, 1973.

The plant was starting up following the Spring refueling outage with the reactor at approximately 1460 MWt. Reactor output was being increased slowly in an attempt to precondition the fuel assemblies and maintain the future stack gas release rate at as low a value as possible. Stack gas activity at this time was approximately 8500 $\mu\text{Ci/sec}$ well within all limits. There are two levels of continuous monitoring of the radioactivity level of the effluent gases removed from the main condenser by the steam jet air-ejector system. The Off-gas monitors which were continually monitoring the radioactivity level of the gaseous effluent which is eventually released to the stack, are located prior to the holdup pipe and the stack. Using information from the off-gas monitors the stack release rate can be determined. The stack gas monitors continuously monitor the activity of the gas released thru the stack. These monitors see the radioactivity level of the same gas as the off gas monitors after a holdup of 30 minutes and dilution of the gas with ventilation air from the plant.

At 1745 hours #12 stack sample pump tripped and could not be restarted. (Subsequent investigation revealed a bound motor). #11 stack sample pump was out of service and not piped-up at this time, awaiting an oil reservoir jar. The reservoir jar was leaking and although the pump would operate it would require constant monitor of the oil level. #11 stack sample pump was piped up and placed in service at 2000 hours.

6843

Mr. Donald J. Skovholt
U.S. Atomic Energy Commission

September 7, 1973

During the period of time the stack gas monitors were out of service the off gas monitors showed only a variation of 4 Mr/hr. It is important to note that the stack gas monitors provide only an alarm function. The off gas monitors which were functioning normally, provide for automatic closure of the isolation valve in the off gas line at the maximum release rate and their operation is the limiting condition for operation. The information from the stack gas monitoring system is used in preparation of plant radioactive effluent reports and demonstrating compliance with maximum release rates.

Before the stack release rate would have reached a point where the health and safety of the general public would have been endangered, the off gas monitors would have isolated the off gas line to the stack.

To prevent similar future occurrences of this event a third sampling pump will be used as a spare and employed whenever one of the two normal sample pumps are out of service.

Very truly yours,



James Bartlett
Executive Vice President
Operations and Engineering

JB:cm

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 6844

FILE: Mon Du

| | | | | | | | | |
|---|----------------|------------|-----------------------|-----------------------|----------|--|-----|-------|
| FROM:
Niagara Mohawk Power Corp.
Syracuse, N.Y. 13202
Mr. James Bartlett | | | DATE OF DOC
9-7-73 | DATE REC'D
9-10-73 | LTR
X | MEMO | RPT | OTHER |
| TO:
D.J. Skovholt | | | ORIG
1 | CC | OTHER | SENT AEC PDR XXX
SENT LOCAL PDR XXX | | |
| CLASS | UNCLASS
XXX | PROP INFO. | INPUT | NO CYS REC'D
40 | | DOCKET NO:
50-220 | | |

DESCRIPTION:

Ltr adv that on 8-29-73 an abnormal occurrence was noted.....concerning four fuel bundle segments which were found to be operating in excess Tech. Spec Requirements.

ENCLOSURES:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: Nine Mile Point #1

FOR ACTION/INFORMATION 9-11-73 JB

| | | | |
|------------------------|---------------------------|----------------------------|-----------------------|
| BUTLER(L)
W/ Copies | SCHWENCER(L)
W/ Copies | ✓ ZIEMANN(L)
W/7 Copies | REGAN(E)
W/ Copies |
| CLARK(L)
W/ Copies | STOLZ(L)
W/ Copies | DICKER(E)
W/ Copies | W/ Copies |
| GOLLER(L)
W/ Copies | VASSALLO(L)
W/ Copies | KNIGHTON(E)
W/ Copies | W/ Copies |
| KNIEL(L)
W/ Copies | SCHEMEL(L)
W/ Copies | YOUNGBLOOD(E)
W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|--|---|---|---|--|
| <u>REG FILE</u>
✓ AEC PDR
✓ OGC, ROOM P-506A
✓ MUNTZING/STAFF
✓ CASE
GIAMBUSSO
BOYD
MOORE (L)(BWR)
DEYOUNG(L)(PWR)
✓ SKOVHOLT (L)
P. COLLINS | <u>TECH REVIEW</u>
✓ HENDRIE
✓ SCHROEDER
✓ MACCARY
✓ KNIGHT
✓ PAWLICKI
✓ SHAO
✓ STELLO
✓ HOUSTON
✓ NOVAK
✓ ROSS
✓ IPPOLITO
✓ TEDESCO
✓ LONG
✓ LAINAS
✓ BENAROYA
✓ VOLLMER | DENTON
GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

<u>ENVIRO</u>
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR

HARLESS | <u>LIC ASST</u>
✓ DIGGS (L)
GEARIN (L)
GOULBOURNE (L)
LEE (L)
MAIGRET (L)
SERVICE (L)
SHEPPARD (E)
SMITH (L)
TEETS (L)
WADE (E)
WILLIAMS (E)
WILSON (L) | <u>A/T IND</u>
BRAITMAN
SALTZMAN

<u>PLANS</u>
MCDONALD
DUBE

<u>INFO</u>
C. MILES
✓ B. King (RO)(OOE) |
|--|---|---|---|--|

EXTERNAL DISTRIBUTION

| | | |
|---|--|---|
| ✓ 1 - LOCAL PDR <u>Oswego, N.Y.</u>
✓ 1 - DTIE(ABERNATHY)
✓ 1 - NSIC(BUCHANAN)
1 - ASLB(YORE/SAYRE/
WOODARD/"H" ST.
✓ 16 - CYS ACRS XXXXXXXX Sent to Diggs
9-11-73 | (1)(2)(10)-NATIONAL LAB'S
1-R.Schoonmaker, OC, GT, D-323.
1-R. CATLIN, E-256-GT
1-CONSULTANT'S
NEWMARK/BLUME/AGBABIAN
1-GERALD ULRICKSON...ORNL | 1-PDR-SAN/LA/NY
1-GERALD LELLOUCHE
BROOKHAVEN NAT. LAB
1-AGMED(WALTER KOESTER
RM-C-427-GT
1-RD..MULLER..F-309 GT |
|---|--|---|



...

...

... ..

...

...

...

... ..

...

...

...

...

...

...

Regulatory


File Cy.

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD WEST
SYRACUSE, N.Y. 13202

September 7, 1973



Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545



Re: Provisional Operating License: DPR-17
Docket No.: 50-220

Dear Mr. Skovholt:

At approximately 1600 hours on August 29, 1973 following a routine calibration of the Local Power Range Monitors (LPRM) and subsequent core power distribution calculations, four fuel bundle segments were found to be operating slightly in excess of the allowable average planar LHGR as shown in Technical Specifications Figure 3.1.7 (change 9). This event was reported to Region I Compliance on August 30, 1973 at 1130 hours.

Technical Specification 3.1.7 a states:

a. Average Planar LHGR

During steady state power operation, the average linear heat generation rate (LHGR) of all the rods in any fuel assembly, as a function of average planar exposure, at any axial location shall not exceed the maximum average planar LHGR shown in Figure 3.1.7.

The LPRM's are routinely calibrated following extensive rod manipulations or upon the completion of each full power month. This consists of physically adjusting the gain of each LPRM amplifier by a factor determined thru a computer calculation. Following the physical adjustment of all LPRM amplifiers the Traversing Incore Probe (TIP) system is used to traverse each LPRM string and supply the current axial flux distribution to the computer system. Using this axial flux distribution base and the current LPRM readings along with the other thermal hydraulic parameters, a highly accurate power distribution can then be obtained from the computer.

Prior to the 27th of August, steps were taken to achieve compliance with the fuel densification specification¹ limiting both local LHGR and average planar LHGR within the reactor core and at the same time minimize possible electrical output loss from the station.

6844

¹ Ltr.; Giambusso A.E.C.-P.D. Raymond NMPC - Aug. 24, 1973



101
102
103

Mr. Donald J. Skovholt
U.S. Atomic Energy Commission

September 7, 1973

Adjustments in the power distribution were made to obtain an optimum power distribution and power output from the reactor. In conjunction with this, control rods were shifted to move the axial peaks higher in the core into more voided regions and thus flatten the axial power distribution. In order to closely monitor the power distribution, calculations were performed following each step and reactor power was reduced to provide an additional degree of conservatism.

Upon completion of preliminary rod movements on August 26-27, 1973 the new axial flux distributions were supplied to the process computer system via the TIP system. The subsequent calculation of power distribution on August 27, 1973 showed that all bundles were within prescribed limits and the reactor power could be increased. In an attempt to optimize plant power output more control rods were inserted thus increasing the margin between the existing average KW/FT and the limit. Reactor power was then increased using recirculation flow. Due to the fact that more control rods had been manipulated following the last axial flux distribution base supplied to the computer system it was necessary to update these distributions using the TIP system. However due to mechanical problems within the TIP system this was not possible until August 29, 1973. Following the LPRM calibration and inputting of the new axial flux distributions into the computer system a core power distribution was performed. A slight shift in calculated power distribution was noted and four fuel bundle segments were found to be slightly higher in maximum average planar LHGR than the limit prescribed in Figure 3.1.7 of the Technical Specifications. The four fuel bundle segments (reload 1) have a nodal exposure of 1930 MWD/ST and corresponding limit of 10.6 KW/FT (Figure 3.1.7). The four segments were operating .15 KW/FT over this limit. Immediate steps were taken to reduce the maximum average planar LHGR by reducing core thermal power using reactor recirculation flow. Subsequent core power distribution calculations showed all fuel types to be operating within limits shown on Figure 3.1.7.


To prevent reoccurrence of this abnormal occurrence, the LPRM's will be calibrated once every two full power weeks of operation or twice as often as was previously done. In addition, extension movement of control rods will be done at a substantially lower power level and once assurance to specification 3.1.7 is obtained, power will be slowly increased so as to assure validity of power distribution calculations. This violation is the first of its kind and evaluation of the safety implications of the incident in light of the cumulative experience obtained previously is not applicable. However, due to the degree of conservatism built into the calculations it is felt that no undue hazard would have been presented to the general public even had a LOCA occurred during this period.

Very truly yours,



James Bartlett
Executive Vice President
Operations and Engineering

JB:cm



AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 6075

FILE:

| | | | | | | | | |
|---|----------------|-----------|-----------------------|----------------------|----------------------|--|-----|-------|
| FROM: Niagara Mohawk Power Corporation
Lycoming, N.Y. 13093
Mr. P.A. Burt | | | DATE OF DOC
8-1-73 | DATE REC'D
8-8-73 | LTR
X | MEMO | RPT | OTHER |
| TO: D.J. Skovholt | | | ORIG
1 | CC | OTHER | SENT AEC PDR <u>xxx</u>
SENT LOCAL PDR <u>xxx</u> | | |
| CLASS | UNCLASS
XXX | PROP INFO | INPUT | NO CYS REC'D
40 | DOCKET NO:
50-220 | | | |

DESCRIPTION:
Ltr. reporting Abnormal Occurance concern.
a reactor scram during routine surveillance
testing of Main Steam Isolation Valves.

ENCLOSURES:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: Nine Mile Point

FOR ACTION/INFORMATION

8-8-73

jdb

| | | | |
|------------------------|---------------------------|----------------------------|-----------------------|
| BUTLER(L)
W/ Copies | SCHWENCER(L)
W/ Copies | ZIEMANN(L)
W/ 7 Copies | REGAN(E)
W/ Copies |
| CLARK(L)
W/ Copies | STOLZ(L)
W/ Copies | DICKER(E)
W/ Copies | W/ Copies |
| GOLLER(L)
W/ Copies | VASSALLO(L)
W/ Copies | KNIGHTON(E)
W/ Copies | W/ Copies |
| KNIEL(L)
W/ Copies | SCHEMEL(L)
W/ Copies | YOUNGBLOOD(E)
W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|---|---|--|--|--|
| <u>REG FILE</u>
AEC PDR
OGC, ROOM P-506A
MUNTZING/STAFF
CASE
GIAMBUSSO
BOYD
MOORE (L) (BWR)
DEYOUNG (L) (FWR)
SKOVHOLT (L)
P. COLLINS | <u>TECH REVIEW</u>
HENDRIE
SCHROEDER
MACCARY
KNIGHT
PAWLICKI
SHAO
STELLO
HOUSTON
NOVAK
ROSS
IPPOLITO
TEDESCO
LONG
LAINAS
BENAROYA
VOLLNER | DENTON
GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

ENVIRO
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR

HARLESS | <u>LIC ASST</u>
BROWN (E)
DIGGS (L)
GEARIN (L)
GOULBOURNE (L)
LEE (L)
MAIGRET (L)
SERVICE (L)
SHEPPARD (E)
SMITH (L)
TEETS (L)
WADE (E)
WILLIAMS (E)
WILSON (L) | <u>A/T IND</u>
BRAITMAN
SALTZMAN

<u>PLANS</u>
MCDONALD
DUBE

<u>INFO</u>
C. MILES
B. King (Reg. Op.)
(OOE) E/W |
| <u>REG OPR</u>
FILE & REGION(3)
MORRIS
STEELE | | | | |

EXTERNAL DISTRIBUTION

| | | |
|--|--|--|
| 1 - LOCAL PDR Oswego, N.Y. | (1) (2) (9) - NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| 1 - DTIE (ABERNATHY) | 1-R. Schoonmaker, OC, GT, D-323 | 1-GERALD LELLOUCHE |
| 1 - NSIC (BUCHANAN) | 1-R. CATLIN, E-256-GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB (YORE/SAYRE/
WOODARD/"H" ST. | 1-CONSULTANT'S
NEWMARK/BLUME/AGBABIAN | 1-AGMED (WALTER KOESTER
RM-C-427-GT |
| 16 - CYS ACRS HOLDING Sent to R. Diggs
8-8-73 | 1-GERALD ULRIKSON...ORNL | 1-RD..MULLER..F-309..GT |

(36

55

d.

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK



Nine Mile Point Nuclear Station
Post Office Box 32
Lycoming, New York 13093

August 1, 1973

Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Skovholt:

Re: Provisional Operating License: DPR-17
Docket No.: 50-220



The following is a report relating to the operation of Nine Mile Point Nuclear Station Unit # 1 in which during routine surveillance testing of main steam isolation valves, a reactor scram occurred.

On July 8, 1973 at 0552 hours, Nine Mile Point Unit #1 experienced a reactor scram while operating at 560 MW_e and 1740 MW_t. The scram occurred during surveillance testing of the main steam line isolation valves. All systems operated as designed following the scram and no safety limits were exceeded.

Subsequent investigation showed that the scram resulted from the isolation of #12 main steam line, which caused an increase in reactor pressure which in turn resulted in a high neutron flux scram. The isolation of No. 12 main steam line was caused by the closing of the outside isolation valve in that line during the surveillance test.

Reactor pressure increased from a value of 1012 psig at the time of the scram to a peak value of 1091 psig, 12 seconds after the scram. This pressure increase occurred when high steam flow in the No. 11 steam line caused main steam line isolation. The high steam flow signal was caused because all of the steam being produced was being forced into one steam line at this time. The steam line isolation occurred approximately 7 seconds after the reactor scram. The electromatic valves and isolation condensers operated during the transient to relieve reactor pressure. Information pertaining to these operations is limited due to the nature of the data logging program in the process computer. The program is initiated by any half scram and runs for 5 seconds. It then is interrupted for approximately 2 minutes to allow data collection for the Post Mortem Recall program. It was during this time that the turbine trip occurred, electromatic valves and isolation condensers operated. Hence, the exact times of operation were not recorded. However, by observing the reactor pressure at one second intervals on the Post Mortem Recall print out, it was determined that the electromatic valves and isolation condensers did operate.

The Post Mortem Recall data indicates that the relief valves operated when the reactor pressure reached 1091 psig at 12 seconds after the scram. During the next 6 seconds, reactor pressure decreased from 1091 psig to 1067 psig while steam flow to the torus increased from 406 k lb/hr. to 1022 k lb/hr. and then decreased to 638 k lb/hr. At

August 1, 1973

this time, reactor pressure again started to increase and again reached 1091 psig at 21 seconds after the scram. Once again the relief valves operated to relieve pressure. Steam flow to the torus increased from 210 k lb/hr. to 1086 k lb/hr. and then decreased to 575 k lb/hr. 27 seconds after the trip. Reactor pressure decreased to 1069 psig. At this point, reactor pressure again started to increase but did not go high enough to actuate relief valve operation. Instead the isolation condensers controlled pressure. The reactor pressure increased to 1086 psig at 32 seconds after the scram and then began to decrease on a steady downward ramp.

During the transient the feedwater control system provided adequate automatic control limiting reactor water level to -3.20 ft. 13 seconds after the scram and recovering to +1.08 ft. 37 seconds after the scram.

Immediately following the transient, members of the Nine Mile Point supervisory staff analyzed the transient and observed many operations of all four main steam line isolation valves in an attempt to determine if the valve controls had malfunctioned. All valves operated properly.

At this time, the staff members agreed that no safety limits had been exceeded and that a reactor startup could commence.

On July 9, 1973 the onsite review committee held a special meeting for the purpose of reviewing this transient. The control room operator was also interviewed by the committee.

The closure of a main steam isolation valves are a requirement for the safety analysis. To insure valve operability, a surveillance test is conducted twice weekly. Although the valve closed during a test, it assumed the proper position to preserve the health and safety of the general public.

The committee reached the following conclusions:

- a. The reactor scram resulted from high neutron flux due to a pressure transient which occurred when #12 main steam line isolated.
- b. Number 12 main steam line isolation was caused by the closure of a main steam isolation valve during surveillance testing.
- c. The committee agreed that no safety limits had been exceeded and that all systems operated as designed. There was no threat to the health and safety of the general public during or following the transient.

Very truly yours,



P. Allister Burt
General Superintendent
Nuclear Generation

PAB:pw

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 5366

FILE:

| | | | | | | | | |
|---|----------------|-----------|-----------------------|-----------------------|----------|------------------------------------|-----|-------|
| FROM:
Niagara Mohawk Power Corporation
Syracuse, New York 13202
Rudolph R. Schneider | | | DATE OF DOC
7-6-73 | DATE REC'D
7-11-73 | LTR
x | MEMO | RPT | OTHER |
| TO:
D. J. Skovholt | | | ORIG
1 signed | CC
39 | OTHER | SENT AEC PDR X
SENT LOCAL PDR X | | |
| CLASS | UNCLASS
XXX | PROP INFO | INPUT | NO CYS REC'D
40 | | DOCKET NO:
50-220 | | |

DESCRIPTION:

Ltr reporting a condition relating to operation of Unit # 1...during routine surveillance testing the core spray differential pressure instrumentation(Barton 288-480 3) was found to read higher value than set forth in instrumentation surveillance check list....

PLANT NAME: Nine Mile Point Unit # 1

ENCLOSURES:

ACKNOWLEDGED

DO NOT REMOVE

FOR ACTION/INFORMATION 7-12-73 fod

| | | | |
|------------------------|---------------------------|----------------------------|-----------------------|
| BUTLER(L)
W/ Copies | SCHWENCER(L)
W/ Copies | ZIEMANN(L)
W/7 Copies | REGAN(E)
W/ Copies |
| CLARK(L)
W/ Copies | STOLZ(L)
W/ Copies | DICKER(E)
W/ Copies | |
| GOLLER(L)
W/ Copies | VASSALLO(L)
W/ Copies | KNIGHTON(E)
W/ Copies | W/ Copies |
| KNIEL(L)
W/ Copies | SCHEMEL(L)
W/ Copies | YOUNGBLOOD(E)
W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|--|---|--|--|--|
| <u>REG FILE</u>
AEC PDR
OGC, ROOM P-506A
MUNTZING/STAFF
CASE
GIAMBUSSO
BOYD
MOORE (L)(BWR)
DEYOUNG(L)(PWR)
SKOVHOLT (L)
P. COLLINS | <u>TECH REVIEW</u>
HENDRIE
SCHROEDER
MACCARY
KNIGHT
PAWLICKI
SHAO
STELLO
HOUSTON
NOVAK
ROSS
IPPOLITO
TEDESCO
LONG
LAINAS
BENAROYA
VOLLMER | DENTON
GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

ENVIRO
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR


HARLESS | <u>LIC ASST</u>
BROWN (E)
DIGGS (L)
GEARIN (L)
GOULBOURNE (L)
LEE (L)
MAIGRET (L)
SERVICE (L)
SHEPPARD (E)
SMITH (L)
TEETS (L)
WADE (E)
WILLIAMS (E)
WILSON (L) | <u>A/T IND</u>
BRAITMAN
SALTZMAN

<u>PLANS</u>
MCDONALD
DUBE

<u>INFO</u>
C. MILES
B. KING(RO,OOE)
E/W Bldg |
| <u>REG OPR</u>
FILE & REGION(3)
MORRIS
STEELE | | | | |

EXTERNAL DISTRIBUTION

| | | |
|---|--------------------------------|-------------------------|
| 1 - LOCAL PDR Oswego, N. Y. | (1) (2) (9) - NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| 1 - DTIE(ABERNATHY) | 1-R.Schoonmaker, OC, GT, D-323 | 1-GERALD LELLOUCHE |
| 1 - NSIC(BUCHANAN) | 1-R. CATLIN, E-256-GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB(YORE/SAYRE/
WOODARD/"H" ST. | 1-CONSULTANT'S | 1-AGMED(WALTER KOESTER |
| 16 - CYS ACRS Sent 7-12-73 to
R. Diggs for Dist. | NEWMARK/BLUME/AGBABIAN | RM-C-427-GT |
| | 1-GERALD ULRIKSON...ORNL | 1-RD..MULLER..F-309..GT |



NIAGARA MOHAWK POWER CORPORATION


NIAGARA  MOHAWK

300 ERIE BOULEVARD WEST
SYRACUSE, N.Y. 13202

July 6, 1973

Regulatory

File Cy.



Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Skovholt:

Re: Provisional Operating License: DPR-17
Docket No.: 50-220

This letter is to report a condition relating to the operation of Nine Mile Point Nuclear Station, Unit #1, in which, during routine surveillance testing the core spray differential pressure instrumentation (Barton 288-4802&3) was found to read higher value than that as set forth in the instrumentation surveillance check list. Technical Specification 4.1.4. (d) states:

"Core spray header ΔP Instrumentation"

| | |
|-----------|---------------|
| Check | once/day |
| Calibrate | once/3 months |
| Test | once/3 months |

On June 30, 1973 at 0100 hours during routine surveillance testing both of the core spray differential pressure instruments were found to be reading 8.3 psid or 3.3 psi above the value as stated in the instrument surveillance check list, (5 psid). This is the first deviation from the procedural accepted value of 5 psid. Notification was made to Mr. Brickly, Region I, Division of Regulatory Operations on June 30, 1973. These switches are designed and intended to provide an alarm only and do not have a protective circuitry function.

As a portion of the daily activities for the plant operators, they are required to read the dial indicator of the core spray differential pressure in the north instrument room (E1. 237'). If these dial indicators had reached 5 psid or above (the alarm limit) it would have been recorded and thus awareness of an abnormal condition in the core spray header would be made known to Station Supervision that same day.

The primary function of the core spray differential pressure indicators is to monitor the condition of the core spray piping between the reactor vessel wall and the shroud inside the reactor vessel. As a consequence if ever the core spray piping between the reactor vessel wall and the shroud should suffer a loss of integrity the differential pressure instrument would read essentially recirculation pump differential pressure. Under normal power operating conditions the recirculation pump differential pressure would be in the range of 20-25 psid.

5366

7201816

Mr. Donald J. Skovholt
U.S. Atomic Energy Commission


July 6, 1973

Therefore even had the integrity of the piping suffered a loss an alarm would have been sounded in the control room.

To prevent reoccurrence of this problem the cycle of calibration will be increased to every two weeks for a month. If no instrument drift problems occur during this increased surveillance the technical specification surveillance schedule will be reinstated.



It is therefore concluded that no undue hazard was present to the general public as a result of this procedural deviation from set point.

Very truly yours,



Rudolph R. Schneider
Vice President - Electric Operations

RRS:cm



AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 5329

FILE:

| | | | | | | | | |
|--|-----------------------|------------------|------------------------------|-----------------------------|-----------------|--|------------|--------------|
| FROM:
Niagara Mohawk Power Corporation
Syracuse, New York 13202
Rudolph R. Schneider | | | DATE OF DOC
7-3-73 | DATE REC'D
7-9-73 | LTR
x | MEMO | RPT | OTHER |
| TO:
D. J. Skovholt | | | ORIG
1 signed | CC
37 | OTHER | SENT AEC PDR X
SENT LOCAL PDR X | | |
| CLASS | UNCLASS
XXX | PROP INFO | INPUT | NO CYS REC'D
38 | | DOCKET NO:
50-220 | | |

DESCRIPTION:
Ltr reporting a condition during routine surveillance testing of the turbine anticipatory trip bypass switches...two out of four were found to exceed the value specifies in the instrument surveillance check list.....

ENCLOSURES:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: Nine Mile Point Unit # 1

FOR ACTION/INFORMATION 7-10-73 fod

| | | | |
|-----------|--------------|---------------|-----------|
| BUTLER(L) | SCHWENCER(L) | ✓ZIEMANN(L) | REGAN(E) |
| W/ Copies | W/ Copies | W/7 Copies | W/ Copies |
| CLARK(L) | STOLZ(L) | DICKER(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| GOLLER(L) | VASSALLO(L) | KNIGHTON(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| KNIEL(L) | SCHEMEL(L) | YOUNGBLOOD(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|-------------------|--------------------|----------------|-----------------|-------------------|
| <u>REG FILE</u> | <u>TECH REVIEW</u> | <u>DENTON</u> | <u>LIC ASST</u> | <u>A/T IND</u> |
| ✓AEC PDR | ✓HENDRIE | GRIMES | BROWN (E) | BRAITMAN |
| ✓OGC, ROOM P-506A | ✓SCHROEDER | GAMMILL | ✓DIGGS (L) | SALTZMAN |
| ✓MUNTZING/STAFF | ✓MACCARY | KASTNER | GEARIN (L) | |
| ✓CASE | ✓KNIGHT | BALLARD | GOULBOURNE (L) | <u>PLANS</u> |
| GIAMBUSSO, | ✓PAWLICKI | SPANGLER | LEE (L) | MCDONALD |
| BOYD | ✓SHAO | | MAIGRET (L) | DUBE |
| MOORE (L)(BWR) | ✓STELLO | <u>ENVIRO</u> | SERVICE (L) | |
| DEYOUNG(L)(PWR) | ✓HOUSTON | MULLER | SHEPPARD (E) | <u>INFO</u> |
| ✓SKOVHOLT (L) | ✓NOVAK | DICKER | SMITH (L) | C. MILES |
| P. COLLINS | ✓ROSS | KNIGHTON | TEETS (L) | ✓B. KING(RO, OOE) |
| | ✓IPPOLITO | YOUNGBLOOD | WADE (E) | E/W Bldg |
| <u>REG OPR</u> | ✓TEDESCO | REGAN | WILLIAMS (E) | |
| ✓FILE & REGION(3) | ✓LONG | PROJECT LDR | WILSON (L) | |
| ✓MORRIS | ✓LAINAS | | | |
| ✓STEELE | ✓BENAROYA | <u>HARLESS</u> | | |
| | ✓VOLLMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|--|--------------------------------|--------------------------|
| ✓1 - LOCAL PDR Oswego, N. Y. | (1) (2) (9)-NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| ✓1 - DTIE(ABERNATHY) | 1-R.Schoonmaker, OC, GT, D-323 | 1-GERALD LELLOUCHE |
| ✓1 - NSIC(BUCHANAN) | 1-R. CATLIN, E-256-GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB(YORE/SAYRE/
WOODARD/"H" ST. | 1-CONSULTANT'S | 1-AGMED(WALTER KOESTER |
| ✓16 - CYS ACRS DOCKET Sent 7-10-73 to | NEWMARK/BLUME/AGBABIAN | RM-C-427-GT |
| R. Diggs for Dist. | 1-GERALD ULRIKSON...ORNL | 1-RD...MULLER...F-309-GT |


... ..

... ..

... ..

... ..


NIAGARA MOHAWK POWER CORPORATION



NIAGARA  MOHAWK

300 ERIE BOULEVARD WEST
SYRACUSE, N.Y. 13202

July 3, 1973



Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545

Regulatory File Cy.

Dear Mr. Skovholt:

Re: Provisional Operating License: DPR-17
Docket No.: 50-220

This is to report a condition relating to the operation of Nine Mile Point Nuclear Station, Unit #1, in which, during routine surveillance testing of the turbine anticipatory trip bypass switches, (Barksdale B2T-A12SS) two out of the four were found to exceed the value specified in the instrument surveillance check list. Technical Specifications 2.1.2.(i) states:

"The generator load rejection scram shall be initiated by the signal for turbine control valve fast closure due to a loss of oil pressure to the acceleration relay any time the turbine first stage steam pressure is above a value corresponding to 833 Mwt, i.e. 45 percent of 1850 Mwt."

Technical Specification 2.1.2.(j) states:

"The turbine stop valve closure scram setting shall be initiated at \leq 10 percent of valve closure (stem position) from full open whenever the turbine first stage steam pressure is above a value corresponding to 833 Mwt, i.e. 45 percent of 1850 Mwt."

On June 29, 1973, at approximately 2130 hours during routine surveillance testing, two out of the four (one in RPS channel 11 and one in RPS channel 12) Turbine anticipatory trip bypass switches were found to actuate at a value of 365 psig and 366 psig (approximately 824-826 Mwt) or approximately 5 and 6 psi above the instrument surveillance checklist value of 360 psig. The remaining two switches were found within specifications. Notification of this deviation from the accepted value for calibration was made on June 30, 1973, to Mr. Brickly of Region I, Division of Regulatory Operation.

5329
5329



Mr. Donald J. Skovholt
U.S. Atomic Energy Commission

- 2 -

July 3, 1973

The switches were instrument calibrated on May 25, 1973 and found correct at that time. The two switches actuating at 365 and 366 psig were recalibrated to read 357 and 358 psig.

To prevent possible recurrence of this incident and to insure that a turbine trip will provide a near instantaneous reactor scram above 45% power the Barksdale 02-13 A & B were calibrated lower than 360 psig (357 and 358 psig) and thus lower than 45% power. These will be rechecked in two weeks to insure that the instrumentation is not drifting.

In view of the fact that: (1) Redundancy was provided in the circuitry which would have caused a reactor scram at the 360 psig first stage steam pressure setting following a turbine trip, (2) The instrument surveillance checklist value for first stage steam pressure relates to a value less than that called for in Technical Specifications (806-810 Mwt), and (3) That even with the higher pressure the limit of 833 Mwt trip actuation was not exceeded; it is concluded that there are no implications or effects on the safety or health of the general public.

Very truly yours,



Rudolph R. Schneider
Vice President - Electric Operations

RRS:cm

10-11-12

1. The first part of the report deals with the general situation of the country. It is a very interesting and informative study of the country's development. The author has done a great deal of research and has gathered a wealth of material. The report is well written and is a valuable contribution to the study of the country's development.

2. The second part of the report deals with the economic situation of the country. It is a very interesting and informative study of the country's economic development. The author has done a great deal of research and has gathered a wealth of material. The report is well written and is a valuable contribution to the study of the country's economic development.

3. The third part of the report deals with the social situation of the country. It is a very interesting and informative study of the country's social development. The author has done a great deal of research and has gathered a wealth of material. The report is well written and is a valuable contribution to the study of the country's social development.

4. The fourth part of the report deals with the political situation of the country. It is a very interesting and informative study of the country's political development. The author has done a great deal of research and has gathered a wealth of material. The report is well written and is a valuable contribution to the study of the country's political development.

5. The fifth part of the report deals with the cultural situation of the country. It is a very interesting and informative study of the country's cultural development. The author has done a great deal of research and has gathered a wealth of material. The report is well written and is a valuable contribution to the study of the country's cultural development.

**AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 5015

FILE: _____

| | | | | | | | | |
|---|----------------|-----------|------------------------|-----------------------|----------|------------------------------------|-----|-------|
| FROM:
Niagara Mohawk Power Corporation
Lycoming, New York 13093
P. Allister Burt | | | DATE OF DOC
6-21-73 | DATE REC'D
6-26-73 | LTR
x | MEMO | RPT | OTHER |
| TO:
D. J. Skovholt | | | ORIG
1 signed | CC
39 | OTHER | SENT AEC PDR X
SENT LOCAL PDR X | | |
| CLASS | UNCLASS
XXX | PROP INFO | INPUT | NO CYS REC'D
40 | | DOCKET NO:
50-220 | | |

DESCRIPTION:

Ltr reporting a failure of one of the six electromatic relief valves to close properly following manual actuation from the control room..... W/attached Fig 5..&.6...

ENCLOSURES:

ACKNOWLEDGED DO NOT REMOVE

PLANT NAME: Nube Mile Point Unit # 1

FOR ACTION/INFORMATION 6-27-73 fod

| | | | |
|-----------|--------------|---------------|-----------|
| BUTLER(L) | SCHWENCER(L) | ✓ZIEMANN(L) | REGAN(E) |
| W/ Copies | W/ Copies | W/ 7 Copies | W/ Copies |
| CLARK(L) | STOLZ(L) | DICKER(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| GOLLER(L) | VASSALLO(L) | KNIGHTON(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| KNIEL(L) | SCHEMEL(L) | YOUNGBLOOD(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|-------------------|-------------|-------------|----------------|------------------------|
| ✓REG FILE | TECH REVIEW | DENTON | LIC ASST | A/T IND |
| ✓AEC PDR | ✓HENDRIE | GRIMES | BROWN (E) | BRAITMAN |
| ✓OGC, ROOM P-506A | SCHROEDER | GAMMILL | ✓DIGGS (L) | SALTZMAN |
| ✓MUNTZING/STAFF | ✓MACCARY | KASTNER | GEARIN (L) | |
| CASE | ✓KNIGHT | BALLARD | GOULBOURNE (L) | PLANS |
| GIAMBUSO | ✓PAWLICKI | SPANGLER | LEE (L) | MCDONALD |
| BOYD | ✓SHAO | | MAIGRET (L) | DUBE |
| MOORE (L) (BWR) | ✓STELLO | ENVIRO | SERVICE (L) | |
| DEYOUNG(L) (PWR) | ✓HOUSTON | MULLER | SHEPPARD (E) | INFO |
| ✓SKOVHOLT (L) | ✓NOVAK | DICKER | SMITH (L) | C. MILES |
| P. COLLINS | ✓ROSS | KNIGHTON | TEETS (L) | ✓B. KING(Reg Opr,00E). |
| | ✓IPPOLITO | YOUNGBLOOD | WADE (E) | E/W Bldg) |
| REG OPR | ✓TEDESCO | REGAN | WILLIAMS (E) | |
| ✓FILE & REGION(3) | ✓LONG | PROJECT LDR | WILSON (L) | |
| ✓MORRIS | ✓LAINAS | | | |
| ✓STEELE | ✓BENAROYA | HARLESS | | |
| | ✓VOLLMER | | | |

EXTERNAL DISTRIBUTION

| | | |
|---|----------------------------|------------------------|
| ✓1 - LOCAL PDR Oswego, N. Y. | (1) (2) (9)-NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| ✓1 - DTIE(ABERNATHY) | 1-R. CARROLL-OC,GT-B227 | 1-GERALD LELLOUCHE |
| ✓1 - NSIC(BUCHANAN) | 1-R. CATLIN, E-256-GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB(YORE/SAYRE/
WOODARD/"H" ST. | 1-CONSULTANT'S | 1-AGMED(WALTER KOESTER |
| ✓16 - CYS ACRS NOTED Sent 6-27-73 to | NEWMARK/BLUME/AGBABIAN | RM-C-427-GT |
| R. Diggs for Dist. | 1-GERALD ULRIKSON...ORNL | 1-RD..MULLER..F-309 GT |

35

RECEIVED
JAN 10 1964
U.S. AIR FORCE

100-100000-100000

100-100000-100000

100

100-100000-100000

100

RECEIVED
JAN 10 1964
U.S. AIR FORCE


100-100000-100000

100-100000-100000

RECEIVED
JAN 10 1964
U.S. AIR FORCE

100-100000-100000

RECEIVED
JAN 10 1964
U.S. AIR FORCE



NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

Nine Mile Point Nuclear Station

Post Office Box 32

Lycoming, New York

13093

Regulatory


File Cy.

June 21, 1973

Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Skovholt:

Re: Provisional Operating License: DPR-17
Docket No.: 50-220



The purpose of this letter is to report a failure of one of the six electromatic relief valves to close properly following manual actuation from the control room. This event which occurred on June 12, 1973 at 0808 hours, was reported by phone to Directorate of Regulatory Operations - Region I that same day and followed with a telegram sent that evening containing as much preliminary data as was available at that time. During the Spring 1973 refueling outage of Nine Mile Point, Unit #1 all six of the electromatic relief valves were overhauled. There are three 6" Consolidated electromatic relief valves, Type 1525-VX, installed on each of the two steam lines within the drywell for a total of six. Three are required for depressurization in the loss of coolant accident and five are required to maintain pressure margin between peak transient pressure and the lowest safety valve setting on turbine trip without bypass transient. These valves were operated at low reactor power following the spring outage to ascertain their ability to function properly prior to power operation.

The reactor was operating at approximately 12% power with most of the steam being generated, bypassed to the condenser. Reactor pressure was 950 psig, torus water temperature 75°F and torus water level approximately 3.2-3.4 feet of submergence. Testing of the electromatic relief valves was in progress following their outage overhaul. All valves had responded satisfactorily up to this time and operation of the fifth electromatic (#113) began at 0808 hours.

The indicated bypass steam flow to the condenser dropped from 30% indicated (100% bypass equals 40% total steam) to 16% indicating approximately 400,000 #/hr. of steam was flowing through valve #113. Electromatic valve #113 was then given a close signal (duration of cycle 1.32 seconds) however the indicated bypass steam flow remained at 16%. Special Procedure No. 9 (Inadvertant Operation of an Electromatic Relief Valve) was initiated and an orderly shutdown of the reactor begun.

5015


June 21, 1973

Attempts were made to close the valve by pulling the fuses and depressing the reset button. In addition the containment spray system was aligned to cool the suppression chamber water should it be needed. The drywell was not inerted at this time and personnel were dispatched to close the manual blocking valve upstream of the operating electromatic. The blocking valve was successfully closed and bypassed steam flow returned to 27% indicated. (The reactor was being shutdown therefore the difference between starting and ending flows). Torus temperature peaked at 125°F indicated and torus level increased to approximately 3.6 foot submergence. Reactor water level and pressure remained essentially unchanged during the valve operation. The electromatic valve operated for 43 minutes and released approximately 25,000 gallons of coolant to the torus (207,000 pounds of steam). Torus coolant activity increased to 586 c/m/ml from 470 c/m/ml. The torus temperature returned to normal within an hour of the incident with use of the containment spray system heat exchanger as set forth in Special Procedure No. 9. The reactor was shutdown in an orderly manner to less than 110 psig at 1300 hours the same day. No pressure changes were noted in either the drywell or torus.

Subsequent investigation of the electromatic valve revealed the valve rings were scoured (Fig. 4, part K) causing the valve to stick in the opened position. In addition a possible leaking union on the pilot valve tube extension (part D, Fig. 4 attached) was found. This could have caused leakage from chamber C and thus may have reduced the motive force to close the valve. The union was replaced and new rings and guide were installed in the valve. A retest of the valve showed satisfactory operation upon three openings and closures of the valve.

As the transient occurred from low reactor power, coolant coverage of the reactor provided no problem. Sufficient inventory is available from not only the condenser hotwell but also the condensate storage tanks; demineralized water storage at all power levels. This inventory is so established to provide normal core coverage should this transient occur from 100% power. Therefore, no unreviewed safety questions existed nor did this incident present any significant hazard to the health and safety of the general public.

Very truly yours,



P. Allister Burt
General Superintendent
Nuclear Generation

PAB:cm

Enc.




Fig. 4




Fig. 5




Fig. 6

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 3785

| | | | | | | | |
|---|--|-------------------------------|------------------------------|-----------------|--|------------|--------------|
| FROM:
Niagara Mohawk Power Corporation
Lycoming, N. Y. 13093
P. Allister Burt | | DATE OF DOC:
6-6-73 | DATE REC'D
6-12-73 | LTR
x | MEMO | RPT | OTHER |
| TO:
D. J. Skovholt | | ORIG
1 | CC | OTHER | SENT AEC PDR x
SENT LOCAL PDR x | | |
| CLASS: (U) PROP INFO | | INPUT | NO CYS REC'D
1 | | DOCKET NO:
50-220 | | |

| | |
|---|--------------------|
| DESCRIPTION:
Ltr reporting incident on 4/18-20/73 in which four valves failed to meet the leakage criteria of 12.9 SCFH.... | ENCLOSURES: |
|---|--------------------|

ACKNOWLEDGED
DO NOT REMOVE

PLANT NAMES: Nine Mile Point Unit #1

FOR ACTION/INFORMATION 6-12-73 LB

| | | | |
|-----------|--------------|-------------|---------------|
| BUTLER(L) | SCHWENCER(L) | ✓ZIEMANN(L) | YOUNGBLOOD(E) |
| W/ Copies | W/ Copies | W/9 Copies | W/ Copies |
| CLARK(L) | STOLZ(L) | ROUSE(TM) | REGAN(E) |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| GOLLER(L) | VASSALLO(L) | DICKER(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| KNIEL(L) | SCHEMEL(L) | KNIGHTON(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | |
|---|--|--|--|--|
| <u>REG FILE</u>
✓AEC PDR
✓OGC, ROOM P-506A
✓MUNTZING/STAFF
✓CASE
GIAMBUSSO
BOYD
V. MOORE-L(BWR)
DEYOUNG-L(PWR)
✓SKOVHOLT-L
P. COLLINS

REG OPR
✓FILE & REGION(3)
✓MORRIS
✓STEELE | <u>TECH REVIEW</u>
✓HENDRIE
SCHROEDER
✓MACCARY
✓KNIGHT
✓PAWLICKI
✓SHAO
✓STELLO
✓HOUSTON
✓NOVAK
✓ROSS
✓IPPOLITO
✓TEDESCO
✓LONG
✓LAINAS
✓BENAROYA
✓VOLLMER | DENTON
GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

ENVIRO
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJ LEADER

HARLESS | F & M
SMILEY
NUSSBAUMER

<u>LIC ASST.</u>
SERVICE L
WILSON L
GOULBOURNE L
SMITH L
GEARIN L
✓DIGGS L
TEETS L
LEE L
MAIGRET L
SHAFER F & M | WADE E
BROWN E
G. WILLIAMS E
SHEPPARD E

<u>A/T IND</u>
BRAITMAN
SALTZMAN

<u>PLANS</u>
MCDONALD
DUBE

<u>INFO</u>
C. MILES. |
|---|--|--|--|--|

EXTERNAL DISTRIBUTION

| | | |
|---|---|---|
| 1-LOCAL PDR Oswego, N. Y.
1-DTLE(ABERNATHY)
1-NSIC(BUCHANAN)
1-ASLB-YORE/SAYRE
WOODWARD/H. ST.
✓16-CYS ACRS XXXXXXXX SENT TO LIC ASST
R. DIGGS 6-12-73 | (1)(2)(9)-NATIONAL LAB'S
1-R. CARROLL-OC, GT-B227
1- R. CATLIN, E-256-GT
1- CONSULTANT'S
NEWARK/BLUME/AGABIAN
1- GERLAD ULRIKSON....ORNL | 1-PDR-SAN/LA/NY
1- GERALD LELLOUCHE
BROOKHAVEN NAT. LAB
1-AGMED(WALTER KOESTER,
RM C-427, GT)
1- RD...MULLER...F-309GT |
|---|---|---|

THE RECORD

Regulatory

File Cy.

NIAGARA MOHAWK POWER CORPORATION


NIAGARA  MOHAWK



Nine Mile Point Nuclear Station
Post Office Box 32
Lycoming, New York 13093

June 6, 1973

Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545



Dear Mr. Skovholt:

Re: Provisional Operating License: DPR-17
Docket No.: 50-220

On April 18-20, 1973 during the Spring 1973 refueling outage at Nine Mile Point Nuclear Station, Unit #1, the main steam isolation valves were leak tested, as required by the Station Technical Specifications. Once the results of these tests were evaluated, Division 1, Compliance was notified that three of the four valves failed to meet the leakage criteria of 12.9 SCFH.

The main steam flow from the reactor to the turbine is through two independent 24" lines. Each line contains two isolation valves, one inside the containment and one immediately outside the containment. The three valves that failed to achieve less than the maximum leakage of 12.95 SCFH were both outside isolation valves and one inside isolation valve.

Under containment design basis accident condition therefore one main steam line would remain essentially leak tight while the other line would leak at a rate of 25.5 SCFH into a closed system eventually terminating at the stack.

The MSIV's are intended to be closed during the design basis loss-of-coolant accident with a low leakage rate to assure that any significant release of fission products is retained within the containment system.

The maximum allowable test leak rate from the containment is 1.5%/day as a pressure of 35 psig. This was derived from the maximum allowable accident leak rate of about 1.9%/day when corrected for the effects of containment environment under accident and test conditions.



2000

4. 2

| Condition | Control (%) | MCI (%) | AD (%) |
|-----------|-------------|---------|--------|
| 1 | 100 | 85 | 65 |
| 2 | 95 | 80 | 60 |
| 3 | 90 | 75 | 55 |
| 4 | 85 | 65 | 45 |

•

.

•

2

2

•

•

•

1

10

1

•

•

5

Mr. Donald J. Skovholt
U. S. Atomic Energy Commission

June 6, 1973

Although the dose calculations suggest that the allowable test leakage rate could be increased to about 3.0%/day before the 10 CFR 100 guideline thyroid dose limit would be exceeded. The limit was established at 1.5%/day to provide an adequate margin of safety to assure the health and safety of the general public. In addition the operational limit was established as the multiple of the allowable test leak rate and .75, thereby providing a 25% margin. Therefore even though the test leakage was higher than the operational limit the value is mitigated by the safety margins and conservation used to derive the operational limit, and it can be concluded that even with the slightly higher leakage rates thru the one line, no undue hazard would have been presented to the general public in the event of a containment design basis accident during the previous operating cycle.

The accident analysis for a main steam line break outside the drywell concerns itself with two primary considerations:

1. The coolant inventory of the Reactor Vessel,
2. The radiological releases to the environment.

Both cases depend upon the closure time of the main steam isolation valves. In order to maintain coolant coverage of the reactor core a maximum closure time of 10 seconds is assumed in the analysis. Using this closure time for one valve in each main steam line the reactor core remains covered. The radiological releases to the environment are within limits provided a maximum closure time of 11 seconds is maintained. However, this is also based upon the primary coolant radioactivity concentration limit of 25 μCi total iodine per gram of water.


The actual closure times for the inside isolation valves are below the analysis maximum values used. In addition, the yearly average primary coolant radioactivity concentration was .25 μCi total iodine per gram of water. In conclusion, no undue hazard was presented to the general public if a main steam line break had occurred during the operating cycle.

Results for the four valves are as follows:

| <u>Valve Numbers</u> | <u>Leakage SCFH Before</u> | <u>Leakage SCFH After</u> |
|----------------------|----------------------------|---------------------------|
| #11 inside | 25.5 | 9.90 |
| #11 outside | 1116.1 | 9.55 |
| #12 inside | 5.0 | 5.00 |
| #12 outside | 64.4 | 3.75 |


Following core refueling, repairs were effected to those leakage valves using machine lapping techniques. A blueing of the seats was made before and after repairs. The valves were then retested to determine their leakage. All valves meet the 12.9 SCFH prior to restart of the reactor.

Very truly yours,



P. Allister Burt
General Superintendent
Nuclear Generation

PAB/cm



AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 6162

| FROM: | | DATE OF DOC: | DATE REC'D | LTR | MEMO | RPT | OTHER |
|---|--|--------------|--------------|-------|------------------------------------|-----|-------|
| Niagara Mohawk Power Corporation
Lycoming, N. Y. 13093
P. Allister Burt | | 11-3-72 | 11-9-72 | X | | | |
| TO: | | ORIG | CC | OTHER | SENT AEC PDR X
SENT LOCAL PDR X | | |
| Mr. Skovholt | | 1 | | | | | |
| CLASS: <u>U/PROP INFO</u> | | INPUT | NO CYS REC'D | | DOCKET NO: | | |
| | | | 60 | | 50-220 | | |

DESCRIPTION:
Ltr reporting an incident on 8-9-72, regarding
a failure of the main fuel grapple.....

ENCLOSURES:

**DO NOT REMOVE
ACKNOWLEDGED**

PLANT NAMES: Nine Mile Point Unit 1

| FOR ACTION/INFORMATION | | | | 11-10-72 | AB |
|------------------------|--------------|--------------|---------------|----------|----|
| BUTLER(L) | SCHWENGER(L) | SCHEMEL(L) | KNIGHTON(E) | | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies | | |
| CLARK(L) | STOLZ(L) | ZIEMANN(L) | YOUNGBLOOD(E) | | |
| W/ Copies | W/ Copies | W/9 Copies | W/ Copies | | |
| GOLLER(L) | VASSALLO(L) | CHITWOOD(FM) | REGAN(E) | | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies | | |
| KNIEL(L) | H. DENTON | DICKER(E) | | | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies | | |

INTERNAL DISTRIBUTION

| | | | | | |
|-------------------|--------------------|-------------|------------|---------------|-------|
| <u>REG FILE</u> | <u>TECH REVIEW</u> | VOLIMER | HARLESS | WADE | E |
| AEC PDR | HENDRIE | DENTON | | SHAFFER | F & M |
| OGC, ROOM P-506A | SCHROEDER | GRIMES | F & M | BROWN | E |
| MUNTZING/STAFF | MACCARY | GAMMILL | SMILEY | G. WILLIAMS | E |
| CASE | LANGE | KASTNER | NUSSBAUMER | E. GOULBOURNE | L |
| GIAMBUSSO | PAWLICKI | BALLARD | | A/T IND | |
| BOYD-L(BWR) | SHAO | FINE | LIC ASST. | BRATTMAN | |
| DEYOUNG-L(PWR) | KNUTH | | SERVICE L | SALTZMAN | |
| SKOVHOLT-L | STELLO | ENVIRO | MASON L | | |
| P. COLLINS | MOORE | MULLER | WILSON L | PLANS | |
| | HOUSTON | DICKER | MAIGRET L | MCDONALD | |
| REG OPR | TEDESCO | KNIGHTON | SMITH L | DUBE | |
| FILE & REGION (2) | LONG | YOUNGBLOOD | GEARIN L | | |
| MORRIS | LAINAS | PROJ LEADER | DIGGS L | INFO | |
| STELLE | BENAROYA | | TEETS L | C. MILES | |
| | | REGAN | LEE L | | |

EXTERNAL DISTRIBUTION

| | | |
|--|--------------------------|-------------------------|
| 1-LOCAL PDR Oswego, N. Y. | (1)(5)(9)-NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| 1-DTIE(ABERNATHY) | 1-R. CARROLL-OC, GT-B227 | 1-GERALD LELLOUCHE |
| 1-NSIC(BUCHANAN) | 1-R. CATLIN, E-256-GT | BROOKHAVEN NAT. LAB |
| 1-ASLB-YORE/SAYRE | 1-CONSULANT'S | 1-AGMED(WALTER KOESTER, |
| WOODWARD/H. ST. | NEWMARK/BLUME/AGABIAN | Rm C-427, GT) |
| 16-CYS ACRS XXXXXX SENT TO LIC ASST | | 1-RD...MULLER...F-309GT |
| R. DIGGS ON 11-10-72 | | |

Handwritten marks and scribbles in the top right corner.

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000


1000

NIAGARA MOHAWK POWER CORPORATION

NIAGARA



MOHAWK




Nine Mile Point Nuclear Station
Post Office Box 32
Lycoming, New York 13093

November 3, 1972

Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Skovholt:

Re: Provisional Operation License: DPR-17
Docket No.: 50-220




On August 9, 1972, a failure of the main fuel grapple occurred. Although the failure occurred over the spent fuel storage pool, the grapple was not loaded and no fuel bundles were damaged or upset. The grapple was not carrying fuel at the time.

After transferring a fuel bundle from the spent fuel storage racks to the fuel preparation machine, the operator placed the grapple in the full-up or retracted position. As the operator was moving the bridge to the east side of the pool, he heard the contacts on the grapple and assumed that he had accidentally hit the down lever on the grapple. Normal reaction to this was to reach with the other hand and place the lever in the up position to return the grapple to its retracted position. This was done without shifting his eyes from the direction that the crane was moving. Moments later, there was a loud bang.

When the operator stopped the crane and looked, the grapple was resting on the cab floor and the fuel storage rack in the pool below. The operator anchored the grapple to the bridge trolley with a rope in order to prevent it from dropping into the pool. The operator did not observe anything peculiar just prior to or during the grapple failure, therefore, could not give anyother information concerning the problem.

Inspection showed that the grapple cable had failed and the lower support pins between the first section of the grapple and swivel section had sheared. Failure of the cable allowed the telescoping section to extend out until the grapple head rested on the fuel storage rack in the pool.

6162
RW



Shearing of the support pins allowed the first section to drop, first striking the power control panel support structure, and second, hitting the trolley floor. The grapple control boxes attached to the sides of the grapple came to rest on the trolley grating thus supporting the upper section of the grapple. The grapple was removed from the pool and dismantled.

Investigation showed that the grapple head had cracks in the welding which attached the head to the tubular section. This damage was probably due to the impact received during this incident.

Three parts of the sheared pins were found. The pins showed that they had sheared due to an impact in the downward direction. The diameter of the pin at the shear was 3/8". 1/8" wear had taken place between the pin and gimbal section.

The bushings in the grapple that housed the pins were worn in an oval shape and had cracks at the 12:00, 3:00 and 9:00 o'clock positions indicating over stress.

One arm on the grapple that held the bushing and pin was bent in. This was caused when the grapple fell and struck the power control panel support structure.

The control panels attached to the grapple were undamaged, but the connection attaching the control cable to the right side control box was crushed between the box and trolley floor. Wires in the cable were damaged.


The stops on the first section of the grapple showed markings where the second section made contact but no damage was found.

Further investigation showed that the support pins between the thrust bearing and gimbal were worn as badly as the failed pins and impact load could have sheared these as well.

The thrust bearing was disassembled and found to lack lubrication. No provision was supplied to apply any lubricant to this bearing. The balls and races were worn and had fretting corrosion.

The cam type limit switch which operates the hoist drum and limits both the fully extended and fully retracted grapple positions was found in the permissive position although the hoist drum was wound up to a position above the retracted position. It is felt that this condition can easily occur as the dynamic breaking effects from jogging the hoist near its upper limit can retract the grapple slightly above its upper limit. If the grapple is far enough beyond its upper limit, the limit switch becomes inoperable and the grapple hoist can be raised or lowered from this position.

Another limit switch was mounted on the top of the grapple and is called the overtravel switch. This switch was removed when the grapple was removed from the pool and could not be checked for proper adjustment. Although the switch was operable electrically, it is assumed that this switch was out of adjustment.



Mr. Donald J. Skovholt
U. S. Atomic Energy Commission

-3-

November 3, 1972

The load cell was checked for operability with a 1650 lb. load. Although the load cell did interrupt the hoist circuit at 1650 lbs., the hoist continued coasting for a short period of time until the mechanical brake stopped travel. No dynamic breaking occurs when the grapple is beyond its overtravel limit. The load on the cable was found to be 2400 lbs.

The vendor has been contacted concerning this matter. They have recommended the following system modifications for preventing this incident in the future:

1. Installation of a torque limiter between the hoist motor and the gear box to the hoist drive.
2. Change the dynamic breaking timer from a one second duration to 0.5 second duration.
3. Reconnect main hoist master switch wiring such that full hoisting speed is reduced to half hoisting speed electrically when any vertical limit trip is indicated.

These modifications have not yet been accepted by Niagara Mohawk. The major area of concern is the reliability of torque limiting devices. Further analysis of system modifications are underway.

On the matter of weld crack damage to the grapple head, the vendor has not yet resolved a final recommendation. There is concern over in plant re-plating methods after welding repairs. Testing of nickel plated specimens similar to the material used on the grapple are underway. Repairs to the grapple head will be initiated as soon as an acceptable method is approved.

Very truly yours,



P. Allister Burt
General Superintendent
Nuclear Generation

PAB:pw



60



27

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 6247

| | | | | | | | |
|--|--|-------------------------|------------------------|----------------------|--------------------------------|-----|-------|
| FROM: Niagara Mohawk Power Corp.
Lycoming, N.Y. 13093
P. Allister Burt | | DATE OF DOC:
11-3-72 | DATE REC'D
11-15-72 | LTR
X | MEMO | RPT | OTHER |
| TO:
Mr. Donald J. Skovholt | | ORIG
1 signed | CC | OTHER | SENT AEC PDR
SENT LOCAL PDR | | |
| CLASS: <u>USE PROP INFO</u> | | INPUT | NO CYS REC'D
1 | DOCKET NO:
50-220 | | | |

DESCRIPTION: Ltr adv of a problem on 9-19-72 when the identifiable leakage into #11 drywell equipment drain tank started to slowly increase.....

*PLEASE CIRCULATE-INSUFFICIENT CYS FOR FULL DISTRIBUTION

ENCLOSURES:

PLANT NAMES: Nine Mile Pt. Station

**ACKNOWLEDGED
DO NOT REMOVE**

FOR ACTION/INFORMATION

DL 11-15-72

| | | | |
|-----------|--------------|--------------|---------------|
| BUTLER(L) | SCHWENGER(L) | SCHEMEL(L) | KNIGHTON(E) |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| CLARK(L) | STOLZ(L) | ZIEMANN(L) | YOUNGBLOOD(E) |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| GOLLER(L) | VASSALLO(L) | CHITWOOD(FM) | REGAN(E) |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |
| KNIEL(L) | H. DENTON | DICKER(E) | |
| W/ Copies | W/ Copies | W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

| | | | | | |
|------------------------------|--------------------|-------------|------------|---------------|-------|
| <u>REG FILE</u> | <u>TECH REVIEW</u> | VOLLMER | HARLESS | WADE | E |
| <u>AEC PDR</u> | <u>HENDRIE</u> | DENTON | | SHAFFER | F & M |
| <u>OGC, ROOM P-506A</u> | <u>SCHROEDER</u> | GRIMES | F & M | BROWN | E |
| <u>MUNIZING/STAFF</u> | *MACCARY | GAMMILL | SMILEY | G. WILLIAMS | E |
| <u>CASE</u> | LANGE | KASTNER | NUSSBAUMER | E. GOULBOURNE | L |
| <u>LIAMBUSSO</u> | PAWLICKI | BALLARD | | A/T IND | |
| <u>BOYD-L(BWR)</u> | SHAO | FINE | LIC ASST. | BRATTMAN | |
| <u>DEYOUNG-L(PWR)</u> | *KNUTH | | SERVICE | SALTZMAN | |
| <u>SKOVHOLT-L</u> | STELLO | ENVIRO | MASON | | |
| <u>P. COLLINS</u> | MOORE | MULLER | WILSON | PLANS | |
| | BOUSTON | DICKER | MAIGRET | MCDONALD | |
| <u>REG OPR</u> | *TEDESCO | KNIGHTON | SMITH | DUBE | |
| <u>FILE & REGION (2)</u> | LONG | YOUNGBLOOD | GEARIN | | |
| <u>MORRIS</u> | LAINAS | PROJ LEADER | DIGGS | INFO | |
| <u>STELLE</u> | BENAROYA | | TEETS | C. MILES | |
| | | REGAN | LEE | | |

EXTERNAL DISTRIBUTION

| | | |
|--------------------------|--------------------------|-------------------------|
| 1-LOCAL PDR Oswego, N.Y. | (1)(5)(9)-NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| 1-DTIE(ABERNATHY) | 1-R. CARROLL-OC, GT-B227 | 1-GERALD LELLOUCHE |
| 1-NSIC(BUCHANAN) | 1-R. CATLIN, E-256-GT | BROOKHAVEN NAT. LAB |
| 1-ASLB-YORE/SAYRE | 1-CONSULANT'S | 1-AGMED(WALTER KOESTER, |
| WOODWARD/H. ST. | NEWMARK/BLUME/AGABIAN | Rm C-427, GT) |
| 16-CYS ACRS | SENT TO LIC. ASST. R. | 1-RD...MULLER...F-309GT |
| | DIGGS ON 11-15-72 | |

23

1

.....

*

*

*

.....

128


128

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

Nine Mile Point Nuclear Station
P. O. Box 32
Lycoming, New York 13093

November 3, 1972




Regulatory File Cy.

Mr. Donald J. Skovholt
Assistant Director for Reactor Operations
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Skovholt:

Re: Provisional Operating License: DPR-17
Docket No.: 50-220



On September 19, 1972, with the Nine Mile Point Unit operating at 602 MW (e) the identifiable leakage into #11 drywell equipment drain tank started to slowly increase. The trend of this leakage closely followed previous trends resulting from recirculation system valve packing leakage into the drywell equipment drain tanks. The primary inputs to #11 drywell equipment drain tanks consist of #11 and #12 reactor recirculation pump suction and discharge valves and #13 reactor recirculation pump discharge valve. A planned program to discover the exact source of leakage was undertaken. The unit load was reduced to 510 MW (e) and reactor recirculation pumps #11, #12 and #13 were individually isolated to determine the effect in total drywell leakage. Throughout this period accurate determination of leakage was obtained on a continuous basis. No substantial change in leakage could be detected during the isolation attempts, however, the pressure on #11 reactor recirc pump low pressure seals fluctuated during the time that the pump was isolated as seen in the control room indication.

On September 20, 1972, surveillance data revealed that leakage into #11 DWEDT was approaching the limiting condition for operation (25 gpm total) . At 1745 hours plant shutdown was initiated in order to repair the pump seal on #11 reactor recirculation pump and repack certain recirculation system isolation valves. Four hours after starting to shutdown, the leakage reversed its trend and began to decrease with power level. Cold shutdown was achieved at 1400 hours on September 21, 1972 and recirculation system repairs were started.

6247
fw

Mr. Donald Skovholt
U.S. Atomic Energy Commission

November 3, 1972

During the repair to the #11 recirculation pump seal, the pump suction valve was closed manually as the motor operated actuator (Limitorque valve operator) could not close the valve. Following repairs to the pump seal, the suction valve was cycled to test the valve operator, however, the valve locked up in the open position. Neither the motor operated or manual mode of operation could move the valve. The valve was jacked to the closed position and locked there.

Inspection of the valve operator revealed that extensive internal damage had occurred and immediate repairs could not be made. Damage to the valve operator was identified as a broken worm shaft in the drive assembly and a cracked case around the stem drive nut which damaged a thrust bearing assembly on the lower side of the drive nut. A replacement valve operator was ordered. Until installation of the replacement valve operator, the plant output was limited to 80% as only four of the five recirculation loops were in service.

On the weekend of October 28, 1972, the limitorque SMA-1 valve operator was successfully replaced by an SMB-1 valve operator as the SMA-1 is no longer made. The replacement unit is larger than the original and has greater power transmission capabilities, however, the driver motor is the same size as on the original unit. During this outage, considerable packing maintenance was also accomplished on all of the reactor recirculation isolation valve packing. All work was completed by October 29, 1972 and the plant was started up with all five recirculation loops available for service.

Very truly yours, .



P. Allister Burt
General Superintendent
Nuclear Generation

PAB/cm

200.42