

50-237

## NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER  
INCIDENT REPORT

TO: Mr. Norman C. Moseley

FROM: Commonwealth Edison  
Morris, Illinois 60450  
B. B. StephensonDATE OF DOCUMENT  
05-09-77DATE RECEIVED  
05-16-77☒ LETTER  
☐ ORIGINAL  
☒ COPY☐ NOTORIZED  
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

## DESCRIPTION

Ltr. Trans The Following:

( 1 page )

**DO NOT REMOVE**

PLANT NAME: DRESDEN UNIT # 2

jcm

**ACKNOWLEDGED**

## ENCLOSURE

Licensee Event Report (RO-50-237/77-19)  
on 04-25-77 concerning APRM/RBM flow-bias  
indication exceeded 100% on both channels A and  
B.....

( 2 pages )

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED  
SEND DIRECTLY TO KREGER/J. COLLINS

## FOR ACTION/INFORMATION

BRANCH CHIEF:

Davis

W/3 CYS FOR ACTION

LIC. ASST.:

Diggs

W/ CYS

ACRS 16 CYS HOLDING/SENT as Cat B

## INTERNAL DISTRIBUTION

REG FILE

NRC-PDR

I &amp; E (2)

MIPC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES

CASE

BUTLER

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/BUNCH

KREGER/J. COLLINS

## EXTERNAL DISTRIBUTION

LPDR: Morris FAL

TIC:

NSIC:

## CONTROL NUMBER

771370023






**Commonwealth Edison**  
Dresden Nuclear Power Station  
R.R. #1  
Morris, Illinois 60450  
Telephone 815/942-2920

BBS Ltr. # 77-419

May 9, 1977

Mr. James G. Keppler, Regional Director  
Directorate of Regulatory Operations - Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

**REGULATORY DOCKET FILE COPY**



Enclosed please find Reportable Occurrence report number 50-237/1977-19.  
This report is being submitted to your office in accordance with the Dresden  
Nuclear Power Station Technical Specifications, Section 6.6.B.

  
B. B. Stephenson  
Station Superintendent  
Dresden Nuclear Power Station

BBS:sm

Enclosure

cc: Director of Inspection & Enforcement  
Director of Management Information & Program Control  
File/NRC

771370023



# LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME						LICENSE NUMBER										LICENSE TYPE				EVENT TYPE			
01	1	L	D	R	S	2	0	0	0	0	0	0	0	0	0	4	1	1	1	1	0	1	
7	8	9				14	15									25	26				30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE				REPORT DATE									
01	CONT		T	L	0	5	0	0	2	3	7	0	4	2	5	7	7	0	5	0	9	7	7
7	8	57	58	59	60	61					68	69					74	75					80

**EVENT DESCRIPTION**

02	During normal operation it was discovered that with core flow at 100%, the APRM/RBM	80
03	flow-bias indication exceeded 100% on both channels A and B. At 100% core flow, the	80
04	APRM scram setpoint (117% reactor power) would not have been exceeded; however, at	80
05	reduced flow rates, the flow-biased scram setpoint would have been non-conservative	80
06	by approximately 3%. The flow bias flow indication has exceeded 100% in the past	80

(continued)

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOLATION			
07	1	A	D	I	N	S	T	R	U	N	G	0	8	0	Y
7	8	9	10	11	12				17	43	44			47	48

**CAUSE DESCRIPTION**

08	During the recent outage, the recirculation drive flow instruments and the APRM/RBM	80
09	flow converters which receive their input from the instruments were calibrated to	80
10	appropriate original specifications. The procedure which was followed, however, did	80

(continued)

FACILITY STATUS		% POWER	OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	E	0	8	3	NA	B	NA	NA
7	8	9	10	12	13	44	45	46

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE	AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
12	Z	Z	NA	NA	NA	NA
7	8	9	10	11	44	45

**PERSONNEL EXPOSURES**

NUMBER	TYPE	DESCRIPTION
13	0	0
7	8	9

**PERSONNEL INJURIES**

NUMBER	DESCRIPTION
14	0
7	8

**OFFSITE CONSEQUENCES**

15	NA
7	8

**LOSS OR DAMAGE TO FACILITY**

TYPE	DESCRIPTION
16	Z
7	8

**PUBLICITY**

17	NA
7	8

**ADDITIONAL FACTORS**

18	NA
7	8

19	
7	8

NAME: T. Rausch

PHONE: Ext. 266



EVENT DESCRIPTION (continued)

(50-237/1977-2) as a result of calibration of the total core flow indication. The safety implications of this event were minimal because safety and transient analyses do not assume a flow-biased scram function (50-237/1977-19).

CAUSE DESCRIPTION (continued)

not take into account the present correlation between recirculation drive flow and total core flow (to which the APRM/RBM flow converter readings are referenced). As a result the APRM/RBM scram trip levels could have been non-conservative at core flow rates of less than 100%.

On April 25, 1977, the APRM/RBM flow converters were readjusted to read 100% at 100% total core flow. To prevent a reoccurrence of this event, the appropriate instrument calibration procedure will be revised to include the present correlation between recirculation drive flow and total core flow.



1990

26. 4. 2