

50-237

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO:

Mr. James G. Keppler

FROM:

Commonwealth Edison Company
Morris, Illinois
B. B. StephensonDATE OF DOCUMENT
4/29/77DATE RECEIVED
5/23/77☒ LETTER☐ NOTORIZED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

☒ ORIGINAL
☐ COPY☒ UNCLASSIFIED

1 SIGNED

DESCRIPTION

ENCLOSURE

Licensee Event Report (RO 50-237/1977-14)
on 4/2/77 concerning control rod drive H-8
being found to uncouple & overtravel when
withdrawn to position 48.....

DO NOT REMOVE

PLANT NAME:

Dresden Unit No. 2

(1-P)

(2-P)

RJL

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

ACKNOWLEDGED

FOR ACTION/INFORMATION

BRANCH CHIEF:

ZIEMANN

W/3 CYS FOR ACTION

LIC. ASST.:

DIGGS

W/1 CYS

ACRS 16 CYS HOLDING/SENT

AS CPT 13

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I & E (2)

MIPC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES

BUTLER

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/BUNCH

KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: MORRIS ILL

TIC:

NSIC:

771430043



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

H. Lanham

BBS Ltr. # 77-378

April 29, 1977

Mr. James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



REGULATORY DOCKET FILE COPY
Enclosed please find Reportable Occurrence report number 50-2377/1977-14.
This report is being submitted to your office in accordance with the Dresden
Nuclear Power Station Technical Specifications, Section 6.6.B.

B. B. Stephenson
B. B. Stephenson
Station Superintendent
Dresden Nuclear Power Station


BBS/skm

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

MAY 4 1977

771430043



1948 1949

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME 01 I L D R S 2	LICENSE NUMBER 0 0 - 0 0 0 0 0 - 0 0	LICENSE TYPE 4 1 1 1 1	EVENT TYPE 0 3
CATEGORY 01 CONT	REPORT TYPE L	REPORT SOURCE L	DOCKET NUMBER 0 5 0 - 0 2 3 7
EVENT DATE 0 4 0 2 7 7	REPORT DATE 0 4 2 9 7 7		

EVENT DESCRIPTION

02 During routine start-up operations, control rod drive (CRD) H-8 was found to uncouple
03 and overtravel when withdrawn to position 48. All CRD's were subsequently inserted
04 to position 00 and verified to be fully inserted by computer. CRD H-8 was then
05 withdrawn to position 48 and checked for overtravel four separate times. Each over-
06 travel check proved satisfactory, and the drive was determined to be recoupled and

(continued)

SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
R B	E	C R D R V E	N	G O 8 0	N

CAUSE DESCRIPTION

08 Symptom and performance evaluations indicate that a loosened inner filter in the CRD,
09 may potentially cause the blade and drive to uncouple at the fully withdrawn position.
10 Loosening of the filter may have resulted from a combination of improper installation

(continued)

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
C	0 0 0	NA	A	NA

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
Z	Z	NA	NA

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
0 0 0	Z	NA

PERSONNEL INJURIES

NUMBER	DESCRIPTION
0 0 0	NA

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION
Z	NA

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 NA

19

NAME: Robert Herbert

PHONE: Ext. 265

EVENT DESCRIPTION (continued)

operable. Normal start-up operations were resumed. (50-237/1977-14)

CAUSE DESCRIPTION (continued)

and latching spring fatigue. It has been determined that a loosened filter cannot exert sufficient pressure to uncouple the blade except when the drive is fully withdrawn to position 48; upon insertion, the blade and drive automatically recouple. Because the potential for uncoupling the blade exists only when the drive is fully withdrawn, the safety implications of this event are minimal.

As a precautionary measure, an operating order has been issued to ensure that a coupling check is performed whenever drive H-8 is withdrawn to position 48. During the next Unit-2 refueling outage, CRD H-8 will be disassembled and inspected. If another primary cause of failure is determined at that time, a supplemental report will be submitted. Control rod drive/blade uncoupling incidents have occurred several times in the past.

RECEIVED DOCUMENT
PROCESSING UNIT

1977 MAY 20 PM 1 56