

E 03/10/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)  
DISTRIBUTION FOR INCOMING MATERIAL

50-220

REC: GRIER B H  
NRC

ORG: SCHNEIDER R R  
NIAGARA MOHAWK PWR

DOCDATE: 03/01/78  
DATE RCVD: 03/07/78

DOCTYPE: LETTER NOTARIZED: NO

COPIES RECEIVED

SUBJECT:

LTR 0 ENCL 1

LICENSEE EVENT REPT (RO 50-220/78-07) ON 02/06/78 CONCERNING DURING  
STEADY STATE OPERATAION, AN INSPEC OF THE LIQUID WASTE SURGE TANK  
FOUND SEVERAL PINHOLE LEAKS...W/ATT LERS 78-008, 78-009 AND 78-010.

PLANT NAME: NINE MILE PT - UNIT 1

REVIEWER INITIAL: XJM  
DISTRIBUTOR INITIAL: DL

\*\*\*\*\* DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS \*\*\*\*\*

INCIDENT REPORTS  
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF ~~LEAR~~\*\*W/4 ENCL

INTERNAL:

REG FILE\*\*W/ENCL  
I & E\*\*W/2 ENCL  
SCHROEDER/IPPOLITO\*\*W/ENCL  
NOVAK/CHECK\*\*W/ENCL  
KNIGHT\*\*W/ENCL  
HANAUER\*\*W/ENCL  
EISENHUT\*\*W/ENCL  
SHAO\*\*W/ENCL  
KREGER/J. COLLINS\*\*W/ENCL  
K SEYFRIT/IE\*\*W/ENCL

NRC PDR\*\*W/ENCL  
MIPC\*\*W/3 ENCL  
HOUSTON\*\*W/ENCL  
GRIMES\*\*W/ENCL  
BUTLER\*\*W/ENCL  
TEDESCO\*\*W/ENCL  
BAER\*\*W/ENCL  
VOLLMER/BUNCH\*\*W/ENCL  
ROSA\*\*W/ENCL

EXTERNAL:

LPDR'S  
OSWEGO, NY\*\*W/ENCL  
TIC\*\*W/ENCL  
NSIC\*\*W/ENCL  
ACRS CAT B\*\*W/16 ENCL

DISTRIBUTION: LTR 45 ENCL 45  
SIZE: 1P+1P+4P

CONTROL NBR: 780680045

\*\*\*\*\* THE END

\*\*\*\*\*

1. The first part of the document discusses the importance of maintaining accurate records of all transactions and the role of the accounting department in ensuring the integrity of the financial data. It emphasizes the need for transparency and accountability in all financial reporting.

2. The second part of the document outlines the various methods used to collect and analyze financial data, including the use of spreadsheets, databases, and specialized accounting software. It also discusses the importance of regular audits and the role of external auditors in verifying the accuracy of the financial statements.

3. The third part of the document focuses on the importance of budgeting and financial planning. It discusses the various factors that can affect a company's financial performance and the need for a comprehensive budgeting process that takes into account all aspects of the business.

4. The fourth part of the document discusses the importance of financial reporting and the role of the accounting department in preparing and presenting the financial statements. It emphasizes the need for clear and concise reporting that provides a comprehensive overview of the company's financial performance.

5. The fifth part of the document discusses the importance of financial management and the role of the accounting department in ensuring the efficient use of the company's resources. It emphasizes the need for a strong financial management system that can track and control all financial transactions.

6. The sixth part of the document discusses the importance of financial risk management and the role of the accounting department in identifying and mitigating potential financial risks. It emphasizes the need for a comprehensive risk management system that can identify and assess all potential risks to the company's financial health.

7. The seventh part of the document discusses the importance of financial compliance and the role of the accounting department in ensuring that the company's financial practices comply with all applicable laws and regulations. It emphasizes the need for a strong compliance system that can monitor and enforce all financial regulations.


8. The eighth part of the document discusses the importance of financial communication and the role of the accounting department in providing clear and concise financial information to all stakeholders. It emphasizes the need for a strong communication system that can effectively convey financial information to all levels of the organization.

9. The ninth part of the document discusses the importance of financial innovation and the role of the accounting department in adopting new technologies and practices to improve financial performance. It emphasizes the need for a strong innovation system that can identify and implement all new financial technologies and practices.

10. The tenth part of the document discusses the importance of financial sustainability and the role of the accounting department in ensuring the long-term financial health of the company. It emphasizes the need for a strong sustainability system that can monitor and manage all financial aspects of the company's operations.

March 1, 1978

Mr. Boyce H. Grier  
Director  
United States Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, PA. 19406



RE: Docket No. 50-220

Dear Mr. Grier:

In accordance with Nine Mile Point Nuclear Station Unit #1  
Technical Specifications, we hereby submit the following Licensee  
Event Reports:

- LER 78-07, which is in violation of Section 6.9.2b(4) of  
the Technical Specifications
- LER 78-08, which is in violation of Section 3.6.2 of the  
Technical Specifications
- LER 78-09, in accordance with the Technical Specifications
- LER 78-10, which is in violation of Section 3.6.2 of the  
Technical Specifications

These reports were completed in the format designated in  
NUREG-0161, dated July 1977.

Very truly yours,

R.R. Schneider  
Vice President -  
Electric Production

mtm

Attachments (3 copies)

xc: Director, Office of I&E (30 copies)  
Director, Office of MIPC (3 copies)

780680045

A002/s \*  
o/i



20

10-10-66

10-10-66

10-10-66

10-10-66

10-10-66

10-10-66

10-10-66

10-10-66

## LICENSEE EVENT REPORT

CONTROL BLOCK: 

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT		58

CON'T

REPORT SOURCE 7 8 60 61 68 69 74 75 80

0 1 L 6 0 5 0 0 0 2 2 0 7 0 2 0 6 7 8 8 0 2 2 8 7 8 9

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During steady state operation, an inspection of the liquid waste surge  
0 3 | tank found several pinhole leaks. There were no measurable losses of  
0 4 | liquid but leaks could be identified by dried deposit tracks on the  
0 5 | side of the tank. This is reportable per T.S. 6.9.2b(4). This  
0 6 | condition resulted in minimal safety implications.  
0 7 |  
0 8 |

09		SYSTEM CODE M A		CAUSE CODE B	CAUSE SUBCODE C	COMPONENT CODE A C C U M U				COMP. SUBCODE Z	VALVE SUBCODE Z					
7	8	9	10	11	12	13	14	15	16	17	18	19	20			
LER/RO REPORT NUMBER 17		EVENT YEAR 7 8			SEQUENTIAL REPORT NO. 0 0 7			OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0				
21		22		23	24		25	26		27	28		29	30	31	32
ACTION TAKEN X		FUTURE ACTION F		EFFECT ON PLANT Z	SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER N		COMPONENT MANUFACTURER P 2 7 0	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | A 50,000 gal. aluminum B-209 tank built by Pittsburgh-Des Moines Steel Co.  
1 1 | was constructed with walls 0.1875 inches thick. During assembly, weld-  
1 2 | ing and grinding reduced the thickness in spots to half of this value  
1 3 | apparently leaving pinhole leaks. A tank liner is being considered as  
1 4 | a permanent solution, currently usage is strictly controlled.

7 8 9 FACILITY STATUS 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

1 5 E 0 9 9 NA C Tank Inspection

7 8 9 FACILITY STATUS 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

1 5 E 0 9 9 NA C Tank Inspection

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  
1 6 Z (33) Z (34) NA LOCATION OF RELEASE (36)  
2 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0					
			(37) Z	(38) NA (39)					

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0	0
0	0	0	40
		NA	

7		8		9		10		11		12	
LOSS OF OR DAMAGE TO FACILITY						(43)					
TYPE				DESCRIPTION							
1	9	Z	(42)	NA							

7 8 9 10 PUBLICITY  
ISSUED DESCRIPTION (45)  
2 0 N 44 NA  
7 8 9 10 68 69 80 NRC USE ONLY

NAME OF PREPARER Dennis K. MacVittie

PHONE: 315-343-2110 ext. 1558

1-800-917-926



10

10

10

10

10

10

10

10

10

10

10

10

10

10

10

10

10

10

10

10

10

10

# LICENSEE EVENT REPORT

CONTROL BLOCK: 

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	1	4			5
7	8	9						14	15	25										26	30					57	58			
		LICENSEE CODE							LICENSE NUMBER											LICENSE TYPE						CAT				

CON'T

0	1	REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE									
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																			
		L	6	0	5	0	0	0	2	2	0	7	0	2	1	0	7	8	8	0	2	2	8	7	8	9															

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)**

0 2 | During steady state operation, performance of surveillance test N1-ISP-  
0 3 | RE22, found RE22C with a setpoint of 103.5 PSID, RE22E at 103.0 PSID,  
0 4 | and RE22F at 103.5 PSID. Required setpoint for these main steam line  
0 5 | high flow indicating switches is 105 PSID +/- 1 PSID. This condition  
0 6 | resulted in minimal safety implications. The three instruments drifted  
0 7 | in a more conservative direction.  
0 8 |

[illegible]

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The deviation in setpoints experienced on the Barton Model 278 Differen-

1 1 | tial Pressure Indicating Switches was due to instrument drift. RE22C

1 2 | was reset at 105.5 PSID, RE22E at 105.0 PSID, and RE22F at 104.7 PSID.

1 3 | Current surveillance testing schedules are adequate to insure early

1 4 | detection of future instrument drifts.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (28) 0 9 9 (29) NA OTHER STATUS (30) METHOD OF DISCOVERY (31) B DISCOVERY DESCRIPTION (32) Surveillance Testing

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 Z 33 10 34 NA

7 8 9 11

AMOUNT OF ACTIVITY (35)

NA

45 80

LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES									
NUMBER				TYPE	DESCRIPTION				
1	7	0	0	0	Z	NA			

PERSONNEL INJURIES										
NUMBER				DESCRIPTION						
1	8	0	0	(40)	NA					

1		9		Z		42		NA		43	
7	8	9	10	80							

PUBLICITY  
ISSUED (2) (0) (N) (44) DESCRIPTION (45) NA  
7 8 9 10 68 69 80  
NRC USE ONLY

NAME OF PREPARER Dennis K. MacVittie

**PHONE:**

315-343-2110 ext 1558



2.4

1.2 2.3

1.1 2.2 2.3

1.1

1.2

1.3

1.4

1.5

1.6

1.7

1.8

1.9

1.10

1.11

1.12 1.13 1.14

1.15

1.16

1.17

1.18 1.19

**CONTROL BLOCK:**

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	2	0	7	0	2	2	1	7	8	8	0	2	2	8	7	8	9
60	61	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80			

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[illegible]

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS (28) E (28) % POWER (29) 0 9 9 (29) OTHER STATUS (30) NA (30) METHOD OF DISCOVERY (31) B (31) DISCOVERY DESCRIPTION (32) Surveillance Testing (32)

ACTIVITY CONTENT RELEASED OF RELEASE (33) Z (33) (34) Z (34) AMOUNT OF ACTIVITY (35) NA (35) LOCATION OF RELEASE (36) NA (36)

PERSONNEL EXPOSURES NUMBER (37) 0 0 0 (37) TYPE (38) Z (38) DESCRIPTION (39) NA (39)

PERSONNEL INJURIES NUMBER (40) 0 0 0 (40) DESCRIPTION (41) NA (41)

LOSS OF OR DAMAGE TO FACILITY TYPE (42) Z (42) DESCRIPTION (43) NA (43)

PUBLICITY		ISSUED		DESCRIPTION		NRC USE ONLY																	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
2	0	N	NA	(44)	(45)																		

PHONE: 315-343-2110 x 1558

10-11-68

10-11-68

10-11-68

February 28, 1978

Mr. Boyce H. Grier  
Director  
United States Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, PA. 19406

RE: Docket No. 50-220  
LER 78-09/01T-0  
Nine Mile Point Nuclear Station Unit #1

Dear Mr. Grier:

During routine station operation with the TIP detectors withdrawn, explosive charges in the TIP System shear valves were replaced with new charges. The explosive operated TIP shear isolation valves are a back-up system to be used for isolation of the TIP tubes in the event it is not possible to withdraw the detector so the normal automatic isolation system may function.

Following replacement, performance of Maintenance Procedure, N1-IMP-TIP-3 found that the ohmmeter continuity test for acceptable electric contact was unsatisfactory. The normal TIP tube isolation system was operable at this time.

It was found that the actual electrical connections to the explosive charges were not as described in the Maintenance Procedure. General Electric NED Product Service was informed of the problem and given the numbers of the drawings used to wire the system. A revision to the drawing, which had originally been issued in February 1968, was located. The configuration shown in this revision would cause the charges to fire.

The wiring for firing the charges in the TIP System was changed to match that shown in the revised drawing. All of the old charges were test fired using the wiring scheme shown in the revised drawing. They all fired successfully.

A review of the Pre-Operational Test of our Liquid Poison System showed that the explosive shear valves in that system had been operationally tested prior to startup.

In addition to the wiring problems uncovered, it was found that the 2 AMP fuses required in the squib circuits were instant blow devices instead of the slow blow type specified by the vendor. All of the fuses in the monitor/control units were replaced with new devices.

An evaluation of the safety implications is being conducted.

2.1.2

1.1.1

1.1.2

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

7 8

REPORT SOURCE

L	(6)	0	5	0	0	0	2	2	0	(7)	0	2	0	4	7	8	(8)	0	2	2	8	7	8	(9)
---	-----	---	---	---	---	---	---	---	---	-----	---	---	---	---	---	---	-----	---	---	---	---	---	---	-----

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)**

09		SYSTEM CODE IB		CAUSE CODE E		CAUSE SUBCODE E		COMPONENT CODE INSTRU				COMP. SUBCODE S		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
LER/RO REPORT NUMBER		EVENT YEAR 78		SEQUENTIAL REPORT NO. 010		OCCURRENCE CODE 03		REPORT TYPE L		REVISION NO. 0		ACTION TAKEN EZ		EFFECT ON PLANT Z	
23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38
SHUTDOWN METHOD Z		HOURS 000		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. Y		PRIME COMP. SUPPLIER N		COMPONENT MANUFACTURER B080		ACTION Z		FUTURE ACTION Z	
39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (28) 1 5 E

% POWER 0 9 3 (29)

OTHER STATUS (30) NA

METHOD OF DISCOVERY (31) B

DISCOVERY DESCRIPTION (32) Surveillance Testing

PERSONNEL EXPOSURES										DESCRIPTION													
NUMBER					TYPE																		
1	7	0	0	0	37	Z	38	NA	39														
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30

1		9		Z		42		NA		43	
7		8		9		10				80	
LOSS OF OR DAMAGE TO FACILITY											
TYPE				DESCRIPTION							

							PUBLCITY			(45)	NRC USE ONLY									
ISSUED		DESCRIPTION																		
2	0	N	NA																	
7	8	9	10																	

PHONE: 315-343-2110 x 1558

20  
21