

E 03/10/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL

50-220

REC: GRIER B H
NRC

ORG: SCHNEIDER R R
NIAGARA MOHAWK PWR

DOCDATE: 02/24/78
DATE RCVD: 03/07/78

DOCTYPE: LETTER NOTARIZED: NO
SUBJECT:

COPIES RECEIVED
LTR 0 ENCL 1

LICENSEE EVENT REPT (RO 50-220/78-06) ON 01/27/78 CONCERNING
PERFORMANCE OF SURVEILLANCE TEST IC-75 FOUND A TRIP SETPOINT OF
22.5 INCHES WATER ON ONE VACUUM SWITCH IN THE VACUUM RELIEF SYSTEM
FROM THE PRESSURE SUPPRESSION CHAMBER TO THE RX BLDG (68-12B).

PLANT NAME: NINE MILE PT - UNIT 1

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL: DL

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF LEARN/4 ENCL

INTERNAL: REG FILE**W/ENCL
I & E**W/2 ENCL
SCHROEDER/IPPOLITO**W/ENCL
NOVAK/CHECK**W/ENCL
KNIGHT**W/ENCL
HANAUER**W/ENCL
EISENHUT**W/ENCL
SHAO**W/ENCL
KREGER/J. COLLINS**W/ENCL
K SEYFRIT/IE**W/ENCL

NRC PDR**W/ENCL
MIPC**W/3 ENCL
HOUSTON**W/ENCL
GRIMES**W/ENCL
BUTLER**W/ENCL
TEDESCO**W/ENCL
BAER**W/ENCL
VOLLMER/BUNCH**W/ENCL
ROSA**W/ENCL

EXTERNAL: LPDR'S
OSWEGO, NY**W/ENCL
TIC**W/ENCL
NSIC**W/ENCL
ACRS CAT B**W/16 ENCL

DISTRIBUTION: LTR 45 ENCL 45
SIZE: 1P+1P

CONTROL NBR: 780680044

***** THE END *****

THEY ARE THE ONLY TWO WHO HAVE BEEN

THEY ARE THE ONLY TWO WHO HAVE BEEN

THEY ARE THE ONLY TWO WHO HAVE BEEN

THEY ARE THE ONLY TWO WHO HAVE BEEN

THEY ARE THE ONLY TWO WHO HAVE BEEN

THEY ARE THE ONLY TWO WHO HAVE BEEN

THEY ARE THE ONLY TWO WHO HAVE BEEN

THEY ARE THE ONLY TWO WHO HAVE BEEN

THEY ARE THE ONLY TWO WHO HAVE BEEN

THEY ARE THE ONLY TWO WHO HAVE BEEN

THEY ARE THE ONLY TWO WHO HAVE BEEN

THEY ARE THE ONLY TWO WHO HAVE BEEN

THEY ARE THE ONLY TWO WHO HAVE BEEN

REGULATORY DOCKET ~~101~~ COPY.

NMP-0124

NIAGARA MOHAWK POWER CORPORATION/300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202/TELEPHONE (315) 474-1511

February 24, 1978

Mr. Boyce H. Grier
Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406

RE: Docket No. 50-220

Dear Mr. Grier:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specifications, we hereby submit Licensee Event Report LER 78-06, which is in violation of Section 3.3.6.F of the Technical Specifications.

This report was completed in the format designated in NUREG-0161, dated July 1977.


Very truly yours,

ORIGINAL SIGNED BY R.R. SCHNEIDER

R.R. Schneider
Vice President -
Electric Production

mtm
Attachments (3)

xc: Director, Office of I&E (30 copies)
Director, Office of MIPC (3 copies)



780680044

A002/s *
91

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	2	0	7	0	1	2	7	7	8	8	0	2	2	4	7	8	9
60	61									68	69						74	75						80
DOCKET NUMBER										EVENT DATE										REPORT DATE				

02 | During steady state operation, performance of surveillance test IC-75

03 | found a trip setpoint of 22.5 inches water on one vacuum switch in the

04 | vacuum relief system from the pressure suppression chamber to the Rx

05 | Building (68-12B). T.S. 3.3.6.F requires a setpoint less than or equal

06 | to 0.5 psig (13.85 inches water). This condition resulted in minimal

07 | safety implications. A redundant switch was available to initiate

08 | operation of the vacuum relief valve.

0 9		SYSTEM CODE S A		CAUSE CODE E		CAUSE SUBCODE E		COMPONENT CODE I N S T R U						COMP. SUBCODE S		VALVE SUBCODE Z													
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23													
LER/RO REPORT NUMBER		EVENT YEAR 7 8		SEQUENTIAL REPORT NO. 0 0		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0		ACTION TAKEN E		FUTURE ACTION Z		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. Y		PRIME COMP. SUPPLIER N		COMPONENT MANUFACTURER M 2 3 5	
24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53

1 0 | The cause of the failure was instrument drift in a mercoird model CP4122

1 1 | vacuum switch. Trip setpoint was reset to 6.8 inches water. Current

1 2 | surveillance testing schedules are adequate to ensure early detection

1 3 | of future instrument drifts.

1	4											80			
7	8	9											80		
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION						80	
1	5	E	28	0	9	6	29	NA	B	31	Surveillance Testing				80
7	8	9	10	11	12	13	14	15	16	17	18	19	20	80	
ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE						80	
1	6	Z	33	Z	34	NA		NA						80	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	80	
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION								80	
1	7	0	0	0	37	Z	38	NA						80	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	80	
PERSONNEL INJURIES		NUMBER		DESCRIPTION										80	
1	8	0	0	0	40	NA								80	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	80	
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION										80	
1	9	Z	42	NA										80	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	80	
PUBLICITY ISSUED		DESCRIPTION												80	
2	0	1	N	44	NA										80
													NRC USE ONLY		
<div style="display: flex; justify-content: space-between;"> 1 2 3 4 5 6 7 8 9 0 1 2 3 4 5 6 7 8 9 0 </div>															

NRC USE ONLY

NAME OF PREPARER Dennis MacVittie

PHONE: 315-343-2110 ext. 1558

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58	

REPORT
SOURCE

0	1	REPORT SOURCE															DOCKET NUMBER															EVENT DATE															REPORT DATE														
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																																							
		L	6	0	5	0	0	0	2	2	0	7	0	1	2	7	7	8	8	0	2	2	4	7	8	9																																			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During steady state operation, performance of surveillance test IC-75

0 3 | found a trip setpoint of 22.5 inches water on one vacuum switch in the

0 4 | vacuum relief system from the pressure suppression chamber to the Rx

0 5 | Building (68-12B). T.S. 3.3.6.F requires a setpoint less than or equal

0 6 | to 0.5 psig (13.85 inches water). This condition resulted in minimal

0 7 | safety implications. A redundant switch was available to initiate

0 8 | operation of the vacuum relief valve.

SYSTEM CODE S A 11		CAUSE CODE E 12		CAUSE SUBCODE E 13		COMPONENT CODE I N S T R U 14				COMP. SUBCODE S 15		VALVE SUBCODE Z 16					
EVENT YEAR 17 18		SEQUENTIAL REPORT NO. 006		OCCURRENCE CODE 03		REPORT TYPE L		REVISION NO. 0									
ACTION TAKEN E 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0000 22		ATTACHMENT SUBMITTED N 23		NPRD-4 FORM SUB. Y 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER M 23 5 26	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of the failure was instrument drift in a mercoid model CP4122

1 1 | vacuum switch. Trip setpoint was reset to 6.8 inches water. Current

1 2 | surveillance testing schedules are adequate to ensure early detection

1 3 | of future instrument drifts.

1	4	
7	8	80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
1	5	E	28	0	9	6	29	NA	B	31	Surveillance Testing	32
7	8	9	10	11	12	13	14	15	16	17	18	19

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)
1 6 Z (33) Z (34) NA
7 8 9 10 11 44
NA LOCATION OF RELEASE (36)
45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z	(38) NA	(39)		

PERSONNEL INJURIES										
NUMBER				DESCRIPTION (41)						
1	2	0	0	0	(40)	NA				

		LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE		DESCRIPTION		
1	9	Z	(42)	NA

PUBLICITY		NRC USE ONLY	
ISSUED	DESCRIPTION		
NA	(45)		

NRC USE ONLY

NAME OF PREPARER Dennis MacVittie

PHONE: 315-343-2110 ext. 1558

1-928

TELECOPY MESSAGE

TO: 215-337-1150 FROM: 315-343-2110 DATE/TIME 2/21/78 - 1610
Telephone Number Telephone Number

TO: Director of Regulatory Operation
USNRC Region 1
631 Park Avenue
King of Prussia, PA. 19406

From: Niagara Mohawk Power Corporation
Nine Mile Point Nuclear Station
Unit #1
P.O. Box #32
Lycoming, New York 13093

SUBJECT: PROMPT REPORTABLE OCCURRENCE
DOCKET NO. 50-220 LICENSE NO. DPR-63
ASSIGNED LER NO. 78-09

EVENT DATE: 780221 REPORT DATE: 780221

EVENT DESCRIPTION:

SEE ATTACHED.

COMPONENTS INVOLVED: TIP machine shear valve squib devices

CAUSE AND REMEDIAL ACTION: Institution of modification in squib
circuit per GE revision.

FACILITY STATUS: % THERMAL MW 1840

c) Routine Startup _____
d) Routine Shutdown _____
e) Steady State Oper X _____
f) Load Change _____

g) Shutdown _____
h) Refueling _____
i) Other _____
j) Not Applicable _____

A written follow-up report will be sent within two weeks.

TELECOPY TO B.H. Grier FROM T.J. Perkins DATE 2/21/78
R/R/R R/R/R

ATTACHMENT TO LER 78-09

Event Description:

During routine station operation with the TIP detectors withdrawn, replacement explosive charges in the TIP system shear valves were replaced with new charges. Following replacement, it was found that the ohmmeter continuity test for acceptable electric contact was unsatisfactory. The normal TIP tube isolation system was operable at this time.

It was found that the actual electrical connections to the explosive charges were not as described in the maintenance procedure. The shear valves would not have operated to isolate the TIP guide tube with the TIP inserted. Electrical connections will be checked and tested to assure that the explosive valves will operate as described in the operating procedures. Station records, including the maintenance procedures, will be corrected to reflect the correct wiring connections. An end-to-end demonstration of the explosive shear valves will be performed with the explosive charge removed from the system. Corrective action will be completed before the TIP system is again used.

The explosive operated TIP shear isolation valves are a back-up system to be used for isolation of the TIP tubes in the event it is not possible to withdraw the detector so the normal automatic isolation system may function.

