

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9002160137 DOC.DATE: 90/02/05 NOTARIZED: NO DOCKET #  
 FACIL:50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv 05000387  
 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylv 05000388

AUTH.NAME AUTHOR AFFILIATION  
 KEISER,H.W. Pennsylvania Power & Light Co.  
 RECIP.NAME RECIPIENT AFFILIATION  
 GALLO,R.M. Region 1, Ofc of the Director

SUBJECT: Responds to NRC 900105 ltr re violations noted in Insp Repts  
 50-387/89-01 & 50-388/89-01.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR ( ENCL 1 SIZE: 4  
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:LPDR 1 cy Transcripts. 05000387  
 LPDR 1 cy Transcripts. 05000388

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD1-2 PD	1 1	THADANI,M	1 1
INTERNAL: ACRS	2 2	AEOD	1 1
AEOD/DEIIB	1 1	AEOD/TPAD	1 1
DEDRO	1 1	NRR SHANKMAN,S	1 1
NRR/DLPQ/LPEB10	1 1	NRR/DOEA DIR 11	1 1
NRR/DREP/PEPB9D	1 1	NRR/DREP/PRPB11	2 2
NRR/DRIS/DIR	1 1	NRR/DST/DIR 8E2	1 1
NRR/PMAS/ILRB12	1 1	NUDOCS-ABSTRACT	1 1
OE LIEBERMAN,J	1 1	OGC/HDS2	1 1
REG FILE 02	1 1	RES MORISSEAU,D	1 1
RGN1 FILE 01	1 1		
EXTERNAL: LPDR	1 1	NRC PDR	1 1
NSIC	1 1		

NOTES: 2 2

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 28 ENCL 28

R  
I  
D  
S  
/  
A  
D  
D  
S  
  
R  
I  
D  
S  
/  
A  
D  
D  
S



# Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215/770-5151

Harold W. Keiser  
Senior Vice President-Nuclear  
215/770-4194

FEB 05 1990

Mr. Robert M. Gallo, Chief  
Operations Branch  
Division of Reactor Safety  
U.S. Nuclear Regulatory Commission  
Region I  
475 Allendale Road  
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION  
RESPONSE TO NOTICE OF VIOLATION  
(387/89-33; 388/89-31)  
PLA-3336 FILES R41-1C, R41-2

Docket Nos. 50-387  
and 50-388

Dear Mr. Gallo:

This letter provides Pennsylvania Power & Light Company's response to the Notice of Violation for NRC Combined Inspection Report 50-387/89-33 and 50-388/89-31 dated January 5, 1990.

The notice required submittal of a written reply within thirty (30) days of the date of the letter. We trust that the commission will find the attached response acceptable.

Very truly yours,

H. W. Keiser

Attachment

cc: NRC Document Control Desk (original)  
NRC Region I  
Mr. G. S. Barber, NRC Sr. Resident Inspector  
Mr. M. C. Thadani, NRC Project Manager

9002160137 900205  
PDR ADUCK 05000387  
Q PDC

1E01  
11

## RESPONSE TO NOTICE OF VIOLATION

### VIOLATION (388/89-31-01)

Technical Specification 4.0.5, specifies that inservice testing of pumps shall be performed in accordance with Section XI of the ASME Boiler and Pressure Vessel Code.

Section XI of the ASME Boiler and Pressure Vessel Code, Article IWP-3000, Inservice Test Program paragraph IWP-3230(b) specifies that if test quantities fall within the required action range, the pump shall be declared inoperative and not returned to service until the cause of the deviation has been determined and the condition corrected.

Contrary to the above, during the performance of surveillance testing, conducted on March 28, 1989, of residual heat removal service water pump 2P506B, when the differential pressure test quantity of 77.6 PSID fell within the required action range (above the acceptance range of 65 - 71 PSID) the pump was declared operable and returned to service without the cause of the deviation being determined.

### RESPONSE:

#### 1. Reason for the Violation If Admitted:

PP&L does not contest that during the performance of surveillance testing, conducted on March 28, 1989, of residual heat removal service water pump 2P506B, when the differential pressure test quantity of 77.6 PSID fell within the required action range (above the acceptance range of 65 - 71 PSID) the pump was declared operable and returned to service without a final cause of the deviation being formally determined and dispositioned. As the deviation involved a differential pressure being higher than the capability of the pump as defined in the pump's head curve, evaluations performed immediately following the Residual Heat Removal Service Water (RHRSW) system flow verification deviation determined that the pump was operable. These evaluations were consistent with the intent of the ASME Code.

The purpose of the quarterly flow verification surveillance is to determine pump degradation. High values of the performance test quantities are not indicative of pump degradation. Rather, they are indicative of instrumentation or system changes. Such anomalies warrant prompt investigation and resolution; but in no way justify any declaration of pump inoperability. PP&L will therefore submit a relief request which will allow for the cause of the deviation to be determined expeditiously as possible and either the causative condition will be corrected prior to successful completion of the affected test or else corrective action taken per IWP-3230(c).

**2. Corrective Steps Which Have Been Taken and the Results Achieved**

The flow deviation on March 28, 1989, was immediately recognized as one requiring corrective action, in accordance with ASME Code Section XI, IWP-3230(b) and (c) requirements, and the following actions were taken.

- a) The subject pump remained in an inoperable status until the cause of the deviation had been determined per IWP-3230 and until the condition had been corrected by the method of analysis demonstrating that the condition did not impair pump operability and that the pump would still perform its design function.
- b) The observed deviation indicated an improvement in pump performance of 400 gpm. It was confirmed that no significant work had been done to the pump since its previous test, and no physical mechanism exists for performance of the pump to improve by itself. Comparison of pump head data to the design pump curve and vibration measurements to those of previous tests confirmed the continuing good performance of the pump. PP&L therefore concluded that the pump was not the source of the deviation.
- c) Test instrument calibration checks performed shortly following the test showed the instruments to be indicating accurately.
- d) PP&L considers the cause of the indicated flow deviation to be attributable to possible fouling of the flow element installed inside the 26" RHRSW system piping. Our determination, however, could not be conclusively established due to the inability to drain and inspect the RHRSW system which may require the shutdown of both Unit 1 and Unit 2.

3. Corrective Steps Which Will Be Taken to Avoid Further Violations

No further action is required.

4. Date of Full Compliance

Based on the above, PP&L is in full compliance.