

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N Y N M P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T
01 REPORT SOURCE L 6 0 5 0 0 0 2 2 0 7 0 9 1 8 7 9 8 1 0 0 1 7 9 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 Found one seismic constraint on containment spray system outside
03 the primary containment was not installed as required by construction
04 drawings.
05
06
07
08

09 SYSTEM CODE S A 11 CAUSE CODE B 12 CAUSE SUBCODE F 13 COMPONENT CODE X X X X X X 14
7 8 9 10 11 12 13 18 19 20 15 16
17 LER-RO REPORT NUMBER 7 9 21 22 23 24 25 26 27 28 29 30 31 32 REVISION NO. 0
18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
ACTION FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
A 18 A 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 X 25 Z 9 9 9 9 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Not installed at construction. Initiated design and order to install
11 constraint. Declared applicable containment spray loop inoperable.
12 Performing redundant loop operability test as required by technical
13 specifications.
14

15 FACILITY STATUS E 28 % POWER 0 9 4 29 OTHER STATUS 30 METHOD OF DISCOVERY C 31 DISCOVERY DESCRIPTION 32
7 8 9 10 12 13 44 45 46 80

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
7 8 9 10 11 44 45 80

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
7 8 9 11 12 13 80

18 PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8 9 11 12 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
7 8 9 10 80

20 PUBLICITY ISSUED DESCRIPTION 45
7 8 9 10 80

NAME OF PREPARER L.S. Sun

79101 00 384
NRC USE ONLY
PHONE: (315) 343-2110 X1506

NIAGARA MOHAWK POWER CORPORATION/300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202/TELEPHONE (315) 474-1511

October 1, 1979

Mr. Boyce H. Grier
Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406

RE: Docket No. 50-220
LER 79-022/T-0

Dear Mr. Grier:

On September 18, 1979, during the course of the current piping system examination per NRC I.E. Bulletin 79-14, it was discovered that one (1) seismic constraint, 80-SC-28, on one (1) of four (4) Containment Spray Piping Systems, had not been installed during plant construction. The effected loop was immediately declared inoperable, the appropriate redundant component surveillance was performed, and a work order was issued for fabrication and installation of the restraint. On September 19, 1979, the Commission was informed of the event by telecopy message, and work on the restraint had commenced.

A review of data from NRC I.E. Bulletin 79-02 restraint inspection of this piping system revealed that the subject constraint had been noted on the piping isometric inspection sheet with a "circle", however, was not identified on the drawing by the inspection team with the word "missing". Subsequently, in the review of this data for 79-02 purposes, this deficiency was inadvertently missed.

On September 20, 1979, an Engineering Evaluation was performed. It was determined that the piping system material strengths would withstand the design basis seismic event stresses without 80-SC-28 seismic constraint being installed. However, installation of the constraint was progressing as scheduled, and work was completed on September 21, 1979.

Very truly yours,

R.R. Schneider
Vice President -
Electric Production

mtm