

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	14						15	25										26	30					57	CAT 53			
		LICENSEE CODE							LICENSE NUMBER											LICENSE TYPE									

CON'T

REPORT SOURCE L 6 0 5 0 0 0 2 2 0 7 0 8 2 7 8 0 8 0 9 0 9 8 0 9

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 SEE ATTACHED

03

Q 4

0	5
---	---

0	6
---	---

0	7
---	---

08

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	CONF. SUBCODE	VALVE SUBCODE
----------------	---------------	------------------	----------------	------------------	------------------

0 9
 X X (11)
 B (12)
 C (13)
 P E N E T R (14)
 C (15)
 Z (16)

(17) LER-RO REPORT NUMBER

EVENT YEAR			SEQUENTIAL REPORT NO.				OCCURRENCE CODE			REPORT TYPE		REVISION NO.
8	0	—	0	1	9	/	0	4	T	—	0	
21	22	23	24	25	26	27	28	29	30	31	32	

ACTION . FUTURE TAKEN ACTION		EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	APRD-4 FORM 425.	DRIVE COUP. SUPPLIER	COMPONENT MANUFACTURER
B	15	2	Z	0 0 0 0	N	N	L	P 1 1 0
23	24	25	26	37	41	42	43	44

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

110 | SEE ATTACHED

1 1

017

[illegible][illegible]

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
(1) 5 E (28)	0 9 9 (29)	N/A (30)	C (31)	STATION NRC INSPECTION (32)

ACTIVITY		CONTENT		RELEASED		OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	6	2	33	2	34	N/A		N/A		N/A	
7	8	9	10	11	12	13	14	15	16	17	18

PERSONNEL EXPOSURES				DESCRIPTION	
NUMBER	TYPE	DESCRIPTION	39		
17	000(37)	Z(38)	N/A		

7	8	9	10	11	12	13	14	15	16	17	18	19	20
PERSONNEL INJURIES													
NUMBER			DESCRIPTION (41)										

I	R
7	9
0	0
0	(30)
N/A	

1		9		Z		N/A	

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

PUBLICITY

ISSUED DESCRIPTION (45)

8009180278

NRC USE ONLY

Paul Harrison

PHONE: (315) 343-2110, ext. 1212

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

During normal operation an NRC inspector observed light shining through an apparent gap under the outer door of the Reactor building track bay. Immediate investigation by station management and the Inspector revealed that the removable bottom door seals had not properly been installed after the last closure of the door. At the time, the inner door of the track bay was open; thus, secondary containment integrity was dependent upon the outer door. However, since the reactor was at steady state operation during this time period, there was no apparent effect on the environment.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

In order to ensure secondary containment integrity, the inner track bay door was promptly closed and action was initiated to properly install the outer door seals. Failure to properly install the seals was a procedural violation, and thus the procedure was subsequently reviewed with the personnel involved with the incident as well as with other persons who may have cause for its use in the future.

