

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 H Y N M P 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 4 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

01 REPORT SOURCE L 0 5 0 0 0 2 2 0 7 1 2 1 6 8 0 8 1 2 3 0 8 0 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation, an unnecessary amount of air was observed  
03 venting from #11 Feedwater Flow Control Valve Pneumatic  
04 positioner unit. This showed no immediate effect on valve operation  
05 but maintenance action was instituted. To allow corrective maintenance  
06 this valve was manually closed which rendered the #11 Feedwater/HPCI  
07 branch out of service for the maintenance period. This resulted in no  
08 adverse affects on safe plant operation.  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

09 SYSTEM CODE C H 11 CAUSE CODE X 12 CAUSE SUBCODE Z 13 COMPONENT CODE V A L V O P 14 COMP. SUBCODE 0 15 VALVE SUBCODE Z 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
17 LEAD REPORT NUMBER 18 19 EVENT YEAR 20 21 22 SEQUENTIAL REPORT NO. 23 24 25 OCCURRENCE CODE 26 27 28 REPORT TYPE 29 30 31 REVISION NO. 32 33  
ACTION TAKEN 34 FUTURE ACTION 35 EFFECT ON PLANT 36 SHUTDOWN METHOD 37 38 HOURS 39 40 ATTACHMENT SUBMITTED 41 N/A 42 N/A 43 N/A 44 COMPONENT MANUFACTURER 45 F I T 3 0  
18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Upon disassembly of the pneumatic relay portion, rubber goods were  
11 found worn and cracked. Subsequently, the rubber goods were replaced  
12 with operability testing showing satisfactory corrective maintenance  
13 results. Long term preventative action involves Operation's continuous  
14 equipment monitoring and a scheduled testing and overhaul program of  
15 this valve positioner equipment.  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

15 FACILITY STATUS E 28 0 8 2 29 N/A METHOD OF DISCOVERY C 31 Operator Observation  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

16 ACTIVITY CONTENT RELEASED OR RELEASE Z 23 24 N/A AMOUNT OF ACTIVITY 35 N/A LOCATION OF RELEASE 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION 39 N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION 41 N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION 43 N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 PUBLICITY ISSUED N 44 DESCRIPTION 45 N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

8101120

369

NRC USE ONLY

NAME OF PREPARER

P. Harrison

PHONE: (315-343-2110)

