

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	9						14	15	L											25	26	L				30	57	CAT	58		5
		LICENSEE CODE							LICENSE NUMBER													LICENSE TYPE										

CON'T

0	1	REPORT SOURCE										L	6	0	5	0	0	0	2	2	0	7	0	1	0	7	8	1	8	0	2	0	6	8	1	9												
7	8											60	61	DOCKET NUMBER										68	69	EVENT DATE										74	75	REPORT DATE										80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation, while performing the monthly surveillance, an Emergency
0 3 | Diesel Generator output breaker tripped on excessive current due to failure of the
0 4 | generator voltage regulator. This had no adverse affect on safety since the alter-
0 5 | nate Emergency Diesel Generator was proven operable.
0 6 |
0 7 |
0 8 |
7 8 9

SYSTEM CODE E E 11		CAUSE CODE X 12		CAUSE SUBCODE Z 13		COMPONENT CODE I N S T R U 14				COMP. SUBCODE C 15		VALVE SUBCODE Z 16					
LER/RO REPORT NUMBER 17		EVENT YEAR 8 1 21 22		SEQUENTIAL REPORT NO. 0 0 1 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32							
ACTION TAKEN A 33		FUTURE ACTION X 34		EFFECT ON PLANT Z 35		SHUTDOWN METHOD Z 36		HOURS 0 0 0 0 37 40		ATTACHMENT SUBMITTED N 41		NPRD-4 FORM SUB. N 42		PRIME COMP. SUPPLIER I 43		COMPONENT MANUFACTURER C 1 0 0 0 44 47	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Investigation found that pieces of bailing wire used in the area to attach frames for
1 1 structural fire proofing had fallen on top of the control cabinet and through the
1 2 protective screen. Evidence of shorting was found at the voltage regulator control
1 3 circuit contacts, causing the protective fuse to blow and consequently failure of the
1 4 voltage regulator. After correction of this condition, operability of (SEE OVER)

FACILITY STATUS		% POWER		OTHER STATUS (30)		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION (32)			
1	5	E	(23)	0	9	1	(29)	N/A	B	(31)	Surveillance Testing Event
7	8	9		10	11	12	13	14	15	16	17

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) Z (34) N/A N/A

7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z	(38) N/A	(39)		

PERSONNEL INJURIES		NUMBER		DESCRIPTION (41)	
1	8	0	0	0	(40) N/A

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53																																																							

PUBLICITY		ISSUED		DESCRIPTION	NRC USE ONLY
2	0	(44)		N/A	

NRC USE ONLY

8102200590

NAME OF PREPARER Paul Harrison

PHONE: ~~(315) 343-2110, ext. 1212~~

000 017-038

FEB 23 1981

this generator was satisfactorily performed. Potential situations of this nature will be scrutinized for preventative measures during subsequent construction work in areas of vulnerable safety equipment.

FEB 11 2 39 PM '81

018392