

LICENSEE EVENT REPORT

CONTROL BLOCK:										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)									
<div> <div>01</div> <div>M I P A L L</div> <div>200-00000-000</div> <div>341111</div> <div>4</div> <div>5</div> </div>										<div> <div>LICENSEE CODE</div> <div>LICENSE NUMBER</div> <div>LICENSE TYPE</div> <div>CAT 58</div> </div>									
<div> <div>CON'T</div> <div>01</div> </div>										<div> <div>REPORT SOURCE</div> <div>6005000255701037980201799</div> <div>DOCKET NUMBER</div> <div>EVENT DATE</div> <div>REPORT DATE</div> </div>									
<div> <div>EVENT DESCRIPTION AND PROBABLE CONSEQUENCES</div> <div>10</div> </div>										<div> <div>During normal plant operation, steam generator (SG) specific conductivity increased to 7.65 micro-mho per cm. SG blowdown rate was increased, and morpholine/hydrazine feedrate was decreased. Conductivity was returned to the limits of TS 3.18 in 8.5 hours. No hazard to public health or safety existed.</div> </div>									
<div> <div>03</div> </div>										<div> <div>increased to 7.65 micro-mho per cm. SG blowdown rate was increased, and morpholine/hydrazine feedrate was decreased. Conductivity was returned to the limits of TS 3.18 in 8.5 hours. No hazard to public health or safety existed.</div> </div>									
<div> <div>04</div> </div>										<div> <div>increased to 7.65 micro-mho per cm. SG blowdown rate was increased, and morpholine/hydrazine feedrate was decreased. Conductivity was returned to the limits of TS 3.18 in 8.5 hours. No hazard to public health or safety existed.</div> </div>									
<div> <div>05</div> </div>										<div> <div>increased to 7.65 micro-mho per cm. SG blowdown rate was increased, and morpholine/hydrazine feedrate was decreased. Conductivity was returned to the limits of TS 3.18 in 8.5 hours. No hazard to public health or safety existed.</div> </div>									
<div> <div>06</div> </div>										<div> <div>increased to 7.65 micro-mho per cm. SG blowdown rate was increased, and morpholine/hydrazine feedrate was decreased. Conductivity was returned to the limits of TS 3.18 in 8.5 hours. No hazard to public health or safety existed.</div> </div>									
<div> <div>07</div> </div>										<div> <div>increased to 7.65 micro-mho per cm. SG blowdown rate was increased, and morpholine/hydrazine feedrate was decreased. Conductivity was returned to the limits of TS 3.18 in 8.5 hours. No hazard to public health or safety existed.</div> </div>									
<div> <div>08</div> </div>										<div> <div>increased to 7.65 micro-mho per cm. SG blowdown rate was increased, and morpholine/hydrazine feedrate was decreased. Conductivity was returned to the limits of TS 3.18 in 8.5 hours. No hazard to public health or safety existed.</div> </div>									
<div> <div>09</div> </div>										<div> <div>SYSTEM CODE</div> <div>CAUSE CODE</div> <div>CAUSE SUBCODE</div> <div>COMPONENT CODE</div> <div>COMP. SUBCODE</div> <div>VALVE SUBCODE</div> </div>									
<div> <div>17</div> <div>LER/RO REPORT NUMBER</div> <div>EVENT YEAR</div> <div>SEQUENTIAL REPORT NO.</div> <div>OCCURRENCE CODE</div> <div>REPORT TYPE</div> <div>REVISION NO.</div> </div>										<div> <div>11</div> <div>12</div> <div>13</div> <div>14</div> <div>15</div> <div>16</div> </div>									
<div> <div>18</div> <div>19</div> <div>20</div> <div>21</div> <div>22</div> <div>23</div> <div>24</div> <div>25</div> <div>26</div> <div>27</div> <div>28</div> <div>29</div> <div>30</div> <div>31</div> <div>32</div> </div>										<div> <div>17</div> <div>18</div> <div>19</div> <div>20</div> <div>21</div> <div>22</div> <div>23</div> <div>24</div> <div>25</div> <div>26</div> <div>27</div> <div>28</div> <div>29</div> <div>30</div> <div>31</div> <div>32</div> </div>									
<div> <div>33</div> <div>34</div> <div>35</div> <div>36</div> <div>37</div> <div>38</div> <div>39</div> <div>40</div> <div>41</div> <div>42</div> <div>43</div> <div>44</div> <div>45</div> <div>46</div> <div>47</div> </div>										<div> <div>33</div> <div>34</div> <div>35</div> <div>36</div> <div>37</div> <div>38</div> <div>39</div> <div>40</div> <div>41</div> <div>42</div> <div>43</div> <div>44</div> <div>45</div> <div>46</div> <div>47</div> </div>									
<div> <div>CAUSE DESCRIPTION AND CORRECTIVE ACTIONS</div> <div>27</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>10</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>11</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>12</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>13</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>14</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>15</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>16</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>17</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>18</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>19</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>20</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>21</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>22</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>23</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>24</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>25</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>26</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air inleakage was subsequently reduced to an acceptable level.</div> </div>									
<div> <div>27</div> </div>										<div> <div>Air inleakage to the main condenser, combined with morpholine/hydrazine chemical control, may have resulted in the conductivity increase. The immediate corrective action taken is described above. The air</div></div>									

7902060335