

50-335

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

INCIDENT REPORT

TO: Mr. Norman C. Moseley		FROM: Florida Power & Light Company Miami, Florida A. D. Schmidt		DATE OF DOCUMENT 3/18/77
<input checked="" type="checkbox"/> LETTER <input checked="" type="checkbox"/> ORIGINAL <input checked="" type="checkbox"/> COPY		<input type="checkbox"/> NOTORIZED <input checked="" type="checkbox"/> UNCLASSIFIED		DATE RECEIVED 4/1/77
PROP		INPUT FORM		NUMBER OF COPIES RECEIVED 1 signed

DESCRIPTION

Ltr. trans the following:

ACKNOWLEDGED

PLANT NAME:

St. Lucie Unit No. 1

(1-P)

RJL

DO NOT REMOVE

ENCLOSURE

Licensee Event Report (RO 50-335/77-10) on 2/17/77 concerning an alarm being received in the control room indicating the circuit breaker for the "C" steam driven auxiliary feedwater pump steam valve control circuit tripped.....

(2-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

BRANCH CHIEF:	<i>Ziemann</i>
W/3 CYS FOR ACTION	
LIC. ASST.:	<i>Disss</i>
W/7 CYS	
ACRS	<i>16 CYS HOLDING/SENT AS CAT B</i>

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE				
NRC PDR				
T & E (2)				
MIPC				
SCHROEDER/IPPOLITO				
HOUSTON				
NOVAK/CHECK				
GRIMES				
CASE				
BUTLER				
HANAUER				
TEDESCO/MACCARY				
EISENHUT				
BAER				
SHAO				
VOLLMER/BUNCH				
KREGER/J. COLLINS				

EXTERNAL DISTRIBUTION

LPDR: <i>Ft Pierce Plant</i>				
TIC:				
NSIC:				

CONTROL NUMBER



77-01940107

A04
50

1944

1944

1944



March 18, 1977

PRN-LI-77-72

REGULATORY DOCKET FILE COPY

Mr. Norman C. Moseley, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 1217
Atlanta, Georgia 30303

Dear Mr. Moseley:

REPORTABLE OCCURRENCE 335-77-10
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: FEBRUARY 17, 1977
STEAM DRIVEN AUXILIARY FEEDWATER PUMP

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

for J.R. Benson
A. D. Schmidt
Vice President
Power Resources

MAS/cpc

Attachment

cc: Robert Lowenstein, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)

77940107

THE UNIVERSITY OF CHICAGO

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME 01 F L S L S 1	LICENSE NUMBER 0 0 - 0 0 0 0 0 - 0 0	LICENSE TYPE 4 1 1 1 1	EVENT TYPE 0 3
CATEGORY 01 CONT	REPORT TYPE L	REPORT SOURCE L	DOCKET NUMBER 0 5 0 - 0 3 3 5
EVENT DATE 0 2 1 7 7 7	REPORT DATE 0 3 1 4 7 7		

EVENT DESCRIPTION

02 | During normal plant operation, an alarm received in the control room indicated the
03 | circuit breaker for the "C" steam driven auxiliary feedwater pump steam valve control
04 | circuit had tripped. Inspection of the circuit showed a shorted terminal in the speed
05 | sensing and control circuit. The shorted terminal was repaired and the turbine speed
06 | controller replaced.

SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
07 H H	B	C K T B R K	A	W 2 9 0	N

CAUSE DESCRIPTION

08 | The steam valve control circuit breaker for the steam driven auxiliary feedwater pump
09 | tripped due to a shorted terminal caused by moisture buildup in a control box.
10 |

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
11 B	0 9 0	NA	A	NA

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
12 Z	Z	NA	NA

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
13 0 0 0	Z	NA

PERSONNEL INJURIES

NUMBER	DESCRIPTION
14 0 0 0	NA

PROBABLE CONSEQUENCES

15	NA
--	--

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION
16 Z	NA

PUBLICITY

17	NA
--	--

ADDITIONAL FACTORS

18	See page two for continuation of Event Description.
--	---

19	
--	--

NAME: M. A. Schoppman

PHONE: 305/552-3779

REPORTABLE OCCURRENCE 335-77-10
LICENSEE EVENT REPORT
PAGE TWO

EVENT DESCRIPTION (Continued)

During the time the "C" auxiliary feedwater pump was out of service, both electric-driven auxiliary feedwater pumps were operable as required by Technical Specification 3.7.1.2. The "C" auxiliary feedwater pump was returned to operable status within 72 hours as required by the Technical Specification.

This was the fifth reportable occurrence associated with the steam driven auxiliary feedwater pump. Two previous occurrences involved an open circuit in a solder joint (335-76-11) and a wiring diagram error (335-76-13) and are unrelated. The other three occurrences (335-76-22, 335-76-36 and 335-76-47) are related in that they involve control circuit corrosion. Action taken since the last reportable occurrence (335-76-47) has been the completion of rerouting of nearby steam drains away from the vicinity of the turbine.

Other means of long term corrective action are being studied. One possibility under consideration to further correct the situation is to replace the present junction boxes and relocate them to a position off the turbine, making them less susceptible to the effects of heat and moisture buildup. This will require a cold shutdown of the plant of sufficient duration to permit accomplishment. (335-77-10).

RECEIVED DOCUMENT
PROCESSING UNIT

1977 APR 1 PM 2 49