

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

A number line starting at 1 and ending at 6. There are 5 equal intervals between the numbers. A circled 1 is next to the line.

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---------------|---|---|---|---|---|----|----------------|---|---|---|---|---|---|---|---|---|----|--------------|---|---|---|---|----|-----|--|----|---|
| 0 | 1 | V | A | S | P | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | | 5 |
| 7 | 8 | LICENSEE CODE | | | | | | 14 | LICENSE NUMBER | | | | | | | | | | 25 | LICENSE TYPE | | | | | 30 | CAT | | 58 | |

CON'T

| | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---------------|----|---------------|---|---|---|---|---|---|---|----|----|------------|---|---|---|----|----|-------------|---|---|---|----|---|---|
| 0 | 1 | REPORT SOURCE | | | | | | | | | | | | | | | | | | | | | | | | |
| 7 | 8 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 8 | 0 | 7 | 0 | 9 | 2 | 7 | 7 | 8 | 8 | 1 | 0 | 1 | 7 | 7 | 8 | 9 |
| | | 60 | 61 | DOCKET NUMBER | | | | | | | | 68 | 69 | EVENT DATE | | | | 74 | 75 | REPORT DATE | | | | 80 | | |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During periodic testing, Channel II Pressurizer Pressure (Protection) P-456 failed
0 3 | high. This is contrary to Technical Specifications 3.7.B, because the required
0 4 | degree of redundancy was not maintained. This event is reportable as per Technical
0 5 | Specification 6.6.2.b.(2).
0 6 |
0 7 |
0 8 |

| | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-------------------|---|----------------------|--------------------|-------------------|-----------------|----------------------|----|--------------------------------|----------------------|----|-------------------------------|------------------------|--|----|---------------------------|------------------|----|-----------------------|-------------------|----|---------------------------|----|----|-----------------------------------|--|----|
| 09 | | SYSTEM CODE I B | | 11 | CAUSE CODE E | | 12 | CAUSE SUBCODE E | | 13 | COMPONENT CODE I N S T R U | | | | | | 14 | COMP. SUBCODE X | | 15 | VALVE SUBCODE Z | | 16 | | | |
| 7 | 8 | 9 | 10 | | 11 | | 12 | | 13 | | | | | | 18 | | 19 | | 20 | | | | | | | |
| 17 | | LER/RO REPORT NUMBER | | EVENT YEAR 7 8 | | 21 | 22 | SEQUENTIAL REPORT NO. 0 2 9 | | 24 | 26 | OCCURRENCE CODE 0 3 | | 28 | 29 | REPORT TYPE L | | 30 | REVISION NO. 0 | | 32 | | | | | |
| ACTION TAKEN A | | 18 | FUTURE ACTION Z | | 19 | EFFECT ON PLANT Z | | 20 | SHUTDOWN METHOD Z | | 21 | HOURS 0 0 0 0 | | 22 | ATTACHMENT SUBMITTED Y | | 23 | NPRD-4 FORM SUB. Y | | 24 | PRIME COMP. SUPPLIER N | | 25 | COMPONENT MANUFACTURER F 1 2 0 | | 26 |
| 33 | | 34 | | 35 | | 36 | | 37 | | | | 40 | | 41 | | 42 | | 43 | | 44 | | 47 | | | | |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 This event was caused by the failure of the Oscillator amplifier module of the transmitter.

1 1 Channel II Pressurizer Pressure and Channel II Overtemperature Delta T were placed in

1 2 trip to provide the required degree of redundancy. The oscillator amplifier was

1 3 replaced, tested and Channel II was returned to service.

1 4

| | | | | | | | | | |
|-------------------------------|---|---------------------|----|--------------------|----|---------------------|----|-----------------------|----|
| FACILITY STATUS | | % POWER | | OTHER STATUS | | METHOD OF DISCOVERY | | DISCOVERY DESCRIPTION | |
| 1 | 5 | E | 28 | 1 | 0 | 0 | 29 | NA | 30 |
| ACTIVITY CONTENT | | RELEASED OF RELEASE | | AMOUNT OF ACTIVITY | | LOCATION OF RELEASE | | | |
| 1 | 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36 |
| PERSONNEL EXPOSURES | | NUMBER | | TYPE | | DESCRIPTION | | | |
| 1 | 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39 |
| PERSONNEL INJURIES | | NUMBER | | DESCRIPTION | | | | | |
| 1 | 8 | 0 | 0 | 0 | 40 | NA | 41 | NA | 42 |
| LOSS OF OR DAMAGE TO FACILITY | | TYPE | | DESCRIPTION | | | | | |
| 1 | 9 | Z | 42 | NA | 43 | NA | 44 | NA | 45 |
| PUBLICITY | | ISSUED | | DESCRIPTION | | | | | |
| 2 | 0 | N | 44 | NA | 45 | NA | 46 | NA | 47 |

NRC USE ONLY

78⁸10⁹20¹⁰0118

NAME OF PREPARER T. L. Baucom

PHONE: (804) 357-3184

Surry Power Station
Docket No: 50-280
Report No: 78-029/03L-0
Event Date: 9-27-78
Failure of Pressurizer Pressure Channel

1. Description of Event:

During periodic testing of Pressurizer Pressure (Protection) instrumentation, PI-456 (Channel II) failed high. The channel had just been tested and removed from the test position when the failure occurred. The High Pressure Reactor Trip Ch. II signal was received.

2. Probable Consequences:

The pressurizer pressure indicator signal feeds the following units: High Pressurizer Pressure Reactor Trip, Low Pressurizer Pressure Reactor Trip, Low Pressure Safety Injection and Overtemperature-Delta T instrumentation. Technical Specifications require a minimum of two (2) operable channels with a degree of redundancy of one (1) for each of these channels. Because the pressure indicator failed high, the minimum degree of redundancy was not retained in the Low Pressurizer Pressure Reactor Trip, Low Pressure Safety Injection, and the Overtemperature Delta T Setpoint instrumentation. This is contrary to Technical Specifications 3.7.B.

3. Cause:

The event was caused by the failure of the Oscillator amplifier module of the pressure transmitter.

4. Immediate Corrective Action:

Immediate corrective action taken was to place the Pressurizer Pressure (Protection) Channel II and the Overtemperature Delta T Channel II in the trip mode. This gave all affected systems the required degree of redundancy. The module was replaced, tested, and the channels returned to normal mode. Because the necessary actions were taken to maintain the required instrument operating conditions, the health and safety of the general public were not affected.

5. Scheduled Corrective Action:

No further corrective action will be required.

6. Action Taken to Prevent Recurrence:

This failure is considered a random event, therefore no further action will be taken.

7. Generic Implications:

None. This is considered to be a random failure.