

208/02/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL

50-335

REC: OREILLY J P
NRC

ORG: SCHMIDT A D
FL PWR & LIGHT

DOCDATE: 07/13/78
DATE RCVD: 07/31/78

DOCTYPE: LETTER NOTARIZED: NO

COPIES RECEIVED

SUBJECT:

LTR 1 ENCL 1

FORWARDING LICENSEE EVENT REPT (RO 50-335/78-022) ON 06/15/78 CONCERNING
DURING PWR OPERATION, THE DIGITAL DATA PROCESSING SYSTEM MANFUNCTIONED, DUE
TO MALFUNCTIONING MULTIPLEXER CARD.

PLANT NAME: ST LUCIE #1

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL: DL

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF ORB#4 BC**W/4 ENCL

INTERNAL:

REG FILE**W/ENCL
I & E**W/2 ENCL
I & C SYSTEMS BR**W/ENCL
NOVAK/CHECK**W/ENCL
AD FOR ENG**W/ENCL
HANAUER**W/ENCL
AD FOR SYS & PROJ**W/ENCL
ENGINEERING BR**W/ENCL
KREGER/J. COLLINS**W/ENCL
K SEYFRIT/IE**W/ENCL

NRC PDR**W/ENCL
MIPC**W/3 ENCL
EMERGENCY PLAN BR**W/ENCL
EEB**W/ENCL
PLANT SYSTEMS BR**W/ENCL
AD FOR PLANT SYSTEMS**W/ENCL
REACTOR SAFETY BR**W/ENCL
VOLLMER/BUNCH**W/ENCL
POWER SYS BR**W/ENCL

EXTERNAL:

LPDR'S
FT PIERCE, FL**W/ENCL
TIC, LIZ CARTER**W/ENCL
NSIC**W/ENCL
ACRS CAT B**W/16 ENCL

DISTRIBUTION: LTR 45 ENCL 45
SIZE: Q

CONTROL NBR: 782140096

***** THE END *****

[The page contains extremely faint, illegible text, likely a scan of a document with very low contrast or significant degradation. Two dark circular marks are visible near the top center.]

REGULATORY DCKET FILE COPY



PRN-LI-78-188

July 13, 1978

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 1217
Atlanta, Georgia 30303

US NRC
DISTRIBUTION SERVICES
BRANCH

1978 JUL 31 AM 10 39

U.S. NUCLEAR REGULATORY COMMISSION
DISTRIBUTION SERVICES UNIT

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 335-78-22
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: JUNE 15, 1978

TECHNICAL SPECIFICATION 3.1.3.3
DIGITAL DATA PROCESSING SYSTEM

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

A. D. Schmidt
A. D. Schmidt
Vice President
Power Resources

MAS/mal

Attachment

cc: Harold F. Reis, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)

782140096

A002
5/11

CONTROL BLOCK:

.					
---	--	--	--	--	--

 ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01			F1LSL1			2000-0000-0000			341114			41		
7 3			9 14 15			25 26			30 31 32 33			37 38 39		
CONT			REPORT SOURCE			EVENT DATE			REPORT DATE					
01			160150000335			706115178			301713178			9		
7 3			60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80			85 86 87 88 89 90			95 96 97 98 99 100					
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)														
02			During power operation, the Digital Data Processing System (DDPS) mal-											
03			functioned. This resulted in loss of CEA backup position indication and											
04			the incore flux detector system used to monitor flux distribution. Ac-											
05			tion required by Specifications 3.1.3.3 and 4.2.1.3 was initiated and											
06			power was reduced. The DDPS was repaired and placed back into service in											
07			two hours. This was the first occurrence involving loss of the DDPS due											
08			to the cause described below in the Cause Description.											
7 3 9			9											
09			SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE											
7 3			9 10 11 12 13 14 15 16											
17			LEA/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.											
7 3			21 22 23 24 25 26 27 28 29 30 31 32											
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER														
18 19 20 21 22 23 24 25 26 27 28 29 30 31 32														
7 3 9			33 34 35 36 37 38 39 40 41 42 43 44 45 46 47											
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)														
10			The cause of the DDPS failure was a malfunctioning multiplexer card.											
11			The card was replaced and the DDPS returned to service in two hours.											
12														
13														
14														
7 3 9			9											
15			FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION											
7 3			10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50											
16			ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE											
7 3 9			10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50											
17			PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION											
7 3 9			10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50											
18			PERSONNEL INJURIES NUMBER DESCRIPTION											
7 3 9			10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50											
19			LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION											
7 3 9			10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50											
20			PUBLICITY ISSUED DESCRIPTION											
7 3 9			10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50											
21			NRC USE ONLY											
7 3 9			10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50											
NAME OF PREPARER M. A. Schoppman PHONE: (305) 552-3802														