

208/02/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL 50-335

REC: OREILLY J P
NRC

ORG: SCHMIDT A D
FL PWR & LIGHT

DOCDATE: 07/07/78
DATE RCVD: 07/31/78

DOCTYPE: LETTER NOTARIZED: NO

COPIES RECEIVED

SUBJECT:

LTR 1 ENCL 1

FORWARDING LICENSEE EVENT REPT (RO 50-335/78-020) ON 06/07/78 CONCERNING
DURING PWR ASCENSION PHYSICS TESTING FOLLOWING A REFUELING OUTAGE, CEA #65
DROPPED... W/ATT.

PLANT NAME: ST LUCIE #1

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL: DL

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF ORB#4 BC**W/4 ENCL

INTERNAL: REG FILE**W/ENCL
I & E**W/2 ENCL
I & C SYSTEMS BR**W/ENCL
NOVAK/CHECK**W/ENCL
AD FOR ENG**W/ENCL
HANAUER**W/ENCL
AD FOR SYS & PROJ**W/ENCL
ENGINEERING BR**W/ENCL
KREGER/J. COLLINS**W/ENCL
K SEYFRIT/IE**W/ENCL

NRC PDR**W/ENCL
MIPC**W/3 ENCL
EMERGENCY PLAN BR**W/ENCL
EEB**W/ENCL
PLANT SYSTEMS BR**W/ENCL
AD FOR PLANT SYSTEMS**W/ENCL
REACTOR SAFETY BR**W/ENCL
VOLLMER/BUNCH**W/ENCL
POWER SYS BR**W/ENCL

EXTERNAL: LPDR'S
FT PIERCE, FL**W/ENCL
TIC, LIZ CARTER**W/ENCL
NSIC**W/ENCL
ACRS CAT B**W/16 ENCL

DISTRIBUTION: LTR 45 ENCL 45
SIZE: 1P+1P+1P

CONTROL NBR: 782140109

***** THE END *****



[The text in this section is extremely faint and illegible due to the quality of the scan. It appears to be several paragraphs of a letter or document.]

REGULATORY DOCKET FILE COPY



July 7, 1978

PRN-LI-78-180

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 1217
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 335-78-20
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: JUNE 7, 1978

TECHNICAL SPECIFICATION 3.1.3.1.e
CEA 65

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

A. D. Schmidt
Vice President
Power Resources

MAS/cpc

Attachment

cc: Harold F. Reis, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)

US NRC
DISTRICT SERVICES
BRANCH

1978 JUL 31 AM 10 35

RECEIVED DISTRIBUTION
SERVICES UNIT

782140109

A002
S.11

24

000000

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 3 9 14 15 25 26 30 37 38
FIL SIL IS 1 2 0 0 1 - 0 0 0 0 0 0 1 - 0 0 0 3 4 1 1 1 1 1 1 4 5
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

01 3 50 61 53 59 74 75 30
CONT
01 3 50 61 53 59 74 75 30
REPORT SOURCE L 6 0 15 10 10 10 1 3 13 15 7 0 6 10 17 17 18 3 0 17 10 17 17 18 9
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

012 During power ascension physics testing following a refueling outage, CEA
013 #65 dropped. Reactor power was about 80 percent and the CEA group, of
014 which CEA #65 was a part, was in the process of being inserted manually
015 for testing. Required action in accordance with Technical Specification
016 3.1.3.1.e was taken and CEA #65 was restored to its normal position within
017 the applicable time limit.

013 7 8 9
09 3 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
R B 11 X 12 X 13 Z Z Z Z Z Z Z 14 X 15 Z 16
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
7 18 1 0 2 10 1 0 3 L 0
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED APPROX. FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
Z 18 Z 19 B 20 Z 21 10 10 10 1 Y 22 N 24 Z 25 Z 9 9 9 9 26
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The cause of the dropped CEA is not known. No cause could be determined
11 for tripping and no other abnormal conditions were found. CEA #65
12 operated properly when restored to its normal position and has performed
13 normally for four weeks.

13 7 8 9 30
15 3 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
B 23 0 18 10 29 NA A 31 Operator Observation 32
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
15 3 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
Z 33 Z 34 NA NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
17 3 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
0 0 0 37 Z 33 NA
PERSONNEL INJURIES NUMBER DESCRIPTION
13 3 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
0 0 0 40 NA
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
19 3 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
Z 42 NA
PUBLICITY ISSUED DESCRIPTION
20 3 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
N 44 NA
NRC USE ONLY

NAME OF PREPARER M. A. Schoppman

PHONE: (305) 552-3802

REPORTABLE OCCURRENCE 335-78-20
LICENSEE EVENT REPORT
PAGE TWO

Additional Event Description

As a result of the reactivity insertion, azimuthal power tilt (T_q) increased to 0.076 and total integrated radial peaking factor (F_r^t) increased to 1.576, which required action in accordance with Technical Specifications 3.2.4 and 3.2.3, respectively. Reactor power was reduced, and T_q and F_r^t were returned to normal within the applicable time limits. This was the third occurrence of a dropped CEA for which the cause is not known (refer to LER 335-77-6 and LER 335-78-18).