

A 07/10/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL

50-335

REC: X OREILLY J P
NRC

ORG: SCHMIDT A D
FL PWR & LIGHT

DOCDATE: 06/28/78
DATE RCVD: 07/07/78

DOCTYPE: LETTER NOTARIZED: NO
SUBJECT:

COPIES RECEIVED
LTR 1 ENCL 1

FORWARDING LICENSEE EVENT REPT (RO 50-335/78-019) ON 05/30/78 CONCERNING
DURING SPECIAL LOW PWR FEEDWATER CONTROL SYSTEM TEST, A 15% FEEDWATER BYPASS
CONTROL VALVE INADVERTENTLY OPENED FULLY CAUSING EXCESSIVE COOLING OF 1A
STEAM GENERATOR.

PLANT NAME: ST LUCIE #1

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL: *m*

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF ~~OREILLY~~ RC**W/4 ENCL

INTERNAL:

REG FILE ENCL
I & E**W/2 ENCL
I & C SYSTEMS BR**W/ENCL
NOVAK/CHECK**W/ENCL
AD FOR ENG**W/ENCL
HANAUER**W/ENCL
AD FOR SYS & PROJ**W/ENCL
ENGINEERING BR**W/ENCL
KREGER/J. COLLINS**W/ENCL
K SEYFRIT/IE**W/ENCL

NRC PDR**W/ENCL
MIPC**W/3 ENCL
EMERGENCY PLAN BR**W/ENCL
EEB**W/ENCL
PLANT SYSTEMS BR**W/ENCL
AD FOR PLANT SYSTEMS**W/ENCL
REACTOR SAFETY BR**W/ENCL
VOLLMER/BUNCH**W/ENCL
POWER SYS BR**W/ENCL

EXTERNAL:

LPDR'S
FT PIERCE, FL**W/ENCL
TIC**W/ENCL
NSIC**W/ENCL
ACRS CAT B**W/16 ENCL

A104

DISTRIBUTION: LTR 45 ENCL 45
SIZE: 1P+1P

CONTROL NBR: 781880119

***** THE END *****

60

REGULATORY DOCKET FILE COPY



June 28, 1978

PRN-LI-78-173

US NRC
DISTRIBUTION SERVICES
BRANCH

1978 JUL 7 AM 8 39

RECEIVED DISTRIBUTION
SERVICES UNIT

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N. W., Suite 1217
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 335-78-19
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: MAY 30, 1978

TECHNICAL SPECIFICATION 3.1.1.5
RCS AVERAGE TEMPERATURE

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

for A. D. Schmidt
A. D. Schmidt
Vice President
Power Resources

MAS/pa

Attachment

cc: Harold F. Reis, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)

781880119

A002
5/11

100

100

100

100

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59

7 3 14 25 26 30 37 CAT 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CCNT
01
7 3

REPORT
SOURCE L 6 10 5 1 0 0 1 3 1 3 5 7 10 5 1 3 1 0 7 8 3 10 6 1 2 8 1 7 1 8 9
50 61 DOCKET NUMBER 63 63 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During a special low power (about 3%) feedwater control system test, a 15%
03 feedwater bypass control valve inadvertently opened fully causing excessive
04 cooling of 1A Steam Generator. Reactor coolant system average temperature
05 dropped slightly below 515F (about 1F) requiring ACTION in accordance with
06 Specification 3.1.1.5. The reactor was tripped manually when this occurred.
07 This was the first occurrence of this type at St. Lucie.

01a		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50	
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMP. SUBCODE		VALVE SUBCODE		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTOOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRO-1 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER																																																							
R B		E		X		C		Z		0119		013		L		0		E		Z		A		B		000		N		N		C490																																																									

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 A vendor proposed modification of the 15% Feedwater Control System was tem-
11 porarily installed on the A loop for feasibility testing (to improve stabil-
12 ity of the automatic mode). Gain settings based on analytical results
13 proved to be unrealistic and caused the bypass valve to open. The settings
14 were changed to allow completion of the test.

FACILITY STATUS (1) 5 (2) X (3) 23 POWER (4) 0 (5) 0 (6) 3 (7) 29 OTHER STATUS (30) Special Test (31) A (32) Operator Observation (33) DISCOVERY DESCRIPTION (34)

ACTIVITY CONTENT
RELEASED OF RELEASEZ

1 5 7 3 3 10 11

AMOUNT OF ACTIVITY (35)

N/A

LOCATION OF RELEASE (36)

N/A

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION				
1	7	0	0	0	37	Z	23	N/A	

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
113	0000	30	N/A

LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE	DESCRIPTION	
19	7 (42) N/A	10

ISSUED		DESCRIPTION		NRC USE ONLY	
2	1	N	(44)	N/A	

NAME OF PREPARER M. A. Schoppman

PHONE: (305) 552-3802