

VIRGINIA ELECTRIC AND POWER COMPANY

RICHMOND, VIRGINIA 23261

June 3, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Serial No. 486
NO/EHT:baw
Docket No. 50-280
License No. DPR-32

Dear Mr. O'Reilly:

IE Bulletin 79-13
Metallurgical Examination Results for
Surry Power Station Unit 1

In response to the subject bulletin, "Cracking in Feedwater System Piping", Virginia Electric and Power Company herewith forwards the attached Westinghouse WCAP-6938, Metallurgical Investigation of Cracks in the Steam Generator Feedwater Lines of Surry Station No. 1. Our letter Serial No. 5308, dated September 5, 1979, contained a commitment to provide this information. Please note that, despite the December, 1979, date of the attached report, it was received by us on May 27, 1980.

If you have any questions or require additional information, please contact this office.

Very truly yours,

Original signed by
B. R. Sylvia

B. R. Sylvia
Manager-Nuclear Operations
and Maintenance

cc: Director, Office of Inspection
and Enforcement
Division of Reactor Operations Inspection
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555 (w/attachment)

Office of Nuclear Reactor Regulation
Attn: Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
Division of Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555 (w/attachment)

8006090388

4001
5/11