

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 V A S P S 1 00 - 000000 - 00 3 4 1 1 1 1 4 5  
7 E 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 58

01 REPORT SOURCE L E 0 5 0 0 0 2 8 0 7 0 5 1 6 8 0 E 0 6 0 5 8 0 9  
7 E 9 DOCKET NUMBER 66 67 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

012 While Releasing Waste Gas Decay Tank 1-GW-TK-1B an operator observed that  
013 the Tank was still lined up to receive gaseous waste from Boron Recovery  
014 System. This is Nonconservative with respect to T.S. 3.11.B.6 and is  
015 reportable Per T.S. 6.6.2.b.2. Process vent particulate and Gaseous Monitors  
016 were operable and were capable of performing their intended function Per T.S.  
017 Table 3.7-5. Therefore Health and Safety of the public were not affected.

0 E 80

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
7 E 9 M B 11 A 12 A 13 Z Z Z Z Z Z 14 Z 15 Z 16  
10 11 12 13 14 15 16 20

17 LER/RO REPORT NUMBER 8 0 23 24 25 26 27 28 29 30 31 32  
21 22 23 24 25 26 27 28 29 30 31 32  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
7 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 Z 25 Z 9 9 9 26  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The inlet valve to the tank (1-GW-29) was inadvertently left open. Action  
11 was taken to terminate the release and to line up the tanks properly as  
12 required by the station procedures.

13

14

15 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32  
7 E 9 E 22 1 0 0 29 NA A 31 Operator Observation  
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36  
7 E 9 Z 33 Z 34 NA NA  
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  
7 E 9 0 0 0 37 Z 38 NA  
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

18 PERSONNEL INJURIES NUMBER DESCRIPTION 41  
7 E 9 0 0 0 40 NA  
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43  
7 E 9 Z 42 NA  
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

20 PUBLICITY ISSUED DESCRIPTION 45  
7 E 9 N 44 NA  
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

NAME OF PREPARER J.L Wilson

PHONE: (804) 357-3184

ATTACHMENT 1  
SURRY POWER STATION, UNIT NO. 1  
DOCKET NO: 50-280  
REPORT NO: 80-028/03L-0  
EVENT DATE: 5-16-80

TITLE OF REPORT: GASEOUS WASTE TANK (1-GW-TK-1B) RELEASE

1. DESCRIPTION OF EVENT:

During steady state operation of Surry Unit No. 1 at 100% power an operator discovered that the inlet valve to 1-GW-TK-1B was inadvertently left open thereby establishing a flow path into the tank that was being released. This is nonconservative with respect to T.S. 3.11.B.6 and is reportable Per T.S. 6.6.2.b.2.

2. PROBABLE CONSEQUENCES/STATUS OF REDUNDANT SYSTEM:

Process vent particulate and gaseous monitors RM-GW-101 and RM-GW-102 were operable and were capable of terminating the release if the activity in the discharge line had exceeded the setpoints for the monitors. Therefore health and safety of the public were not affected.

3. CAUSE OF EVENT:

The cause is determined to be personnel error. The inlet valve 1-GW-29 to the waste gas decay tank 1-GW-TK-1B was inadvertently left open.

4. IMMEDIATE CORRECTIVE ACTION:

The Release was terminated.

5. SCHEDULED CORRECTIVE ACTION:

None required

6. ACTION TAKEN TO PREVENT RECURRENCE:

Procedure has been revised instructing the operators to check and to make sure that the inlet valve to the tank is closed prior to commencing a release.

7. GENERIC IMPLICATIONS:

None