

CONTROL BLOCK:

						(1)
--	--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	V	A	S	P	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	LICENSEE CODE						14	LICENSE NUMBER										25	LICENSE TYPE					30	CAT		58

CON'T

0	1	REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE									
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																			
		L	6	0	5	0	0	0	2	8	0	7	0	9	2	3	8	0	8	1	0	2	3	8	0	9															

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 With refueling in progress, the radiation monitoring sampling pumps, 1-SW-P-5C and D
0 3 were found to be inoperable. These pumps are required for post accident radiation
0 4 monitoring of the service water from the recirculation spray heat exchangers.. This is
0 5 reportable as PerT.S. 6.6.2.b(4). Other monitors and/or methods were available for the
0 6 detection and identification of a leaking heat exchanger. Therefore the health and
0 7 safety of the public were not affected.

08 | _____ | 80

09		SYSTEM CODE X X		CAUSE CODE E		CAUSE SUBCODE X		COMPONENT CODE P U M P X X				COMP. SUBCODE R		VALVE SUBCODE 7	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
LER/RO REPORT NUMBER 17		EVENT YEAR 8 0		SEQUENTIAL REPORT NO. 0 6 8		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0		ACTION TAKEN A		FUTURE ACTION Z	
33		34		35		36		37		38		39		40	
EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED Y		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER A		COMPONENT MANUFACTURER T 0 7 5		26	
19		20		21		22		23		24		25		26	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The pump impeller and seals were found to be corroded preventing the shafts from
1 1 rotationg. All four pumps will be removed, inspected, and tested prior to Unit
1 2 startup.
1 3
1 4

FACILITY STATUS (1) 5 (X) (28) % POWER (0) (0) (0) (29) OTHER STATUS (30) S/G Replacement METHOD OF DISCOVERY (A) (31) DISCOVERY DESCRIPTION (32) Operator Observation

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 7 33 7 34 N/A N/A

7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	(38)	N/A		

PERSONNEL INJURIES		DESCRIPTION (41)	
NUMBER			
1 8	0 0 0 (40)	N/A	

		LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE		DESCRIPTION		
1	9	7	(42)	N/A

8 9 10		PUBLICITY		80	
ISSUED		DESCRIPTION		NRC USE ONLY	
2	0	N	(44)	N/A	

· NRC USE ONLY

NAME OF PREPARED J. L. Wilson

PHONE: (804) 357-3184

ATTACHMENT 1
SURREY POWER STATION, UNIT 1
DOCKET NO: 50-280
REPORT NO: 80-068/03L-0
EVENT DATE: 09-24-80

TITLE OF EVENT: 1-SW-P-5C-5D FAILURE

1. Description of Event:

On 9-23-80, with refueling in progress, a service water flush of the Recirculation Spray heat exchangers was being conducted. The RSHX radiation monitoring sample pumps (1-SW-P-5A, 5B, 5C, and 5D) were manually started. 1-SW-P-5C & 5D were found to be inoperable. Initial investigation revealed that 1-SW-P-5D was drawing locked rotor current and that the motor overload heaters for 1-SW-P-5C had been removed. The overload heaters were replaced. 1-SW-P-5C subsequently drew locked rotor current.

This reportable per Technical Specification 6.6.2.b(4).

2. Probable Consequences and Status of Redundant Equipment:

The Recirc Spray Service Water Radiation Monitoring system, of which these pumps are part, performs two functions 1) detection of outleakage of RS fluid to the service water system 2) identification of the leaking RS heat exchanger. The RS service water system discharges to the circulating water discharge tunnel. The discharge tunnel radiation monitor will also detect outleakage. The FSAR assumes only 2 of 4 RS subsystems to be operable, thereby allowing the isolation of RS subsystems (one at a time) to identify the leaking heat exchanger. Therefore the health and safety of the public were not affected.

3. Cause of Occurance:

The pump seals and impeller were found to be corroded thereby preventing the pump shaft from rotating.

4. Immediate Corrective Action:

Since the unit was defueled, the immediate corrective action was to issue a maintenance request for the repair of the pumps.

5. Subsequent Corrective Action:

Pump 5C and 5D will be repaired and tested prior to the startup of this unit. In addition, pumps 5A and 5B will be inspected and retested.

6. Action taken to Prevent Recurrence:

The Recirc Spray Service Water Radiation Monitoring sample pumps will be flow tested and preventative maintenance will be performed each refueling outage.

7. Generic Implications:

None

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	8	1	7	0	9	2	4	8	0	8	1	0	2	3	8	0	9
60	61								68	69						74	75							80
DOCKET NUMBER										EVENT DATE										REPORT DATE				

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	8	
---	---	--

09		SYSTEM CODE W A		11	CAUSE CODE X		12	CAUSE SUBCODE Z		13	COMPONENT CODE P U M P X X				14	COMP. SUBCODE B		15	VALVE SUBCODE Z		16
7	8	9	10		11	12		13	14	15	16	17	18	19	20						
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19		20		21		22		23		24		25		26		27	
17		18		19																	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	4	
---	---	--

7		8		9								80	
		FACILITY STATUS								METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1		5		E		(28)		% POWER		OTHER STATUS		(30)	
1		0		0		(29)		NA		(31)		Operational Event	
7		8		9		10		11		12		13	
44		45		46		47		48		49		80	

ACTIVITY		CONTENT		RELEASED		OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	6	Z	33	Z	34	NA		NA			

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION (39)				
1	7	0	0	0	(37)	Z	(38)	NA	

7	8	9	11	12	13	80
		PERSONNEL INJURIES				
		NUMBER	DESCRIPTION		(41)	NA

1	8	0	0	0	(40)																80
7	8	9	11	12																	
LOSS OF OR DAMAGE TO FACILITY					(43)																

TYPE		DESCRIPTION		NA	
1	9	Z	(42)	8010290166	
7	8	9	10	80	

PUBLICITY
 ISSUED DESCRIPTION (45) NA NRC USE ONLY
 2 0 N (44)

NRC USE ONLY

J. L. Wilson

PHONE: (804) 357-3184

ATTACHMENT 1
SURRY POWER STATION, UNIT 2
DOCKET NO: 50-281
REPORT NO: 80-018/03E-0
EVENT DATE: 09-24-80

TITLE OF EVENT

2-SW-P-10A MALFUNCTION

1. Description of Event:

With the unit at full power, the charging pump service water pumps, 2-SW-P-10A, would not develop the proper discharge pressure. This contrary to T.S.-3.3.A.8.b. and is reportable per T.S.-6.6.2.b(2).

2. Probable Consequences of Occurrence:

The charging pump service water pumps supply cooling water to the charging pump intermediate seal and lube oil coolers. The "B" pump was operable. Therefore the health and safety of the public were not affected.

3. Cause of Occurrence:

The reduced capacity of 2-SW-P-10A was caused by the accumulation of sediments and suspended material in the suction side of the pump.

4. Immediate Corrective Action:

The immediate corrective action was to inspect and clean the pump suction strainer. This action was followed by submitting an MR to have the pump inspected and repaired if necessary.

5. Subsequent Corrective Action:

The subsequent corrective action was to disassemble, inspect, and clean the pump. The pump was subsequently verified operable.

6. Action Taken to Prevent Recurrence:

No additional actions deemed necessary

7. Generic Implications:

None