

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1	REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE									
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																			
		L	6	0	5	0	0	0	2	8	1	7	0	1	0	7	8	1	8	0	1	3	0	8	1	9															

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | With Unit No. 2 at 100% power, "A" Reactor Trip Breaker failed to open while per-

0 3 | forming PT-8.1. T.S.4.1, table 4.1-1, requires PT-8.1 to be performed monthly. This

0 4 | event is reportable per T.S.6.6.2.b.(2). The "B" Reactor Trip Breaker operated

0 5 | satisfactorily during the performance of PT-8.1. Therefore, the health and safety of

0 6 | the public were not affected.

0	7
---	---

03 | _____

0 9 7 8 I A 9 10 11 E 11 12 B 12 13 C K T B R X 13 14 A 14 15 Z 15 16

(17) LER/RO REPORT NUMBER 81 — 004 / 03 L — 0

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
A	18	Z	19	Z	20	Z	21	0	0	0	0	Y	23	N	24	A	25	W	1	2	0
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | A sporadic failure of the under voltage device prevented the Breaker from opening. A

1 1 | missing bushing created excessive play in the UV device's linkage. The under voltage

1 2 | device was replaced and the breaker tested.

1	3
---	---

7 8 9 80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION			
1	5	E	28	1	0 0	29	N/A	B	31	Routine test	32

7 8 9 10 12 13 44 45 46 80

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 Z (33) Z (34) N/A

7 8 9 10 11 44

45 46 80

LOCATION OF RELEASE (36)

N/A

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z	(38) N/A	(39)		

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	3	0	0	0	40 N/A

7		9		11		12		30	
LOSS OF OR DAMAGE TO FACILITY (43)									
TYPE		DESCRIPTION							
1	9	Z	(42)	N/A					

7		8	9	10	30									
PUBLICITY														
ISSUED		DESCRIPTION												
2	0	NT	(44)	(45)	N/A									
					NRC USE ONLY									

NRC USE ONLY

2	0	N	(44)	N/A																			
7	3	9	10	58										59 30									

NAME OF PREPARER J. L. Wilson

PHONE: (804) 357-2941 Ext 210

8102050 582

ATTACHMENT 1
SURRY POWER STATION, UNIT 2
DOCKET NO: 50-281
REPORT NO: 81-004/03L-0
EVENT DATE: 1-7-81

TITLE of REPORT: REACTOR TRIP BREAKER FAILURE

1. DESCRIPTION of EVENT:

With Unit No.2 at 100% power, "A" Reactor Trip Breaker failed to open while performing PT-8.1 (Monthly Reactor Protection System Logic). The "A" Reactor Trip bypass breaker was racked in at this time, The bypass breaker receives a trip signal from "B" train of RPS. Technical Specification 4.1, table 4.1-1, requires PT-8.1 to be performed monthly. This event is reportable per Technical Specification 6.6.2.b(2).

2. PROBABLE CONSEQUENCES and STATUS of REDUNDANT EQUIPMENT:

The power to the Control Rod Drive Mechanisms (CRDM) is fed through two series reactor trip breakers. Each trip breaker receives a trip signal from independent and redundant actuation trains. The tripping of either breaker will remove power from the CRDM's, thereby inserting the control rods into the core. The "B" Reactor Trip Breaker operated satisfactory during the performance of PT-8.1 and would have performed its intended function. Therefore, the health and safety of the public were not affected.

3. CAUSE:

The failure of "A" Reactor Trip Breaker was caused by a sporadic failure of the under voltage tripping device. The failure of a small retaining clip had allowed a bushing to be dislodged, thereby creating an excessive amount of play in the mechanical linkage of the under voltage device.

4. IMMEDIATE CORRECTIVE ACTION:

The "A" Reactor Trip Breaker was replaced and tested satisfactory.

5. SUBSEQUENT CORRECTIVE ACTION:

The under voltage device was replaced. The malfunctioning under voltage device was operated approximately 100 times in an attempt to duplicate the event. The under voltage device failed to function only once.

6. ACTION TAKEN TO PREVENT RECURRENCE:

Electrical Maintenance procedures will be revised to address the inspection of the retaining devices.

7. GENERIC IMPLICATIONS:

Since the other under voltage devices were inspected and failed to show any similar problems, this appears to be an isolated case.