

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 V A S P S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T  
01 L 6 0 5 0 0 0 2 8 0 7 0 1 2 9 8 1 8 0 2 1 9 8 1 9  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During the performance of PT-26.1, Radiation Monitoring Equipment Test, with the  
03 unit I defueled and unit 2 at 100% power, the Radiation Alarm Setpoint for the  
04 Component Cooling System was found to be greater than twice background as listed in  
05 Tech. Spec. 3.7, Table 3.7-5. This is reportable in accordance with Tech. Spec.  
06 6.6.2.b.(4). Since the activity levels were within allowable limits, the health  
07 and safety of the public were not affected.  
08 \_\_\_\_\_  
7 8 9 80

09 M C 11 X 12 Z 13 I N S T R U 14 Y 15 Z 16  
7 8 9 10 11 12 13 18 19 20

17 8 1 — 0 0 3 — 0 3 L — 0  
21 22 23 24 26 27 28 29 30 31 32

18 Z 19 Z 20 Z 21 0 0 0 0 22 Y 23 N 24 A 25 V 1 1 5 26  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The improper setpoint was attributed to a decrease in background radiation levels.  
11 The activity levels in the CC system were verified to be within allowable limits  
12 and the setpoint for monitor, RM-CC-105 and 106, were reset.  
13 \_\_\_\_\_  
14 \_\_\_\_\_  
7 8 9 80

15 H 28 0 0 0 29 N/A B 31 Routine Test 32  
7 8 9 10 12 13 44 45 46 80

16 Z 33 Z 34 N/A N/A 36  
7 8 9 10 11 44 45 80

17 0 0 0 37 Z 38 N/A 39  
7 8 9 10 11 12 13 80

18 0 0 0 40 N/A 41  
7 8 9 10 11 12 80

19 Z 42 N/A 43  
7 8 9 10 11 12 80

20 N 44 N/A 45  
7 8 9 10 11 12 80

8102250 426

NAME OF PREPARER J. L. Wilson PHONE: (804) 357-3184

NRC USE ONLY

ATTACHMENT , PAGE 1 of 1  
SURRY POWER STATION, UNIT I  
DOCKET NO: 50-280  
REPORT NO: 81-003/03L-0  
EVENT DATE: 01-29-81

TITLE OF EVENT: RADIATION MONITORS (RM-CC-105 and 106) SETPOINT

1. DESCRIPTION OF EVENT:

During the performance of PT-26.1, Radiation Monitoring Equipment Test, with Unit 1 defueled and Unit 2 at 100% power, the Radiation Alarm Setpoints for the Component Cooling System was found to be greater than twice background as listed in Tech. Spec. 3.7, Table 3.7-5. Operating in this condition, the Component Cooling System's surge tank vent valve would not have automatically closed at twice background. This event is reportable in accordance with Tech. Spec. 6.6.2-b.(4).

2. PROBABLE CONSEQUENCES AND STATUS OF REDUNDANT SYSTEMS:

Upon discovery of the improper setpoints, the activity levels in the CC system were checked, and verified to be within allowable limits. Consequently, the automatic operation of the surge tank vent valve was not required and the health and safety of the public were not affected.

3. CAUSE:

The improper setpoints were attributed to a decrease in background radiation levels.

4. IMMEDIATE CORRECTIVE ACTION:

Activity levels in the CC system were verified to be within allowable limits and a maintenance report initiated to change the monitor's setpoints.

5. SUBSEQUENT CORRECTIVE ACTION:

The setpoints for monitors, RM-CC-105 and 106, were reset.

6. ACTION TAKEN TO PREVENT RECURRENCE:

Administrative setpoints have been established to prevent recurrence.

7. GENERIC IMPLICATIONS:

None.