

## LICENSEE EVENT REPORT

UPDATED REPORT-PREVIOUS REPORT DATED 3-27-81

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 V A S P S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CONT

0 1 REPORT SOURCE L 6 0 5 0 0 0 2 8 0 7 0 2 2 5 8 1 8 0 5 0 4 8 1 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80  
DOCKET NUMBER EVENT DATE REPORT DATE

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On February 25, 1981, radiation monitor recorder (RR-175) was found to be printing  
0 3 erratically. This is contrary to T.S. 3.11A.5, 3.11.B.4, 4.9C and is reportable per  
0 4 T.S. -6.6.2.b(4). A liquid waste release that was in progress was terminated  
0 5 immediately. The associated radiation monitors, including the alarm and automatic  
0 6 actuating functions, were operable. Therefore, the health and safety of the public  
0 7 were not affected.

0 8  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
M C 11 E 12 B 13 I N S T R U 14 R 15 Z 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

17 LER/RO REPORT NUMBER 8 1 0 0 4 0 3 X 1  
21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
A 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 A 25 H 2 6 0 26  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause was a loose gear on the balance motor, thereby allowing the drive cable to  
1 1 slip. A set screw on the drive gear was tightened and the recorder returned to  
1 2 service.

1 3

1 4

1 5 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
H 28 0 0 0 29 N/A A 31 Operator Observation  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
Z 33 Z 34 N/A N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
0 0 0 37 Z 38 N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION  
0 0 0 40 N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
Z 42 N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

2 0 PUBLICITY ISSUED DESCRIPTION  
N 44 N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NRC USE ONLY

NAME OF PREPARER J. L. Wilson

PHONE: (804) 357-3184

8105080269

UPDATED REPORT-PREVIOUS REPORT DATED 3-27-81

ATTACHMENT 1 (PAGE 1 of 1)  
SURRY POWER STATION, UNIT 1  
DOCKET NO: 50-280  
REPORT NO: 81-004/03X-1  
EVENT DATE: 02-25-81

TITLE OF REPORT: RADIATION MONITOR RECORDER (RR-175) MALFUNCTION

1. DESCRIPTION OF EVENT:

With Unit 1 defueled, and Unit 2 operating steady state at 100% power, radiation monitor recorder (RR-175) was found to be printing erratically and therefore was declared inoperable. This is contrary to T.S. 3.11.A.5, T.S. 3.11.B.4, and T.S. 4.9C and is reportable as per T.S. 6.6.2.b.(4).

2. PROBABLE CONSEQUENCES AND STATUS OF REDUNDANT SYSTEMS:

The radiation monitor recorder (RR-175) serves to record, for permanent record, the gross activity of liquids and gases being released. The recorder, in itself, does not mitigate the consequences of any system malfunction. The associated radiation monitors, including the alarm and automatic actuating functions, remained operable. The discharge tunnel radiation monitor and its recorder remained operable. Therefore, the health and safety of the public were not affected.

3. CAUSE:

The cause of the recorder malfunction was due to a loose gear on the balance motor which allowed the drive cable to slip.

4. IMMEDIATE CORRECTIVE ACTION:

The immediate corrective action was to terminate a liquid waste release that had just started. Also, as outlined in abnormal procedure 5.16 and 5.17, a check was made to insure no other releases were in progress.

5. SUBSEQUENT CORRECTIVE ACTION:

A set screw on the loose drive gear was tightened and the drive cable was replaced. The recorder was proven operable and returned to service.

6. ACTIONS TAKEN TO PREVENT RECURRENCE:

Preventative maintenance is performed on these recorders at least twice per year. Therefore, no additional actions are deemed necessary.

7. GENERIC IMPLICATIONS:

This is a random event and as such is not considered to be generic.