

*Certified
Mail*

AMERICAN ELECTRIC POWER Service Corporation



2 Broadway, New York, N. Y. 10004
(212) 422-4800

JOHN E. DOLAN

Senior Executive Vice President
Engineering & Construction

May 31, 1977

Donald C. Cook Nuclear Plant Unit Nos. 1 and 2
Docket Nos. 50-315 and 50-316
DPR No. 58
CPPR No. 61

Mr. J. G. Keppler, Regional Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

This letter is in response to your letter of April 29, 1977, which transmitted to us IE Bulletin No. 77-01 entitled, "Pneumatic Time Delay Relay Setpoint Drift." You requested us, if we have been notified of the potential problem by the manufacturer, to describe actions taken regarding corrective measures to identify and resolve any setpoint drift problems with the ITE time delay relays. You also requested us to provide the basis for concluding that existing pneumatic time delay relays are functioning as required, or provide plans to assure satisfactory operation.

We have not received notification of any deficiencies in pneumatic time delay relays prior to the receipt of IE Bulletin No. 77-01. There are no ITE pneumatic time delay relays in use at the Donald C. Cook Nuclear Plant.

JUN 6 1977

10 2
GD

Mr. J. G. Keppler

- 2 -

May 31, 1977

All time delay relays used in safety systems are Elastic Stop Nut "Agastat" series 7000 relays. These relays have a repeat accuracy of $\pm 5\%$. No evidence of drift in excess of the specified 5% has been detected. All critical timing circuits make allowance for the 5% tolerance.

Yours very truly,

John E. Dolan
John E. Dolan

Senior Executive Vice President
Engineering and Construction

JED:mam

cc: R. C. Callen
P. W. Steketee
R. Walsh
G. Charnoff
R. J. Vollen
R. S. Hunter
R. W. Jurgensen - Bridgman

