

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL

50-315

REC: KEPPLER J G
NRC

ORG: SHALLER D V
IN & MI PWR

DOCDATE: 01/06/78
DATE RCVD: 01/19/78

DOCTYPE: LETTER NOTARIZED: NO
SUBJECT:

COPIES RECEIVED
LTR 1 ENCL 1

FORWARDING SUPPLEMENTAL LICENSEE EVENT REPT (RO 50-315/77-41) ON 12/03/77
CONCERNING CONTROL ROOM PRESSURIZER LEVEL INDICATION IMPLIED A DEVIATION OF
8% BETWEEN CHANNELS I AND II, AND A DEVIATION OF 2% BETWEEN CHANNELS II AND
III... CORRECTING BLOCKS 59

PLANT NAME: COOK - UNIT 1

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL:

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BRANCH CHIEF DAVIS**W/4 ENCL

INTERNAL:

REG FILE**W/ENCL
I & E**W/2 ENCL
SCHROEDER/IPPOLITO**W/ENCL
NOVAK/CHECK**W/ENCL
KNIGHT**W/ENCL
HANAUER**W/ENCL
EISENHUT**W/ENCL
SHAO**W/ENCL
KREGER/J. COLLINS**W/ENCL
L. CROCKER**W/ENCL

NRC PDR**W/ENCL
MIPC**W/ENCL
HOUSTON**W/ENCL
GRIMES**W/ENCL
BUTLER**W/ENCL
TEDESCO**W/ENCL
BAER**W/ENCL
VOLLMER/BUNCH**W/ENCL
ROSA**W/ENCL

EXTERNAL:

LPDR'S
ST. JOSEPH, MI**W/ENCL
TIC**W/ENCL
NSIC**W/ENCL
ACRS CAT B**W/ 16 ENCL

DISTRIBUTION: LTR 28 ENCL 28
SIZE: 2P+2P

CONTROL NBR: 780200001

***** THE END *****

D. Lankam


REGULATORY DOCKET FILE COPY



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

January 6, 1978



Mr. J. G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

On December 30, 1977, Licensee Event Report #RO-050-315/77-41 was submitted to you in compliance with the reporting requirements listed in Appendix A of the Unit 1 Technical Specifications and the United States Nuclear Regulatory Commission Regulatory Guide 1.16, Revision 4, Section 2B. On line one of the aforementioned report, the required entries in blocks 59 and 60 were erroneously omitted. The errors have been corrected and the attached supplemental report is hereby submitted to you which supersedes the report previously submitted.

Sincerely,

D. V. Shaller
Plant Manager

/cga

Attachment

cc: J. E. Dolan
R. W. Jurgensen
G. E. Lien
R. Kilburn
R. J. Vollen, BPI
K. R. Baker, RO: III
P. C. Callen, MPSC
P. W. Steketee, ESQ.

A002
1/1
5
JAN 13 1978

780200001

100



J. G. Keppler
January 6, 1978
Page 2

cc: R. Walsh, ESQ.
G. Charnoff, ESQ.
G. Olson
J. M. Hennigan
PNSRC
J. F. Stietzel
DIR., IE (30 copies)
DIR., MIPC (3 copies)

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6
---	---	---	---	---	---

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE				EVENT TYPE							
01	M	I	D	C	1	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3
7	8	9			14	15											25	26			30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE											
01	CONT	L	L	0	5	0	-	0	3	1	5	1	2	0	3	7	7	0	1	0	6	7	8
7	8	57	58	59	60	61				68	69					74	75						80

EVENT DESCRIPTION

02	WHILE IN MODE 3, IT WAS FOUND THAT THE CONTROL ROOM PRESSURIZER LEVEL INDICATION																					80
03	IMPLIED A DEVIATION OF 8% BETWEEN CHANNELS I AND II, AND A DEVIATION OF 2%																					80
04	BETWEEN CHANNELS II AND III. THE UNIT WAS MAINTAINED IN MODE 3 WHILE TECHNICIANS																					80
05	INVESTIGATED THE CAUSE OF THE DEVIATION. (R0-050-315/77-41)																					80
06																						80

SYSTEM CODE	CAUSE CODE	COMPONENT CODE				PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION		
I	B	I	N	S	T	R	U	N	B	0	8	0	N
7	8	9	10	11	12	13	17	43	44	45	46	47	48

CAUSE DESCRIPTION

08	THE PRESSURIZER LEVEL TRANSMITTER OUTPUT SIGNALS WERE MEASURED WHICH CONFIRMED																					80
09	THE LEVEL DEVIATION INDICATED IN THE CONTROL ROOM. FURTHER INVESTIGATION																					80
10	REVEALED THAT THE DIFFERENCE WAS DUE TO A PARTIAL LOSS OF THE (SEE SUPPLEMENT)																					80

FACILITY STATUS	% POWER	OTHER STATUS		METHOD OF DISCOVERY	DISCOVERY DESCRIPTION						
G	0	0	0	N/A	B	N/A					
7	8	9	10	11	12	13	44	45	46		80

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY		LOCATION OF RELEASE						
Z	Z	N/A		N/A						
7	8	9	10	11	12	44	45			80

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION					
0	Z	N/A					
7	8	9	11	12	13		80

PERSONNEL INJURIES

NUMBER	DESCRIPTION					
0	N/A					
7	8	9	11	12		80

OFFSITE CONSEQUENCES

15	N/A																					80
----	-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION				
Z	N/A				
7	8	9	10		80

PUBLICITY

17	N/A																					80
----	-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	N/A																					80
----	-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19	N/A																					80
----	-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: T.P. BEILMAN

PHONE: 616-465-5901, EXT. 368

LICENSEE EVENT REPORT
SUPPLEMENT

CAUSE DESCRIPTION

TRANSMITTER REFERENCE LEGS. THE CHANNEL II LEVEL TRANSMITTER WAS PLACED OUT OF SERVICE, CALIBRATED AND THE REFERENCE LEG REFILLED. UPON RETURN TO SERVICE CHANNEL II INDICATED LESS THAN A 0.5% DIFFERENCE OF CHANNEL III. THE CHANNEL I LEVEL TRANSMITTER WAS SUBSEQUENTLY PLACED OUT OF SERVICE AND THE REFERENCE LEG FILLED. UPON RETURN TO SERVICE, CHANNEL I INDICATION WAS WITHIN 0.5% OF CHANNELS II AND III. NO FURTHER PROBLEMS HAVE BEEN ENCOUNTERED.